On-scene Investigation / Vehicle to Vehicle Dynamic Science, Inc. / Case Number:DS00-006 2000 Ford Taurus California May, 2000 This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points be coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the precrash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

Technical Report Documentation Page

		Technical Report Documentation Fage				
1. Report No.	2. Government Accession No.	3. Recipient Catalog No.				
DS00-006						
4. Title and Subtitle		5. Report Date				
In-Depth Accident Invest	tigation	January 29, 2001				
r	-8	6. Performing Organization Report No.				
7. Author(s)	- T	8. Performing Organization Report No.				
Dynamic Science	è, Inc.					
9. Performing Organization name and Addres	ss	10. Work Unit No. (TRAIS)				
Dynamic Science, Inc.						
530 College Parkway, S	ite. K	11. Contract or Grant no.				
Annapolis, MD 21401		DTNH22-94-D-27058				
12. Sponsoring Agency Name and Address		13. Type of report and period Covered				
U.S. Dept. of Transporta	ation (NRD-32)	[Report Month, Year]				
National Highway Traffic	2 Safety Administration	14. Sponsoring Agency Code				
400 7th Street, SW						
Washington, DC 20590						
15. Supplemental Notes						
16. Abstract						
asphalt roadway was dry and f lane, and a middle turn lane. T is a marked area for parking.	ia in May, 2000 at 1042 hours. The crash took place in a the free of defects. The north-south undivided roadway is comp The western edge of the northbound roadway is marked for the There are no controls for north or southbound traffic. The sp is comprised of one westbound and one eastbound travel la	prised of a northbound travel lane, a southbound travel bicycle traffic by a single white line. Adjacent to this lane beed limit is 56 km/h (35 mph) in both directions. The				

The case vehicle, a 2000 Ford Taurus four-door sedan driven by a restrained 40-year-old female (168 cm/66 in., 50 kg/110 lbs.), was traveling southbound approaching the intersection. The other vehicle, a 1989 Mercury Grand Marquis, driven by a 31-year-old male, was in the middle turn lane traveling northbound prior to making a left hand turn to go west. The rear left seat was occupied by a restrained 9-year-old male. The rear right seat was occupied by a second restrained 9-year-old male. The driver of the case vehicle indicated that she saw the Marquis moving slowly in the turn lane. She took her foot off the accelerator and then noticed that the Marquis was going to turn. She braked and swerved to the right to avoid the crash. The front of the case vehicle (12FDEW1) struck the right side of the Marquis. The case vehicle sustained a longitudinal delta v of -18.4 km/h (-11.4 mph) as computed by WinSmash. The impact was of insufficient magnitude to deploy the driver's air bag and the front right passenger's air bag. The driver's side seat belt pretensioner did however fire at this time.

There were no injuries to any of the parties in this crash.

17. Key Words		18. Distribution Statement	
Air bag, non-deployment, no injury, redesigned, pretensioner			
pretensioner 19. Security Classif. (of this report) 20. Security Classif. (of this page)		21. No of pages	22. Price

Form DOT F 1700.7 (8_72) Reproduction of this form and completed page is authorized

Dynamic Science, Inc. Accident Investigation Case Number: DS00-006

TABLE OF CONTENTS

Background
Description
Investigation Type1
Crash Location
Crash Date1
Notification Date1
Field Work Completed1
Summary
Scene Diagram
Detailed Information
Vehicles
Occupants7
Injuries and Injury Mechanisms
Occupant Kinematics

Attachment 1.	EDR report						11
---------------	------------	--	--	--	--	--	----

BACKGROUND:

Description:	This Advanced Occupant Protection Systems case was generated by DSI through existing insurance contacts. NHTSA was notified of the case on July 07, 2000. DSI was assigned the case on July 12, 2000 and an on-site investigation was conducted.
Investigation Type:	On-scene

Crash Location:	California
Crash Date:	May, 2000
Notification Date:	July 7, 2000
Field Work Completed:	July 12, 2000

SUMMARY:

This crash occurred in California in May, 2000 at 1042 hours. The crash took place in a three-leg intersection. The weather was clear and the asphalt roadway was dry and free of defects. The north-south undivided roadway is comprised of a northbound travel lane, a southbound travel lane, and a middle turn lane. The western edge of the northbound roadway is marked for bicycle traffic by a single white line. Adjacent to this lane is a marked area for parking. There are no controls for north or southbound traffic. The speed limit is 56 km/h (35 mph) in both



Figure 1. Case vehicle approach to area of impact

directions. The western leg of the intersection is comprised of one westbound and one eastbound travel lane. Eastbound traffic is controlled by a stop sign.

The case vehicle, a 2000 Ford Taurus four-door sedan driven by a restrained 40-year-old female (168 cm/66 in., 50 kg/110 lbs.), was traveling southbound approaching the intersection.

A1989 Mercury Grand Marquis, driven by a 31-year-old male, was in the middle turn lane traveling northbound prior to making a left hand turn to go west. The rear left seat was occupied by a restrained 9-year-old male. The rear right seat was occupied by a second restrained 9-year-old male.

The driver of the case vehicle indicated that she saw the Marquis moving slowly in the turn lane. She took her foot off the accelerator and then noticed that the Marquis was going to turn. She braked and swerved to the right to avoid the crash. The front of the case vehicle (12FDEW1) struck the right side of the Marquis.

The case vehicle sustained a longitudinal delta v of -18.4 km/h (-11.4 mph)¹ as computed by WinSmash. The



Figure 2. Exterior, case vehicle



Figure 3. Driver's seated position


downloaded Electronic Data Recorder (EDR) data indicates a cumulative longitudinal delta v of -16.7 km/h (-10.4 mph) at the 78 ms mark. The data indicates that the driver's seat belt was latched and that the pretensioner on the driver's side fired. The EDR report is included as an attachment to this report.

¹Calculated using stiffness values provided by Ford

The impact was of insufficient magnitude to deploy the driver's air bag and the front right passenger's air bag. The driver's side seat belt pretensioner did however fire at this time. The pretensioner tube measurement on the driver's side was 5.6 cm. There was no movement of the steering column shear capsules.

There were no injuries to any of the parties in this crash.

Scene Diagram



DETAILED INFORMATION

Vehicles

2000 Ford Taurus				
Description:	2000 Ford Taurus			
VIN:	1FAFO5222YGxxxxx	XX		
Odometer:	5,037 km (3,130 miles	5)		
Engine:	V6			
Reported Defects:	None			
Cargo:	None			
Damage Description:	Minor to moderate fro grille.	ntal crush to bumper and		
CDC:	12FDEW1			
Delta V:	Total	18.7 km/h (11.6 mph)		
	Longitudinal	-18.4 km/h (-11.4 mph)		
	Latitudinal	3.2 km/h (2.0 mph)		
	Energy	14,229 joules (10,495 ft-lbs)		

1989 Mercury Grand Marquis

Description:	1989 Mercury Grand Ma	rquis		
VIN:	Unknown			
Odometer:	Unknown			
Engine:	Unknown			
Reported Defects:	None reported			
Cargo:	Unknown			
Damage Description:	Described as "Major" side damage by police			
CDC:	Unknown			
Delta V:	Total	17.1 km/h (10.6 mph)		
	Longitudinal	-11.5 km/h (-7.1 mph)		
	Latitudinal	-12.7 km/h (-7.9 mph)		
	Energy	32,364 joules (23,847 ft-lbs)		

Occupants

Ford Taurus	Occupant 1
Age/Sex:	40/Female
Seated Position:	Front left
Seat Type:	Bucket
Height:	168 cm (66 in.)
Weight:	50 kg (110 lbs.)
Occupation:	Sales
Pre-existing Medical Condition:	None
Alcohol/Drug Involvement:	None
Driving Experience:	Unknown
Body Posture:	Normal, upright
Hand Position:	Both hands on steering wheel-at 1 and 11 o'clock positions.
Foot Position:	Right foot on brake, left on
	floor.
Restraint Usage:	floor. Lap and shoulder belt used properly.

Occupants

Mercury Grand Marquis

Age/Sex:	30/Male	9/Male	9/Male
Seated Position:	Front left	Rear left	Rear right
Seat Type:	Unknown	Unknown	Unknown
Height:	170 cm (67 in.)	Unknown	Unknown
Weight:	67 kg (147 lbs.)	Unknown	Unknown
Occupation:	Unknown	NA	NA
Pre-existing Medical Condition:	None noted	None noted	None noted
Alcohol/Drug Involvement:	None	NA	NA
Driving Experience:	Unknown	NA	NA
Body Posture:	Unknown	Unknown	Unknown
Hand Position:	Unknown	Unknown	Unknown
Foot Position:	Unknown	Unknown	Unknown
Restraint Usage:	Lap and shoulder belt used	Lap and shoulder belt used	Lap and shoulder belt used

Injuries and Injury Mechanisms

Ford Taurus

	<u>INJURY</u>	OIC CODE	<u>ICD-9</u>	<u>SOURCE</u>
Driver:	Not injured			
Mercury Grand Mar	quis			
	INJURY	OIC CODE	<u>ICD-9</u>	<u>SOURCE</u>
Driver:	Not injured			
Rear left occupant	Not injured			
Rear right occupant	Not injured			

Occupant Kinematics

The 40-rear-old female driver (168 cm/66 in., 50 kg/110 lbs.) of the case vehicle was seated in a forward facing fashion. She was wearing the available lap and shoulder belt. The shoulder belt upper anchorage was adjusted to the mid position. The seat was in the full rearward position at the time of inspection, but the driver indicated that she normally had the seat in a more middle position. The seat back was set at 13 degrees from vertical. The tilt steering wheel was adjusted to between the full up and the center position. The driver of the case vehicle indicated that she saw the Marquis moving slowly in the turn lane. She took her foot off the accelerator and then noticed that the Marquis was going to turn. She braked and swerved to the right to avoid the crash. At impact, the driver pitched forward and to the left in response to the 350 degree direction of force. The impact was of insufficient magnitude to deploy the driver's air bag and the front right passenger's air bag. The driver's side seat belt pretensioner did however fire at this time. The pretensioner tube measurement on the driver's side was 5.6 cm. There was no movement of the steering column shear capsules. There was a small scuff found on the lower left instrument panel, but there were no reported injuries.




Figure 5. Compressed driver's buckle




Figure 6. Possible contact point to lower left instrument panel

Attachment 1. EDR report



2000 Taurus/Sable EDR Report - Charts



EDR Summary Report

Page 2

2000 Taurus/Sable EDR Report - Memory Dump

Address	00	01	02	03	04	05	06	07	08	09	0A	0B	0C	0D	0E	0F
0800	OF	48	40	76	14	FB	FF	FF	FF	FF	0E	24	0 F	2D	3A.	4C
0810	CS	FF	OD	FF	52	60	52	60	60	52	E3	20	30	78	D6	A0
0820	80	03	28	37	5F	OF	0.F	0A	F5	-0A	B7	8.4	A1	5E	D5	AA .
0830	03	0C	1B	15	0.0	FF	3C	3C	80	0.6	28	6.4	6.4	0.0	0 C	01
0840	SA	96	50	FF	FF	FF	EF	DF	D2	E7	FF	72	4E	13	25	B1
0850	EC	14	0.9	0F	01	FF	FF	88	7F	FF	CD	4.4	08	FF	FF	9.5
0860	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
0870	05	38	E9	ED	E6	0.0	8F	FF	-59	46	31	41	0.0	0.2	FF	0.0
0880	02	E8	80	33	E8	80	30	E8	80	16	EF	80	FF	FF	0.0	FF
0890	FF	FF	OD	FF	FF	0.0	FF	FF	0.0	FF	FF	0.0	FF	FF	0.0	FF
08A0	0.4	0.0	40	0.0	0.0	0.0	0.9	0.0	0.0	0.0	FF	FF	FF	FF	FF	FF
08B0	0.2	FF	81	38	0.0	SD	01	FF	FF	FF	FF	FF	22	01	CE	11
03C0	FF	22	01	CE	12	31	01	CE	12	51	01	61	44	22	FF	FE
08 D0	01	0B	OC.	80	02	58	16	87	1F	BE	0.1	0 A.	0.0	8 C	0.1	0.4
08E0	0.0	FO	01	36	0.0	7.0	01	54	0.0	3F	0.2	30	0.2	C7	0.2	8A
08F0	05	14	07	08	01	20	0.3	CA	0.4	CE	0.6	40	73	33	0.0	A0
0900	3F	FF	0.0	03	00	4B	01	CC	00	0.3	0F	FF	0.0	14	0.0	78
0910	0.0	A0	0.0	6E	0A	16	FF	01	0.0	0.0	0.0	7F	0 F	0 C	0 F	0.2
0920	03	5A	32	46	05	50	02	02	FA	1E	08	0.0	-0A	1C	02	23
0930	- 0.9	- 06	28	32	-16-	20	16	1F	-5F	FF	FF	0.2	FF	FF	FF	11
0940	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
0950	- 33	0.0	0.0	0.0	- 33	0.0	0.0	0B	0.0	0.0	0.4	07	1F	5.4	28	0.0
0960	OD.	0.0	0.0	25	- 33	1B	0.9	0.0	0.0	0.0	0.0	20	2D	0.4	22	0.0
0970	0.0	0.0	AC	90	A3	78	B3	AE	AE	B1	A6	9E	BO	B1	B3	9B
0980	B1	AF	- AA	B1	C9	D2	BE	AA.	88	60	84	D5	89	C1	AC	68
0990	79	C9	E5	DF	C2	-64	C7	DE	A1	96	в7	BC	85	A1	B.9	9C
09A0	91	99	A6	98	96	AF	94	A4	9D	9A	97	98	A2	98	97	98
09B0	92	97	8C	93	8F	94	A1	A0	8E	9.9	A0	93	87	95	98	8 D
0900	- 99	96	8E	92	89	A6	89	81	85	81	73	- 77	- 74 -	7.4	72	7 D
09D0	TD	TC	83	7F	79	70	79	70	70	7F	80	82	83	83	7B	88
09E0	90	86	87	78	87	84	84	7B	81	7D	7C	7C	-7A	8 E	78	0.0
09F0	0.0	0.0	0.0	00	0.0	0.0	0.0	FF	FF	60	0.0	FF	FF	FF	FF	0.4

Hexidecimal Module Memory Dump

EDR Summary Report