On-scene Investigation / Vehicle to Vehicle
Dynamic Science, Inc. / Case Number: DS00-010
2000 Ford Taurus
Missouri
June, 2000

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points be coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the precrash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

Technical Report Documentation Page

1. Report No.	2. Government Accession No.	3. Recipient Catalog No.					
DS00-010							
4. Title and Subtitle			5. Report Date				
In-Depth Accident Inves	tigation		September 16, 2000				
			6. Performing Organization Report No.				
7. Author(s) Dynamic Science	e, Inc.		8. Performing Organization Report No.				
9. Performing Organization name and Addre	ess		10. Work Unit No. (TRAIS)				
Dynamic Science, Inc.							
530 College Parkway, S	Ste. K		11. Contract or Grant no.				
Annapolis, MD 21401			DTNH22-94-D-27058				
12. Sponsoring Agency Name and Address			13. Type of report and period Covered				
U.S. Dept. of Transporta	ation (NRD-32)		[Report Month, Year]				
National Highway Traffic	c Safety Administration		14. Sponsoring Agency Code				
400 7th Street, SW			The operation of the second of				
Washington, DC 20590)						
15. Supplemental Notes							
16. Abstract							
			ash took place on a curved two-lane, one-way lway was wet. The posted speed limit is 89 km/h				
second lane from the right. traveling eastbound in the f	The other vehicle, a 1985 Ch	evrolet C20 4 x 2 four-do gher speed than the case	7-year-old male, was traveling eastbound in the or pickup truck driven by a 23-year-old male, was evehicle. The front right seat was occupied by 42-				
vehicle. Both drivers lost co		ther vehicle veered to the	e lane line and struck the right side of the case e right and struck a concrete barrier on the right side				
concrete barrier with its fror	nt end. Both front air bags de	ployed at this time. Acc	t), crossed the adjacent lane, and also struck the ording to the EDR, this was a first stage stacted the right side of Vehicle 2 with its left side.				
			. He was not treated or transported. The driver cles were towed from the scene due to damage.				
17. Key Words		18. Distribution Statement					
Air bag, deployment, injur	ry, Ford, AOPS						
19. Security Classif. (of this report) 20. Security Classif. (of this page) 21. No of pages 22. Price							

Form DOT F 1700.7 (8_72) Reproduction of this form and completed page is authorized

Dynamic Science, Inc. Accident Investigation Case Number: DS00-010

TABLE OF CONTENTS

Background
Description
Investigation Type
Crash Location
Crash Date
Notification Date
Field Work Completed
Summary
Scene Diagram
Detailed Information
Vehicles
Occupants
Injuries and Injury Mechanisms
Occupant Kinematics
Attachments

1. EDR report

BACKGROUND:

Description: This Advanced Occupant Protection Systems (AOPS) case was

generated by DSI through existing insurance contacts. NHTSA was notified of the case on August 9, 2000. DSI was assigned the case on August 9,2000. Field work was completed on August 12, 2000.

Investigation Type: On-scene

Crash Location: Missouri
Crash Date: June, 2000
Notification Date: August 9, 2000
Field Work Completed: August 12, 2000

SUMMARY:

This two-vehicle crash occurred in Missouri in June, 2000 at 1010 hours. The crash took place on a curved two-lane, one-way interstate ramp. It was raining at the time of the crash and the level asphalt roadway was wet. The posted speed limit is 89 km/h (55 mph).

The case vehicle, a 2000 Ford Taurus 4-door sedan driven by an unrestrained 67-year-old male(173

cm/68 in., 91 kg/200 lbs), was traveling eastbound in the second lane from the right. Restraint use was based on a lack of physical evidence showing usage and a "Not Engaged" indication from the Event Data Recorder (EDR) report¹.

The other vehicle, a 1985 Chevrolet C20 4 x 2 four-door pickup truck driven by a 23-year-old male, was traveling eastbound in the first lane from the right at a higher speed than the case vehicle. The front right seat was occupied by 42-year-old female. The Chevrolet C20 was pulling a four-wheel, two-axle trailer.

As the Chevrolet was negotiating the curve, the driver lost control and this vehicle crossed the lane line and struck the right side (06RZES1) of the case



Figure 1. Front view, case vehicle – barrier impact

vehicle. Both drivers lost control of their vehicles. The Chevrolet veered to the right and struck a concrete barrier on the right side of the roadway. The Chevrolet then over-rode the barrier and came to rest on top of it.

¹See Attachment 1

The case vehicle also veered to the right (possibly after over-correcting to the left), crossed the adjacent lane, and also struck the concrete barrier with its front end (12FDEW1). The case vehicle sustained a longitudinal delta v of -19.2 km/h (-11.9 mph)². Maximum crush was located at C₆ and measured 17.5 cm (6.9 in.). The EDR reported a longitudinal cumulative delta V of -23.9 km/h (-14.9 mph) at the 78 ms mark.



Figure 2. Left side vehicle, Vehicle 1- impact 3

Both front air bags deployed at this time. According to the EDR, this was a first stage deployment. The case vehicle rotated clockwise after striking the barrier and contacted the right side of the other vehicle with its left side (09LDEW1).

The driver of the case vehicle sustained a minor contusion to his lower abdomen. He was not treated or transported. The driver and front right occupant of the other vehicle did not report any injuries.

Both vehicles were towed from the scene due to damage.



Figure 3. Right side view, Vehicle 1

The case vehicle was equipped with front left and front right frontal air bags and seat belt pretensioners at the front left and front right seating positions.

The driver's air bag was circular and measured 45 cm (17.7 in.) in diameter. It was equipped with two tethers and two vent holes. There appeared to be eight horizontal folds and possibly five vertical folds. There was black smudges on top left quadrant and an unknown yellow-colored transfer on the top right quadrant. The module cover opened in an "H" configuration. There were no indications of any damage to the cover.

²Calculated using WinSmash barrier option and using averaged d0/d1 values from NCAP test.

The front right occupant's frontal air bag was rectangular and measured 58 cm (22.8) laterally. It was equipped with two vent ports and did not have any tethers. On the face of the air bag there was cover-related scuffing. The single flap module did not sustain any damage.

Both front seat positions were equipped with seat belt pretensioners. The pretensioner barrels were checked and measured 11 cm (4.3 in.), indicating that they had not deployed.

There was no steering column stroke and the steering column breakaway coupling was intact. There was no intrusion nor any integrity loss.

The data from the RCM module was downloaded on scene.




Figure 4. Driver's seated position–shows left knee contact



Figure 5. Overview of deployed air bags

Scene Diagram



DETAILED INFORMATION

Vehicles

<u>Case vehicle</u>

Description: 2000 Ford Taurus SE four-door

VIN: 1FAFP56S4YGxxxxxx

Odometer: 13,848 km (8,605 miles)

Engine: 3.0 L 6

Reported Defects: None

Cargo: None

Damage Description: Moderate damage to front bumper. Light contact

to right rear side. Moderate contact damage along

entire left side. Towed from the scene.

CDC: Impact 1: 06RZES1

Impact 2: 12FDEW1
Impact 3: 09LDEW1

Delta V (Impact 2)³: Total 12.9 km/h (8.0 mph)

Longitudinal -12.8 km/h (-7.9 mph)

Latitudinal 2.2 km/h (1.4 mph)

Energy 11,461 joules

(8,452 ft-lbs)

³EDR reported a longitudinal cumulative delta V of -23.9 km/h (-14.9 mph) at the 78 ms mark.

Other vehicle				
Description:	1985 GMC conventional cab 4 x 2 four-door 3/4 ton pickup truck—pulling a trailer			
VIN:	1GTGC23W1F5xxxxxx			
Odometer:	Unknown			
Engine:	7.4L V8			
Reported Defects:	None			
Cargo:	Unknown			
Damage Description:	Police indicate contact damage to the rear of the right side, rear of the left side, and to the undercarriage. Vehicle was towed from the scene			
CDC:	Unknown			
Delta V:	Total	Unknown		
	Longitudinal	Unknown		
	Latitudinal	Unknown		
	Energy	Unknown		

Occupants

<u>Case vehicle</u> Occupant 1

Age/Sex: 67/Male

Seated Position: Front left

Seat Type: Bucket–cloth covered

Height: 173 cm (68 in.)

Weight: 91 kg (200 lbs.)

Occupation: Sales

Pre-existing Medical Condition: None reported

Alcohol/Drug Involvement: None

Driving Experience: >20 years

Body Posture: Normal, upright

Hand Position: Both on steering wheel. Left

higher than right while in turn.

Foot Position: Right foot on accelerator, left

on floor prior to initial impact

Restraint Usage: None used

Air bag: Deployed during second

impact (impact with bridge

rail)

Other vehicle Occupant 1 Occupant 2

Age/Sex: 23/Male 42/Female

Seated Position: Front left Front right

Seat Type: Unknown Unknown

Height: Unknown Unknown

Weight: Unknown Unknown

Occupation: Unknown Unknown

Pre-existing Medical Condition: None noted None noted

Alcohol/Drug Involvement: None NA

Driving Experience: <10 years NA

Body Posture: Unknown Unknown

Hand Position: Unknown Unknown

Foot Position: Unknown Unknown

Restraint Usage: Lap and shoulder, per police Lap and shoulder, per police

Injuries and Injury Mechanisms

Case vehicle

<u>INJURY</u> <u>OIC CODE</u> <u>ICD-9</u> <u>SOURCE</u>

Driver: Contusion, lower abdomen 590402.1,4 922.2 Air bag

Other vehicle

<u>INJURY</u> <u>OIC CODE</u> <u>ICD-9</u> <u>SOURCE</u>

Driver: Not injured

FR occupant: Not injured

Occupant Kinematics

The male driver (173 cm/68 in., 91 kg/200 lbs) of the case vehicle was seated in normal, upright position. At the time of the inspection, the seat was found to be located 29 cm rearward of the A pillar. According to the EDR report, the driver seat track was in the forward position⁴. The driver does not appear to have been wearing the available lap and shoulder belt. There were indications of usage, but nothing related to this crash. The EDR report indicated that the driver seat buckle was not engaged. There was negligible driver movement during the initial sideswiping type impact on the right side of the vehicle. The driver steered to the left in response to the impact, then steered sharply to the right as he overcorrected. As the case vehicle struck the barrier, the driver pitched forward and engaged the deploying air bag with his chest and lower abdomen. There is an indication that his left knee contacted the lower instrument panel.



Figure 7. Left knee contact




Figure 8. Left knee contact

⁴The "forward" position reported by the RCM is not fully forward.

2000 Taurus/Sable EDR Report - Summary Page



Investigation Data

File Name: File Read-out Date:	ds00-010.hex	File Save Date:	14-Aug-2000		
File Read-out Date:	N/A	Report Date:	14-Aug-2000		
Report Version:	1.3				

EDR Control Module Data

Data Validity Check:	Valid	EDR Model Version:	141
Time From Side Safing D	ecision to Left (Driv	er) Side Bag Deployment:	Not Deployed
Time From Side Safing D	ecision to Right (Pa	ssenger) Side Bag Deployment:	Not Deployed
Passenger Airbag Switch	Position During Ev	ent:	N/A
Diagnostic Codes Active	When Event Occurr	red:	0

Algorithm Times Aduat initiation depends on restraint system status (below).	ms
Time From Algorithm Wakeup to Pretensioner:	76
Time From Algorithm Wakeup to First Stage - Unbelted:	76
Time From Algorithm Wakeup to First Stage - Belted:	0
Time From Algorithm Wakeup to Second Stage:	0

Restraint System Status

Driver Seat Belt Buckle;	Not Engaged
Passenger Seat Belt Buckle:	Not Engaged
Driver Seat Track in Forward Position:	Yes
Passenger Seat Weight Switch Position:	N/A

Deployment Initiation Attempt Times	Driver	Passenger	
Time From Algorithm Wakeup to Pretensioner Deployment Attempt	Unbelted	Unbelted	
Time From Algorithm Wakeup to First Stage Deployment Attempt:	76	76	
Time From Algorithm Wakeup to Second Stage Deployment Attempt:	Disposal	Disposal	


Notes

- 1. Read-out date is set by the PC interface tool.
- 2. Features and data parameters which are not available on the module are marked "N/A".
- 3. CFC 60 is a Butterworth 4-pole phaseless digital filter. (See SAE J211 Part 1 Appendix C dated March 1995.)
- 4. Total and maximum Delta-V results are not available from truncated/incomplete crash pulses.
- 5. Algorithm wakeup (0 ms) is not the first moment of vehicle contact or impact.6. The Excal "Analysis ToolPak" Add-in must be enabled for this spreadsheet to operate properly.

2000 Taurus/Sable EDR Report - Charts


Longitudinal Cumulative Delta-V

Time (ms)	0	10	20	30	40	50	60	70	78
Delta-V (MPH)	-0.3	-1.9	-3.9	-5.4	-7.0	-8.6	-11.0	-13.5	-10.9



Lateral Cumulative Delta-V

Time (ms)	0	10	20	30	40	50	60	70	78
Delta-V (MPH)	0.2	0.1	0.5	-0.2	-1.0	-2.0	-2.5	-2.3	-2.0



File Name: ds00-010.hex