On-scene Investigation / Vehicle to Concrete Light Pole Dynamic Science, Inc. / Case Number: DS00-013 2000 Ford Taurus SES Wisconsin July, 2000 This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points be coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the pre-crash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

			Technical Report Documentation Page
1. Report No.	2. Government Accession No.		3. Recipient Catalog No.
DS00-013			
4. Title and Subtitle In-Depth Accident Inve	estigation		5. Report Date
			6. Performing Organization Report No.
			DS00-013
^{7. Author(s)} Dynamic Science, Inc.			8. Performing Organization Report No.
9. Performing Organization name and Ad	dress		10. Work Unit No. (TRAIS)
Dynamic Science, Inc.			
530 College Parkway,	Ste. K		11. Contract or Grant no.
Annapolis, MD 21401			DTNH22-94-D-27058
12. Sponsoring Agency Name and Addre	SS		13. Type of report and period Covered
U.S. Dept. of Transpor	tation (NRD-32)		[Report Month, Year]
	fic Safety Administration	l	
400 7th Street, SW	,		14. Sponsoring Agency Code
Washington, DC 2059	0		
15. Supplemental Notes			
16. Abstract			
			d Advanced Occupant Protection System. The collision n avoidance maneuver to avoid a dog leading to a collision into
vehicle had exited the driveway of dog crossed directly in front the of	of a restaurant/bar heading south a case vehicle. The driver of the case	nd then turned left and heade e vehicle swerved to the right	24-year-old male (173 cm-68 in/113 kg-250 lbs). The case d east. As the case vehicle crossed through an intersection, a in an effort to avoid hitting the dog. The case vehicle ran up corner (12FREE2). On impact, both front air bags in the case
scene due to damage and was la	ater declared a total loss. The police a laceration to the right side of his fo	e report indicates that no injur	ender and the windshield. The case vehicle was towed from the ies were reported by the driver of the case vehicle. The driver of pain to both of his knees. The driver was picked up from the
delta v of -29.0 km/h (-18.0 mph) downloaded Electronic Data Rec km/h (-4.7 mph) at the 78 ms ma attachment to this report. The ca	and a latitudinal delta v of 0 km/h order (EDR) data indicates a cumu rk. There is a reasonable match be se vehicle was assigned a Collisio	(0 mph). This is a borderline lative longitudinal delta v of etween the WinSmash results n Deformation Classification	ion as a total delta v of 29.0 km/h (18.0 mph), a longitudinal reconstruction, but the results appear reasonable. The \cdot 28.6 km/h (-17.8 mph) and a cumulative lateral delta v of -7.6 s and the EDR data. The EDR report is included as an (CDC) of 12FREE2 and a Principle Direction of Force (PDOF) H L = 148 cm (58.3 in)], and the maximum crush depth was
case vehicle were equipped with	seat belt pretensioners. The depth	n of the pretensioner barrels v	front right passenger's air bag. Both front seat positions of the vere checked and measured. The depth of the driver's barrel measured 10.8 cm (4.3 in.), indicating it had not deployed.
^{17. Key Words} Air bag, deployment, ad	dvanced, AOPS	18. Distribution Statement	
19. Security Classif. (of this report)	20. Security Classif. (of this page)	21. No of pages	22. Price

Form DOT F 1700.7 (8_72) Reproduction of this form and completed page is authorized

Dynamic Science, Inc. Accident Investigation Case Number: DS00-013

TABLE OF CONTENTS

BACKGROUND	1
Description	1
Investigation Type	
Crash Location	1
Crash Date	1
Notification Date	1
Field Work Completed	1
SUMMARY	1
AOPS discussion	
Scene Diagram	4
DETAILED INFORMATION	5
Vehicles	
Occupants	6
Injuries and Injury Mechanisms	7
Occupant Kinematics	8
Attachment 1. EDR report	9

BACKGROUND:

Description:	This Event Data Recorder and Advanced Occupant Protection System case was reported to the National Highway Traffic Safety Administration (NHTSA) by Dynamic Science, Inc. on August 17, 2000. The NHTSA assigned the case to DSI on August 18, 2000 and an on-scene investigation was conducted.
Investigation Type:	On-scene
Crash Location:	Wisconsin
Crash Date:	July, 2000
Notification Date:	August 17, 2000
Field Work Completed:	August 19, 2000

SUMMARY:

The collision occurred in Wisconsin in July, 2000 at 0300 hours. This was a single vehicle collision involving an avoidance maneuver to avoid a dog leading to a collision into a concrete light pole. At the area of impact, the roadway is a four leg intersection that was controlled by standard tri-colored signals. The east-west roadway consists of two travel lanes for eastbound traffic and three lanes for westbound traffic. The roadway was dry, straight and level concrete surface with a posted speed limit of 40 km/h (25 mph). The south-east corner of the intersection is bordered by a 15 cm (5.9



the intersection is bordered by a 15 cm (5.9 Figure 1. Approach to impact. in) high concrete curb, and there was a 16 cm (6.3 in) diameter light support.

The case vehicle, a rented 2000 Ford Taurus SES 4-door sedan, was driven by an unrestrained 24-year-old male (173 cm-68 in/113 kg-250 lbs). The case vehicle had exited the driveway of a restaurant/bar heading south and then turned left and headed east. As the case vehicle crossed through the intersection, a dog crossed directly in front the case vehicle. The driver of the case vehicle swerved to the right in an effort to avoid hitting the dog. The case vehicle ran up and over the south-east concrete curb and then struck the concrete light pole with its front right corner (12FREE2). On impact, both front air bags in the case vehicle deployed.

The case vehicle sustained moderate damage to the front bumper, hood, grille area, front right fender and the windshield. The case vehicle was towed from the scene due to damage and was later declared a total loss.

The police report indicates that no injuries were reported by the driver of the case vehicle. The

driver indicated that he had sustained a laceration to the right side of his forehead and he complained of pain to both of his knees. The driver was picked up from the scene and driven home. He did not seek any medical treatment.

The Delta V for the case vehicle was computed using WinSmash version 2.12 with the pole option as a total delta v of 29.0 km/h (18.0 mph), a longitudinal delta v of -29.0 km/h (-18.0 mph) and a latitudinal delta v of 0 km/h (0 mph). This is a borderline reconstruction, but the results appear reasonable. The downloaded Electronic Data Recorder (EDR) data indicates a cumulative longitudinal delta v of -28.6 km/h (-17.8 mph) and a cumulative lateral delta v of -7.6 km/h (-4.7 mph) at the 78 ms mark. There is a reasonable match between the WinSmash results and the EDR data. The EDR report is included as an attachment to this report. The case vehicle was assigned a Collision Deformation Classification (CDC) of 12FREE2 and a Principle Direction of Force (PDOF) of 000 degrees. The combined direct and induced damage width was 127.5 cm (50.2 in) [CRASH L = 148 cm (58.3 in)], and the maximum crush depth was 32.7 cm (12.9 in) located at C_5 .

The case vehicle is equipped with grey fabric-covered bucket seats¹ in the outboard front seating positions and a gray fabric-covered bench seat in the rear. The front left seat had been removed prior to the vehicle inspection. The front left seat position was equipped with a manual lap and shoulder belt and emergency locking retractor (ELR). At time of inspection the front right seat back was reclined rearward at a 35E angle from vertical and the seat was adjusted to the rear most track position. This seat position was equipped with a manual lap and shoulder belt and a switchable retractor in ELR mode.

AOPS discussion

This vehicle was equipped with an advanced occupant protection system. The system consists of a Restraint Control Module (RCM), dual stage front air bags, seat belt pretensioners, seat track sensors, and seat belt latch usage detectors. The system is controlled by the RCM. The primary function of the RCM is to control the deployment of the occupant protection systems. The system records longitudinal and lateral acceleration. Data related to the driver and passenger air bag deployment include: 78 milliseconds of crash pulse, deployment strategy of the dual-stage air bag system, seat belt latch use, pretensioner operation, and driver seat track location.

The EDR report further indicates that:

- 1. This was a first stage deployment.
- 2. The driver's seat was not in the forward position.
- 3. The front left and front right seat buckles were not engaged.
- 4. The front left and front right pretensioner did not deploy-neither of the seat buckles were engaged.
- 5. The time from algorithm wake-up to first stage unbelted was 12 milliseconds.

¹ At the time of the vehicle inspection the driver's seat had been removed and the driver's air bag cut off. The driver's seat was placed back in the case vehicle for photography purposes. Photograph showing the driver's air bag on the steering wheel were obtained from the insurance company.

The case vehicle was equipped with a driver's steering wheel mounted air bag and a top-mount front right passenger's air bag. The driver's air bag was cut off prior to the vehicle inspection. The dual module covers opened in an "H" configuration. The front right passenger's air bag was rectangular and measured 41 cm (16.1 in) high by 54 cm (21.3 in) wide. It was equipped with two vent ports and was not tethered. On the face of the air bag there were black smudges that were caused by the module cover. The single flap module cover opened properly and was not damaged.

Both front seat positions of the case vehicle were equipped with seat belt pretensioners. The depth of the pretensioner barrels were checked and measured. The depth of the driver's barrel measured 10.9 cm (4.3 in.), indicating that it had not deployed. The depth of the front right barrel measured 10.8 cm (4.3 in.), indicating it had not deployed.

Scene Diagram




Figure 2. Scene diagram

DETAILED INFORMATION

Vehicles

Case vehicle		
Description:	2000 Ford Taurus	SES 4-door
VIN:	1FAFP55U7YGxxx	XXX
Odometer:	7,245 km (11,659 m	iiles)
Engine:	3.0L 6 cyl	
Reported Defects:	None	
Cargo:	None	
Damage Description:	0	o the front bumper, hood, nt fender and windshield
CDC:	12FREE2	
Delta V:	Total	29.0 km/h (18.0 mph)
	Longitudinal	-29.0 km/h (-18.0 mph)
	Latitudinal	0.0 km/h (0.0 mph)
	Energy	56,952 joules (42,006 ft-lbs)



Figure 3. Exterior damage to case vehicle.

Occupants

Case vehicle	Occupant 1
Age/Sex:	24/Male
Seated Position:	Front left
Seat Type:	Gray fabric-covered bucket seat. Seat had been removed prior to inspection. The seat track position at impact is not known.
Height:	173 cm (68 in)
Weight:	113 kg (250 lbs)
Occupation:	Unknown
Pre-existing Medical Condition:	None noted
Alcohol/Drug Involvement:	None
Alcohol/Drug Involvement: Driving Experience:	None Presumed to be greater than 6 years
-	Presumed to be greater than 6
Driving Experience:	Presumed to be greater than 6 years
Driving Experience: Body Posture:	Presumed to be greater than 6 years Assumed normal, upright
Driving Experience: Body Posture: Hand Position:	Presumed to be greater than 6 years Assumed normal, upright Unknown
Driving Experience: Body Posture: Hand Position: Foot Position:	Presumed to be greater than 6 years Assumed normal, upright Unknown Unknown

Injuries and Injury Mechanisms

Case vehicle

	<u>INJURY</u>	OIC CODE	<u>ICD-9</u>	<u>SOURCE</u>
Driver:	Laceration to the right side of forehead	290602.1, 7	873.42	Windshield
	Complained of pain to both his knees—Not codeable			

Occupant Kinematics

The 24-year-old male driver of the case vehicle is assumed to have been seated in a normal, upright fashion in the fabric-covered bucket seat. He was not wearing the available lap and shoulder belt. The EDR showed that the restraint buckle was not engaged. At impact, the driver responded to the 0 degree direction of force by moving straight forward. The driver engaged the deploying air bag in some fashion with his torso although there was no evidence of contact. As he loaded the bag and the steering wheel, the steering column shear capsules were stroked—1.5 cm (0.6 in) to the right capsule and 2.5 cm (1.0 in) to the left capsule. His head struck the windshield-there was hair embedded in the glass, causing the laceration to his forehead. Both of his knees struck the rigid plastic covers on the left instrument panel area, deforming the knee bolster. He complained of pain to both of his knees. The driver was picked up from the scene and driven home. He did not seek medical treatment.



Figure 4. Deformed knee bolster.



Figure 5. Driver contact to windshield and mirror.



Figure 6. Left side steering column.

Attachment 1. EDR report

2000 Taurus/Sable EDR Report - Summary Page



Investigation Data

File Name:	ds00-013.hex	File Save Date:	06-Sep-2000
File Read-out Date:	N/A	Report Date:	06-Sep-2000
Report Version:	1.4		00.000 2000

EDR Control Module Data

Data Validity Check: Valid	EDR Model Version:	141
Time From Side Safing Decision to Left (Driver)	Side Bag Deployment:	Not Deployed
Time From Side Safing Decision to Right (Passe	enger) Side Bag Deployment:	Not Deployed
Passenger Airbag Switch Position During Event		N/A
Diagnostic Codes Active When Event Occurred:		0

Algorithm Times	Actual initiation depends on restraint system status (below).	ms
Time From Algorithm W	akeup to Pretensioner:	12
Time From Algorithm W	akeup to First Stage - Unbelted:	12
Time From Algorithm W	akeup to First Stage - Belted:	22
Time From Algorithm W	akeup to Second Stage:	0

Restraint System Status

Driver Seat Belt Buckle:	Not Engaged	
Passenger Seat Belt Buckle:	Not Engaged	
Driver Seat Track In Forward Position:	No	8. A.
Passenger Seat Weight Switch Position:	N/A	

Deployment Initiation Attempt Times	Driver	Passenger
Time From Algorithm Wakeup to Pretensioner Deployment Attempt:	Unbelted	Unbelted
Time From Algorithm Wakeup to First Stage Deployment Attempt:	12	12
Time From Algorithm Wakeup to Second Stage Deployment Attempt:	Disposal	Disposal

Notes

1. Read-out date is set by the PC interface tool.

2. Features and data parameters which are not available on the module are marked "N/A".

3. CFC 60 is a Butterworth 4-pole phaseless digital filter. (See SAE J211 Part 1 Appendix C dated March 1995.)


4. Total and maximum Delta-V results are not available from truncated/incomplete crash pulses.

5. Algorithm wakeup (0 ms) is not the first moment of vehicle contact or impact.

6. The Excel "Analysis ToolPak" Add-in must be enabled for this spreadsheet to operate properly.


•

2000 Taurus/Sable EDR Report - Charts



Lateral Cumulative Delta-V

Time (ms)	0	10	20	30	40	50	60	70	78
Delta-V (MPH)	0.1	0.6	0.1	-0.1	-1.8	-4.1	-5.4	-4.9	-4.7





2000 Taurus/Sable EDR Report - Memory Dump

Address	00	01	02	03	04	05	06	07	08	09	OA	0B	0C	0D	0E	0F
0800	OF	4A	40	76	14	FB	FF	FF	FF	FF	0E	24	OF	2D	ЗA	4C
0810	C8	FF	00	FF	52	60	52	60	60	52	E3	20	3C	78	D6	AO
0820	08	03	28	37	5F	OF	0F	0A	F5	OA	в7	84	A1	5E	D5	AA
0830	03	0C	1B	1E	00	FF	3C	3C	80	06	28	64	64	00	0C	01
0840	5A	96	50	FF	FF	FF	EF	DF	D5	E7	FF	72	4E	13	25	B1
0850	EC	14	09	OF	01	FF	FF	88	7F	FF	CD	44	08	FF	FF	95
0860	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
0870	05	3A	F7	06	EA	00	8F	FF	59	46	31	41	00	02	FF	19
0880	02	FD	80	06	FF	7E	12	FD	80	1C	FF	80	2B	FF	80	FF
0890	33	FF	80	35	FF	80	38	FF	80	FF	FF	00	FF	FF	00	FF
08A0	44	00	04	10	00	08	28	01	00	00	FF	FF	FF	FF	FF	FF
08B0	02	FF	81	38	00	8D	01	FF	FF	FF	FF	FF	11	01	D9	57
0800	FF	34	01	D9	57	43	01	D9	57	51	03	24	73	45	FF	FE
0800	01	0E	0C	80	02	58	16	87	1F	BE	01	0A	00	8C	01	04
08E0	00	FO	01	36	00	AO	01	54	00	ЗF	02	30	02	C7	02	8A
08F0	05	14	07	08	01	2C	03	CA	04	CE	06	40	73	33	00	AO
0900	3F	FF	00	03	00	4B	01	CC	00	03	OF	FF	00	14	00	78
0910	00	AO	00	6E	0A	16	FF	01	00	00	00	7F	OF	0C	OF	02
0920	03	5A	32	46	05	50	02	02	FA	1E	08	0C	0A	1C	02	23
0930	09	06	28	32	16	20	16	1F	SF	FF	FF	02	FF	FF	FF	11
0940	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
0950	0C	00	16	00	0C	00	00	05	00	00	04	09	OB	07	21	2B
0960	07	08	OC	15	0C	12	09	00	00	00	09	16	1E	07	OF	13
0970	00	00	D1	10	A1	75	B2	B2	A8	AB	B1	6C	58	9B	B9	75
0980	78	AE	DC	BA	Dl	B8	A1	C8	94	80	9C	AC	AD	В9	AD	B3
0990	AB	A 8	AB	Aб	AA	B6	8A	Aб	B2	A7	A5	AD	AF	AB	B2	93
09A0	90	83	8C	A9	81	93	8A	96	98	8C	9B	99	8F	93	85	7A
09B0	8E	88	9A	74	5E	62	75	60	74	76	41	BC	7E	92	6E	85
0900	AF	BD	в7	B2	A7	95	A2	84	86	89	7F	7D	86	7C	68	87
0900	72	89	7A	7F	77	82	7E	82	74	6C	6F	5D	5C	48	53	E6
09E0	37	3D	8A	70	80	67	71	80	8A	90	8B	87	80	78	86	00
09F0	00	00	00	00	00	00	00	FF	FF	AC	00	FF	FF	FF	FF	04

Hexidecimal Module Memory Dump

File name:

ds00-013.hex

Page 3

1

.