Advanced Occupant Protection Systems On-scene Investigation
Dynamic Science, Inc. / Case Number: DS01-006
2000 Ford Taurus SES 4-door
California
December, 2000

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points be coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the pre-crash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

**Technical Report Documentation Page** 1. Report No. 2. Government Accession No. 3. Recipient Catalog No. DS01-006 4. Title and Subtitle 5. Report Date In-Depth Accident Investigation 6. Performing Organization Report No. 7. Author(s) 8. Performing Organization Report No. Dynamic Science, Inc. 9. Performing Organization name and Address 10. Work Unit No. (TRAIS) Dynamic Science, Inc. 530 College Parkway, Ste. K 11 Contract or Grant no Annapolis, MD 21401 DTNH22-94-D-27058 12. Sponsoring Agency Name and Address 13. Type of report and period Covered [Report Month, Year] U.S. Dept. of Transportation (NRD-32) National Highway Traffic Safety Administration 14. Sponsoring Agency Code 400 7th Street, SW Washington, DC 20590 15. Supplemental Notes 16. Abstract This case was initiated because the case vehicle was equipped with an Event Data Recorder (EDR) and Advanced Occupant Protection System (AOPS). The collision occurred in southern California in December, 2000 at 1145 hours. This was a single vehicle versus a concrete street lamp pole, a tree and then a rollover type collision. The collision occurred on a four-lane, two-way, undivided roadway. The case vehicle is a 2000 Ford Taurus SES 4-door driven by a 70-year-old female (160 cm-63 in./57 kg-125 lbs). The case vehicle was traveling northbound in the left lane. The driver of the case vehicle was unaware of a pre-existing medical condition of heart arrhythmia. She lost consciousness and the case vehicle veered to the left into on-coming southbound travel lanes, departed the roadway, and traveled on the west sidewalk area. The case vehicle collided head-on into a concrete lamp pole (overlapping CDC). The frontal air bags in the case vehicle probably deployed at this time. The vehicle continued traveling northbound off the roadway approximately 7 meters (23 ft) and collided head-on (12FDEW3) with a tree. The case vehicle bounced off the tree and rolled over onto its top, having rotated ninety degrees. It came to final rest heading east approximately 2.7 meters (9 ft) north of the impact with the tree. Both the concrete lamp pole and the tree were knocked down and uprooted with the tree falling on a parked 1989 GMC U.S. postal vehicle. The case vehicle was towed from the scene due to damage and subsequently

The impact with the concrete street lamp post and tree were overlapping damage. Frontal crush measurements were taken and a Collision Deformation Classification(CDC) entered for the second impact with the tree. It is assumed that the impact with the tree was the severest damage. The case vehicle was assigned a CDC of 12FDEW3 with a Principle Direction of Force (PDOF) of 000 degrees. The Delta V for the case vehicle was computed using WinSmash version 2.12 and the pole option. WinSmash calculated a total delta v of 33.0 km/h (20.5 mph), a longitudinal delta v of -33.0 km/h (0.0 mph). The downloaded EDR data indicates a cumulative longitudinal delta v of -35.2 km/h (-21.9 mph) at the 70 ms mrk. Due to the overlapping damage and the yielding object, the WinSmash results are borderline.

The driver could not remember anything about the collision. She indicated that she lost consciousness and came to in the vehicle upside down and held in place by the lap and shoulder belt. She was transported to a trauma center via ambulance. She sustained a contusion to the right side of her face as a result of contact with the driver's air bag. There was evidence of contact to the driver's air bag with makeup and lipstick transfers to the front center area. She sustained a contusion to her stomach from the seat belt. She also complained of pain to her back, knees and chest. She indicated she had a preexisting medical condition concerning her back, but was not aware of the hear arrhythmia. She was hospitalized for five days and diagnosed with the heart arrhythmia.

17. Key Words		18. Distribution Statement	
Air bag, deployment, injury, advanced, Event Data Recorder, AOPS, RCM,  19. Security Classif. (of this report)  20. Security Classif. (of this page)			
19. Security Classif. (of this report)	20. Security Classif. (of this page)	21. No of pages	22. Price

Form DOT F 1700.7 (8\_72) Reproduction of this form and completed page is authorized

# Dynamic Science, Inc. Accident Investigation Case Number: DS01-006

# TABLE OF CONTENTS

BACKGROUND	1
Description	1
Investigation Type	
Crash Location	
Crash Date	1
Notification Date	
Field Work Completed	
SUMMARY	1
Scene Diagram	3
DETAILED INFORMATION	4
Vehicles	4
AOPS Discussion	5
Occupants	7
Injuries and Injury Mechanisms	
Occupant Kinematics	9
Attachment 1. EDR report	10

#### **BACKGROUND:**

Description: This Event Data Recorder (EDR) and Advanced Occupant

Protection Systems (AOPS) case was reported to the NHTSA by DSI on March 20, 2001 and the case was assigned on March 21, 2001. An on-site investigation was conducted. All field work was

completed on February 02, 2002.

Investigation Type: On-scene

Crash Location: California

Crash Date: December, 2000 Notification Date: March 20, 2001 Field Work Completed: February 02, 2002

#### **SUMMARY:**

The collision occurred in southern California in December, 2000 at 1145 hours. This was a single vehicle versus a concrete street lamp pole, a tree and then a rollover type collision. The collision occurred on a four-lane, two-way, undivided roadway. The north and southbound roadways are comprised of two travel lanes in each direction. The northbound roadway is straight with a positive 3.8% grade. At the area of impact the north and south roadway intersect an east-west roadway that did not play a role in the collision. The weather was clear and the bituminous roadway surface was dry. The posted speed limit was 56 km/h (35 mph).



Figure 1. Approach to impact areas—north.

The case vehicle is a 2000 Ford Taurus SES 4-door driven by a 70-year-old female (160 cm-63 in./57 kg-125 lbs). The case vehicle was traveling northbound in the left lane. The driver of the case vehicle was unaware of a pre-existing medical condition of heart arrhythmia<sup>1</sup>. She lost consciousness and the case vehicle veered to the left into on-coming southbound travel lanes, departed the roadway, and traveled on the west sidewalk area. The case vehicle collided head-on into a concrete lamp pole (overlapping CDC). The frontal air bags in the case vehicle probably deployed at this time. The vehicle continued traveling northbound off the roadway approximately 7 meters (23 ft) and collided head-on (12FDEW3) with a tree. The case vehicle climbed over the

<sup>&</sup>lt;sup>1</sup> Excessively slow heart rhythms cause the cardiac output to be insufficient, and this can cause symptoms of fatigue, weakness, lightheadedness, fainting, shortness of breath.

tree and rolled over onto its top about its longitudinal axis, and rotated ninety degrees clockwise. It came to final rest heading east approximately 2.7 meters (9 ft) north of the impact with the tree. Witnesses reported to police that a minor fire started in the engine compartment and that it was extinguished with a fire extinguisher. Both the concrete lamp pole and the tree were knocked down and uprooted with the tree falling on a parked 1989 GMC U.S. postal vehicle.

The impact with the concrete street lamp post and tree were overlapping damage. Frontal crush measurements were taken and a Collision Deformation Classification (CDC) entered for the

second impact with the tree. It is assumed that the impact with the pole caused the airbags in the case vehicle to deploy, and the second impact with the tree was the severest damage (highest delta v). The case vehicle was assigned a CDC of 12FDEW3 for the second impact, with a Principle Direction of Force (PDOF) of 000 degrees. The combined direct and induced damage width was 95.0 cm (37.4 in.) [CRASH L = 148 cm](58.3 in.)], and the maximum crush depth was 66.5 cm (26.2 in.) located at C<sub>4</sub>. The Delta V for the case vehicle was computed using WinSmash version 2.12 and the pole option with stiffness coefficients provided by Figure 2. Rollover damage to case vehicle.



Ford of a 20 cm (8 in.) center pole crash. The Ford stiffness coefficients provided reasonable WinSmash delta v results. WinSmash calculated a total delta v of 33.0 km/h (20.5 mph), a longitudinal delta v of -33.0 km/h (-20.5 mph), and a latitudinal delta v of 0.0 km/h (0.0 mph). The results are borderline due to the overlapping damage and the yielding objects. The results are presented in this report as a reference but were not coded in the EDCS. The downloaded EDR data indicates a cumulative longitudinal delta v of -35.2 km/h (-21.9 mph) at the 70 ms mark.

The case vehicle was towed from the scene due to damage and subsequently declared a total loss and sold as salvage.

The driver could not remember anything about the collision. She indicated that she lost consciousness and came to in the vehicle upside down and held in place by the lap and shoulder belt. She was transported to a trauma center via ambulance. She sustained a contusion to the right side of her face as a result of contact with the driver's air bag. There was evidence of contact to the driver's air bag with makeup and lipstick transfers to the front center area. She sustained a contusion to her stomach from the seat belt. She also complained of pain to her back, knees and chest. She indicated she had a preexisting medical condition concerning her back, but was not aware of the heart arrhythmia. She was hospitalized for five days and diagnosed with the heart arrhythmia.

# **Scene Diagram**




Figure 3. Scene diagram

#### **DETAILED INFORMATION**

#### Vehicles

Case vehicle

Description: 2000 Ford Taurus SES

VIN: 1FAFP55SXYGxxxxxx

Odometer: 2,066 km (1,284 miles)

Engine: 3.0 L V6

Reported Defects: None

Cargo: None

Damage Description: Severe frontal damage to the bumper, grille,

hood, windshield, and top. Small fire reported to have started in engine compartment post impact. Vehicle towed from scene and subsequently declared a total loss and sold as salvage.

CDC:

Impact 1 vs concrete lamp pole Unknown–overlapping damage

Impact 2 vs tree 12FDEW3
Impact 3 rollover 00TPD03

Delta V for Impact 2 vs tree (highest

delta v):

Total 33.0 km/h (20.5 mph)

Longitudinal -33.0 km/h (-20.5 mph)

Latitudinal 0.0 km/h (0.0 mph)

Energy 72,090 joules

(53,171 ft-lbs)



**Figure 4**. Exterior overlapping front damage to the case vehicle.

### **AOPS Discussion**

This vehicle was equipped with an advanced occupant protection system. The system consists of a Restraint Control Module (RCM) dual stage front air bags, seat belt pretensioners, seat track sensors, and seat belt latch usage detectors. The system is controlled by the RCM. The primary function of the RCM is to control the deployment of the occupant protection systems. The system records longitudinal and lateral acceleration. Data related to the driver and passenger air bag deployment include: 78 milliseconds of crash pulse, deployment strategy of the dual-stage air bag system, seat belt latch use, pretensioner operation, and driver seat track location.

The downloaded EDR data indicates the highest cumulative longitudinal delta v of -21.9 km/h (-35.2 mph) at the 70 ms mark. The EDR report is included as an attachment to this report.

The EDR report further indicates that:

- 1. This was a first stage deployment.
- 2. The driver's seat track was in the forward position.
- 3. The left front seat buckle was engaged and the right front seat buckle was not.
- 4. The time from algorithm wakeup to pretensioner was 37 milliseconds.
- 5. The time from algorithm wakeup to first stage belted was 38 milliseconds.

Note that as a result of driver's seat track in the forward position, the second stage deployment was suppressed.

The case vehicle driver's air bag was circular and measured 44 cm (17.3 in.) in diameter. It was equipped with two tethers and two vent holes at the 11 and 01 o'clock positions. The front center of the air bag there was a driver contact consisting of makeup and a lipstick imprint. The driver's air bag also had dirt from exposure. The dual module covers opened in an "H" configuration.

There were no indications of any damage to driver's air bag or the module covers. The case vehicle front right passenger's air bag was rectangular and measured 42 cm (16.5 in.) high by 48 cm (18.9 in.) wide. It was equipped with two vent ports at the 10 and 02 o'clock positions and was not tethered. There was dirt all over the air bag from exposure. There was no damage to the air bag. The single flap module cover opened properly and was not damaged. Both front seat positions of the case vehicle were equipped with seat belt buckle pretensioners. The front right pretensioner

barrel was checked and measured 11.1 cm (4.4 in.)—indicating that it had not fired. The



Figure 5. Driver's air bag.

front left pretensioner barrel was checked and measured 50.0 cm (19.7 in.)-indicating that it had fired.

The case vehicle was equipped with power adjustable pedals which were adjusted to within 2.6 cm (1.0 in.) of the rear most position.

The driver loaded the steering column; there was complete separation of the steering column breakaway coupling. The left shear capsule had been stroked 1.7 cm (0.7 in.) and the right capsule had completely separate with the stroke measured as 3.1 cm (1.2 in.).



Figure 6. Separation of right shear capsule.

# **Occupants**

<u>Case vehicle (Ford Taurus)</u> Occupant 1

Age/Sex: 70/Female

Seated Position: Front left

Seat Type: Gray colored, fabric covered

bucket seat. Seat track was

adjusted forward most

position.

Height: 160 cm (63 in.)

Weight: 57 kg (125 lbs)

Occupation: Not working

Pre-existing Medical Known back problems. She

Condition: was unaware of heart

arrhythmia which was the direct cause of the collision.

Alcohol/Drug Involvement: None

Driving Experience: Presumed to be greater than

50 years.

Body Posture: Unknown due to

unconsciousness.

Hand Position: Unknown

Foot Position: Unknown

Restraint Usage: Lap and shoulder belt

available, used. Seat belt found cut and RCM indicated belt buckle was

engaged.

Air bag: Steering wheel mounted air

bag, deployed

# **Injuries and Injury Mechanisms**

# Case vehicle (Ford Taurus)

	<u>INJURY</u>	OIC CODE	ICD-9	<u>SOURCE</u>
Driver:	Contusion to right side of face	290402.1, 1	920	Air bag
	Contusion to stomach	590402.1, 8	922.2	Seat belt
	Pain to back, left knee and ankle–non codeable injuries			

## **Occupant Kinematics**

The driver of the case vehicle appears to have been unconscious prior to the collision. She was wearing the available manual lap and shoulder belt. The EDR indicates that the driver's seat belt buckle was engaged and the seat belt was found to be cut and there was evidence of loading on the seat belt webbing. The shoulder belt upper anchorage adjustment was in the mid position. The grey colored, fabric-covered bucket seat was adjusted to the forward most track position. The seat back angle was adjusted to a 21 degrees rearward reclined position. The power adjustable pedals were adjusted to within 2.6 cm (1.0 in.) of the rear most position. At impact with the pole, the driver responded to the 0 degrees principal direction of force by moving straight forward. The lap and shoulder belts restricted this forward motion but her legs struck the



Figure 7. Driver's seat area.

rigid plastic cover of the instrument panel displacing it slightly. Her face contacted the center of the air bag—there was makeup and lipstick transfer on the front center area. Contact with the air bag caused a contusion to the right side of her face. The case vehicle continued moving forward and struck the tree. The driver responded by moving straight forward and again the lap and shoulder belts restricted this forward motion. As the vehicle rolled over and came to rest on it roof the driver was held in place by the lap and shoulder belt and caused a contusion to her stomach. It is at this point that the driver remember regaining consciousness. She was assisted and removed from the vehicle by bystanders.

The driver of the case vehicle was transported to a trauma center and was hospitalized for five days. She was diagnosed with the heart arrhythmia.

## Attachment 1. EDR report

# 2000 Taurus/Sable EDR Report - Summary Page



#### **Investigation Data**

File Name:	ds01-006.hex	File Save Date:	25-Mar-2001
File Read-out Date:	N/A	Report Date:	26-Mar-2001
Report Version:	1.6		

#### **EDR Control Module Data**

Data Validity Check:	Valid	EDR Model Version:	141
Time From Side Safing De	cision to Left (Driver	) Side Bag Deployment:	Not Deployed
Time From Side Safing De	cision to Right (Pass	senger) Side Bag Deployment:	Not Deployed
Passenger Airbag Switch	Position During Ever	nt:	N/A
Diagnostic Codes Active V	When Event Occurred	d:	0

Algorithm Times	Actual initiation depends on restraint system status (below).	ms
Time From Algorithm W	/akeup to Pretensioner:	37
Time From Algorithm W	/akeup to First Stage - Unbelted:	38
Time From Algorithm W	/akeup to First Stage - Belted:	41
Time From Algorithm W	/akeup to Second Stage:	0

## **Restraint System Status**

Driver Seat Belt Buckle:	Engaged	
Passenger Seat Belt Buckle:	Not Engaged	
Driver Seat Track In Forward Position:	Yes	
Passenger Seat Weight Switch Position:	N/A	

Deployment Initiation Attempt Times	Driver	Passenger
Time From Algorithm Wakeup to Pretensioner Deployment Attempt:	37	Unbelted
Time From Algorithm Wakeup to First Stage Deployment Attempt:	38	38
Time From Algorithm Wakeup to Second Stage Deployment Attempt:	Disposal	Disposal

## Notes

- 1. Read-out date is set by the PC interface tool.
- 2. Features and data parameters which are not available on the module are marked "N/A".
- 3. CFC 60 is a Butterworth 4-pole phaseless digital filter. (See SAE J211 Part 1 Appendix C dated March 1995.)
- 4. Total and maximum Delta-V results are not available from truncated/incomplete crash pulses.
- 5. Algorithm wakeup (0 ms) is not the first moment of vehicle contact or impact.
- 6. The Excel "Analysis ToolPak" Add-in must be enabled for this spreadsheet to operate properly.
- 7. Acceleration data and plots are only valid for frontal impact event recordings.


EDR Summary Report Page 1

# 2000 Taurus/Sable EDR Report - Charts

## Longitudinal Cumulative Delta-V

Time (ms)	0	10	20	30	40	50	60	70	78
Delta-V (MPH)	-0.2	-0.4	-0.3	-2.6	-3.1	-8.8	-15.9	-21.9	-20.3


Note: Acceleration data and plots are only valid for frontal impact event recordings.



#### Lateral Cumulative Delta-V

Time (ms)	0	10	20	30	40	50	60	70	78
Delta-V (MPH)	0.1	0.0	0.5	0.7	1.0	-0.2	-1.5	-5.0	-6.8

Note: Acceleration data and plots are only valid for frontal impact event recordings.



File Name: ds01-006.hex

EDR Summary Report Page 2

# 2000 Taurus/Sable EDR Report - Memory Dump

# **Hexidecimal Module Memory Dump**

Address	00	01	02	03	04	05	06	07	80	09	0A	0B	0C	0D	0E	0F
0800	10	4A	40	76	14	FB	FF	FF	FF	FF	0E	24	0F	2D	3.A	57
0810	C8	FF	00	FF	52	60	52	60	60	52	E3	20	3C	78	D6	A0
0820	08	03	28	37	5F	OF	OF	OA	F5	0A	B7	84	A1	5E	C9	95
0830	03	OC.	1B	1E	0.0	FF	3C	3C	80	06	28	64	64	0.0	OC	01
0840	5A	96	50	FF	FF	FF	EF	DF	D5	E7	FF	72	4E	13	25	B1
0850	EC	14	09	OF	01	FF	FF	73	7F	FF	CD	44	0.8	FF	FF	95
0860	FF	FF														
0870	05	3C	49	10	6C	00	8F	FF	59	46	31	41	0.0	03	FF	19
0880	02	FE	80	09	FE	80	0A	FE	80	OF	FE	80	13	FE	80	FF
0890	2B	FE	80	35	FF	80	38	FF	80	FF	FF	0.0	FF	FF	00	FF
0A80	04	86	08	0.0	0.0	08	20	01	00	0.0	FF	FF	FF	FF	FF	FF
08B0	02	FF	81	38	0.0	8D	01	FF	FF	FF	FF	FF	23	01	E1	EF
08C0	FF	14	01	E1	F0	43	01	E1	F0	08	50	88	71	0.3	FF	FE
08D0	01	0E	0C	80	02	58	16	87	1F	BE	01	0A	0.0	8C	01	04
08E0	0.0	FO	01	36	0.0	A0	01	54	00	3 F	02	30	02	C7	02	8A
08F0	05	14	07	0.8	01	2C	03	CA	04	CE	06	40	73	33	0.0	A0
0900	3F	FF	0.0	0.3	0.0	4B	01	CC	0.0	03	0F	FF	0.0	14	0.0	78
0910	00	A0	0.0	6E	0A	16	FF	01	0.0	0.0	0.0	7F	OF	0C	OF	02
0920	03	5A	32	46	0.5	50	02	02	FA	1E	08	0C	0A	1C	02	23
0930	09	06	28	32	16	20	16	1F	5F	FF	FF	02	FF	FF	FF	11
0940	FF	FF														
0950	26	0.0	29	0.0	25	0.0	00	1E	0.0	0.0	01	00	20	1E	1F	1F
0960	24	26	30	25	25	26	21	0.0	00	0.0	0.0	29	31	2A	27	29
0970	00	0.0	BD	B0	A1	7E	B2	B3	AF	AF	B3	B9	B3	AC	B1	B0
0980	A3	B4	В3	BB	B0	CC	A8	5B	6C	68	87	95	6F	5F	В3	D2
0990	5A	AD	9A	AD	BD	A6	A0	A5	В8	AC	BE	AE	B9	B8	B5	9A
09A0	9D	A1	A5	98	A1	A5	9F	A3	A1	A0	92	A0	A2	66	81	D2
09B0	5E	94	97	B5	69	A0	6B	80	2B	08	A2	EB	19	34	29	9B
0900	1D	84	AE	70	B0	DD	CE	83	86	7F	79	77	7B	82	84	86
09D0	84	80	7F	83	77	88	7C	82	80	82	93	6E	76	88	75	73
09E0	58	3C	5C	7B	98	90	5D	40	76	71	54	37	85	71	75	00
09F0	0.0	00	0.0	0.0	0.0	0.0	0.0	FF	FF	B3	0.0	FF	FF	FF	FF	04

File name: ds01-006.hex

EDR Summary Report Page 3