On-Site Certified Advanced 208 Compliant Crash Investigation Dynamic Science, Inc. / Case Number: DS03006 2003 Chevrolet K1500 Silverado extended cab pickup Arizona January, 2003 This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points be coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the precrash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

			Technical Report Documentation Page
1. Report No.	2. Government Accession No.		3. Recipient Catalog No.
DS03006			
4. Title and Subtitle			5. Report Date
On Site Certified Advance	ced 208 Compliant Investi	gation	January 31, 2004
	1	<i>5</i> ········	6. Performing Organization Report No.
7. Author(s) Dynamic Science, Inc.			8. Performing Organization Report No.
9. Performing Organization name and Addre	ess		10. Work Unit No. (TRAIS)
Dynamic Science, Inc.			
530 College Parkway, S	Ste. K		11. Contract or Grant no.
Annapolis, MD 21401			DTNH22-94-D-27058
12. Sponsoring Agency Name and Address			13. Type of report and period Covered
U.S. Dept. of Transporta	ation (NRD-32)		[Report Month, Year]
National Highway Traffic	c Safety Administration		14. Sponsoring Agency Code
400 7th Street, SW			and the second s
Washington, DC 20590			
15. Supplemental Notes			
16. Abstract			
The speed limit for all involve	ved roadways is 80 km/h (50	mph). The case vehicle	ed within the confines of a four-leg intersection. was a 2003 Chevrolet K1500 Silverado extended I at a police estimated speed of 64-72 km/h (40-45
The other vehicle was a 1997 Honda Accord four-door sedan driven by a restrained 76-year-old female traveling westbound at a police estimated speed of 64-80 km/h (40-50 mph). It is this investigator's opinion, however, that the driver of the Honda stopped the intersection first. The driver then attempted to cross the intersection in front of the case vehicle. The Honda accelerated to an estimated speed of 21 km/h (13 mph). The driver of the case vehicle saw the Honda and began braking. The front of the case vehicle (12FYEW1) struck the right side of the Honda (03RYAW2). The driver's air bag in the case vehicle deployed at this time. The passenger's frontal air bag did not deploy. The Honda was pushed in a counterclockwise direction and there was a second, side slap type impact between the left side of the Chevrolet (09LPEW1) and the right side of the Honda. The Honda departed the intersection in a southwestern direction. The case vehicle rotated in clockwise direction and came to rest in the intersection.			on, however, that the driver of the Honda stopped at of the case vehicle. The Honda accelerated to an onda and began braking. The front of the case air bag in the case vehicle deployed at this time. The relockwise direction and there was a second, sideside of the Honda. The Honda departed the
The driver of the case vehicle sustained minor abrasions to his left forearm (AIS=1). These were likely as a result of the air bag deployment. He was transported from the scene to a local hospital where he was treated and released. The driver of the other vehicle sustained minor lacerations to her right hand and fingers (AIS=1).			
Both vehicles were towed f	rom the scene due to damage	e. The case vehicle was	under repair at the time of the inspection.
17. Key Words		18. Distribution Statement	
Air bag, deployment, injuradvanced	y, crash, 208 compliant,		
19. Security Classif. (of this report)	20. Security Classif. (of this page)	21. No of pages	22. Price

Form DOT F 1700.7 (8\_72) Reproduction of this form and completed page is authorized

# Dynamic Science, Inc. Accident Investigation Case Number: DS03006

## TABLE OF CONTENTS

Background	1
Description	1
Investigation Type	1
Crash Location	1
Crash Date	1
Notification Date	1
Field Work Completed	1
Commence	1
Summary	
Crash Site	
Pre-crash	
Crash	
Post-crash	3
Vehicle Data - 2003 Chevrolet Silverado	4
Vehicle Damage	
Air Bag System	
Manual Restraint System	
Vehicle Data - 1997 Honda Accord	8
Occupant Demographics	9
Occupant Injuries	11
Occupant Kinematics	12
Attachment 1. Scene Diagram	13
Attachment 2. Calculations	
Attachment 3. Vetronix output	18

#### **BACKGROUND:**

Description: This Advanced 208 Compliant case was identified by National

Automobile Sampling System (NASS) Zone Center 2. The crash occurred in January, 2003. The case was reported to DSI on February 12, 2003. DSI contacted the repair shop on that same day and learned that the vehicle was already in the process of being torn down for repair. It was determined that police photographs would be available and these

were obtained. The case vehicle was inspected and the System Diagnostic Module (SDM) downloaded on February 25, 2003.

Investigation Type: On-scene Crash Location: Arizona

Crash Date: January, 2003
Notification Date: February 12, 2003
Field Work Completed: February 25, 2003

#### **SUMMARY**

#### **Crash Site**

The crash occurred in January, 2003 at 1612 hours in Arizona. The crash occurred within the confines of a four-leg intersection. The southbound leg of the intersection is comprised of one southbound travel lane, one northbound travel lane, and one left hand turn lane. The westbound leg of the intersection is comprised of one westbound travel lane and one eastbound lane. The westbound roadway is controlled by a stop sign and a flashing stop signal. The roadways were clear and free of defects. The asphalt roadways were dry and straight. The speed limit for all involved roadways is 80 km/h (50 mph).



**Figure 1**. Case vehicle approach to area of impact (south)

#### **Pre-Crash**

The case vehicle was a 2003 Chevrolet K1500 Silverado extended cab 4x4 pickup driven by an unrestrained 48-year-old male (86 kg/190 lbs) traveling southbound at a police estimated speed of 64-72 km/h (40-45 mph). Data from the SDM shows the case vehicle to be traveling 92 km/h (57 mph) prior to braking. DSI calculates the prebraking travel speed to be 93 km/h (58 mph)<sup>1</sup>. The other vehicle was a 1997 Honda Accord fourdoor sedan driven by a restrained 76-year-old female traveling westbound at a police estimated speed of 64-80 km/h (40-50 mph). It is this investigator's opinion, however, that the driver of the Honda stopped at the intersection first. The driver then attempted to cross the intersection in front of the case vehicle. The Honda accelerated to an estimated speed of 21 km/h (13 mph)<sup>2</sup>. The driver of the case vehicle saw the Honda and began braking.

#### Crash

The front of the case vehicle (12FYEW1) struck the right side of the Honda (03RYAW2). The SDM recorded a maximum longitudinal velocity change of -11.29 km/h (-7.02 mph). The total velocity change



**Figure 2**. Other vehicle approach to area of impact (west)



Figure 3. Final rest, case vehicle (south)

calculated by the WINSMASH collision model using CDCs only was 14.0 km/h (8.7 mph). The longitudinal and lateral delta V components were -13.8 km/h (-8.6 mph) and 2.4 km/h (1.5 mph), respectively. The driver's air bag in the case vehicle deployed at this time. The passenger's frontal air bag did not deploy. The total velocity change for the other vehicle was 23.0 km/h (14.3 mph). The longitudinal and lateral delta V components were -4.0 km/h (-2.5 mph) and -22.7 km/h (-14.1 mph), respectively.

<sup>&</sup>lt;sup>1</sup>See Attachment 2

<sup>&</sup>lt;sup>2</sup>Calculated using an acceleration rate of 4 ft/sec/sec

The Honda was pushed in a counterclockwise direction and there was a second, side-slap type impact between the left side of the Chevrolet (09LPEW1) and the right side of the Honda. The Honda departed the intersection in a southwestern direction. The case vehicle rotated in clockwise direction and came to rest in the intersection.

## **Post-Crash**

The driver of the case vehicle was able to exit the vehicle on his own. He sustained a minor abrasion to the back of the left wrist (AIS=1)--where his watch had been worn. The injury was likely the result of the air bag deployment. He was transported from the scene to a local hospital and arrived at 1705 hours, 53 minutes post-crash. He was treated and then released at 1927 hours.

The driver of the other vehicle sustained minor lacerations to her right hand and fingers (AIS=1). She was treated at the scene by local medical personnel. She refused any additional treatment.

Both vehicles were towed from the scene due to damage. The case vehicle was under repair at the time of the inspection.



Figure 4. Front left, case vehicle. Police photo.



**Figure 5**. Side slap damage to left rear door panel



Figure 6. Right side, Honda Accord

## **VEHICLE DATA - 2003 Chevrolet Silverado**

## VEHICLE DAMAGE

Description:

CDC:

4x4 pickup. Vehicle equipped with Z71 off-road package. The Z71 Package includes: 46mm shock absorbers, off-road jounce bumpers and stabilizer bars, skid plate package, and a high-capacity air cleaner. VIN: 2GCEK19T931xxxxxx Odometer: Unknown 5.3L, V8 Engine: Reported Defects: None noted Cargo: Aluminum tool box (unknown weight) Damage Description: Moderate damage to front bumper, grille, hood from initial impact. Minor crush damage to left

Impact 1: 12FYEW1

Impact 2: 09LPEW1

Delta V (Impact 1)<sup>3</sup>: Total 14.0 km/h (8.7 mph)

Longitudinal -13.8 km/h (-8.6 mph)

2003 Chevrolet K1500 Silverado extended cab

Latitudinal 2.4 km/h (1.5 mph)

rear door. Vehicle towed due to damage.

Energy 20,450 joules

(15,083 ft lbs)

<sup>&</sup>lt;sup>3</sup>WINSMASH collision model using CDCs only



Figure 7. Front right, case vehicle

## **Air Bag System**

This vehicle was equipped with an advanced occupant protection system. The system consists of the SDM, dual stage front air bags, a front right passenger sensing system, and a driver's seat belt latch usage detector. The system is equipped with an air bag shutoff switch for the front right passenger air bag. The switch was set to AUTO at the time of the inspection. The system is controlled by the SDM. The SDM is located beneath the driver's seat. The primary function of the SDM is to control the deployment of the occupant protection systems. The system records the vehicle's forward velocity change. The SDM will record 100 milliseconds of data after the deployment criteria is met and up to 50 milliseconds of data before deployment criteria is met.

The downloaded data indicated that the case vehicle had a maximum recorded longitudinal velocity change of -11.29 km/h (-7.02 mph) at the 112 ms mark.

The Vetronix report further indicates that:

- 1. The driver's belt switch status was unbuckled.
- 2. The time from algorithm enable (AE) to maximum recorded velocity change was 112.5 milliseconds
- 3. This was a first stage deployment with the time from AE to deployment command criteria met being 17.5 milliseconds.
- 4. There was no second stage deployment.
- 5. The brake switch status was ON two seconds before algorithm enable.
- 6. The vehicle speed was 92 km/h (57 mph) five seconds before AE, decelerating to 72 km/h (45 mph) one second before AE.



Figure 8. Face of driver's air bag



Figure 9. Driver's seat

The case vehicle was equipped with frontal air bags mounted in the steering wheel and mid mounted in the instrument panel of the front right seat position. The driver's air bag deployed. With an unrestrained driver, the deployment threshold would necessarily be lower. The passenger air bag did not deploy. The driver's air bag module had been removed from the vehicle. The driver air bag module was located in the center hub of the steering wheel rim. The air bag module cover had an I-configuration. It was equipped with one tether and had two vent ports (11 and 1 o'clock positions). There was no contact evidence on the face of the air bag.

## **Manual Restraint System**

The 3-point manual restraint systems were integrated into the driver and front passenger seats. The restraint system for the rear bench seat consisted of 3-point lap and shoulder belts with fixed D-rings for the outboard positions and a center lap belt. There was no indication of seat belt usage.



**Figure 10**. Close up of driver's seat belt



**Figure 11**. Passenger air bag cut off switch in AUTO position

## **VEHICLE DATA - 1997 Honda Accord**

Description: 1997 Honda Accord LX four-door

VIN: 1HGCD5630VAxxxxxx

Odometer: Unknown

Engine: Unknown

Reported Defects: None noted

Cargo: Unknown

Damage Description: Police report describes vehicle as being

disabled. Vehicle towed due to damage.

Damage described as heavy contact to its right side; damage to right front fender, right front wheel, right side mirror, right front door, and right rear fender. Windshield damaged.

CDC: Impact 1: 03RYAW2

Impact 2: Unknown

Delta V (Impact 1): Total 23.0 km/h (14.3 mph)

Longitudinal -4.0 km/h (-2.5 mph)

Latitudinal -22.7 km/h (-14.1 mph)

Energy 22,788 joules

(16,808 ft lbs)



Figure 12. Right side, Honda. Police photo.

## **OCCUPANT DEMOGRAPHICS**

2003 Chevrolet Silverado Occupant 1

Age/Sex: 48/Male

Seated Position: Front left

Seat Type: Fabric covered bucket seat,

unknown seat track position

(seat removed prior to

inspection)

Height: Unknown

Weight: 86 kg (190 lbs)

Occupation: Driver

Pre-existing Medical Condition: High blood pressure

Alcohol/Drug Involvement: None

Driving Experience: Presumed to be greater than

10 year

Body Posture: Presumed to be normal,

upright

Hand Position: Left hand on steering wheel,

right unknown

Foot Position: Right foot on brake, left on

floor

Restraint Usage: Integrated lap and shoulder

belt, not used

Air bag: Steering wheel mounted air

bag, deployed

## 1997 Honda Accord

Age/Sex: 76/Female

Seated Position: Front left

Seat Type: Bucket

Height: Unknown

Weight: Unknown

Occupation: Presumed to be retired

Pre-existing Medical Condition: None noted

Alcohol/Drug Involvement: None

Driving Experience: Presumed to be greater than

10 years

Body Posture: Unknown

Hand Position: Unknown

Foot Position: Right foot presumed to be on

accelerator, left on floor

Restraint Usage: Lap and shoulder belt

available, used – per police

report

## **OCCUPANT INJURIES**

## 2003 Chevrolet Silverado

	<u>INJURY</u>	OIC CODE	<u>ICD-9</u>	<u>SOURCE</u>
Driver:	Abrasion, left wrist	790202.1,2	913.0	Air bag

## 1997 Honda Accord

	<u>INJURY</u>	OIC CODE	<u>ICD-9</u>	<u>SOURCE</u>
Driver:	Minor lacerations, right hand	790600.1,1	882.0	Unknown
	Minor lacerations, right fingers	790600.1,1	883.0	Unknown

## **OCCUPANT KINEMATICS**

The 48-year-old driver of the case vehicle was seated in a normal, upright fashion in the fabric covered bucket seat. The seat had been removed prior to inspection and the seat track position is not known. He was not wearing the available 3-point integrated lap and shoulder belt. There were no indications of usage in this crash. The SDM indicated the seat belt was unbuckled. Prior to impact, his right foot was on the brake; the left was on the floor. Both hands were on the steering wheel.

Upon impact, the driver's front air bag deployed. The driver responded to the 12 o'clock direction of force by exhibiting a forward trajectory. His head and torso likely loaded the deployed air bag to some degree. The driver's left wrist/watch came



Figure 13. Overview of driver's seated area

into contact with the deploying air bag—causing a minor abrasion. During the second impact, the driver pitched to the left to some slight degree. There were no indications of interior contacts or any resultant injuries. He was transported by a ground ambulance to a local trauma center where he was examined and released at 1927 hours. The transport was mainly due to his elevated blood pressure.

## **Attachment 1. Scene Diagram**




Figure 14. Scene diagram

## **Attachment 2. Calculations**

**CASE NUMBER: DS03006** 

Comments: Other vehicle - accelerate from stop

## \* \* VELOCITY AT ANY POINT IN A SKID/ACCEL \* \*

 $V = \sqrt{Vo^2 \pm (2 \times a \times D)}$ 

 $V = \sqrt{0.00^2 + (2 \times 4.00 \times 46.00)}$ 

 $V = \sqrt{0.00 + 368.00}$ 

 $V = \sqrt{368.00}$ 

V = 19.18

V = The Velocity in FPS.

Vo = The Original Velocity in FPS.

2 = A Constant.

a = The Acceleration Rate.

D = The Distance in Feet.

INPUTS:	
The Acceleration Rate is:	4.00
The Velocity in FPS is:	0.00
The Distance in Feet is:	46.00

RESULTS:		
The Speed in MPH is:	13.08	
The Velocity in FPS is:	19.18	

## CASE NUMBER: ds03006

Comments: speed assuming brakes on for 2 seconds (83 fps 1st second, 65 fps 2nd second)

## \* \* MINIMUM SPEED W/ KNOWN DRAG FACTOR \* \*

 $S = \sqrt{30 \times D \times f}$ 

 $S = \sqrt{30 \times 148.00 \times 0.65}$ 

 $S = \sqrt{2886.00}$ 

S = 53.72

S = The Speed in MPH. 30 = A Constant. D = The Distance in Feet.

f =The Adjusted Accel/Drag Factor.

INPUTS:	
The Acceleration/Drag Factor is:	0.65
The Distance in Feet is:	148.00

RESULTS:		
The Speed in MPH is:	53.72	
The Velocity in FPS is:	78.75	

## CASE NUMBER: ds03006

Comments: post impact skid

## \* \* MINIMUM SPEED W/ KNOWN DRAG FACTOR \* \*

 $S = \sqrt{30 \times D \times f}$ 

 $S = \sqrt{30 \times 22.00 \times 0.65}$ 

 $S = \sqrt{429.00}$ 

S = 20.71

S = The Speed in MPH. 30 = A Constant.

D = The Distance in Feet.

f =The Adjusted Accel/Drag Factor.

INPUTS:	
The Acceleration/Drag Factor is:	0.65
The Distance in Feet is:	22.00

RESULTS:	
The Speed in MPH is:	20.71
The Velocity in FPS is:	30.36

## **CASE NUMBER: DS03006**

Comments: combined speeds (pre-impact braking, post impact skid, delta v)

## \* \* COMBINED MINIMUM SPEEDS W/ KNOWN SPEEDS \* \*

 $S = \sqrt{S^2(1) + S^2(2) + ... S^2(n)}$ 

 $S = \sqrt{(53.72)^2 + (20.71)^2 + (7.02)^2 + (0.00)^2 + (0.00)^2 + (0.00)^2 + (0.00)^2 + (0.00)^2}$ 

 $S = \sqrt{2885.83 + 428.90 + 49.28 + 0.00 + 0.00 + 0.00 + 0.00 + 0.00}$ 

 $S = \sqrt{3364.01}$ 

S = 58.00

S = The Speed in MPH.

 $S^2$  = The Individual Min. Speed.

(1), (2), (n) = The # of the individual speed.

INPUTS:	
Speed #1 in MPH is:	53.72
Speed #2 in MPH is:	20.71
Speed #3 in MPH is:	7.02

RESULTS:	
The Speed in MPH is:	58.00
The Velocity in FPS is:	85.02


## Attachment 3. Vetronix output

## **CDR File Information**


Vehicle Identification Number	2GCEK19T931xxxxxx
Investigator	
Case Number	
Investigation Date	
Crash Date	
Filename	DS03006.CDR
Saved on	02/25/2003 8:12:53 AM
Data check information	F316BD0F
Collected with CDR version	Crash Data Retrieval Tool 2.00
Collecting program verification number	A31D1C76
Reported with CDR version	Crash Data Retrieval Tool 2.00
Reporting program verification number	A31D1C76
Event(s) recovered	Deployment

System Status At Deployment

Cystem status At Deployment	
SIR Warning Lamp Status	OFF
Driver's Belt Switch Circuit Status	UNBUCKLED
Ignition Cycles At Deployment	1714
Ignition Cycles At Investigation	1719
Maximum SDM Recorded Velocity Change (MPH)	-7.02
Algorithm Enable to Maximum SDM Recorded Velocity Change (msec)	112.5
Driver First Stage Time Algorithm Enabled to Deployment Command Criteria Met (msec)	17.5
Driver Second Stage Time Algorithm Enabled to Deployment Command Criteria Met (msec)	N/A
Passenger First Stage Time Algorithm Enabled to Deployment Command Criteria Met (msec)	N/A
Passenger Second Stage Time Algorithm Enabled to Deployment Command Criteria Met (msec)	N/A
Time Between Non-Deployment And Deployment Events (sec)	N/A
Frontal Deployment Level Event Counter	1
Event Recording Complete	Yes
Multiple Events Associated With This Record	No
One Or More Associated Events Not Recorded	No



Seconds Before AE	Vehicle Speed (MPH)	Engine Speed (RPM)	Percent Throttle	Brake Switch Circuit Status		
-5	57	1600	23	OFF		
-4	57	1600	7	OFF		
-3	57	1600	15	OFF		
-2	56	1600	0	ON		
-1	45	1024	0	ON		



Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
Recorded Velocity Change (MPH)	-0.62	-1.55	-2.48	-4.03	-5.27	-5.89	-6.20	-6.51	-6.51	-5.82	-682	N/A	N/A	N/A	N/A