Remote / Vehicle vs Tractor Trailer vs Vehicle vs Vehicle vs Vehicle vs Vehicle Dynamic Science, Inc. / Case Number: DS97023

1996 Mercedes Benz E320 4-door

California
September, 1997

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points be coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the precrash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

Technical Report Documentation Page 1. Report No. 2. Government Accession No. 3. Recipient Catalog No. DS97023 4. Title and Subtitle 5. Report Date In-Depth Accident Investigation 6. Performing Organization Report No. 7. Author(s) 8. Performing Organization Report No. Dynamic Science, Inc. 9. Performing Organization name and Address 10. Work Unit No. (TRAIS) Dynamic Science, Inc. 530 College Parkway, Ste. K. 11. Contract or Grant no. Annapolis, MD 21401 DTNH22-94-D-27058

13. Type of report and period Covered

14. Sponsoring Agency Code

15. Supplemental Notes

400 7th Street, SW Washington, DC 20590

12. Sponsoring Agency Name and Address

U.S. Dept. of Transportation (NRD-32)

National Highway Traffic Safety Administration

16. Abstract

This collision occurred in California on September, 1997 at 2145 hours. This was a five vehicle collision with multiple impacts. The collision occurred on a heavily traveled northbound Interstate. The collision occurred during night hours with the roadway being lighted by street lights. It was raining, and the roadway was wet. Vehicle 1, was a 1996 Mercedes Benz E320 4-door sedan driven by a properly restrained 17-year-old female (48 kg, 106 in / 167.6 cm, 66 in), and traveling northbound on the acceleration lane. Vehicle 2, was a 1996 White Freightliner 3-axle tractor towing a trailer driven by a 37-year-old male, and traveling northbound in the far right lane. Vehicle 3, was a 1994 Mazda MP4 driven by a 38-year-old male, and traveling northbound in the far left lane. Vehicle 4, was a 1985 Lincoln Town Car driven by a 62-year-old male, and traveling northbound in the second lane from the right. Vehicle 5, a 1994 Honda Civic driven by a 21-year-old male, traveling in the second lane from the right, directly behind Vehicle 4. The front right seat of Vehicle 5 was occupied by a 21-year-old male. Vehicle 1 was accelerating to merge onto the Interstate. Due to the wet roadway, the driver lost control of the vehicle and began a clockwise rotation. The driver over-corrected the vehicle to the left, and started to spin counterclockwise in a westerly direction across all northbound travel lanes. The driver of Vehicle 2 saw Vehicle 1 out of control and applied his brake, but was unable to stop. The front of Vehicle 2 struck the left side of Vehicle 1 at the left rear door. At impact, the driver's door mounted side air bag in Vehicle 1 deployed. Vehicle 1 continued in a westerly direction and the driver of Vehicle 3 saw Vehicle 1 about to cross into the lane he was traveling in. The driver of Vehicle 3 applied the brakes, but was unable to stop and the front of Vehicle 1 collided with the right side of Vehicle 3. The braking by Vehicle 2, in order to avoid colliding with Vehicle 1, caused Vehicle 2 to "jack knife". The driver of Vehicle 4 saw Vehicle 2 jackknifing and applied the brakes. Vehicle 4 was unable to stop and with the front collided with the left side of the trailer being towed by Vehicle 2. Vehicle 5 saw Vehicle 4 collide into Vehicle 2 and braked, but was unable to stop. The front of Vehicle 5 struck the back of Vehicle 4. At impact, the driver's and front right air bags in Vehicle 5 deployed. Vehicle 1 is equipped with Supplemental Restraint System which includes driver and front right air bags, dual front door mounted side air bags, electronic Emergency Tensioning Retractors (ETR) which also incorporate mechanical belt force limiters, and knee bolsters. Neither front nor side air bags will deploy if the seat is empty (less than eleven pounds detected). Neither front air bag deployed in this collision. The driver's door mounted side air bag did deploy, and the driver's ETR activated. The driver of Vehicle 1 had little recollection of the collision. She indicated that she only remembers beginning to spin out and then blacked out. She sustained injuries consisting of a neck and lower lumbar strains. She was transported by ground ambulance to a local hospital where she received emergency room treatment and was released. She believed that it was the side air bag that prevented possible chest injuries. Vehicle 1 sustained major damage to its front end (2nd event 11FYEW2), left side (1st event), and back end (06BZEW2). Vehicle 1 was not inspected and a CDC of 10LZEW3 was assigned to the deployment of the driver's side air bag, the first event. Delta-V for the event was computed using the barrier routine of WinSmash, and it produced a longitudinal Delta-V of -12.7 km/h (7.9 MPH) and a latitudinal Delta-V of 15.2 km/h (9.5 MPH).

17. Key Words		18. Distribution Statement	
Side air bag, deployment, collision			
19. Security Classif. (of this report)	20. Security Classif. (of this page)	21. No of pages	22. Price

Form DOT F 1700.7 (8_72) Reproduction of this form and completed page is authorized

Dynamic Science, Inc. Accident Investigation Case Number: DS97023

Table of Contents

BACKGROUND
Description
Crash Location
Crash Date
Notification Date
Field Work Completed
SUMMARY
SCENE DIAGRAM -1
DETAILED INFORMATION
Vehicles
Supplemental Restraint System
Occupants
Injuries and Injury Mechanisms
Occupant Kinematics
Photo Index

BACKGROUND:

Description: This case was initiated in response to a driver's door mounted side air

bag deployment. This case is being conducted as a remote investigation. NHTSA was notified by Dynamic Science, Inc.

Crash Location: California

Crash Date: September, 1997
Notification Date: October 19, 1997
Field Work Completed: October, 1997

SUMMARY:

This collision occurred in California in September, 1997 at 2145 hours. This was a five vehicle collision with multiple impacts. The collision occurred on a heavily traveled northbound Interstate. At the point of impact, there are four travel lanes, plus two High Occupant Vehicle lanes, plus one acceleration lane. The Interstate travel lanes have a rained grooved surface with the acceleration lane being an asphalt surface. There were no traffic controls, and the posted speed limit is 105 km/h (65 mph). The collision occurred during night hours with the roadway being lighted by street lights. It was raining, and the roadway was wet.

Vehicle 1 was a 1996 Mercedes Benz E320 4-door sedan driven by a properly restrained 17-year-old female (48 kg, 106 in / 167.6 cm, 66 in), and traveling northbound in the acceleration lane. Vehicle 2 was a 1996 White Freightliner 3-axle tractor towing a trailer driven by a 37-year-old male, and traveling northbound in the far right lane. Vehicle 3 was a 1994 Mazda MP4 driven by a 38-year-old male, and traveling northbound in the far left lane. Vehicle 4, was a 1985 Lincoln Town Car driven by a 62-year-old male, and traveling northbound in the second lane from the right. Vehicle 5 a 1994 Honda Civic driven by a 21-year-old male, was traveling in the second lane from the right, directly behind Vehicle 4. The front right seat of Vehicle 5 was occupied by a 21-year-old male.

Vehicle 1 was accelerating to merge onto the Interstate. Due to the wet roadway, the driver lost control of the vehicle and began a clockwise rotation. The driver over-corrected the vehicle to the left, and started to spin counterclockwise in a westerly direction across all northbound travel lanes. The driver of Vehicle 2 saw Vehicle 1 out of control and applied his brake, but was unable to stop. The front of Vehicle 2 struck the left side of Vehicle 1 at the left rear door. At impact, the driver's door mounted side air bag in Vehicle 1 deployed. Vehicle 1 continued in a westerly direction and the driver of Vehicle 3 saw Vehicle 1 about to cross into the lane he was traveling in. The driver of Vehicle 3 applied the brakes, but was unable to stop and the front of Vehicle 1 collided with the right side of Vehicle 3.

The braking by Vehicle 2, in order to avoid colliding with Vehicle 1, caused Vehicle 2 to "jack knife".

DS97023

The driver of Vehicle 4 saw Vehicle 2 jackknifing and applied the brakes. Vehicle 4 was unable to stop and with the front collided with the left side of the trailer being towed by Vehicle 2. Vehicle 5 saw Vehicle 4 collide into Vehicle 2 and braked, but was unable to stop. The front of Vehicle 5 struck the back of Vehicle 4. At impact, the driver's and front right passenger's air bags in Vehicle 5 deployed.

The final rest position of Vehicle 1 is not known. After colliding with Vehicle 1, Vehicle 2 came to rest straddling the far two right lanes with the trailer jackknifed and the tractor heading in a westerly direction. Vehicle 3's final rest position is not known. Vehicles 4 came to final rest straddling the far two right lanes, against the left side of Vehicle 2's trailer heading east. Vehicle 5 came to final rest in the second lane from the left heading north.

Vehicle 1 is equipped with a Supplemental Restraint System which includes a driver's and a front right passenger's air bag, dual front door mounted side air bags, electronic Emergency Tensioning Retractors (ETR) which also incorporate mechanical belt force limiters, and knee bolsters. Neither front nor side air bags will deploy if the seat is empty (less than eleven pounds detected). Neither frontal air bag deployed in this collision. The driver's door mounted side air bag did deploy, and the driver's ETR activated.

The driver of Vehicle 1 had little recollection of the collision. She indicated that she only remembers beginning to spin out and then blacked out. She sustained injuries consisting of a neck and lower lumbar strains. She was transported by ground ambulance to a local hospital where she received emergency room treatment and was released. She believed the side air bag prevented possible chest injuries.

Vehicle 1 sustained major damage to its front end (2nd event 11FYEW2), left side (1st event), and back end (06BZEW2). Vehicle 1 was not inspected but from photographs a CDC of 10LZEW3 was assigned to the deployment of the driver's door mounted side air bag, the first event. Delta-V for the event was computed using the barrier routine of WinSmash, and it produced the following results:

Vehicle 1

Total: 19.8 km/h (12.3 mph)
Longitudinal: -12.7 km/h (7.9 mph)
Latitudinal: 15.2 km/h (9.4 mph)

This is a borderline reconstruction, but the results fit the collision model and appear reasonable. Vehicle 1 was towed from the scene due to damage and was declared a total loss by the insurance company.

The PAR notes that the driver of Vehicle 2 was wearing the lap/shoulder restraints, and did not report any injuries. Vehicle 2 sustained damage to its front and left sides, and was towed from the scene.


DS97023

The PAR notes that the driver of Vehicle 3 was wearing the lap/shoulder restraints, and did not report any injuries. Vehicle 3 was driven from the scene.


The PAR notes that the driver of Vehicle 4 was wearing the lap/shoulder restraints. He complained of pain to his right knee and stated that he would seek his own medical treatment. Vehicle 4 sustained moderate damage to its front and right side, and was towed from the scene.

The PAR notes only the deployment of the driver's and front right passenger's air bags in Vehicle 5. The driver did not report any injuries. The front right occupant sustained a dislocation of his right shoulder. He was transported to a local hospital via ground ambulance for medical treatment. Vehicle 5 sustained major damage to its front end, and was towed from the scene.

SCENE DIAGRAM -1



SCENE DIAGRAM -2



Vehicle 1

Description: 1996 Mercedes Benz E320 4-door

VIN: WDBJF55F4TJXXXXXX

Odometer: Unknown digital display

Engine: V6/3.2-liter

Reported Defects: None

Cargo: None visible

Damage Description: Major damage to the hood, grille area, both front

quarter panels, the entire left side, the back end, hood, and rear right quarter panel. There was damage to the rear axle, with both of the rear tires restricted. The vehicle was declared a total loss by the insurance

company.

CDC Impact # 1 Vehicle 1 vs Vehicle 2 Driver's side air bag deployment event (not the highest Delta-V):

10LZEW3



Figure 1. Left side damage.

Impact Speed: Unknown

Delta V¹: Total 19.8 km/h

(12.3 MPH)

Longitudinal -12.7 km/h

(-7.9 MPH)

¹ Damage (CDC only from photographs) barrier algorithm of WinSmash.

Latitudinal 15.2 km/h

(9.4 MPH)

Energy 41,995 joules

(31,007 ft-lbs)

This is a borderline reconstruction, but the results fit the collision model and appear reasonable.

Supplemental Restraint System:

Vehicle 1 is equipped with a Supplemental Restraint System which includes a driver and a front right passenger air bag, dual front door mounted side air bags, electronic Emergency Tensioning Retractors (ETR) which also incorporate mechanical belt force limiters, and knee bolsters. Neither front nor side air bags will deploy if the seat is empty (less than eleven pounds detected). Neither frontal air bag deployed in this collision. The driver's door mounted side air bag did deploy, and the driver's ETR activated.



Figure 2. Driver's side ETR and air bag.




Figure 3. Driver's door mounted side air bag.

<u>Vehicle 2</u>

Description: 1996 Freight/White 3-axle tractor towing a 1988

Utility box van

VIN: Unknown

Odometer: Unknown

Engine: Unknown

Reported Defects: None noted

Cargo: Unknown

Damage Description: Damage noted on the PAR to the front, and the right

side of the tractor

CDC Impact # 1, Vehicle 1 vs Vehicle 2: Unknown

Impact Speed: Unknown

Delta V: Not calculated,

insufficient data

Vehicle 3

Description: 1994 Mazda MPV Van

VIN: Unknown

Odometer: Unknown

Engine: Unknown

Reported Defects: None noted

Cargo: Unknown

Damage Description: PAR noted moderate damage to the right side

CDC Impact # 2, Vehicle 1 vs Vehicle 3: Unknown

Impact Speed: Unknown

Delta V^2 : Total 30.8 km/h

(19.1 MPH)

Longitudinal -8.0 km/h

(-5.0 MPH)

Latitudinal -29.8 km/h

(-18.5 MPH)

Energy 112,885 joules

(83,327 ft-lbs)

This is a borderline reconstruction, but the results fit the collision model and appear reasonable.

² CDC only of Vehicle 1, and the Missing Vehicle algorithm of WinSmash.

Vehicle 4	
-----------	--

Description: 1985 Lincoln Towncar

VIN: Unknown

Odometer: Unknown

Engine: Unknown

Reported Defects: None noted

Cargo: Unknown

Damage Description: PAR noted moderate damage to the front end

CDC Impact # 3 Vehicle 4 vs Vehicle 2: Unknown

Impact Speed: Unknown

Delta V: Not calculated,

insufficient data

	V	ehicle	5
--	---	--------	---

Description: 1994 Honda Civic

VIN: Unknown

Odometer: Unknown

Engine: Unknown

Reported Defects: None noted

Cargo: Unknown

Damage Description: PAR noted major damage to the front end

CDC Impact # 4, Vehicle 5 vs Vehicle 4: Unknown

Impact Speed: Unknown

Delta V: Not calculated,

insufficient data

Occupants

Vehicle 1 Occupant 1

Age/Sex: 17/Female

Seated Position: Left front

Seat Type: Bucket

Height: 168 cm (66 in)

Weight: 48 kg (106 lbs)

Occupation: Unknown

Pre-existing Medical Condition: Unknown

Alcohol/Drug Involvement: None

Driving Experience: Unknown

Body Posture: Assumed normal, upright

Hand Position: Assumed both on steering

wheel

Foot Position: Unknown

Restraint Usage: Lap and shoulder belts

used/pretensioner fired

Supplemental Restraint System: The steering wheel mounted

frontal air bagdid not deploy. Driver's door mounted side air bag deployed. Driver's

side ETS activated.

Vehicle 2 Occupant 1

Age/Sex: 37/Male

Seated Position: Left front

Seat Type: Unknown

Height: 178 cm (70 in)

Weight: 77 kg (170 lbs)

Occupation: Truck driver

Pre-existing Medical Condition: Unknown

Alcohol/Drug Involvement: None

Driving Experience: . 20 years

Body Posture: Assumed normal,

upright

Hand Position: Presumably on

steering wheel

Foot Position: Right foot on brake

pedal

Manual Restraint/Usage: Lap and shoulder

belts used according

to PAR

Supplemental Restraint System: None

Vehicle 3 Occupant 1

Age/Sex: 38/Male

Seated Position: Left front

Seat Type: Unknown

Height: 188 cm (74 in)

Weight: 84 kg (185 lbs)

Occupation: Unknown

Pre-existing Medical Condition: Unknown

Alcohol/Drug Involvement: None

Driving Experience: . 22 years

Body Posture: Assumed normal,

upright

Hand Position: Presumably on

steering wheel

Foot Position: Right foot on brake

pedal

Manual Restraint/Usage: Lap and shoulder

belts used per PAR

Supplemental Restraint System: None

Vehicle 4 Occupant 1

Age/Sex: 62/Male

Seated Position: Left front

Seat Type: Unknown

Height: 178 cm (70 in)

Weight: 77 kg (170 lbs)

Occupation: Unknown

Pre-existing Medical Condition: Unknown

Alcohol/Drug Involvement: None

Driving Experience: . 46 years

Body Posture: Assumed normal,

upright

Hand Position: Presumably on

steering wheel

Foot Position: Right foot on brake

pedal

Manual Restraint/Usage: Lap and shoulder

belts used per PAR

Supplemental Restraint System: None per PAR

<u>Vehicle 5</u> Occupant 1 Occupant 2

Age/Sex: 21/Male 21/Male

Seated Position: Left front Right front

Seat Type: Bucket Bucket

Height: 165 cm (65 in) Unknown

Weight: 66 kg (145 lbs) Unknown

Occupation: Unknown Unknown

Pre-existing Medical Condition: Unknown Unknown

Alcohol/Drug Involvement: None NA

Driving Experience: . 5 years NA

Body Posture: Presumed normal, Unknown

upright

Hand Position: Presumably on NA

steering wheel

Foot Position: Right foot on brake NA

pedal

Manual Restraint/Usage: 3-point lap and 3-point lap and

shoulder belts, shoulder belts, unknown if used unknown if used

Supplemental Restraint System: Driver's air bag Mid-mounted front

mounted in the right air bag,

steering wheel hub, deployed on impact deployed on impact with Vehicle 4.

with Vehicle 4.

DS97023

Injuries and Injury Mechanisms

Vehicle 1

	<u>INJURY</u>	OIC CODE	ICD-9	SOURCE
Driver:	Neck strain	640278,1.6	847.0	Inertial motion
	Lower lumbar strain	640678,1.8	847.2	Inertial motion

Occupant Kinematics

The driver of Vehicle 1 was seated in the left front seat. She was wearing the available 3-point lap and shoulder belts. Initially both hands were probably on the steering wheel and her right foot was on the accelerator. As she began to lose control of the vehicle, she began to turn the steering wheel to the left and it is unknown where her hands were located upon impact with Vehicle 2. At impact with Vehicle 2, her upper torso began to move laterally to the left when door mounted side air bag deployed. The ETS activated retracting and locking the 3-point lap and shoulder belts. The secondary impact involving the front of Vehicle 1 and the right side of Vehicle 3 caused the driver of Vehicle 1 to move slightly forward; the ETS maintained a locked position.

Vehicle 2				
Driver:	INJURY Not injured			
Vehicle 3				
Driver:	INJURY Not injured			
Vehicle 4				
Driver:	INJURY Complained of pain to right knee. Not a codeable injury			
Vehicle 5				
5.	<u>INJURY</u>	OIC CODE	ICD-9	SOURCE
Driver:	Not injured			

751030,2.1

831.00

Unknown

Dislocated right shoulder

Front right

occupant:

Photo Index

Photo no.	Vehicle No.	Direction of Picture	Subject Matter
01-03	All vehicles	North	All travel lanes of Interstate. Areas of travel, impact and final rest.
04	1	North	Direction of travel as it merged onto the Interstate and headed for the impact areas.
05-06	2	North	Areas of impact from the far right lane.
07-24	1	NA	Exterior damage of vehicle.
25-30	1	NA	Driver's seat and deployed door mounted side air bag.
31-32	1	NA	Rear left seat. Note intrusion to door panel.
33	1	NA	Driver's air bag, windshield, and instrument areas. Note non-deployment of driver's air bag.
34	1	NA	Front, center and right air bag, windshield, and instrument areas. Note non-deployment of front right air bag.