Remote, Redesigned Air Bag Special Study FOR NHTSA'S INTERNAL USE ONLY

Dynamic Science, Inc., Case Number (1998-049-808E) 1998 Ford Taurus Texas September/1998

Technical Report Documentation Page					
Report No. 2. Government Accession No.		3. Recipient Catalog No.			
1998-049-808E					
4. Title and Subtitle		5. Report Date			
		April 1, 1999			
		6. Performing Organization Report No.			
^{7. Author(s)} Dynamic Science, Inc.		8. Performing Organization Report No.			
9. Performing Organization name and Addres	S	10. Work Unit No. (TRAIS)			
Dynamic Science, Inc.					
530 College Parkway, S	te. K	11. Contract or Grant no.			
Annapolis, MD 21401		DTNH22-94-D-27058			
12. Sponsoring Agency Name and Address		13. Type of report and period Covered			
U.S. Dept. of Transportation (NRD-32)		[Report Month, Year]			
National Highway Traffi	c Safety Administration				
400 7th Street, SW		14. Sponsoring Agency Code			
Washington, DC 20590					
15. Supplemental Notes					
16. Abstract					
fleet. This minor injury crash o occurred at a four-leg intersect northbound roadway is undivid	eed on the redesigned air bag system deployment of a 1998 ccurred in September, 1998 in the mid-morning. The weather ion. The westbound roadway is undivided and is comprised ed and is comprised to one northbound and one southbound controlled by tri-color traffic signals. The roadway is level.	er was clear and the concrete roadway was dry. The crash of two westbound and two eastbound travel lanes. The			
	four-door (case vehicles) driven by a 33-year-old male (178 g s restrained by the available manual lap/shoulder restraint. F				
Vehicle 2, a 1992 Isuzu Rodeo utility vehicle, driven by a 32-year-old male, was traveling northbound. The driver was restrained by the availal manual lap/shoulder restraint. The front right seat was occupied by a 31 year-old-male who was restrained by the available manual lap/should restraint. The light was green for northbound traffic.					

The driver of Vehicle 1 failed to yield at the red light and entered the intersection. The front of the left side of Vehicle 1 (11LYAW2) was struck by the front of Vehicle 2 (82FDEW2). Vehicle 1 sustained a longitudinal delta V of -13 km/h (-8.1 mph) and a lateral delta V of +7 km/h (4.3 mph). Vehicle 2 sustained a longitudinal delta V of -7 km/h (-4.3 mph) and a lateral delta V of -12 km/h (-7.5 mph). As a result of the this impact, the supplemental restraint system (driver's and passenger's side redesigned air bags) of the case vehicle deployed. Vehicle 1 was pushed into a clockwise rotation and came to rest in the intersection facing to the northwest. Vehicle 2 was pushed into a counterclockwise rotation and came to rest facing generally northwest.

The driver of Vehicle 1 was transported to an area hospital but no injuries were reported.

Both vehicles became disabled due to damage sustained in the crash and were towed from the scene.

17. Key Words		18. Distribution Statement		
Redesigned, air bag				
19. Security Classif. (of this report)	20. Security Classif. (of this page)	21. No of pages	22. Price	

Remote, Redesigned Air Bag Special Study <u>FOR NHTSA'S INTERNAL USE ONLY</u> Dynamic Science, Inc., Case Number (1998-049-808E) 1998 Ford Taurus Texas September/1998

Summary

This remote investigation focused on the redesigned air bag system deployment of a 1998 Ford Taurus four-door. This vehicle was part of a rental fleet. This minor injury crash occurred in September, 1998 in the mid-morning. The weather was clear and the concrete roadway was dry. The crash occurred at a four-leg intersection. The westbound roadway is undivided and is comprised of two westbound and two eastbound travel lanes. The northbound roadway is undivided and is comprised to one northbound and one southbound travel lanes. The speed limit in all directions is 48 km/h (30 mph). The intersection is controlled by tri-color traffic signals. The roadway is level.

Vehicle 1, a 1998 Ford Taurus four-door (case vehicles) driven by a 33-year-old male (178 cm/70 in., 68 kg/150 lbs.), was traveling westbound through the intersection. The driver was restrained by the available manual lap/shoulder restraint. He was wearing glasses at the time of the crash. The lights were red for westbound traffic.

Vehicle 2, a 1992 Isuzu Rodeo utility vehicle, driven by a 32-year-old male, was traveling northbound. The driver was restrained by the available manual lap/shoulder restraint. The front right seat was occupied by a 31 year-old-male who was restrained by the available manual lap/shoulder restraint. The light was green for northbound traffic.



Figure 1. Exterior, Vehicle 1, 1998 Ford Taurus

Crash Events

The driver of Vehicle 1 failed to yield at the red light and entered the intersection. The front of the left side of Vehicle 1 (11LYAW2) was struck by the front of Vehicle 2 (82FDEW2). Vehicle 1 sustained a longitudinal delta V of -13 km/h (-8.1 mph) and a lateral delta V of +7 km/h (4.3 mph). Vehicle 2 sustained a longitudinal delta V of -7 km/h (-4.3 mph) and a lateral delta V of -12 km/h (-7.5 mph).

As a result of the this impact, the supplemental restraint system (driver's and passenger's side redesigned air bags) of the case vehicle deployed.

Vehicle 1 was pushed into a clockwise rotation and came to rest in the intersection facing to the northwest. Vehicle 2 was pushed into a counterclockwise rotation and came to rest facing generally northwest.

The driver of Vehicle 1 was transported to an area hospital but no injuries were reported.

Both vehicles became disabled due to damage sustained in the crash and were towed from the scene.



Figure 2. Exterior, Vehicle 1



Figure 3. Exterior, Vehicle 2, 1992 Isuzu Rodeo

Table 1. Delta V

	Case Vehicle		Other Vehicle		
	km/h	mph	km/h	mph	
Total	15	9.3	13	8.1	
Longitudinal	-13	-8.1	-7	-4.3	
Lateral	7	4.3	-12	-7.5	

Exterior of Case Vehicle

Table 2. Vehicle Information

Model year, make and model	1998 Ford Taurus
VIN	1FAFP52U6WA
CDC	11LYAW2

Table 3. Crush Measurements

Plane of Impact	Field L cm/in.	C1 cm/in.	C2 cm/in.	C3 cm/in.	C4 cm/in.	C5 cm/in.	C6 cm/in.
Mid door	152	0	5	16	11	8	15
	59.8	0	2	6.3	4.3	3.1	5.9

Interior of Case Vehicle

The interior of the Ford Taurus sustained minor damage from occupant contact. There were no areas of intrusion into the passenger compartment. There was occupant contact evidence to the driver's side front air bag.

The case vehicle was equipped with a split bench with separate backs in the front left and the front right seating positions. The front left seat was adjusted to the middle track position. Both front seats were equipped with adjustable head restraints, which were not damaged in the crash. Both seat backs were adjusted to the slightly reclined position. The vehicle was equipped with a tilt steering column which was adjusted to the center position. There was no steering wheel deformation. The second row of the vehicle was equipped bench seats with folding back(s) for both the back left and back right seating positions.

Case Vehicle Occupant Protection Systems

The Ford Taurus was equipped with a redesigned air bag system which consisted of front left and front right air bag modules which housed air bags and depowered inflator units.

The front left air bag was housed in the steering wheel hub and was concealed by H-configuration cover flaps. The circular air bag was equipped with two tethers and two vent ports. Contact evidence consisting of what appeared to be blood was found on the bag. The air bag was not damaged.

The front right air bag was housed in the top-instrument

panel position and was concealed by cover flap. The rectangular air bag was equipped with one tethers and no vent ports.

Contact evidence consisting of what appeared to be blood was found on the bag. The air bag was not damaged.



Figure 4. Driver side air bag



Figure 5. Passenger side air bag

Case Vehicle Occupant Demographics

	Occupant 1		
Age/Sex:	33/Male		
Seated Position:	Left front		
Seat Type:	Split bench with separate backs		
Height (cm/in:):	178	70.1	
Weight (kg/lbs).:	68	150	
Pre-existing Medical Condition:	None noted		
Body Posture:	Unknown		
Hand Position:	Unknown		
Foot Position:	Left on floor, right presumably on accelerator		
Restraint Usage:	Lap and shoulder belts used properly		
Air bag:	Deployed		

Occupant Injuries

The driver of Vehicle 1 was transported to an area hospital but no injuries were reported.




Figure 6. Scene diagram