

On-scene Investigation / Vehicle to Vehicle
Dynamic Science, Inc. / Case Number: DS01-005
2000 Ford Taurus SE 4-door
Texas
January, 2001

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points be coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the pre-crash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crash-worthiness performance of the involved vehicle(s) or their safety systems.

1. Report No. DS01-005		2. Government Accession No.		3. Recipient Catalog No.	
4. Title and Subtitle In-Depth Accident Investigation				5. Report Date .	
				6. Performing Organization Report No.	
7. Author(s) Dynamic Science, Inc.				8. Performing Organization Report No.	
9. Performing Organization name and Address Dynamic Science, Inc. 530 College Parkway, Ste. K Annapolis, MD 21401				10. Work Unit No. (TRAIS)	
				11. Contract or Grant no. DTNH22-94-D-27058	
12. Sponsoring Agency Name and Address U.S. Dept. of Transportation (NRD-32) National Highway Traffic Safety Administration 400 7th Street, SW Washington, DC 20590				13. Type of report and period Covered [Report Month, Year]	
				14. Sponsoring Agency Code	
15. Supplemental Notes					
16. Abstract This case was initiated because the case vehicle was equipped with an Advanced Occupant Protection System. The collision occurred in Texas in January, 2001 at 1734 hours. This was a three vehicle, broadside type collision. The crash occurred on a seven-lane, two-way, divided roadway. The northbound roadway is comprised of three travel lanes and a left turn lane. The southbound roadway is comprised of three travel lanes and a left turn lane. The weather was cloudy and the concrete road surface was wet and slick from rain earlier in the day. The roadway is in both directions straight and level, and the posted speed limit was 72 km/h (45 mph). The case vehicle is a 2000 Ford Taurus SE 4-door that was driven by a restrained 49-year-old male. The other vehicle is a 1998 Nissan Sentra that was driven by a 23-year-old female. The third vehicle is a 1997 Buick Riviera that was driven by a 58-year-old male. The case vehicle was traveling north in the second lane from the left. The Nissan was traveling north in the left lane, next to and ahead of the case vehicle. The Buick was traveling southbound and attempting a left turn into a private parking lot. The Buick attempted the left turn directly in front of the Nissan and the front of the Nissan struck the right side of the Buick. On impact both of the air bags in the Buick deployed. The police report indicates that the air bags in the Nissan deployed. The collision between the Buick and the Nissan caused the Nissan to rotate clockwise and directly in the path of the case vehicle. The front of the case vehicle (12FDEW1) struck the right side of the Nissan and on impact the air bags in the case vehicle deployed. The driver of the case vehicle sustained a cervical strain, a left shoulder sprain, and a tongue laceration (driver bit his tongue).					
17. Key Words Air bag, deployment, injury, advanced, AOPS, SDM, RCM, Vetronix			18. Distribution Statement		
19. Security Classif. (of this report)	20. Security Classif. (of this page)	21. No of pages	22. Price		

**Dynamic Science, Inc.
Accident Investigation
Case Number: DS01-005**

TABLE OF CONTENTS

Background	1
Description	1
Investigation Type	1
Crash Location	1
Crash Date	1
Notification Date	1
Field Work Completed	1
Summary	1
Scene Diagram	4
Detailed Information	5
Vehicles	5
Aops Discussion	6
Occupants	9
Injuries and Injury Mechanisms	12
Occupant Kinematics	13
Attachment 1. EDR report (Ford Taurus)	14
Attachment 2. SDM Report	16

BACKGROUND:

Description: This Advanced Occupant Protection Systems case was reported to the NHTSA by DSI on March 16, 2001 and the case was assigned on March 19, 2001 and an on-site investigation was conducted. All field work was completed on March 22, 2001.

Investigation Type: On-scene

Crash Location: Texas

Crash Date: January, 2001

Notification Date: March 19, 2001

Field Work Completed: March 22, 2001

SUMMARY:

The collision occurred in Texas in January, 2001 at 1734 hours. This was a three vehicle, broadside type collision. The crash occurred on a seven-lane, two-way, divided roadway. The northbound roadway is comprised of three travel lanes and a left turn lane. The southbound roadway is comprised of three travel lanes and a left turn lane. The weather was cloudy and the concrete road surface was wet and slick from rain earlier in the day. The roadway is straight and level, and the posted speed limit was 72 km/h (45 mph).

The case vehicle is a 2000 Ford Taurus SE 4-door that was driven by a restrained 49-year-old male. The other vehicle is a 1998 Nissan Sentra that was driven by a 23-year-old female. The third vehicle is a 1997 Buick Riviera that was driven by a 58-year-old male.



Figure 1. Path of the case vehicle (north)




Figure 2. Direction of travel of third vehicle—Buick (south-east).

The case vehicle was traveling north in the second lane from the left. The Nissan was traveling north in the left lane, next to and ahead of the case vehicle. The Buick was traveling southbound and attempting a left turn into a private parking lot. The Buick attempted the left turn directly in front of the Nissan and the front of the Nissan struck the right side of the Buick. On impact both of the air bags in the Buick deployed. The police report indicates that the air bags in the Nissan deployed.



Figure 3. Exterior damage to case vehicle.

The Sensing and Diagnostic Module (SDM) data was downloaded from the Buick using the Vetronix Crash Data Retrieval system. The data indicates a recorded maximum velocity change of -14.8 km/h (-9.21 mph) at the 120 ms mark. The data indicates that the driver was unbuckled. The SDM report is included as an attachment to this report. The Buick sustained a total Δv of 14.9 km/h (9.2 mph)¹.



Figure 4. Exterior damage, other vehicle (Nissan Sentra)

The collision between the Buick and the Nissan caused the Nissan to rotate clockwise and directly in the path of the case vehicle. The front of the case vehicle

(12FDEW1) struck the right side of the Nissan and on impact the air bags in the case vehicle deployed. The case vehicle sustained a total Δv of 24.3 km/h (15.1 mph), a longitudinal Δv of -23.9 km/h (-14.8 mph), and a latitudinal Δv of 4.2 km/h (2.6 mph)². The downloaded Electronic Data Recorder (EDR) data indicates a cumulative longitudinal Δv of -22.2 km/h (-13.8 mph) at the 78 ms mark. The data indicates that the driver's seat belt was engaged and that the pretensioner on the driver's side fired. The Nissan sustained a total Δv of 34.2 km/h (21.2 mph), a longitudinal Δv of 22.0 km/h (13.6 mph), and a latitudinal Δv of -26.2 km/h (-16.3 mph). The WinSmash results fit the collision model for both vehicles and appear reasonable for the case vehicle but borderline for the Nissan.

¹Calculated using WinSmash with estimated CDC only for the Sentra

²Calculated using the Missing Vehicle algorithm of Winsmash 1.2.1 and stiffness values for the case vehicle calculated using NCAP crash data.

All the vehicles were towed from the scene due to damage. The engine in the case vehicle started but there was no radiator fluid. The engine in the Buick also started but the rear right axle was severely damaged.

The police were notified of the collision at 1736 hours and arrived at the scene at 1743 hours. The local fire department was notified at 1734 hours and arrived at the scene at 1748 hours.

The driver of the case vehicle sustained a cervical strain, a left shoulder sprain, and a tongue laceration (driver bit his tongue).

The police reported that he sustain "B" type injuries consisting of pain throughout his body. He was transported to a hospital by the local fire department personnel where he was treated and released after three hours.


The driver of the Nissan sustained "B" type injuries consisting of a cut on the left side of her neck. She declined medical treatment at the scene and indicated that she would seek medical attention at a later time.

The driver of the Buick did not report any injuries to the police at the scene.



Figure 5. Exterior damage to other vehicle (Buick Riviera).

Scene Diagram



DETAILED INFORMATION**Vehicles**Case vehicle

Description:	2000 Ford Taurus SE	
VIN:	1FAFP53U9YGxxxxxx	
Odometer:	28,203 km (17,525 miles)	
Engine:	3.0 L V6	
Reported Defects:	None	
Cargo:	None	
Damage Description:	Moderate frontal damage. Bumper, grille, radiator. Vehicle towed from scene.	
CDC:	12FDEW1	
Delta V:	Total	24.3 km/h (15.1 mph)
	Longitudinal	-23.9 km/h (-14.8 mph)
	Latitudinal	4.2 km/h (2.6 mph)
	Energy	14,591 joules (10,767 ft-lbs)



Figure 7. Front right, case vehicle, Ford Taurus

AOPS discussion

This vehicle was equipped with an advanced occupant protection system. The system consists of a Restraint Control Module (RCM) dual stage front air bags, seat belt pretensioners, seat track sensors, and seat belt latch usage detectors. The system is controlled by the RCM. The primary function of the RCM is to control the deployment of the occupant protection systems. The system records longitudinal and lateral acceleration. Data related to the driver and passenger air bag deployment include: 78 milliseconds of crash pulse, deployment strategy of the dual-stage air bag system, seat belt latch use, pretensioner operation, and driver seat track location.

At impact the case vehicle sustained a total delta v of 24.3 km/h (15.1 mph), a longitudinal delta v of -23.9 km/h (-14.8 mph), and a latitudinal delta v of 4.2 km/h (2.6 mph) as computed by WinSmash. The downloaded Electronic Data Recorder (EDR) data indicates a cumulative longitudinal delta v of -22.2 km/h (-13.8 mph) at the 78 ms mark. There is a reasonable match between the WinSmash results and the EDR data. The EDR report is included as an attachment to this report.

The EDR report further indicates that:

1. This was a first stage deployment.
2. The driver's seat was not in the forward position.
3. The left front seat buckle was engaged and the right front seat buckle was not.
4. The time from algorithm wake-up to pretensioner was 16 milliseconds.
5. The time from algorithm wake-up to first stage - belted was 26 milliseconds.

The case vehicle driver's air bag was circular and measured 43 cm (16.9 in) in diameter. It was equipped with two tethers and two vent holes. On the top left of the air bag face there was black transfer that appeared not to be a driver contact. The dual module covers opened in an "H" configuration. There were no indications of any damage to driver's air bag or the covers. The case vehicle front right passenger's air bag was rectangular and measured 44 cm (17.3 in) high by 57 cm (22.4 in) wide. It was equipped with two vent ports and did not have any tethers. On the face of the air bag there were black smudges that were caused by the module cover. The single flap module cover opened properly and was not damaged.

Both front seat positions of the case vehicle were equipped with seat belt pretensioners. The front right pretensioner barrel was checked and measured 3.5 cm (1.4 in.)—indicating that it had fired. The front left pretensioner barrel was checked and measured 10.8 cm (4.3 in)—indicating that it had not fired.

There was no steering column stroke and the steering column breakaway coupling was intact.

Other vehicle (Nissan Sentra)

Description: 1998 Nissan Sentra
 VIN: 3N1AB41D8WLXXXXXX
 Odometer: Unknown
 Engine: 1.6 L 4 cylinder
 Reported Defects: None
 Cargo: Unknown
 Damage Description: Moderate frontal damage from initial impact. Bumper, grille, hood. Moderate front right fender damage from second impact.

CDC

(Impact 1 v. Buick) 12FDEW1 (estimated from photo)
 (Impact 2 v. case vehicle): 04RFEW2

Delta V (Impact 2 v. case vehicle):	Total	34.2 km/h (21.2 mph)
	Longitudinal	22.0 km/h (13.6 mph)
	Latitudinal	-26.2 km/h (-16.3 mph)
	Energy	84,019 joules (61,970 ft-lbs)



Figure 8. Front right, Nissan Sentra

Other vehicle (Buick Riviera)

Description:	1997 Buick Riviera	
VIN:	G4GD2211V4xxxxxx	
Odometer:	84,900 km (52,756 miles)	
Engine:	3.8 L V6	
Reported Defects:	None	
Cargo:	None	
Damage Description:	Moderate lateral crush to right rear.	
CDC:	02RZEW4	
Delta V:	Total	14.9 km/h (9.2 mph)
	Longitudinal	-9.5 km/h (-5.9 mph)
	Latitudinal	-11.4 km/h (-7.1 mph)
	Energy	25,606 joules (18,898 ft-lbs)



Figure 9. Right side, Buick Riviera

Occupants

<u>Case vehicle (Ford Taurus)</u>	Occupant 1
Age/Sex:	49/Male
Seated Position:	Front left
Seat Type:	Fabric covered bucket. Seat track was adjusted to rear-most position.
Height:	173 cm (68 in.)
Weight:	84 kg (185 lbs)
Occupation:	Nurse.
Pre-existing Medical Condition:	None
Alcohol/Drug Involvement:	None
Driving Experience:	Presumed to be greater than 20 years.
Body Posture:	Normal, upright.
Hand Position:	Unknown
Foot Position:	
Restraint Usage:	Lap and shoulder belt available, used
Air bag:	Steering wheel mounted air bag, deployed

Other vehicle (Nissan Sentra)

Age/Sex:	23/Female
Seated Position:	Front left
Seat Type:	Unknown
Height:	Unknown
Weight:	Unknown
Occupation:	Charity case manager
Pre-existing Medical Condition:	Unknown
Alcohol/Drug Involvement:	None
Driving Experience:	Unknown
Body Posture:	Unknown
Hand Position:	Unknown
Foot Position:	Unknown
Restraint Usage:	Lap and shoulder belt used—per police
Air bag:	Air bag deployed—per police

Other vehicle (Buick Riviera)

Age/Sex:	58/Male
Seated Position:	Front left
Seat Type:	Bucket
Height:	Unknown
Weight:	Unknown
Occupation:	Unknown
Pre-existing Medical Condition:	Unknown
Alcohol/Drug Involvement:	None
Driving Experience:	Presumed to be greater than 20 year
Body Posture:	Unknown
Hand Position:	Unknown
Foot Position:	Unknown
Restraint Usage:	Lap and shoulder belt used—per police
Air bag:	Air bag deployed—per police

Injuries and Injury MechanismsCase vehicle (Ford Taurus)

	<u>INJURY</u>	<u>OIC CODE</u>	<u>ICD-9</u>	<u>SOURCE</u>
Driver:	Cervical strain	640278.1,6	847.0	Air bag
	Left shoulder sprain	740402.1,2	840.9	Seat belt
:	Tongue laceration (driver bit his tongue)	243402.1,8	873.8	Air bag

Other vehicle (Buick Riviera)

	<u>INJURY</u>	<u>OIC CODE</u>	<u>ICD-9</u>	<u>SOURCE</u>
Driver:	No reported injuries			

Other vehicle (Nissan Sentra)

	<u>INJURY</u>	<u>OIC CODE</u>	<u>ICD-9</u>	<u>SOURCE</u>
Driver:	No reported injuries			

Occupant Kinematics

The 49-year-old male driver (173 cm/68 in, 84 kg/185 lbs) of the case vehicle was seated in a normal, upright fashion. He was wearing the available lap and shoulder belt. The upper anchorage adjustment was in the mid position. The fabric-covered bucket seat was adjusted to the rear most track position. The seat back angle was adjusted at 73 degrees from horizontal. He was wearing glasses. His right foot was on the accelerator. At impact, the driver responded to the 350 degrees direction of force by moving straight forward. The lap and shoulder belts restricted this forward motion—causing the left shoulder sprain. His face came into contact with the deployed air bag—causing the cervical strain as his head loaded the air bag and also causing the driver to bite his tongue. The driver reported that he felt a stinging sensation as the air bag contact his face. His glasses were knocked off his face but were not damaged. He also reported seeing a lot of smoke in the vehicle and hearing a loud bang from the air bag. He was transported to a hospital by the local fire department personnel where he was treated and released after three hours.



Figure 10. Driver's seated position




Figure 11. Front left interior

Attachment 1. EDR report (Ford Taurus)

2000 Taurus/Sable EDR Report - Summary Page

Investigation Data

File Name:	DS01-005.hex	File Save Date:	25-Mar-2001
File Read-out Date:	N/A	Report Date:	28-Mar-2001
Report Version:	1.6		

EDR Control Module Data

Data Validity Check:	Valid	EDR Model Version:	141
Time From Side Safing Decision to Left (Driver) Side Bag Deployment:			Not Deployed
Time From Side Safing Decision to Right (Passenger) Side Bag Deployment:			Not Deployed
Passenger Airbag Switch Position During Event:			N/A
Diagnostic Codes Active When Event Occurred:			0

Algorithm Times

Actual initiation depends on restraint system status (below).

	ms
Time From Algorithm Wakeup to Pretensioner:	16
Time From Algorithm Wakeup to First Stage - Unbelted:	25
Time From Algorithm Wakeup to First Stage - Belted:	26
Time From Algorithm Wakeup to Second Stage:	0

Restraint System Status

Driver Seat Belt Buckle:	Engaged
Passenger Seat Belt Buckle:	Not Engaged
Driver Seat Track In Forward Position:	No
Passenger Seat Weight Switch Position:	N/A

Deployment Initiation Attempt Times

	Driver	Passenger
Time From Algorithm Wakeup to Pretensioner Deployment Attempt:	16	Unbelted
Time From Algorithm Wakeup to First Stage Deployment Attempt:	26	26
Time From Algorithm Wakeup to Second Stage Deployment Attempt:	Disposal	Disposal

Notes


1. Read-out date is set by the PC interface tool.
2. Features and data parameters which are not available on the module are marked "N/A".
3. CFC 60 is a Butterworth 4-pole phaseless digital filter. (See SAE J211 Part 1 Appendix C dated March 1995.)
4. Total and maximum Delta-V results are not available from truncated/incomplete crash pulses.
5. Algorithm wakeup (0 ms) is not the first moment of vehicle contact or impact.
6. The Excel "Analysis ToolPak" Add-in must be enabled for this spreadsheet to operate properly.
7. Acceleration data and plots are only valid for frontal impact event recordings.

2000 Taurus/Sable EDR Report - Charts

Longitudinal Cumulative Delta-V

Time (ms)	0	10	20	30	40	50	60	70	78
Delta-V (MPH)	-0.4	-1.6	-2.3	-4.4	-7.1	-9.9	-12.1	-13.5	-13.8


Note: Acceleration data and plots are only valid for frontal impact event recordings.



Lateral Cumulative Delta-V

Time (ms)	0	10	20	30	40	50	60	70	78
Delta-V (MPH)	0.0	-0.2	-0.3	-0.9	-1.5	-1.3	-0.9	0.3	0.4

Note: Acceleration data and plots are only valid for frontal impact event recordings.



File Name: DS01-005.hex

Attachment 2. SDM Report (Buick)

1G4GD2211V4 [REDACTED] System Status At Deployment	
SIR Warning Lamp Status	OFF
Driver's Belt Switch Circuit Status	UNBUCKLED
Passenger Front Air Bag Suppression Switch Circuit Status	ON
Ignition Cycles At Deployment	8966
Ignition Cycles At Investigation	8974
Time From Algorithm Enable To Deployment Command (msec)	15
Time From Near Deployment To Deployment (msec)	N/A

Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
Recorded Velocity Change (MPH)	-0.88	-2.85	-3.73	-5.05	-6.36	-7.68	-8.34	-8.78	-8.78	-9.00	-9.00	-9.21	-9.00	-8.78	-8.78
Time (milliseconds)	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300
Recorded Velocity Change (MPH)	-8.56	-8.34	-8.34	-8.34	-8.12	-8.12	-7.90	-7.90	-7.68	-7.68	-7.46	-7.46	-7.24	-7.24	-7.02

