



INDIANA UNIVERSITY

TRANSPORTATION RESEARCH CENTER

School of Public and Environmental Affairs
222 West Second Street
Bloomington, Indiana 47403-1501
(812) 855-3908 Fax: (812) 855-3537

ON-SITE CERTIFIED ADVANCED 208- COMPLIANT VEHICLE INVESTIGATION

CASE NUMBER - IN-04-034
LOCATION - Texas
VEHICLE - 2004 MAZDA 3
CRASH DATE - September 2004

Submitted:

April 6, 2005
Revised: October 17, 2007



Contract Number: DTNH22-01-C-07002

Prepared for:

U.S. Department of Transportation
National Highway Traffic Safety Administration
National Center for Statistics and Analysis
Washington, D.C. 20590-0003

DISCLAIMERS

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points be coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the pre-crash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

Technical Report Documentation Page

1. <i>Report No.</i> IN-04-034		2. <i>Government Accession No.</i>		3. <i>Recipient's Catalog No.</i>	
4. <i>Title and Subtitle</i> On-Site Certified Advanced 208-Compliant Vehicle Investigation Vehicle - 2004 Mazda 3 Location - Texas			5. <i>Report Date:</i> April 6, 2005		
			6. <i>Performing Organization Code</i>		
7. <i>Author(s)</i> Special Crash Investigations Team #2			8. <i>Performing Organization Report No.</i>		
9. <i>Performing Organization Name and Address</i> Transportation Research Center Indiana University 222 West Second Street Bloomington, Indiana 47403-1501			10. <i>Work Unit No. (TRAIS)</i>		
			11. <i>Contract or Grant No.</i> DTNH22-01-C-07002		
12. <i>Sponsoring Agency Name and Address</i> U.S. Department of Transportation (NPO-122) National Highway Traffic Safety Administration National Center for Statistics and Analysis Washington, D.C. 20590-0003			13. <i>Type of Report and Period Covered</i> Technical Report Crash Date: September 2004		
			14. <i>Sponsoring Agency Code</i>		
15. <i>Supplementary Notes</i> On-site air bag investigation involving a 2004 Mazda 3, four-door sedan with manual safety belts and dual front advanced air bag system.					
16. <i>Abstract</i> This report covers an on-site investigation of an air bag deployment crash that involved a 2004 Mazda 3 (case vehicle), which ran-off-road and impacted a concrete longitudinal barrier and concrete median barrier. This crash is of special interest because the case vehicle was equipped with multiple Advanced Occupant Protection System (AOPS) features, including certified advanced 208-compliant air bags, the driver's air bag deployed as a result of the crash, and the case vehicle's restrained driver (32-year-old, female) sustained a police reported "C" (possible) injury. The case vehicle was traveling north in the middle northbound lane of a six-lane divided tollway. A non-contact vehicle was northbound in the inside lane and changed lanes to the right and crossed in front of the case vehicle. The case vehicle's driver braked and steered right to avoid the non-contact vehicle, and the case vehicle traveled to the right across the outside lane. The driver then steered left, the case vehicle entered the outside shoulder, and the right rear wheel and quarter panel sideswiped the longitudinal barrier. The case vehicle then rotated counterclockwise across all three northbound travel lanes, and the front impacted a concrete median barrier causing the case vehicle's driver air bag to deploy. The case vehicle's driver was most likely seated in an upright position with both hands on the steering wheel. Her seat track was located in its rear-most position, the seat back was slightly reclined, and the tilt steering column was adjusted to its full-up position. The case vehicle's driver was restrained by her lap and shoulder safety belt system, and the buckle-mounted pretensioner activated during the crash. The driver refused medical treatment at the scene. It is not known if she subsequently sought medical treatment or lost any work days as a result of the crash.					
17. <i>Key Words</i> Advanced Air Bag Deployment, Pretensioner			Motor Vehicle Traffic Crash Injury Severity		
18. <i>Distribution Statement</i> General Public					
19. <i>Security Classif. (of this report)</i> Unclassified		20. <i>Security Classif. (of this page)</i> Unclassified		21. <i>No. of Pages</i> 9	22. <i>Price</i> \$4,900

TABLE OF CONTENTS

IN-04-034

Page No.

BACKGROUND 1

SUMMARY 1

CRASH CIRCUMSTANCES 1

CASE VEHICLE 3

 CASE VEHICLE DAMAGE 3

 AUTOMATIC RESTRAINT SYSTEM 5

 CASE VEHICLE DRIVER KINEMATICS 6

 CASE VEHICLE DRIVER INJURIES 8

CRASH DIAGRAM 9

SELECTED PHOTOGRAPHS

 Figure 1: Overview of trafficway and case vehicle’s northbound approach to the first impact 1

 Figure 2: Damage to case vehicle’s right quarter panel and right rear wheel from sideswipe impact to concrete longitudinal barrier 2

 Figure 3: Overview of concrete longitudinal barrier sideswiped by case vehicle 2

 Figure 4: Damage to front of case vehicle from impact with concrete median barrier 3

 Figure 5: Overview of concrete median barrier impacted by case vehicle 3

 Figure 6: Direct and induced damage to front of case vehicle 4

 Figure 7: Right side view of crush to front of case vehicle 4

 Figure 8: Case vehicle’s driver air bag 5

 Figure 9: Right side view of case vehicle’s steering wheel and steering column 5

 Figure 10: Case vehicle’s driver air bag vent ports 6

 Figure 11: Case vehicle’s driver air bag module flaps 6

 Figure 12: Overview of right instrument panel and location of front right passenger air bag 6

 Figure 13: Load abrasion on case vehicle driver’s shoulder belt 7

 Figure 14: Compression of case vehicle driver’s seat belt buckle stalk due to activation of pretensioner 7

This on-site investigation was brought to NHTSA's attention on or about October 8, 2004 by NASS CDS/GES sampling activities. This crash involved a 2004 Mazda 3 (case vehicle), which ran-off-road and impacted a concrete longitudinal barrier and a concrete median barrier. The crash occurred in September, 2004, at 10:45 a.m., in Texas and was investigated by the Texas Highway Patrol. This crash is of special interest because the case vehicle was equipped with multiple Advanced Occupant Protection System (AOPS) features, including certified advanced 208 compliant air bags, the driver's air bag deployed as a result of the crash, and the case vehicle's driver [32-year-old, Black (unknown if Hispanic) female] sustained a police-reported "C" (Possible) injury. This contractor inspected the case vehicle on October 8, 2004, and inspected the crash scene on October 12, 2004. This contractor was unable to contact the case vehicle's driver. This summary is based on the police crash report, scene and vehicle inspections, occupant kinematic principles and this contractor's evaluation of the evidence.

SUMMARY

The case vehicle was traveling north in the middle northbound lane of a six-lane divided tollway. A non-contact vehicle was northbound in the inside northbound lane and changed lanes to the right and crossed in front of the case vehicle. The case vehicle's driver braked and steered right to avoid the non-contact vehicle and traveled to the right across the outside lane. The driver then steered left, the case vehicle entered the outside shoulder and the right rear wheel and quarter panel sideswiped a concrete longitudinal barrier. The case vehicle then rotated counterclockwise across all three northbound travel lanes, and the front impacted a concrete median barrier causing the case vehicle's driver air bag to deploy. The case vehicle then spun counterclockwise off the barrier, rotated approximately 390 degrees and came to rest facing southwest with the front of the vehicle in the inside lane and the back of the vehicle in the middle lane. The case vehicle's driver was restrained by her lap and shoulder safety belt system, and the buckle mounted pretensioner activated during the crash. The driver refused medical treatment at the scene.

The CDCs for the case vehicle were determined to be: **12-RZES-1 (0 degrees)** for the initial impact with the concrete longitudinal barrier and **02-FDEW-2 (70-degrees)** for the front impact with the concrete median barrier. The WinSMASH reconstruction program, barrier option, calculated the case vehicle's Total, Longitudinal and Lateral Delta Vs for the highest severity impact (i.e., front impact with the longitudinal barrier) as: 22 km.p.h. (13.7 m.p.h.), -7.5 km.p.h. (-4.7 m.p.h.), -20.7 km.p.h. (12.9 m.p.h.). The collision fit the reconstruction model but the results appeared to be low. The case vehicle was towed due to damage.

CRASH CIRCUMSTANCES

Crash Environment: The trafficway on which the case vehicle was traveling was a straight, six-lane, divided tollway, traversing in a north and south direction (**Figure 1** below). Each travel direction contained three travel lanes, and the trafficway was divided by a concrete median barrier. Each travel lane was approximately 3.7 meters (12 feet) wide. Both outside shoulders were bituminous and approximately 3 meters (10 feet) wide. Both inside shoulders were also bituminous and were approximately 1 meter (3.3 feet) wide. The case vehicle's travel lanes were

traffic polished bituminous with an estimated coefficient of friction of 0.65 and an approximate 3% positive grade. The roadway pavement markings consisted of single broken white lane lines, a yellow median line and white edge line. The case vehicle's approach to the crash location was uncontrolled and the speed limit was 88 km.p.h. (55 m.p.h.). There was no regulatory speed limit sign posted near the crash site. At the time of the crash the light condition was daylight, the atmospheric condition was clear, and the roadway pavement was dry. Traffic density was moderate, the site of the crash was urban, and the crash occurred within an interchange area. See the Crash Diagram at the end of this report.

Pre-Crash: The case vehicle was traveling north in the center lane, and the driver was intending to continue northbound (**Figure 1**). A non-contact vehicle was northbound in the inside lane and changed lanes to the right and crossed in front of the case vehicle. The case vehicle's driver braked and steered right to avoid the non-contact vehicle, and the case vehicle traveled to the right across the outside lane. The driver steered left and the case vehicle entered the outside shoulder heading toward the concrete longitudinal barrier. The initial impact of the crash sequence occurred on the outside shoulder of the roadway.

Crash: As the case vehicle's driver steered to the left, the case vehicle's right rear wheel and quarter panel (**Figure 2**) sideswiped the concrete longitudinal barrier (**Figure 3**). As the case vehicle separated from the barrier, it began to rotate counterclockwise and continued to rotate counterclockwise approximately 95 degrees as it traveled to the left across all three northbound travel lanes. The front of the case vehicle (**Figure 4** below) then impacted the concrete median barrier (**Figure 5** below) causing the case vehicle's driver air bag to deploy. The case vehicle's front right air bag did not deploy because there was no front right occupant in the case vehicle. The occupant weight sensor in the front right seat properly determined the absence of an



Figure 1: Overview of trafficway and approach of case vehicle northbound in middle lane (case photo #01)



Figure 2: Damage to right quarter panel and right rear wheel due to sideswiping the concrete longitudinal barrier (case photo #15)



Figure 3: View to northeast to area of case vehicle's sideswipe impact with the concrete longitudinal barrier (case photo #02)

occupant and suppressed deployment of the front right air bag.

Post-Crash: The case vehicle rotated counterclockwise off the median barrier approximately 390 degrees, traveled approximately 24 meters (78.7 feet) and came to final rest facing southwest with the front of the vehicle in the inside lane and the back of the vehicle in the middle lane.

CASE VEHICLE

The 2004 Mazda 3 was a front wheel drive, four-door sedan (VIN: JM1BK323141-----) equipped with four wheel, anti-lock brakes; dual stage driver and front right passenger air bags, front seat back-mounted side impact air bags, front and rear side curtain air bags, driver seat position sensor; driver and front right passenger, height adjustable, three point lap and shoulder safety belts with belt usage sensors, belt pretensioners, and belt force limiters. The front right seat was also equipped with a weight sensor to detect the presence of an occupant. In addition, the case vehicle was equipped with a LATCH system for securing child safety seats, and a brake pedal that was designed to pivot away from the driver during a severe crash.

The various sensors in the case vehicle's advanced occupant restraint system analyze a combination of factors including the predicted crash severity, the driver's safety belt usage and the seat track position to determine the front air bag inflation level appropriate for the severity of the crash. For the front right seat position, an occupant weight sensor determines first, if an occupant is on the seat and, second, if the weight on the seat is at or below 30 kilograms (66 pounds). If no occupant is seated, or the weight on the seat is at or below 30 kilograms (66 pounds), then the deployment of the air bag is suppressed.

CASE VEHICLE DAMAGE

Exterior Damage: The case vehicle's initial impact with the concrete longitudinal barrier involved the right quarter panel and right rear wheel (**Figure 2** above). A few scratches were also observed on the back portion of the right rear door. Direct damage began 198 centimeters (78 inches) rear of the right front axle and extended 124 centimeters (48.8) inches along the right rear door, sill, quarter panel, right rear wheel and right side of the rear bumper cover. The maximum crush to



Figure 4: Damage to front of case vehicle [each stripe on rods is 5 cm (2 in)] from impact with the median barrier (case photo #08)




Figure 5: View to northwest to case vehicle's front impact location (arrow) on concrete median barrier, note case vehicle's yaw marks (case photo #05)

the right quarter panel was about 1.0 centimeter (0.4 inch) occurring at C₂, and the right rear wheel was bent inward at the bottom. The case vehicle's impact with the concrete median barrier involved the front bumper, right fender, right headlamp/turn lamp assembly, grille and hood. (Figure 6). Direct damage began at the right corner of the front bumper and extended 118 centimeters (46.5 inches) across the front of the case vehicle. Crush measurements were taken at the bumper and maximum crush was measured as 31 centimeters (12.2 inches) occurring at C₂ and C₃ (Figure 7). The table below shows the case vehicle's crush profile.



Figure 6: Overview of damage to front of case vehicle from impact with the concrete median barrier (case photo #10)

Units	Event	Direct Damage		Field L	C ₁	C ₂	C ₃	C ₄	C ₅	C ₆	Direct	Field L
		Width CDC	Max Crush								±D	±D
cm	1	138	22	118	20	31	31	30	27	15	20	0
in		54.3	8.7	46.5	7.9	12.2	12.2	11.8	10.6	5.9	7.9	0.0

The right side wheelbase was extended 1.0 centimeter (0.4 inch). The left side wheelbase was unchanged. Induced damage involved the front bumper, grille, hood, right fender and left fender.




Figure 7: Right side view of crush to front of case vehicle (case photo #16)

The recommended tire size was: P205/55R16; however, the case vehicle was equipped P205/50R17 size tires. The maximum tire pressure for these tires was 303 kpa (44 psi) The case vehicle's tire data are shown in the table below.

Tire	Measured Pressure		Recommend Pressure		Tread Depth		Damage	Restricted	Deflated
	kpa	psi	kpa	psi	milli-meters	32 nd of an inch			
LF	172	25	221	32	6	8	None	No	No
RF	186	27	221	32	6	8	None	No	No

Tire	Measured Pressure		Recommend Pressure		Tread Depth		Damage	Restricted	Deflated
	kpa	psi	kpa	psi	milli-meters	32 nd of an inch			
LR	179	26	221	32	6	8	None	No	No
RR	179	26	221	32	6	8	None	No	No

Vehicle Interior: Inspection of the case vehicle’s interior revealed a possible occupant contact on the left center portion of the air bag (**Figure 8**). The contact appeared to be a stain in the air bag material. It did not appear to be a transfer of lip stick or make-up. No other evidence of occupant contact was noted on the case vehicle’s interior. In addition, there was a heavy abrasion noted on the driver’s shoulder belt, and her buckle-mounted pretensioner had activated. No occupant compartment intrusions were observed, and there was no compression of the energy absorbing steering column or deformation of the steering wheel rim (**Figure 9**).



Figure 8: Case vehicle’s driver air bag, arrow shows stain in the air bag material (case photo #25)

Damage Classification: Based on the vehicle inspection, the CDCs for the case vehicle were determined to be: **12-RZES-1 (0 degrees)** for the initial impact with the concrete longitudinal barrier and **02-FDEW-2 (70-degrees)** for the front impact with the concrete median barrier.



Figure 9: Overview of steering wheel and steering column showing lack of deformation (case photo #38)

The WinSMASH reconstruction program, barrier option, was used to reconstruct the Delta V for the case vehicle’s front impact. The Total, Longitudinal and Lateral Delta Vs are, respectively: 22 km.p.h. (13.7 m.p.h.), -7.5 km.p.h. (-4.7 m.p.h.), -20.7 km.p.h. (12.9 m.p.h.). The collision fits the reconstruction model but the results appear to be low. The case vehicle was towed due to damage.

AUTOMATIC RESTRAINT SYSTEM

The case vehicle was equipped with a certified advanced 208-compliant air bag system including dual stage frontal air bags at the driver and front right passenger positions, front seat back-mounted side impact air bags and front and rear side curtain air bags. The driver’s air bag

deployed as a result of the case vehicle's front impact with the concrete median barrier. The case vehicle's other air bags did not deploy because there was no front right passenger in the vehicle, and the vehicle did not sustain a side impact severe enough to require deployment of the side air bags.

The case vehicle's driver air bag was located in the steering wheel hub. An inspection of the air bag module cover flaps and the air bag fabric revealed that the cover flaps opened at the designated tear points. There was no evidence of damage during the deployment to the air bag module cover flaps or the air bag. The deployed driver's air bag (**Figure 8** above) was round with a diameter of approximately 58 centimeters (22.8 inches). The air bag was designed without tethers and had two vent ports (**Figure 10**), each approximately 4 centimeters (1.6 inches) in diameter, located at the 11 and 1 o'clock positions. There were two air bag module cover flaps (**Figure 11**). The top portion of the top flap was rectangular in shape with a semi-circular center portion that mated with the semi-circular center portion of the bottom flap. The top flap was 11 centimeters (4.3 inches) in width at the top, and the bottom flap was 8.5 centimeters (3.3 inches) in width at the bottom. The distance between the mid-center of the driver's seat back and the front surface of the air bag's fabric at full excursion was 20 centimeters (7.9 inches).

The front right passenger air bag was located in the middle of the instrument panel (**Figure 12**). The deployment of the front right air bag was properly suppressed by the case vehicle's advanced occupant protection system because there was no front right occupant in the case vehicle at the time of the crash.

CASE VEHICLE DRIVER KINEMATICS

Immediately prior to the crash, the case vehicle's driver [32-year-old, Black (unknown if Hispanic) female; unknown height and weight] was most likely seated in an upright posture with



Figure 10: Case vehicle's driver air bag vent ports (case photo # 27)



Figure 11: Overview of air bag module flaps (case photo # 22)



Figure 12: Front right air bag located in top of instrument panel above glove box door (case photo #35)

both hands on the steering wheel. Her right foot was likely off the accelerator, but it is not known if she applied the brakes just prior to the impact. The driver's seat track was located in its rear-most position, the seat back was slightly reclined, the tilt steering column was adjusted to its full up position and her head restraint was adjusted to its full up position. Finally, the driver's shoulder belt anchor was adjusted to its full up position.

The evidence observed during the vehicle inspection indicates the case vehicle's driver was using her active, three-point, lap-and-shoulder safety belt system. Inspection of the safety belt assembly revealed a heavy abrasion on the shoulder belt (**Figure 13** above) due to loading on the D-ring during the crash. In addition, the buckle-mounted pretensioner had activated during the crash. The safety belt buckle stalk was observed to be compressed (**Figure 14**), and the pretensioner piston was flush with the end of the cylinder, a movement of approximately 8 centimeters (3.1 inches).

The driver initially braked and steered to the right to avoid the non-contact vehicle. The evidence indicates the driver then steered to the left to avoid the impact with the concrete longitudinal barrier on the right side of the roadway. The case vehicle's sideswipe impact with the longitudinal barrier most likely caused the driver to move forward and to the right along a path opposite the case vehicle's 10 degree direction of principal force, and locked her seat belt retractor. The driver then moved to the right in her seat as the case vehicle rotated counterclockwise and traveled across the roadway. The driver's seat belt retractor would have remained locked during this rotation. The case vehicle's impact with the concrete median barrier deployed the driver's air bag and her buckle mounted pretensioner, and caused the driver to move forward and to the right along a path opposite the case vehicle's 70 degree direction of principal force and load her safety belt. The driver's face and chest most likely contacted her deployed air bag. The driver remained in her seat, and her safety belt remained locked as the vehicle rotated counterclockwise off the median barrier and came to final rest. The driver's upper body most likely moved to the right and left during the post-impact rotation. It is likely the driver was able to exit the case vehicle without assistance.



Figure 13: Load mark on driver's shoulder belt (case photo #30)



Figure 14: Compression of driver's seat belt buckle stalk due to activation of the seat belt pretensioner (case photo # 31)

The police crash report indicated the driver sustained a “C” (possible) injury as a result of the crash and refused treatment at the scene. It is not known if the driver subsequently sought medical treatment or lost any work days as a result of the crash.

