



INDIANA UNIVERSITY

TRANSPORTATION RESEARCH CENTER

School of Public and Environmental Affairs

222 West Second Street

Bloomington, Indiana 47403-1501

(812) 855-3908 Fax: (812) 855-3537

ON-SITE NOT IN TRAFFIC SURVEILLANCE BACK OVER INVESTIGATION

CASE NUMBER - IN-07-018

LOCATION - MISSOURI

VEHICLE - 2006 HONDA CR-V SE

INCIDENT DATE - April 2007

Submitted:

November 29, 2007

Revised February 5, 2008



Contract Number: DTNH22-07-C-00044

Prepared for:

U.S. Department of Transportation
National Highway Traffic Safety Administration
National Center for Statistics and Analysis
Washington, D.C. 20590-0003

DISCLAIMERS

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points be coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the pre-crash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

Technical Report Documentation Page

1. <i>Report No.</i> IN-07-018		2. <i>Government Accession No.</i>		3. <i>Recipient's Catalog No.</i>	
4. <i>Title and Subtitle</i> On-Site Not In Traffic Surveillance Back Over Investigation Vehicle - 2006 Honda CR-V SE Location - Missouri			5. <i>Report Date:</i> November 29, 2007		
			6. <i>Performing Organization Code</i>		
7. <i>Author(s)</i> Special Crash Investigations Team #2			8. <i>Performing Organization Report No.</i>		
9. <i>Performing Organization Name and Address</i> Transportation Research Center Indiana University 222 West Second Street Bloomington, Indiana 47403-1501			10. <i>Work Unit No. (TRAIS)</i>		
			11. <i>Contract or Grant No.</i> DTNH22-07-C-00044		
12. <i>Sponsoring Agency Name and Address</i> U.S. Department of Transportation (NPO-122) National Highway Traffic Safety Administration National Center for Statistics and Analysis Washington, D.C. 20590-0003			13. <i>Type of Report and Period Covered</i> Technical Report Incident Date: April 2007		
			14. <i>Sponsoring Agency Code</i>		
15. <i>Supplementary Notes</i> On-site not in traffic surveillance back over investigation involving a 2006 Honda CR-V SE and a pedestrian.					
16. <i>Abstract</i> This report covers an on-site not in traffic surveillance back over investigation involving a 2006 Honda CR-V SE and a pedestrian. This incident is of special interest because the Honda's driver backed over a pedestrian [her 15-month-old son], who sustained critical injuries, resulting in his death. The Honda CR-V was parked in a narrow, one car garage attached to the driver's residence. The driver, her husband, their 3-year-old son and the pedestrian were all gathered in the middle part of the driveway preparing to leave. The Honda's driver returned to the inside of the house then into the garage to back the Honda out into the driveway to pick up the rest of the family. She thought both of her children were going with her husband to his vehicle while he moved it out of the way. The husband and their 3-year-old son went to the husband's vehicle; however, the pedestrian stayed behind in the driveway. It could not be determined how he became separated from his parents. While the husband was backing his vehicle down the driveway, the Honda's driver began to back out of the garage. Meanwhile the husband noticed the pedestrian in the driveway behind the backing Honda, and he began to honk his horn and yell at the Honda's driver. The left portion of the Honda's back bumper then impacted the pedestrian and knocked him down. The pedestrian got back to his feet as the Honda's driver paused momentarily as she backed out of the narrow garage. The pedestrian was struck by the back bumper again and knocked down a second time. The Honda's driver continued backing up and the left rear tire ran over the pedestrian. The driver, who stated she heard yelling, then stopped the Honda and hurriedly got out. She immediately tried to come to the aid of the pedestrian, who was now between the Honda's left front and left rear wheels. However, upon exiting, she did not shift the Honda's transmission into "Park." The Honda continued to roll backward and the left front tire rolled over the pedestrian. The Honda rolled down the driveway, missed the husband's vehicle, and came to rest in a clump of bushes in a yard across the street. The pedestrian was transported by ambulance to a hospital and was pronounced dead. The driver stated in her interview that before backing the Honda out of the garage, she looked through the rearview mirror and continued to view through this mirror while backing. The visibility study showed that the pedestrian, who was standing approximately 3.9 meters (~13 feet) behind the Honda, was within the Honda's rearview mirror blind zone and not visible to the driver. The Honda was not equipped with a backup/parking aid.					
17. <i>Key Words</i> Back Over Child Fatality			Motor Vehicle Traffic Crash Injury Severity		18. <i>Distribution Statement</i> General Public
19. <i>Security Classif. (of this report)</i> Unclassified		20. <i>Security Classif. (of this page)</i> Unclassified		21. <i>No. of Pages</i> 18	22. <i>Price</i> \$7,400

TABLE OF CONTENTS

IN-07-018

Page No.

BACKGROUND 1

SUMMARY 1

CRASH CIRCUMSTANCES 2

CASE VEHICLE: 2006 HONDA CR-V SE 4

 CASE VEHICLE DAMAGE 4

 CASE VEHICLE DRIVER 4

CASE VEHICLE VISIBILITY STUDY 5

PEDESTRIAN 7

NOMINAL VISIBILITY DIAGRAM 8

SCENE DIAGRAM 9

ATTACHMENTS: NOT IN TRAFFIC SURVEILLANCE BACK OVER DATA FORMS

This incident was brought to NHTSA's attention on or before April 27, 2007 by an on-line article from a Missouri newspaper. This incident involved a 2006 Honda CR-V SE and a pedestrian. The incident occurred in April, 2007 at 8:26 a.m., in Missouri and was investigated by the applicable city police department. The police completed a "Missouri Uniform Accident Report" and submitted a copy of the report to the state. This incident is of special interest because the Honda's driver backed over a pedestrian [15-month-old male], who sustained critical injuries, resulting in his death. This contractor inspected the scene and an exemplar 2006 Honda CR-V on June 21, 2007. This contractor also interviewed the Honda's driver and a witness (i.e., driver's husband) to the incident on June 21, 2007. Additional questions arose during the writing of the Preliminary Case Summary and this report; however, attempts to contact the witness and obtain additional information were unsuccessful. This report is based on the police crash report, interviews with the Honda's driver and witness, scene and exemplar vehicle inspections, and this contractor's evaluation of the evidence.

SUMMARY

The Honda CR-V was parked in a narrow, one car garage attached to the driver's residence. The garage door was open. The driver's husband's vehicle was parked in the driveway. The driver, her husband, their 3-year-old son and the pedestrian (their 15-month-old son), were all gathered in the middle part of the driveway preparing to leave. The husband was going to move his vehicle out of the driveway so they all could leave in the Honda. The Honda's driver returned to the inside of the house and then into the garage to back the Honda out into the driveway to pick up the rest of the family. She thought both of her children were going with her husband to his vehicle while he moved it out of the way. The husband and their 3-year-old son went to the husband's vehicle; however, the pedestrian stayed behind in the driveway. It could not be determined how he became separated from his parents. While the husband was backing his vehicle down the driveway, the Honda's driver began to back out of the garage. Meanwhile the husband noticed the pedestrian in the driveway behind the backing Honda, and he began to honk his horn and yell at the Honda's driver. The left portion of the Honda's back bumper then impacted the pedestrian and knocked him down. The pedestrian got back to his feet as the Honda's driver paused momentarily as she backed out of the narrow garage. The pedestrian was struck by the back bumper again and knocked down a second time. The Honda's driver continued backing up and the left rear tire ran over the pedestrian. The driver, who stated she heard yelling, then stopped the Honda and hurriedly got out. She immediately tried to come to the aid of the pedestrian, who was now between the Honda's left front and left rear wheels. However, upon exiting, she did not shift the Honda's transmission into "Park." The Honda continued to roll backward and the left front tire rolled over the pedestrian. The Honda continued rolling down the driveway veering off the north side of the driveway, narrowly missing the husband's vehicle, and into the street coming to rest in a clump of bushes in a yard across the street. The pedestrian was transported by ambulance to a hospital and was pronounced dead. The driver stated in her interview that before backing the Honda out of the garage, she looked through the rearview mirror and continued to view through this mirror while backing. The visibility study showed that the pedestrian, who was standing approximately 3.9 meters (~13 feet) behind the Honda, was within the Honda's rearview mirror blind zone and not visible to the driver.

Crash Environment: The Honda CR-V was initially parked in a narrow, one car garage that was attached to the driver's residence. The garage was located at the top of a one lane driveway that traversed in an east-west direction (**Figures 1 and 2**). The driveway was 3 meters (9.8 feet) in width. The grade of the driveway was 5.8% negative in the direction the Honda was backing. The incident occurred in the driveway near the garage as the driver backed up. At the time of the incident, the light condition was daylight, the atmospheric condition was clear, the driveway pavement was dry bituminous, and the site of the incident was residential. See the Scene Diagram at end of this report



Figure 1: Overview of scene; arrow shows location of witness vehicle at time of impact



Figure 2: Overview of garage; arrow shows area of impact and final rest of pedestrian

Pre-Crash: The driver and her family (i.e., husband, 3-year-old son and the pedestrian) were about to depart their residence, and they all had gathered at the middle part of the driveway. The husband's vehicle was parked in the driveway approximately midway between the garage and the street. The Honda was parked in the garage with the garage door open. The husband was going to move his vehicle out of the driveway so they all could leave in the Honda. The Honda's driver returned to the inside of the house and then into the garage to back the Honda out into the driveway to pick up the rest of the family. She thought both of her children were going with her husband to his vehicle. The husband and their 3-year-old son went to the husband's vehicle; however, the pedestrian stayed behind in the driveway. The pedestrian's movements and how he got separated from both parents could not be determined, but he was standing in the driveway behind the Honda when first observed by his father as the father was backing his vehicle. Meanwhile, the Honda's driver entered the garage from inside the house, approached the Honda from the left, entered the vehicle and started the engine. According to the Honda's driver, she was unsure if she checked her side view mirrors; however, she is sure she looked in the rearview mirror as she backed up. She estimated that the time between entering the vehicle and the beginning of the backing maneuver was less than 10 seconds. Meanwhile, the driver's husband and their 3-year-old son were in his car, which he had just backed from the middle area of the driveway to near the bottom of the driveway (**Figure 1**), approximately 18 meters (~59 feet) to the east. He was facing the garage, had just noticed the pedestrian standing in the driveway

approximately 3.9 meters (~ 13 feet) behind the Honda, and had a clear view of the unfolding events.

Crash: According to the husband, as the Honda began to back out of the garage, he began honking his horn and yelling at the Honda's driver, who did not see the pedestrian. The Honda's driver continued to back up and the left portion of the back bumper (**Figure 3**) struck and knocked down the pedestrian (**Figure 4**), whose back was toward the Honda. The driver paused momentarily as she backed out of the narrow garage, then continued to back up. According to the husband, the pedestrian got back up on his feet, but was immediately struck again by the back bumper and rolled over by the back left tire. At this point, the Honda's driver, who stated she heard yelling, hurriedly got out of the Honda. She immediately tried to come to the aid of the pedestrian, who was now between the left front and left rear wheels. However, upon exiting, she did not shift the Honda's transmission into "Park." The Honda continued to roll backward and the left front tire rolled over the pedestrian. It seemed unlikely that the pedestrian could be struck by the Honda's back bumper and get to his feet before being struck again. However, during the interview, the driver said she had to back out of the garage slowly because it was narrow, and she had to be careful in order to avoid breaking off either of the side view mirrors. Based on her description, the driver was most likely on and off the brake, inching out of the garage very deliberately. This may explain how the pedestrian was able to regain his footing after being struck by the back bumper the first time. The driver stated she felt a "bump" as she was backing and thought the time between the start of the backing maneuver and impact was in a range of approximately 2-5 seconds. However, based on the driver's description of how she backed and the distance to impact, this estimate appeared to be too fast. Based on the driver's description of how she backed out of the garage, this contractor estimated the speed of the Honda at the initial impact at approximately 2 km.p.h. (~ 1 mph).

Post-Crash: The Honda continued rolling down the driveway and veered off the north side of the driveway (**Figure 4**), narrowly missing the husband's vehicle. The Honda continued into the street and came to rest in a clump of bushes in a yard across the street. The Honda traveled approximately 38 meters (~ 125 feet) from impact to its final rest position. At final rest, the



Figure 3: Back bumper and undercarriage of exemplar 2006 Honda CR-V; scale in tenths of meter




Figure 4: Honda backed straight out of garage to area of impact indicated by white arrow. Long arrow shows direction Honda rolled away after driver exited vehicle.

pedestrian was laying face down near the point of impact (**Figure 4** above). The pedestrian was transported by ambulance to a hospital and was pronounced dead.

CASE VEHICLE

The 2006 Honda CR-V SE (exemplar vehicle depicted in **Figures 5** and **6**) was an all wheel drive, four-door, sport utility vehicle (VIN JHLRD78976C-----) The Honda was not equipped with any after-market equipment and was not equipped with a backup/parking aid. Based on interview data, all the side windows were closed at the time of the incident. The Honda's specified wheelbase was 262 centimeters (103 inches). The specified rear overhang was 94 centimeters (37 inches) and the specified overall length was 460 centimeters (181 inches). The subject Honda CR-V had been sold by the owners. An exemplar 2006 Honda CR-V was obtained by the police detective who was assisting this contractor. The distance from the ground to bottom of the back bumper on the exemplar Honda was measured as 41 centimeters (16.1 inches). The distance from the ground to the bottom of the backlight was measured as 123 centimeters (48.4 inches). The distance from the ground to the beltline was measured as 113 centimeters (44.5 inches).

CASE VEHICLE DAMAGE

According to police, there was no evidence of damage or contact to the Honda's back bumper. Based on the available information, the left portion of Honda's back bumper impacted the pedestrian twice, and the left rear and left front tire passed completely over the pedestrian. The Honda was not towed from the scene.

CASE VEHICLE DRIVER

The Honda's driver was a 38-year-old, White (non-Hispanic) female. She was 163 centimeters (64 inches) tall and weighed 50 kilograms (110 pounds). The driver was wearing contact lenses at the time of the incident. She was not wearing sunglasses. The police crash report indicated that the driver was not under the influence of alcohol or drugs. The driver indicated she drove the Honda daily.



Figure 5: Overview of exemplar 2006 Honda CR-V



Figure 6: Overview of back of exemplar Honda; scale in tenths of meter

A visibility study was conducted using an exemplar 2006 Honda CR-V in order to determine the nominal blind zone behind the Honda as well as the right “D”pillar blind zone. In addition, the blind zones of the rearview mirror and both side view mirrors were assessed. An exemplar 2006 Honda CR-V identical to the subject vehicle was obtained for this study by the assisting police detective. The police detective also served as the surrogate driver for this study. The Honda’s driver did not participate. A surrogate of similar height to the Honda’s driver was not available. However, she allowed the SCI investigator to make a measurement from her hip to her eye level as she was in a seated position. The distance from her mid-hip to her eye level was 65 centimeters (25.6 inches). The surrogate driver’s hip to eye level measurement was 70 centimeters (27.6 inches). The distance from the ground to the surrogate driver’s eye level as he sat in the driver’s seat of the exemplar Honda was 143 centimeters (56.3 inches). Based on these measurements, the Honda driver’s eye height above the ground for the exemplar Honda was estimated to be approximately 138 centimeters (~54 inches). The visibility study was conducted in a level parking lot. Lastly, the standard 71 centimeters (28 inches) high target was used for the study. Please refer to the Nominal Visibility Diagram at the end of this report when reading the following discussion.

For the assessment of the blind zone behind the Honda, the target was positioned behind the Honda and moved rearward until it came into the surrogate driver’s view as he looked over his right shoulder out of the backlight. It was necessary to move the target rearward from the back of the Honda 4.6 meters (15.1 feet) before the surrogate driver could see it (**Figure 7**). At this point, if the target was moved 0.5 meters (1.6 feet) to the right of the approximate centerline, it became obstructed by a raised contour at the bottom of the backlight (**Figure 8** below). Therefore, the target was moved rearward an additional 90 centimeters (35 inches) where it could be seen over the raised contour. When the target was moved right 1.2 meters (3.9 feet) from the centerline, it became obstructed by the spare tire (**Figure 8** below), which was mounted to the tailgate exterior. It would have been necessary to move the target a additional short distance rearward to be seen over the top of the spare tire; however, this measurement was not taken. The target became visible on the right side of the spare tire when it was moved 2.1 meters (6.9 feet) to the right of the centerline. When moved 2.9 meters (9.5 feet) to the right of the centerline, the target became obstructed by the right “D”-pillar. The target became visible again through the right rear-most window when it was moved right an additional 1.4 meters (4.6 feet). When the target was moved 90 centimeters (35 inches) to the left from the Honda’s centerline, it became obstructed by the left “D”-pillar. The surrogate driver could not turn his head far enough to the right to see past the left “D”-pillar.



The surrogate driver was then asked to view behind the Honda through the rearview mirror (Figure 9). The target was not visible to the surrogate driver until it was moved rearward 6.7 meters (22 feet) from the back of the Honda (Figure 10). The target was moved to the right 1 meter (3.3 feet) from the centerline and was obstructed by the very top of the spare tire. As the target was moved further to the right, it became visible again at 1.7 meters (5.6 feet) from the centerline. At 2.5 meters (8.2 feet) to the right of the centerline, the target was obstructed by the right “D”-pillar. The target became visible again when moved right an additional 0.9 meter (3 feet), but was near the edge of the mirror. When moved left from the centerline 1.3 meters (4.3 feet), the target was obstructed by the left “D”-pillar as well as the driver’s face in the rearview mirror and could not be seen if moved further left.

The target was then placed at the left rear corner of the Honda and had to be moved rearward 0.7 meter (2.3 feet) before the surrogate driver could see it in the left side view mirror. The target was then moved to the left 0.8 meters (2.6 feet) where it went out of the left side view mirror’s field of view. The target was then placed at the right rear corner of the Honda and had to be moved rearward 0.9 meter (3 feet) before the surrogate driver could see it in the right side view mirror. The target was then moved to the right 0.9 meters (3 feet) where it went out of the right side view mirror’s field of view.

The driver stated in her interview that before backing the Honda out of the garage, she looked through the rearview mirror and continued to view through this mirror while backing. The visibility study showed that the pedestrian, who was standing approximately 3.9 meters (~13 feet) behind the Honda, was within the Honda’s rearview mirror blind zone and not visible to the driver.



Figure 8: View out of backlight of exemplar Honda from driver’s seat; arrow shows raised contour at base of backlight and top of spare tire.



Figure 9: View through rear view mirror of exemplar Honda.






Figure 10: Arrow shows location target first came into view as surrogate driver looked through rear view mirror of exemplar Honda

The pedestrian [15-month-old, White (non-Hispanic) male; 84 centimeters and 10 kilograms (33 inches, 22 pounds)] was reportedly wearing striped denim overall shorts and white sneakers. The color of the shirt he was wearing is not known. He was transported from the scene by ambulance to a hospital and pronounced dead a short time thereafter. There was no information on the police crash report regarding the cause of death or injuries sustained by the pedestrian. Due to the emotional state of the driver and her husband, this information was not sought during the interview.







1. Case Number

IDENTIFICATION

2. Date of Crash ____ / ____ / ____

3. Time of Crash _____

Code reported military time of crash.

NOTE: Midnight = 2400
Unknown = 9999

AMBIENT CONDITIONS

4. Light Conditions

- Daylight
- Dark
- Dark but lighted
- Dawn
- Dusk
- Unknown

5. Atmospheric Conditions
(Select all that apply)

- Clear-No adverse conditions
- Cloudy
- Rain
- Snow
- Fog, Smog, Smoke
- Sleet, Hail (freezing rain or drizzle)
- Blowing Snow
- Severe Crosswinds
- Blowing Sand, Soil, Dirt
- Other (specify):
- Unknown

6. Temperature

- Below 0 degrees Celsius (Below 32 F)
- 1-10 degrees Celsius (33-50 F)
- >10-24 degrees Celsius (51-75 F)
- Over 24 degrees Celsius (Over 75 F)
- Unknown

SCENE INFORMATION

7. Type of area in which crash occurred
(Select all that apply)

- Single family residential
- Row houses/townhouses
- Multi family housing
- Commercial
- Industrial
- Rural
- Unknown

8. Driver exterior sightline obstructions
(Select all that apply)

- None
- Other vehicles
- Building
- Trees
- Shrubby
- Other (specify) _____
- Utility poles
- Signs
- Glare
- Unknown
- No driver present

9. Crash location

- Driveway
- Parking Lot
- Sidewalk
- Alley
- Intersection of driveway and sidewalk
- Road / street
- Roadside / shoulder
- Other (specify) _____
- Unknown

10. Non motorist sightline obstructions
(Select all that apply)

- None
- Other vehicles
- Building
- Trees
- Shrubby
- Utility poles
- Signs
- Glare
- Other (specify) _____
- Unknown

11. Grade at parked position _____ + / - %

12. Estimated distance from parked position to impact

_____ m

13. Estimated speed at impact _____ kmph

+/-

14. Grade at impact _____ %

15. Estimated distance from impact to vehicle final rest

_____ m

Unknown = 999 Reference Items 11,12, 13, 14, 15



1. Case Number _____

VEHICLE IDENTIFICATION

2. VIN _____

3. Model Year _____

4. Vehicle Make (specify): _____

5. Vehicle Model (specify): _____

GLAZING

Location	Presence (check)	Status (select)	Clarity (select)	Tint (check)	Glazing Obstructions (specify if present)
Windshield		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		
LF		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		
RF		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		
2 nd Left		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		
2 nd Right		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		
3 rd Left		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		
3 rd Right		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		
Backlight		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		
Left Backlight		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		
Right Backlight		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		
Roof		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		
Other (specify)		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		

TIRE DATA

6. Vehicle Manufacturer Recommended Tire Size _____

7. LF Tire Size _____

9. RF Tire Size _____

8. LR Tire Size _____

10. RR Tire Size _____

Seats / Head Restraint Data

Seat Position	Seat Type (Select from below)	Head Restraint (Check if available)	Head Restraint Adjustment (select)	NOTES:
Front Left			Full Down / Mid / Full Up	
Front Middle			Full Down / Mid / Full Up	
Front Right			Full Down / Mid / Full Up	
2 nd Left			Full Down / Mid / Full Up	
2 nd Middle			Full Down / Mid / Full Up	
2 nd Right			Full Down / Mid / Full Up	
3 rd Left			Full Down / Mid / Full Up	
3 rd Middle			Full Down / Mid / Full Up	
3 rd Right			Full Down / Mid / Full Up	

Seat Type codes:

- | | |
|---|--------------------------------------|
| 0 = No seat or seat folded down | 8 = Pedestal (i.e. column supported) |
| 1 = Bucket | 9 = Box mounted (i.e. van type) |
| 2 = Bucket w/ folding back | 10= Other seat type (specify) |
| 3 = Bench | 99= Unknown seat type |
| 4 = Bench with folding back cushions | |
| 5 = Bench w/ folding back | |
| 6 = Split bench w/ separate back cushions | |
| 7 = Split bench w/ separate folding back | |

VEHICLE MEASUREMENTS

Clearance Heights	Measurements (all from ground, and in centimeters)	NOTES
Beltline		
Top of trunk/tailgate		
Bottom of bumper		
Trailer hitch (if applicable)		
Undercarriage		
Sway bar		
Axle		
Differential		
Other (specify):		
Sensor Height (if equipped)		
Camera Height (if equipped)		



1. Case Number

PARKING AID PRESENCE

2. Type of backing/parking aid present

- OEM camera
- OEM ultrasonic/radar sensor
- OEM combination camera-ultrasonic/radar sensor
- OEM Fresnel lens
- OEM interior mirrors
- Aftermarket camera
- Aftermarket ultrasonic/radar sensor
- Aftermarket combination camera-ultrasonic radar sensor
- Aftermarket Fresnel lens
- Aftermarket interior mirrors
- Other (specify): _____

CAMERA INFORMATION

Specify field of view measurements on diagram

3. System make/model

4. Video monitor type

- None present
- LCD (color)
- CRT (black & white)
- Unknown

5. Video display size _____ cm
(Diagonal)

6. Camera location

- None present
- Bumper
- License plate
- Tailgate/Hatch/Trunk
- Other (specify): _____

7. Video image quality under scene lighting conditions

- None present
- Good
- Average
- Poor (specify): _____
- Unknown

8. Was the camera functioning properly

- None present
- Yes
- No, poor image quality due to glare
- No, poor image quality due to atmospheric conditions
- No, camera turned off
- No, camera inoperable
- Unknown

ULTRASONIC/RADAR SENSOR

Specify object detection range on diagram

9. System make/model

10. Auditory warning illumination

- No sensor present
- Yes
- No
- Unknown

11. Number of sensors _____

12. Sensor locations
(Select all that apply)

- No sensor present
- Left bumper
- Center bumper
- Right bumper
- License plate area
- Tailgate/Hatch/Trunk

13. Was warning system functioning properly

- No sensor present
- Yes, system alerted driver
- No, system did not alert driver
- No, system turned off
- No, system inoperable
- Unknown

14. Did driver react to warning

- No sensor present
- Yes
- No
- Unknown

15. Did driver report common false warnings

- No sensor present
- Yes
- No
- Unknown



DRIVER FORM

1. Case Number

DRIVER PROFILE

2. Driver's Age _____
99 = Unknown

3. Driver's Sex Male
 Female
 Unknown

4. Driver's Height _____ cm
999 = Unknown

5. Driver's Weight _____ kg
999 = Unknown

6. Driver eyewear worn
(Select all that apply)
 None
 Eyeglasses
 Sunglasses
 Contacts
 Unknown

7. Driver vision deficiency condition
(Select all that apply)
 None
 Near sighted
 Far sighted
 Astigmatism
 Other (specify): _____
 Unknown

8. Non motorist's relationship to driver
 No relationship
 Child
 Grandchild
 Sibling
 Neighbor
 Friend
 Other (specify): _____
 Unknown

DRIVER ACTIONS

9. Driver approach to vehicle for entry
From left front
 From left
 From left rear
 From right rear
 From right front
 Circled vehicle
 Return trip (backing into driveway/lot)
 Other (specify): _____
 N/A
 Unknown

10. Driver entry interruption
(Select all that apply)
 Direct trip from building to vehicle
 Loaded items into vehicle
 Spoke with family
 Spoke with neighbors
 Spoke with contacted nonmotorist
 Return trip (backing into driveway/lot)
 Other (specify): _____
 N/A
Unknown

11. Purpose of backing
 Leaving parking space in parking lot
 Backing onto roadway from driveway
 Entering parking space in parking lot
 Backing into driveway from roadway
 Other (specify): _____
 N/A
Unknown

12. Where was driver going
Description:

13. Driver in a hurry
 Yes N/A
 No Unknown
 Unknown

14. How did driver check behind (rear area of vehicle)
after vehicle entry
(Select all that apply)
 Did not look
 Checked mirrors
 Turned right and looked back
 Turned left and looked back
 Viewed Camera
 Listened for auditory/visual warning from system
 Other (specify): _____
N/A Unknown

15. Estimated time between vehicle entry and start
of backing
 0-10 Seconds Over 60 Seconds
 11-30 Seconds N/A
 31-60 Seconds Unknown

16. What direction was the driver looking during backing maneuver
(*Select all that apply*)
- Straight ahead
 - Right
 - Left
 - Rearward
 - At object inside the car
 - At mirrors
 - Other (specify): _____
 - N/A
 - Unknown
17. Was the driver distracted during back up maneuver
(*Select all that apply*)
- No non-driving activities
 - External**
 - Looking at other vehicles
 - Looking at other non motorist
 - Looking at intended turn destination
 - External focus, not specified
 - Other external focus (specify): _____
 - Internal**
 - Looking at other occupant
 - Talking to passenger
 - Dialing phone
 - Talking on phone
 - Listening to radio/cd/portable playback device
 - Adjusting radio/cd player
 - Adjusting climate controls
 - Using a device/controls integral to vehicle (specify): _____
 - Reading/adjusting navigation system
 - Eating or drinking
 - Smoking related
 - Retrieving fallen object (specify): _____
 - Internal focus, not specified
 - Focused on other internal object (specify): _____
 - N/A
 - Unknown
18. Driver avoidance actions prior to impact
(*Select all that apply*)
- None
 - Braking
 - Steering left
 - Steering right
 - Accelerating
 - Other (specify): _____
 - N/A
 - Unknown
19. Did driver see struck non motorist prior to impact
(*Select all that apply*)
- No, never saw non motorist
 - Saw non motorist prior to entering vehicle
 - Saw non motorist after entering vehicle
 - Other (specify): _____
 - N/A
 - Unknown
20. Est time between start of backing and impact
- <2 or = 1 second
 - 2-5 seconds
 - 6-10 seconds
 - > 10 seconds
 - N/A
 - Unknown
21. Driver interior sightline obstructions
(*Select all that apply*)
- Pillar
 - Headrest
 - Cargo
 - Other occupant
 - Other (specify) _____
 - Unknown
 - None
22. Recent experience driving this vehicle
- More than 10 times the last three months
 - 6-10 times the last three months
 - 2-5 times the last three months
 - Less than 2 times the last three months
 - First time driving this vehicle
 - N/A
 - Unknown
23. Frequency of driving in this parking lot/driveway
- Daily
 - Weekly
 - Several times a month
 - Monthly
 - Rarely
 - First time in lot/driveway
 - N/A
 - Unknown
24. Driver Impairment
(*Select all that apply*)
- No drugs or alcohol present
 - Alcohol present (specify BAC): _____
 - Drugs present (specify): _____
 - Unknown
25. Source of alcohol/drug results
- Police reported
 - Medical record
 - Other (specify) _____
 - Not Tested
 - Unknown if tested



Non Motorist Form

1. Case Number

NON-MOTORIST PROFILE

2. Non-motorist's Age _____ Months
_____ Years
99 = Unknown

3. Non-motorist's Sex
 Male
 Female
 Unknown

4. Non-motorist's Height _____ cm
999 = Unknown

5. Non-motorist's Weight _____ kg
999 = Unknown

6. Medical outcome
 Not injured
 ER only
 Hospitalized 1-4 days
 Hospitalized 5 days or more
 Treatment later
 Fatal
 Unknown

7. Source of most severe injury
 Bumper
 Tire
 Undercarriage
 Other Specify: _____
 Ground
 N/A
 Unknown

8. Non-motorist impairment
(Select all that apply)
 No drugs or alcohol present
 Positive for alcohol (specify BAC): _____
 Positive for drugs (specify): _____
 Unknown

9. Source of alcohol/drug results
 Police reported
 Medical Report
 Other (specify) _____
 Not Tested
 Unknown if tested

NON-MOTORIST ACTIONS

10. Non-motorist attitude
 Standing
 Bending at waist
 Sitting
 Crouching
 Kneeling
 On skates/skateboard
 On bike/scooter
 Other (specify) _____
 Unknown

11. Non-motorist motion
 Not moving
 Walking slowly
 Walking rapidly
 Running or jogging
 Skipping/Hopping/Jumping
 Falling/Stumbling/Rising
 On skates/skateboard
 On bike/scooter
 Other (specify): _____
 Unknown

12. Non-motorist approach relative to rear of vehicle
 Stationary
 From left
 From right
 From behind
 Other (specify): _____
 Unknown

13. Non-motorist first avoidance action
 No avoidance actions
 Stopped
 Accelerated pace
 Ran away (along vehicle path)
 Jumped
 Turned away from vehicle
 Turned toward vehicle and braced
 Dove or fell away from vehicle
 Other (specify): _____
 Unknown

14. Non-motorist primary focus of attention
 Striking vehicle
 Play object
 Person
 Surrounding traffic
 Animal
 Handheld electronic (phone, MP3 player, etc.)
 Other Object (specify) _____
 Unknown

15. Were any other Non-motorists present?
(Select all that apply)
 Alone
 One adult present
 One other child present
 Multiple adults present
 Multiple children present
 Unknown

NON MOTORIST CLOTHING

NOTES:

- Specify Color, Fabric and Texture/Weight for outermost layer only
- Indicate "NONE" if applicable
- Available codes:

	<u>Colors</u>		<u>Fabrics</u>		<u>Textures</u>		<u>Weights</u>
Black	Charcoal gray		Natural		Soft		Heavy
Lt gray/silver	Brown		Synthetic		Slick		Medium
Gold/tan	Purple		Blend		Coarse		Light
Dark blue	Light blue						
Dark green	Light green						
Maroon	Red						
Orange	Yellow						
White	Other (specify)						

	Clothing	Color	Fabric	Texture	Weight
H E A D W E A R	Hat				
	Helmet				
	Hood				
	Other (specify): _____				
U P P E R B O D Y	Short Sleeve				
	Long Sleeve				
	Light Jacket				
	Heavy Jacket				
	Other (Specify): _____				
L O W E R B O D Y	Shorts				
	Pants				
	Shoes				
	Other (specify): _____				