

Not in Traffic Surveillance Back Over Investigation / Vehicle to Non-Motorist
Dynamic Science, Inc. / Case Number: DS08006
2004 Volvo XC90
California
October 2007

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points be coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the pre-crash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

| | | | | |
|--|--------------------------------------|-----------------|---|--|
| 1. Report No. DS08006 | 2. Government Accession No. | | 3. Recipient Catalog No. | |
| 4. Title and Subtitle Not in Traffic Surveillance Back Over Investigation | | | 5. Report Date April 30, 2008 | |
| | | | 6. Performing Organization Report No. | |
| 7. Author(s) Dynamic Science, Inc. | | | 8. Performing Organization Report No. | |
| 9. Performing Organization name and Address Dynamic Science, Inc. 299 West Cerritos Avenue Anaheim, California 92805 | | | 10. Work Unit No. (TRAIS) | |
| | | | 11. Contract or Grant no. DTNH22-01-C-27002 | |
| 12. Sponsoring Agency Name and Address U.S. Dept. of Transportation National Highway Traffic Safety Administration 1200 New Jersey Ave, SE Washington, DC 20590 | | | 13. Type of report and period Covered [Report Month, Year] | |
| | | | 14. Sponsoring Agency Code | |
| 15. Supplemental Notes | | | | |
| 16. Abstract This single vehicle incident occurred in October 2007 at 1002 hours. The subject vehicle was a 2004 Volvo XC90 sport utility vehicle that was being driven by a 41-year-old female. The son of the driver, a 3-year-old male, was seated in the second row right seat. The Volvo was equipped with a rear parking assistance system that consisted of four ultrasound rear bumper mounted sensors linked to the in-vehicle audio system. This incident took place in a strip mall parking lot. The Volvo was parked in a parking stall facing west. The driver was intending to back out of the stall. The 82-year-old male non-motorist had been dropped off in the parking lot by a friend. He was walking towards his doctor's office. He was walking with the assistance of a cane. As the driver began backing, her son asked her to look at a toy. As she looked at the toy, she heard a signal from the parking system. She stated that she stopped the vehicle at this point. She looked at the rear view mirror and at both side mirrors and did not see anything. The non-motorist had either been struck by the Volvo and had fallen down, or had tried to avoid the backing vehicle and had fallen down. In any event, the non-motorist was on the ground at this time. After the driver looked in her mirrors after stopping, and not seeing anything, she resumed backing the vehicle. There was a constant signal from the parking system at this time and the non-motorist was in the driver's blind zone. A witness to the incident ran over to the Volvo and struck the back window while telling the driver to stop. The driver stopped the Volvo. The non-motorist was partially under the Volvo. He sustained a small laceration under his right eye and abrasions to his right palm. | | | | |
| 17. Key Words Not In Traffic Surveillance (NITS), injury, back over, sensor, parking aid, non-motorist | | | 18. Distribution Statement | |
| 19. Security Classif. (of this report) | 20. Security Classif. (of this page) | 21. No of pages | 22. Price | |

Dynamic Science, Inc.
Crash Investigation
Case Number: DS08006
TABLE OF CONTENTS

| | |
|--------------------------------------|----|
| Background | 1 |
| Summary | 1 |
| Incident Site | 1 |
| Pre-Crash | 2 |
| Crash | 2 |
| Post-Crash | 3 |
| Vehicle Data - 2004 Volvo XC90 | 3 |
| Parking Aids/Sensors | 3 |
| Vehicle Dimensions | 4 |
| Vehicle Sight Distances | 5 |
| Vehicle Damage | 8 |
| Exterior Damage | 8 |
| Interior Damage | 8 |
| Occupant Demographics | 8 |
| Non-Motorist Demographics | 8 |
| Injuries | 9 |
| Attachment 1. Scene Diagram | 10 |
| Attachment 2. Data Forms | 11 |

Background

This single vehicle incident occurred in October 2007 at 1002 hours. The subject vehicle was a 2004 Volvo XC90 sport utility vehicle that was being driven by a 41-year-old female (**Figure 1**). The Volvo was equipped with a rear parking assistance system that consisted of four ultrasound rear bumper mounted sensors linked to the in-vehicle sound system. This incident took place in a strip mall parking lot. The driver of the Volvo entered the vehicle from the left side. The driver's child was in the right rear seat. The Volvo was parked in a parking stall facing west. The driver was intending to back out of the stall. The 82-year-old male non-motorist had been dropped off in the parking lot by a friend. He was walking towards his doctor's office. He was walking with the assistance of a cane. As the driver began backing, her son asked her to look at a toy. As she looked at the toy, she heard a signal from the parking system. She stated that she stopped the vehicle at this point. She looked at the rear view mirror and at both side mirrors and did not see anything. The non-motorist had either been struck by the Volvo and had fallen down, or had tried to avoid the backing vehicle and had fallen down. The driver and at least one witness believe the latter to be the case. The non-motorist stated that he had been knocked down by the vehicle. In any event, the non-motorist was on the ground at this time. After the driver looked in her mirrors after stopping, and not seeing anything, she resumed backing the vehicle. There was a constant signal from the parking system at this time and the non-motorist was in the driver's blind zone. The non-motorist was likely in contact at some point with the vehicle. A witness to the incident ran over to the Volvo and struck the back window while telling the driver to stop. The driver stopped the Volvo. The non-motorist was partially under the Volvo. He sustained a small laceration under his right eye and abrasions to his right palm. He was assisted at the scene by the witnesses. He was then transported to a local hospital for treatment.



Figure 1. 2004 Volvo XC90 at area of impact (looking west)

This remote Not In Traffic Surveillance (NITS) Back Over Investigation was initiated in response to an email notification about an 82-year-old male injured in a back over incident. NHTSA had been notified by the local NASS team. DSI was notified of the incident on January 10, 2008. The police report was included in the notification. Efforts were undertaken to contact the driver. The driver was contacted and interviewed on February 25, 2008. The case vehicle had been sold by the driver. DSI was assigned the case on February 26, 2008. The non-motorist was interviewed on April 28, 2008.

The police on-scene photographs were requested and obtained. The incident site was local to the SCI team and was inspected in person despite the remote status of the case.

SUMMARY

Incident Site

This incident took place in a parking lot adjacent to a number of commercial buildings (**Figure 2**).

The parking lot is configured with parking stalls along the west side of the lot, the east side of the lot, and on the south side of the lot. All the stalls are marked by painted white lines. The lines are generally 5.5 m (18.0 ft) long and are marked 2.7 m (9.0 ft) apart. There is a -4% grade in the eastern direction for vehicles parked to the west. The grade decreases to -3.1% as one moves eastward. The parking lot is of asphalt construction with concrete gutter strips for drainage. There is no posted speed limit. The weather was clear and the parking lot was dry. The temperature at the nearest reporting station was 18 degrees C (64 degrees F). The Volvo was parked in the third stall from the left on the row of parking stalls to the west. It was parked between two other sport utility vehicles (**Figure 3**).



Figure 2. Overview of incident site (looking east)



Figure 3. Volvo XC90 in parking stall (police photo)

Pre-Crash

The 41-year-old female driver of the Volvo entered the vehicle from the left side. The driver's child was in the right rear seat. The Volvo was parked facing west. Based on the police photos, the Volvo was parked between an unknown year Lexus RX on the left and an unknown year Nissan Xterra on the right. The driver intended to back out of the stall. She indicated that she checked both side mirrors and the rear view mirror before backing. The 82-year-old male non-motorist had been dropped off in the parking lot by a friend to the south of the Volvo. He was approaching from the left side of the Volvo. He was walking northwest towards his doctor's office and was walking with the assistance of a cane. As the driver began backing, her son asked her to look at a toy. As she looked at the toy, she heard an intermittent signal from the parking system. The non-motorist would have been standing upright at this time. The driver stated that she stopped the vehicle at this point. She looked at the rear view mirror and at both side mirrors and did not see anything. The non-motorist stated that he had been struck by the vehicle and had fallen down. The driver and at least one witness stated that the non-motorist had fallen down while avoiding the Volvo. Based on the witness statement and the intermittent parking aid signal, it is this investigator's opinion that the non-motorist had fallen down while avoiding the Volvo. Regardless, the non-motorist was on the ground when the driver stopped the vehicle after hearing the intermittent signal.

Crash

After the driver looked in her mirrors after stopping, and not seeing anything, she resumed backing

the vehicle. There was a constant signal from the parking system at this time. A witness to the incident ran over to the Volvo and struck the back window with her hand while telling the driver to stop.

Post Crash

The driver stopped the Volvo. The non-motorist was partially under the Volvo. He sustained a small laceration under his right eye and abrasions to his right palm. He was assisted at the scene by the witnesses. He was then transported to a local hospital for treatment.

Vehicle Data - 2004 Volvo XC90

The 2004 Volvo XC90 was identified by the Vehicle Identification Number (VIN): YV1CZ59H241XXXXXX. The Volvo is four-door sport utility vehicle that was equipped with a 2.5 liter, five-cylinder engine, automatic transmission, traction control, and all wheel drive. There were no indications of a tire damage.



Figure 4. Area of impact (north). Arrow shows path of XC90.

The seating in the Volvo was configured with front bucket seats with adjustable head restraints, 40/20/40 split bench seats with adjustable head restraints in the second row, and a bench seat with adjustable head restraints in the third row.

Parking Aids/Sensors

The Volvo was equipped with a rear parking assistance system that consisted of four ultrasound rear bumper mounted sensors linked to the in-vehicle sound system (**Figure 5**). The system is automatically activated when the reverse gear is selected. When the system is active, the audio system's volume is reduced and an intermittent signal is audible from the audio system's speakers. The signals begin at a distance of approximately 1.5 m (5.0 ft) from an object/person, etc. At a distance of approximately 30.0 cm (12.0 in), the signal will become constant. There are four sensors mounted horizontally along the rear bumper. The sensors are mounted 59.0 cm (23.2 in) above the ground. The driver had owned the vehicle for four years and was familiar with the parking assistance system. The system was active at the time of the incident. Based on the driver's statements, it appears that the system performed as designed. The driver was initially notified of the non-motorist with an intermittent signal. After stopping and looking in her rear view mirrors, she continued backing and the system responded with a constant signal as she got closer to the non-motorist.



Figure 5. Rear parking assistance system sensors (subject vehicle)

Vehicle Dimensions

Dimensions obtained from Canadian vehicle specifications and an exemplar vehicle. Seated eye height was estimated using a surrogate driver seated at the height of the case vehicle driver. Eye position forward was estimated using the position of the surrogate driver with the seat in the middle track position.

| | |
|---|-------------------|
| Ground to belt line: | 124 cm (48.8in) |
| Ground to top of trunk/tailgate: | 124 cm (48.8 in) |
| Ground to top of rear bumper: | 66 cm (25.9 in) |
| Ground to bottom of rear bumper: | 41 cm (16.1 in) |
| Surrogate driver's seated eye height from seat bottom: | 72 cm (28.4 in) |
| Surrogate driver's seated eye height from ground: | 148 cm (58.3 in) |
| Overall vehicle height: | 174 cm (68.5 in) |
| Overall vehicle width: | 190 cm (74.8 in) |
| Overall vehicle length: | 480 cm (189.0 in) |
| Rear overhang: | 104 cm (40.9 in) |
| Track width: | 162 cm (63.8 in) |
| Longitudinal distance between rear most projection and front door latch pillar: | 230 cm (90.6 in) |
| Distance from estimated eye position to tailgate: | 253 cm (9.6 in) |

Vehicle Sight Distances

A visibility study was conducted in order to determine the nominal blind zone behind the vehicle as well as the nominal blind zone of both side view mirrors. Measurements were taken using an exemplar Volvo XC90 four-door sport utility vehicle. The standard 71.0 cm (28.0 in) high target was used to obtain the measurements. The measurements were taken on a paved level surface.

The driver's seated eye height when measured from the seat bottom was 72.0 cm (28.3 in) and when measured from the ground was 1.48 m (4.86 ft). The SCI investigator was able to duplicate the driver's seated eye height by measuring his own eye height from the seat bottom.

The initial set of measurements were taken as if the driver were looking over his right shoulder through the backlight. The target was moved rearward from the rear bumper along the Volvo's centerline until it became visible to the investigator. The point at which the target became visible to the investigator measured 7.16 m (23.50 ft) rearward of the rear bumper. This measurement was used as the point of origin for two sets of lateral measurements which were then taken. Measurements taken laterally to the left and right would result in a visibility zone that could be viewed through the backlight. Two sets of lateral measurements were taken due to the presence of second row head restraints which blocked the investigator's rearward vision. The first set of lateral measurements were taken from the vehicle's center line to the far left and right sides of the backlight. The second set of lateral measurements were taken from the vehicle's center line to the left and right head restraints. There was insufficient space behind the exemplar vehicle to determine at which distance the roadway surface would become visible to the driver when looking through the backlight.

Another set of measurements were taken to simulate the driver using the rear view mirror to look through the backlight. The target was moved rearward from the rear bumper along the Volvo's centerline until it became visible to the investigator. The point at which the target became visible to the investigator measured 6.71 m (22.00 ft) rearward of the rear bumper. This measurement was used as the point of origin for a set of lateral measurements which were then taken. Measurements taken laterally to the left and right would result in a visibility zone that could be viewed through the backlight.

Since the SCI investigator was using an exemplar vehicle, he adjusted the side mirrors appropriately for the driver's seated eye height. With the SCI investigator seated, the side views were examined. The target was placed at the right side of the rear bumper. The target was moved from the side of the vehicle laterally to the right until the target became visible through the right side view mirror. The target was then moved laterally to the right to the point where the target was no longer visible. These measurements resulted in a visibility zone which could be viewed through the side view mirror. This process was repeated on the left side of the vehicle. The area between the left and right



Figure 6. View of sticker on subject vehicle's backlight

visibility zones resulted in a blind zone. Directly behind the rear bumper, the blind zone measured 1.85 m (6.07 ft) in width. The overall width of the vehicle was 1.90 m (6.23 ft). The target was then placed at 6.40 m (21.00 ft) rearward of the rear bumper. Lateral measurements were taken to the left and right at the points at which the investigator could view the target through the side view mirrors. The area between the two visible points resulted in a blind zone. At 6.40 m (21.00 ft) rearward of the rear bumper, the blind zone was approximately 2.09 m (6.86 ft) in width. The target was then moved further to the left and right until it could no longer be viewed through the rear view mirrors. The areas to the left and right in which the target could be viewed resulted in side view visibility zones.

For the involved subject vehicle, vision to the right was blocked somewhat by a small sticker affixed to the lower right backlight (Figure 6).




Figure 7. Nominal visibility diagram (exemplar vehicle)



Figure 8. Driver's view to right rear (exemplar vehicle)



Figure 9. Driver's view down vehicle centerline (exemplar vehicle)



Figure 10. View through left side view mirror (exemplar vehicle)



Figure 11. View through right side view mirror (exemplar vehicle)

Vehicle Damage

Exterior Damage - 2004 Volvo XC90

There was no exterior damage to the vehicle from this incident. There were several gouge marks to the rear bumper, but these do not appear to be related to this incident.



Figure 12. Gouges located on rear bumper

Interior Damage - 2004 Volvo XC90

There was no interior damage.

Occupant Demographics

Driver

| | | |
|----------------------------|--|---|
| Age/Sex: | 41/Female | 3/Male |
| Height: | 173 cm (68 in) | 91 cm (36 in) |
| Weight: | 61 kg (135 lbs) | 14 kg (30 lbs) |
| Seat track position: | Middle | N/A |
| Manual restraint use: | Lap and shoulder belt available, used. | Lap and shoulder belt available, used with child safety seat. |
| Usage source: | Interviewee | Interviewee |
| Eyewear: | None | None |
| Type of medical treatment: | None | None |

Non-Motorist Demographics

| | |
|----------------------------|--------------------------|
| Age/Sex: | 82/Male |
| Height: | 183 cm (72 in) |
| Weight: | 73 kg (160 lbs) |
| Eyewear: | Glasses worn |
| Type of medical treatment: | Transported and released |

INJURIES


Driver: Not injured.

Second row right occupant: Not injured.

Non Motorist: Injuries obtained from interviewee and police report.

| <u>Injury</u> | <u>OIC Code</u> | <u>Injury Mechanism</u> | <u>Confidence Level</u> |
|--------------------------------|-----------------|-------------------------|-------------------------|
| Laceration, under right eye | 290600.1,1 | Unknown | Unknown |
| Abrasions, right palm | 790202.1,1 | Ground | Certain |

Attachment 1. Scene Diagram



Attachment 2. Data Forms



1. Case Number

IDENTIFICATION

2. Date of Crash ____ / ____ / ____

3. Time of Crash _____

Code reported military time of crash.

NOTE: Midnight = 2400
Unknown = 9999

AMBIENT CONDITIONS

4. Light Conditions

- Daylight
- Dark
- Dark but lighted
- Dawn
- Dusk
- Unknown

5. Atmospheric Conditions
(Select all that apply)

- Clear-No adverse conditions
- Cloudy
- Rain
- Snow
- Fog, Smog, Smoke
- Sleet, Hail (freezing rain or drizzle)
- Blowing Snow
- Severe Crosswinds
- Blowing Sand, Soil, Dirt
- Other (specify):
- Unknown

6. Temperature

- Below 0 degrees Celsius (Below 32 F)
- 1-10 degrees Celsius (33-50 F)
- >10-24 degrees Celsius (51-75 F)
- Over 24 degrees Celsius (Over 75 F)
- Unknown

SCENE INFORMATION

7. Type of area in which crash occurred
(Select all that apply)

- Single family residential
- Row houses/townhouses
- Multi family housing
- Commercial
- Industrial
- Rural
- Unknown

8. Driver exterior sightline obstructions
(Select all that apply)

- None
- Other vehicles
- Building
- Trees
- Shrubby
- Other (specify) _____
- Utility poles
- Signs
- Glare
- Unknown
- No driver present

9. Crash location

- Driveway
- Parking Lot
- Sidewalk
- Alley
- Intersection of driveway and sidewalk
- Road / street
- Roadside / shoulder
- Other (specify) _____
- Unknown

10. Non motorist sightline obstructions
(Select all that apply)

- None
- Other vehicles
- Building
- Trees
- Shrubby
- Utility poles
- Signs
- Glare
- Other (specify) _____
- Unknown

11. Grade at parked position _____ +/- %

12. Estimated distance from parked position to impact

_____ m

13. Estimated speed at impact _____ +/- kmph

14. Grade at impact _____ +/- %

15. Estimated distance from impact to vehicle final rest

_____ m

Unknown = 999 Reference Items 11,12, 13, 14, 15



1. Case Number _____

VEHICLE IDENTIFICATION

2. VIN _____

3. Model Year _____

4. Vehicle Make (specify): _____

5. Vehicle Model (specify): _____

GLAZING

| Location | Presence (check) | Status (select) | Clarity (select) | Tint (check) | Glazing Obstructions (specify if present) |
|-----------------------|------------------|--|-------------------------------------|--------------|---|
| Windshield | | Fixed / Closed / Open / Partially Open / Unknown | Clear / Hazy / Very Dirty / Unknown | | |
| LF | | Fixed / Closed / Open / Partially Open / Unknown | Clear / Hazy / Very Dirty / Unknown | | |
| RF | | Fixed / Closed / Open / Partially Open / Unknown | Clear / Hazy / Very Dirty / Unknown | | |
| 2 nd Left | | Fixed / Closed / Open / Partially Open / Unknown | Clear / Hazy / Very Dirty / Unknown | | |
| 2 nd Right | | Fixed / Closed / Open / Partially Open / Unknown | Clear / Hazy / Very Dirty / Unknown | | |
| 3 rd Left | | Fixed / Closed / Open / Partially Open / Unknown | Clear / Hazy / Very Dirty / Unknown | | |
| 3 rd Right | | Fixed / Closed / Open / Partially Open / Unknown | Clear / Hazy / Very Dirty / Unknown | | |
| Backlight | | Fixed / Closed / Open / Partially Open / Unknown | Clear / Hazy / Very Dirty / Unknown | | |
| Left Backlight | | Fixed / Closed / Open / Partially Open / Unknown | Clear / Hazy / Very Dirty / Unknown | | |
| Right Backlight | | Fixed / Closed / Open / Partially Open / Unknown | Clear / Hazy / Very Dirty / Unknown | | |
| Roof | | Fixed / Closed / Open / Partially Open / Unknown | Clear / Hazy / Very Dirty / Unknown | | |
| Other (specify) | | Fixed / Closed / Open / Partially Open / Unknown | Clear / Hazy / Very Dirty / Unknown | | |

TIRE DATA

6. Vehicle Manufacturer Recommended Tire Size _____

7. LF Tire Size _____

9. RF Tire Size _____

8. LR Tire Size _____

10. RR Tire Size _____

Seats / Head Restraint Data

| Seat Position | Seat Type (Select from below) | Head Restraint (Check if available) | Head Restraint Adjustment (select) | NOTES: |
|------------------------|-----------------------------------|--|---------------------------------------|--------|
| Front Left | | | Full Down / Mid / Full Up | |
| Front Middle | | | Full Down / Mid / Full Up | |
| Front Right | | | Full Down / Mid / Full Up | |
| 2 nd Left | | | Full Down / Mid / Full Up | |
| 2 nd Middle | | | Full Down / Mid / Full Up | |
| 2 nd Right | | | Full Down / Mid / Full Up | |
| 3 rd Left | | | Full Down / Mid / Full Up | |
| 3 rd Middle | | | Full Down / Mid / Full Up | |
| 3 rd Right | | | Full Down / Mid / Full Up | |

Seat Type codes:

- | | |
|---|--------------------------------------|
| 0 = No seat or seat folded down | 8 = Pedestal (i.e. column supported) |
| 1 = Bucket | 9 = Box mounted (i.e. van type) |
| 2 = Bucket w/ folding back | 10= Other seat type (specify) |
| 3 = Bench | 99= Unknown seat type |
| 4 = Bench with folding back cushions | |
| 5 = Bench w/ folding back | |
| 6 = Split bench w/ separate back cushions | |
| 7 = Split bench w/ separate folding back | |

VEHICLE MEASUREMENTS

| Clearance Heights | Measurements (all from ground, and in centimeters) | NOTES |
|-------------------------------|---|-------|
| Beltline | | |
| Top of trunk/tailgate | | |
| Bottom of bumper | | |
| Trailer hitch (if applicable) | | |
| Undercarriage | | |
| Sway bar | | |
| Axle | | |
| Differential | | |
| Other (specify): | | |
| Sensor Height (if equipped) | | |
| Camera Height (if equipped) | | |



1. Case Number

PARKING AID PRESENCE

2. Type of backing/parking aid present

- OEM camera
- OEM ultrasonic/radar sensor
- OEM combination camera-ultrasonic/radar sensor
- OEM Fresnel lens
- OEM interior mirrors
- Aftermarket camera
- Aftermarket ultrasonic/radar sensor
- Aftermarket combination camera-ultrasonic radar sensor
- Aftermarket Fresnel lens
- Aftermarket interior mirrors
- Other (specify): _____

CAMERA INFORMATION

Specify field of view measurements on diagram

3. System make/model

4. Video monitor type

- None present
- LCD (color)
- CRT (black & white)
- Unknown

5. Video display size _____ cm
(Diagonal)

6. Camera location

- None present
- Bumper
- License plate
- Tailgate/Hatch/Trunk
- Other (specify): _____

7. Video image quality under scene lighting conditions

- None present
- Good
- Average
- Poor (specify): _____
- Unknown

8. Was the camera functioning properly

- None present
- Yes
- No, poor image quality due to glare
- No, poor image quality due to atmospheric conditions
- No, camera turned off
- No, camera inoperable
- Unknown

ULTRASONIC/RADAR SENSOR

Specify object detection range on diagram

9. System make/model

10. Auditory warning illumination

- No sensor present
- Yes
- No
- Unknown

11. Number of sensors _____

12. Sensor locations
(Select all that apply)

- No sensor present
- Left bumper
- Center bumper
- Right bumper
- License plate area
- Tailgate/Hatch/Trunk

13. Was warning system functioning properly

- No sensor present
- Yes, system alerted driver
- No, system did not alert driver
- No, system turned off
- No, system inoperable
- Unknown

14. Did driver react to warning

- No sensor present
- Yes
- No
- Unknown

15. Did driver report common false warnings

- No sensor present
- Yes
- No
- Unknown



DRIVER FORM

1. Case Number

DRIVER PROFILE

2. Driver's Age _____
99 = Unknown

3. Driver's Sex Male
 Female
 Unknown

4. Driver's Height _____ cm
999 = Unknown

5. Driver's Weight _____ kg
999 = Unknown

6. Driver eyewear worn
(Select all that apply)
 None
 Eyeglasses
 Sunglasses
 Contacts
 Unknown

7. Driver vision deficiency condition
(Select all that apply)
 None
 Near sighted
 Far sighted
 Astigmatism
 Other (specify): _____
 Unknown

8. Non motorist's relationship to driver
 No relationship
 Child
 Grandchild
 Sibling
 Neighbor
 Friend
 Other (specify): _____
 Unknown

DRIVER ACTIONS

9. Driver approach to vehicle for entry
From left front
 From left
 From left rear
 From right rear
 From right front
 Circled vehicle
 Return trip (backing into driveway/lot)
 Other (specify): _____
 N/A
 Unknown

10. Driver entry interruption
(Select all that apply)
 Direct trip from building to vehicle
 Loaded items into vehicle
 Spoke with family
 Spoke with neighbors
 Spoke with contacted nonmotorist
 Return trip (backing into driveway/lot)
 Other (specify): _____
 N/A
Unknown

11. Purpose of backing
 Leaving parking space in parking lot
 Backing onto roadway from driveway
 Entering parking space in parking lot
 Backing into driveway from roadway
 Other (specify): _____
 N/A
Unknown

12. Where was driver going
Description:

13. Driver in a hurry
 Yes N/A
 No Unknown
 Unknown

14. How did driver check behind (rear area of vehicle)
after vehicle entry
(Select all that apply)
 Did not look
 Checked mirrors
 Turned right and looked back
 Turned left and looked back
 Viewed Camera
 Listened for auditory/visual warning from system
 Other (specify): _____
N/A Unknown

15. Estimated time between vehicle entry and start
of backing
 0-10 Seconds Over 60 Seconds
 11-30 Seconds N/A
 31-60 Seconds Unknown

16. What direction was the driver looking during backing maneuver
(Select all that apply)
- Straight ahead
 - Right
 - Left
 - Rearward
 - At object inside the car
 - At mirrors
 - Other (specify): _____
 - N/A
 - Unknown
17. Was the driver distracted during back up maneuver
(Select all that apply)
- No non-driving activities
 - External**
 - Looking at other vehicles
 - Looking at other non motorist
 - Looking at intended turn destination
 - External focus, not specified
 - Other external focus (specify): _____
 - Internal**
 - Looking at other occupant
 - Talking to passenger
 - Dialing phone
 - Talking on phone
 - Listening to radio/cd/portable playback device
 - Adjusting radio/cd player
 - Adjusting climate controls
 - Using a device/controls integral to vehicle (specify): _____
 - Reading/adjusting navigation system
 - Eating or drinking
 - Smoking related
 - Retrieving fallen object (specify): _____
 - Internal focus, not specified
 - Focused on other internal object (specify): _____
 - N/A
 - Unknown
18. Driver avoidance actions prior to impact
(Select all that apply)
- None
 - Braking
 - Steering left
 - Steering right
 - Accelerating
 - Other (specify): _____
 - N/A
 - Unknown
19. Did driver see struck non motorist prior to impact
(Select all that apply)
- No, never saw non motorist
 - Saw non motorist prior to entering vehicle
 - Saw non motorist after entering vehicle
 - Other (specify): _____
 - N/A
 - Unknown
20. Est time between start of backing and impact
- <2 or = 1 second
 - 2-5 seconds
 - 6-10 seconds
 - > 10 seconds
 - N/A
 - Unknown
21. Driver interior sightline obstructions
(Select all that apply)
- Pillar
 - Headrest
 - Cargo
 - Other occupant
 - Other (specify) _____
 - Unknown
 - None
22. Recent experience driving this vehicle
- More than 10 times the last three months
 - 6-10 times the last three months
 - 2-5 times the last three months
 - Less than 2 times the last three months
 - First time driving this vehicle
 - N/A
 - Unknown
23. Frequency of driving in this parking lot/driveway
- Daily
 - Weekly
 - Several times a month
 - Monthly
 - Rarely
 - First time in lot/driveway
 - N/A
 - Unknown
24. Driver Impairment
(Select all that apply)
- No drugs or alcohol present
 - Alcohol present (specify BAC): _____
 - Drugs present (specify): _____
 - Unknown
25. Source of alcohol/drug results
- Police reported
 - Medical record
 - Other (specify) _____
 - Not Tested
 - Unknown if tested



Non Motorist Form

1. Case Number

NON-MOTORIST PROFILE

2. Non-motorist's Age _____ Months
_____ Years
99 = Unknown

3. Non-motorist's Sex
 Male
 Female
 Unknown

4. Non-motorist's Height _____ cm
999 = Unknown

5. Non-motorist's Weight _____ kg
999 = Unknown

6. Medical outcome
 Not injured
 ER only
 Hospitalized 1-4 days
 Hospitalized 5 days or more
 Treatment later
 Fatal
 Unknown

7. Source of most severe injury
 Bumper
 Tire
 Undercarriage
 Other Specify: _____
 Ground
 N/A
 Unknown

8. Non-motorist impairment
(Select all that apply)
 No drugs or alcohol present
 Positive for alcohol (specify BAC): _____
 Positive for drugs (specify): _____
 Unknown

9. Source of alcohol/drug results
 Police reported
 Medical Report
 Other (specify) _____
 Not Tested
 Unknown if tested

NON-MOTORIST ACTIONS

10. Non-motorist attitude
 Standing
 Bending at waist
 Sitting
 Crouching
 Kneeling
 On skates/skateboard
 On bike/scooter
 Other (specify) _____
 Unknown

11. Non-motorist motion
 Not moving
 Walking slowly
 Walking rapidly
 Running or jogging
 Skipping/Hopping/Jumping
 Falling/Stumbling/Rising
 On skates/skateboard
 On bike/scooter
 Other (specify): _____
 Unknown

12. Non-motorist approach relative to rear of vehicle
 Stationary
 From left
 From right
 From behind
 Other (specify): _____
 Unknown

13. Non-motorist first avoidance action
 No avoidance actions
 Stopped
 Accelerated pace
 Ran away (along vehicle path)
 Jumped
 Turned away from vehicle
 Turned toward vehicle and braced
 Dove or fell away from vehicle
 Other (specify): _____
 Unknown

14. Non-motorist primary focus of attention
 Striking vehicle
 Play object
 Person
 Surrounding traffic
 Animal
 Handheld electronic (phone, MP3 player, etc.)
 Other Object (specify) _____
 Unknown

15. Were any other Non-motorists present?
(Select all that apply)
 Alone
 One adult present
 One other child present
 Multiple adults present
 Multiple children present
 Unknown

NON MOTORIST CLOTHING

NOTES:

- Specify Color, Fabric and Texture/Weight for outermost layer only
- Indicate "NONE" if applicable
- Available codes:

| | | | | | | | |
|----------------|----------------------|--|-----------------------|--|------------------------|--|-----------------------|
| | <u>Colors</u> | | <u>Fabrics</u> | | <u>Textures</u> | | <u>Weights</u> |
| Black | Charcoal gray | | Natural | | Soft | | Heavy |
| Lt gray/silver | Brown | | Synthetic | | Slick | | Medium |
| Gold/tan | Purple | | Blend | | Coarse | | Light |
| Dark blue | Light blue | | | | | | |
| Dark green | Light green | | | | | | |
| Maroon | Red | | | | | | |
| Orange | Yellow | | | | | | |
| White | Other (specify) | | | | | | |

| | Clothing | Color | Fabric | Texture | Weight |
|---|---------------------------|--------------|---------------|----------------|---------------|
| H E A D W E A R | Hat | | | | |
| | Helmet | | | | |
| | Hood | | | | |
| | Other (specify): _____ | | | | |
| | | | | | |
| U P P E R B O D Y | Short Sleeve | | | | |
| | Long Sleeve | | | | |
| | Light Jacket | | | | |
| | Heavy Jacket | | | | |
| | Other (Specify): _____ | | | | |
| | | | | | |
| L O W E R B O D Y | Shorts | | | | |
| | Pants | | | | |
| | Shoes | | | | |
| | Other (specify): _____ | | | | |
| | | | | | |