



U.S. Department of Transportation

National Highway Traffic Safety Administration

### Dear Crash Data Researchers/Users:

Thank you for choosing crash data from the National Highway Traffic Safety Administration (NHTSA) for your research or other use. The information contained in this motor vehicle crash report is collected, maintained and distributed in accordance with Public Law 89-564. In accordance with this Public Law, NHTSA is required not to release any case information until completion of quality control procedures. These procedures include a review of the case material to extract all names, licenses and registration numbers, non-coded interview material, non-research related researcher comments in the margins, non-factual data, and the production number portion of the vehicle identification number (VIN).

If you requested NHTSA to query its database files in order to identify a specific crash, then that query was made using non-personal descriptors you provided for use in our search. This motor vehicle crash may have been identified from a data search and matches the general, non-personal descriptors you provided, but we cannot confirm that this is the specific crash report you requested.

If you have any questions with regard to the above procedures, please contact the Field Operations Branch, Crash Investigation Division, National Center for Statistics and Analysis at 202-366-4820. Again, please be advised that we cannot confirm that this is the case that you have specifically requested nor can we certify the information to be correct.

\*\*\* \*\*\* \*\*\*




### TRANSPORTATION RESEARCH CENTER

# Indiana University

# REMOTE AIR BAG REPORT

CASE NO. - 92-06 FLEET - PRIVATE VEHICLE -LOCATION - 🐠 ▶ INDIANA ACCIDENT DATE -1992

Submitted By:



Associate Scientist



Revised Submission:



Contract Number: DTNH22-87-C-07169

## Prepared for:

U.S. Department of Transportation National Highway Traffic Safety Administration National Center for Statistics and Analysis Washington, D.C. 20590

#### **DISCLAIMERS**

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points be coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the precrash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

# Transportation Research Center Indiana University

Remote Air Bag Case No. 92-06

## Summary

This report concerns a motor vehicle accident involving an air bag equipped 1990 Chevrolet Corvette, a 1978 Ford Fairmont, and a 1986 Chevrolet Cavalier occurring on the control of the c

The Corvette was traveling east in the outside lane of a four-lane divided trafficway when it impacted the Fairmont which was traveling south on a two-lane undivided roadway. The Fairmont then struck the Cavalier, which was northbound on the two-lane undivided roadway and stopped at the intersection. The Corvette rotated clockwise after impact. The final rest position of the Corvette is not known. The Fairmont rotated counterclockwise after impact with the Corvette and struck the Cavalier. The Fairmont came to rest on the southeast corner of the intersection, partially off the roadway. The final rest position of the Cavalier is not known.

The front of the Corvette impacted the right front of the Fairmont. Subsequently, they sideslapped with the right quarter panel of the Fairmont impacting the left side of the Corvette. Next, the front of the Fairmont impacted the front left of the Cavalier. CDCs for the Corvette are estimated as: 10-FDEW-1 and 09-LYEW-1. CDCs are not estimable for the Fairmont and Cavalier. No reconstruction program was used on this collision.

The 1990 Chevrolet Corvette was equipped with a driver supplemental restraint system (air bag) which did not deploy as a result of the frontal impact. The driver of the vehicle (27 year-old female) was also restrained by the active three-point lap and shoulder belt. The driver of the Corvette was listed on the Police Accident Report as not sustaining any injury as a result of this accident. The driver (38 year-old male) of the Fairmont was listed on the Police Accident Report as not sustaining any injury. The driver (43 year-old female) of the Cavalier was also listed on the Police Accident Report as not sustaining any injury.

## TRC/IU REMOTE AIR BAG REPORT

#### FLEET - PRIVATE VEHICLE LOCATION -INDIANA CASE NO. - 92-06

ACCIDENT DATA

Location/Street: Intersection of two city streets

Indiana City/Township:

Urban/residential Area/Type:

1992 @ Accident Date/Time: p.m.

Police Department Investigating Police Agency:

Car / Car - right angle Accident Type:

Occupant Injury Severity

No injury (AIS=0) (air bag vehicle):

AMBIENT CONDITIONS

Daylight Light conditions:

Weather Condition: Cloudy

Precipitation: Snow

Road Surface: Wet

**ROADWAY** 

Vehicle #3 Case Vehicle Vehicle #2 City street Location: City street City street Number of Travel Lanes: 4-lanes, 2-lanes, 2-lanes, undivided undivided divided Concrete Surface Type: Concrete Concrete Vertical alignment: Unknown Unknown Unknown Straight Straight Horizontal alignment: Straight Traffic Density: Unknown Unknown Unknown

# ROADWAY (CONT'D.)

	<u>Case Vehicle</u>	<u>Vehicle #2</u>	<u>Vehicle #3</u>
Speed Limit:	35 mph (56 kph)	35 mph (56 kph)	35 mph (56 kph)
Traffic Controls:	On-colors, auto- matic traffic signal light	On-color, auto- matic traffic signal light	On-colors, auto- matic traffic signal light

# <u>VEHICLES</u>

	Case Vehicle	Vehicle #2	Vehicle #3
Year:	1990	1978	1986
Make:	Chevrolet	Ford	Chevrolet
Model:	Corvette	Fairmont	Cavalier
Body Type:	2-door	4-door	Stationwagon
V.I.N.:		Unknown	Unknown
Mileage:	3,800 miles (6,115 kilometers)	Unknown	Unknown
Securiflex windshield:	Unknown	Unknown	Unknown
Windshield damage/ source:	None	Unknown	Unknown
Fleet:	Private vehicle	Private vehicle	Private vehicle
Tow status:	Towed	Towed	Not towed
Reported Defects:	Unknown	Unknown	Unknown

# VEHICLE DAMAGE

	Case Vehicle	<u>Vehicle #2</u>
Nondeployment Impact		
Object Struck:	Vehicle #2	Case vehicle
Event number:	1	1
Damage location:	Front	Right front
CDC:	10-FDEW-1	Unknown
Estimated Maximum Crush:	6-8 inches (15-20 centimeters)	Unknown

# VEHICLE DAMAGE (CONT'D.)

	Case Vehicle	Vehicle #2
Damage components:	Bumper, hood, left & right fenders, right front door	Unknown
Repair Estimate:	Unknown	Unknown
Interior damage:	Unknown	Unknown

<u>Case Vehicle #2</u>

1st Additional Impact

Event number: 2 2

Object Struck: Vehicle #2 Case vehicle

Damage location: Left Right

CDC: 09-LYEW-1 Unknown

Estimated Maximum Crush: Scratches and broken Unknown

fiberglass only

Damage components: Left front door and Unknown

quarter panel

Interior damage: Unknown Unknown

Vehicle #2 Vehicle #3

2nd Additional Impact

Event number: 3

Object Struck: Vehicle #3 Vehicle #2

Damage location: Front Front

CDC: Unknown Unknown

Estimated Maximum Crush: Unknown Unknown

Damage components: Unknown Unknown

Interior damage: Unknown Unknown

## VEHICLE DAMAGE (CONT'D.)

Vehicle #2

3rd Additional Impact

Event number:

Object Struck: Curb

Damage location: Front

CDC: Unknown

Estimated Maximum Crush: Unknown

Damage components: Unknown

Interior damage: Unknown

### **COLLISION SEQUENCE**

According to the police accident report, the case vehicle (Corvette) was traveling east in the outside lane of a four-lane divided city street and was attempting to continue in its direction of travel. Vehicle #2 was traveling south on a two-lane undivided city street and was attempting to continue in its direction of travel. Vehicle #3 was northbound on a two-lane city street and was stopped at the intersection waiting to initiate a left turn. The accident occurred in the intersection of the two streets.

Based on information in the police accident report, from the investigating officer, and from the photographs contained in the "Petition for Defect Investigation Report", the front of the case vehicle impacted the right side of vehicle #2. The damage on the front of the case vehicle indicates an acute angle impact between the case vehicle and vehicle #2. It appears likely that the case vehicle was steered to the right at the time of impact. Following the initial impact, vehicle #2 rotated counterclockwise and the case vehicle rotated clockwise. The right side of vehicle #2 impacted (i.e., sideslapped) the left side of the case vehicle. Vehicle #2 then continued southeastward and impacted vehicle #3. Subsequently, vehicle #2 impacted a curb and came to rest on the southeast corner of the intersection, partially off the roadway. The final rest positions of the case vehicle and vehicle #3 are not known.

The case vehicle's driver side supplemental restraint system (air bag) did not deploy. The police accident report indicated that the driver of the case vehicle was wearing the available lap/shoulder restraint at the time of the accident. The driver sustained no injury as a result of the collision.

# DRIVER DATA

	Case Vehicle	Vehicle #2	Vehicle #3
Age:	27	38	43
Sex:	Female	Male	Female
Height:	Unknown	Unknown	Unknown
Weight:	Unknown	Unknown	Unknown
Occupation:	Unknown	Unknown	Unknown
Active Restraint System/Usage:	3-point lap and shoulder/used	3-point lap and shoulder/used	3-point lap and shoulder/used
Usage Source:	Police accident report	Police accident report	Police accident report
Eye glasses/contacts:	Unknown	Unknown	Unknown
Vehicle Familiarity:	Unknown	Unknown	Unknown
Route Familiarity:	Unknown	Unknown	Unknown
Trip Plan:	Unknown	Unknown	Unknown
Manner of Leaving Scene:	Unknown	Unknown	Unknown
Type of Medical Treatment:	No injury	No injury	No injury

# DRIVER INJURIES

<u>Injury</u>	Severity (AIS)	Source
None	Not applicable	Not applicable

# **ATTACHMENTS**

Police Report Petition for Defect Investigation Concerning Alleged Failure of Air Bag Deployment in Certain GM Chevrolet Corvette Vehicles


		OFFIC	ER'S STA	ANDARD A	CCID	ENT	REPOR	T Č	<u> </u>	C		E USE			$\overline{}$
Fig.		Form 23558R2 Stoc		dent Records S	Section			Ac	Cideni	ID N					回
1	The state of the s				N.					_`*					2 ال
VE	Date of Accident	1.43	Day of Werk	Actual L	ocal Time		× PM	No Mo Vehicle	101	No I	nured T	1 -	Dead 27	No Traile	2)_
V2/	County	1 74		Township			<u> </u>	City	Jone			ily Tox		12	네무,
V2/	2 Inside Corporate	Limits' Property		CSS SIZE S							- "				╝
	Ven :	No Prival	000	Cistance a			Corporate		1	^			<b>/</b>	A Addan Harr	
2) V1:	Road Accident O	ccurred On	T			<del></del>	cting Road			Mercil				Miles Wes	15
09	If not all intersecti	S+	rction N	learest Intersection	no Road N	N I	er intercha		V_	···		•		LD,	12
	of feet from						er miercie	<b>.</b>							20
1	Driver's Name IL	st First MI)					rs Name (			A Francisco	- Carter 3	Redition co		1 E	
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Aggress (Street,	City, State 🍎 o				-	ess (Street	City. St	10/20	ැල්සින ව					
YZ.						2 2 2		**********						marks.	
7	Stat (enter no )	W P Date of E	DAY 27 YEAR	Arrested	"	C App.	vent Phys (enter no )	Sei	Da	te of B		3 B		Arrested	<u>"]</u> [[]
V2	Driver's License 1			Type Lic St		S S S	v s License					J.	ASSA	Lic St Res	
<b>V</b> 14	Color	Ven Yr Make		OP IN	<b>2</b>	Cold		Web	r M			N	TEn	INB	人回
V2/	white	70 Che			ا و.		hite	74 5		_0.c	1		odel Na	ime	4
	Veh Type (enter no.)	Lic Yr License		Lic Stat	· .	Veh	Type H no )	Lic Y	Lec	ense N				Lic State	
	Veh Use	Speed Limit   Fut	H Tax No	/ IN		Veh	Use	Social		True	Hax N			IN	一回
V.	(enter no )	35	/				u uo l		S						
V2	Direction of Travel	No Occupants Fire	Yes !	iles Transportini Hazardous I	المقا	Dire Trav	ction of	No C	ccuper	its Fire		No A		ansporting zardous Mat	ावा
V2	2 10-410		No Towed By	Ves .	No	U Tow	S of to	<u> </u>			Towe	By		Yes ZN	٠ ا
لگا	Required Own	r's Name (Last, Firs				VEHICL 9									
٥١	SAME		· • · · · / .				Siered Owr	_	*e (L29	it, First	, <b>16</b> 11)			_	<b>国</b>
V2	Address (Street.	City State Zipi	/				ress (Street		ale Zi	P)		7	<del></del>		712
	Registered Owne	r's Name (Last, Firs		· · · · · ·	$\prec$	Reg	Stered Own	ner's Nan	ne (Las	it, Ferst	MIV				$\prec$
6		51. 5100 3/2				2					$\angle$			ga d <sup>er</sup> i	154
	Address (Street.	City, State. (Ip)				11	ress (Street	i, City, Si	ate. Zi	/ (۹	,				╗┕╌
	License No	Ma	ke Ye	ar Lic St	Lic Yr	TICE LICE	nse No		<del></del>	Mai	i.e	Ye	or (	Lic. St.  Lic.	11
	INSTIAL IMPACT	Areas Damaged (I	Multiples)			4		Direction	<u> </u>		·	1			2
	V1 1 V32	MI		dercarriage	<b>X</b>	FY	<u>.</u> 10	Caracta	J. 30	eev i mi	riway	10,		Apparent Billy: Stal. Jorder no	
	DAMAGE EST	LA STA	₹ 12 · No	न	710	7,	12 2		Not in	1080WE	Y	before	ccot	17 Enter No.	1
	AGE	OTHER PR		LUDE CARGO)	VEHIC			2 3 4	Players	ng in roa g in roa	dway ' xking.e	n vehicle	,	L	$\dashv$
	Name of Object		ER'S NAME AN			Damegi (use ci	Est Sylvert)	5 6 7	Other Walkin	working	19,700	dway with traffi igainst tr			
	curb	Dept of Tr	u viberta	Tien			- d	10	Gettin	g on or on or ing or e	off sen off sen nterina	icle ool bus nol al in	lerseës.		
				= -				ظر	Other	and or e	ntering	al inters	ection		ا:
	16 17 18 18 19			20				Per		Traffe					₹-
			BIVER OF Y	VEHICLE 1 (a	ne liete d		`	0	1.1	22   23	24 2	25. 26	27 28	29	4
	311			venicle i (a	15 115160	above	)		"	1					
	3 11	D	RIVER OF	VEHICLE 2 (a	as listed	above	)	0	11	X			/	1	
									1 1				+	1	-
				<del></del>	ertified	i to be	true co	DDY	++	+	++	+-	+	-	
								·	$\sqcup$		$\coprod$	$\perp \perp$			$\Box$
			/												

Diogram				<del></del>	
	N	\$		7	(T)
				· · · · · · · · · · · · · · · · · · ·	
	1.1				Indicate NORTH by an arrow
	1 11		•	. :	
	} '		•	•	
			-		
	=				
	P				
	_EA		·	_ :	
	18	3/2		••••••	
	)				
	1 1		• • • • • • •	• • • • • • • • • • • • • • • • • • • •	
				• • • • • • • • • • • • • • • • • • • •	
	•••				
			• • • • • • • • • • • • • • • • • • • •		
			<u> </u>		
NAI		Vehicle by Number)		·	
Driver HI said she was FIR in the corb !	ane of W.	1. At the i	stericct.	on of W	St. and
N. driver I had the green as	utomatic sig	ml and she are	it he has	real than inter	certos colos
Webself # 2 discreased the red light	and come is	ito the interes	tion D.	heal land	ant et
and struct whichend. Vehicle +2 the	nsour into	uphiele 43 wait	رود : مناه	1/8 lana	4 11
Au of W. 1. Vehicle #2 then	sa: a alectia	e was and ear	) to	d a h c	15
W. B. D. W	3 2011 101	( ())	ישר ישוני	i nume 2	E COLNELD
D 42 11	1.1				
Driver "2 said he was waiting at the ligh		11,12	1111		B. Driver 12
said the light turned greenfor him a	w he proceed	ta s/B on N.		Al. Which	( H)
come that the intersection and street	ude vehicle #	2 spaninghim	into ve	hick #3 ar	of then only
the curb.					
In the second se					
Driver +3 said she was we lineder H	he light at W.	St. In	.44.	(A., .)/a	Name H3
Oriver & said She was working for the	he light at W.	St. liv	MN.	۾ اِلو سھا	. Dryec#3
	he light at W.	91.5 10	<b>M</b> N ·	آلو بهار	Dryec#3
O1 Inqured By	he light at W.	91.5 10	√I N· ]		
Other Participent(s) Name, Address (etc.)	Address	91.5 10	MN-	Location at Time	of Accident
Other Participent(s) Name, Address (etc.)  Name of Witness No. 1  Name of Witness No. 2	Address Address	D2 Insured By			of Accident
Other Participent(s) Name, Address (etc.)  Name of Witness No. 1  Name of Witness No. 2  Name of Person Arrested	Address Address 1 C Code(s)	91.5 10	ad /	Location at Time	of Accident
Other Participent(s) Name, Address (etc.)  Name of Witness No. 1  Name of Witness No. 2  Name of Person Arrested	Address Address 1 C Code(s)	D2 Insured By	ad /	Location at Time  Location at Time  1.C.	of Accident of Accident Code(s) os Taken
Other Participent(s) Name, Address (etc.)  Name of Witness No. 1  Name of Person Arrested  Time Notified IAM Time Arrived IAM Other Location  Assisting Officer	Address Address 1 C Code(s)	D2 Insured By	nd In <u>vest</u> ypatio	Location at Time	of Accident  Df Accident  Code(s)  Os Taken  Yes No
Other Participent(s) Name, Address (etc.)  Name of Witness No. 1  Name of Witness No. 2  Name of Person Arrested	Address  Address  1 C Code(s)  on of Investigation	D2 Insured By  Marne of Person Arreste	nd In <u>vest</u> ypatio	Location at Time	of Accident  D1 Accident  Code(s)  os Taken  Ves No

BEST AVAILABLE COPY OFFICER'S STANDARD ACCIDENT REPORT OFFICE USE ONLY State Form 23558R2 Stock 302 Mail to Police Accident Records Section 2 No Motor Vehicles Day of Week Date of Accident Actual Local Time No Crad No Injured No Trailers **142** R • County OWNSHIP City Town or Nearest City Town 1 Inside Corporate Limits? Property Distance and Direction From Corporate Limits DIVA Yes Gire Miles North Miles South . \_\_\_\_ Miles East Miles West Road Accident Occurred On Intersecting Road Mile Marker Interchange • 2 <u>V2</u> Direction / If not at Intersection of leet from Nearest Intersecting Road Mile Mark Driver's Name (Last First MI) Driver's Name (Last First MI) D D 10 Address (Street City, State, Zip 2 Address (Street, City State, Zip 33/F\_Y Date of Birth 43 Apparent Phys Stat (enter no ) Arrested? Apparent Phys Stat (enter no ) DRIVER Date of Birth  $\overline{\mathbf{m}}$ Yes No Yes 1 Lic Type Restr Lic SI Driver's License No Lic Type LIC/SI Restr AB IN 00 Color Veh Yr Make 12 /(su) Color Veh Yr Make Model M GRY Cher 4 Lic Yr Veh Type License No Lic State Ven Type LIC YI License No Lic State 91 ٩ enter no l IN 131 Veh Use Speed Limit Fuel Tax No Veh Use (enter no ) Speed Limit Fuel Tax 1 (enter no ) ष्ठ No Occupants No Axies Transporting Direction of Fire? Direction of No Occupant Transporting Hazardous Mat Fire No Aules Travel Travel V2 VEHICLE : 14 Yes Yes No Yes ☐ No เว Towed To VZ. Towed By Registered Owner's Name (Last, First, MI) Registered Owner's Name (Last, First, MI) न्डि SAME Address (Street, City State Zip) 2 Address (Street, Cyty State Zip) Registered Owner's Name (Last, First, MI) Registered Owner's Name (Last, First, MI) 15A 2 b Address (Street, City, State, Zip) Address/(Street, City, State, Zip) TRAILER License No. Lic Si Year LIC Y License No Make Lic. St. Lic. Yr INITIAL IMPACT Areas Damaged (Multiples) Direction Street/Highw Arrested Apperent Phys. Stat. Jenter no.) 3 3 4 6 g 10 - Undercarriage 3 \_\_ Yes 2/0 DAMAGE EST ) 6 9 6 1 - Trailer What was pedestrian doing before acc was pedestrian doing before accident?

Not in roseway
Standing in roseway
Playing in roseway
Playing in roseway
Playing in roseway
Playing or working on vehicle
Other working or Joadway
Walking in puddway against traffic
Getting or or off school bus
Crossing or entering not at intersection
Crossing or entering at intersection
Other Neiz 1 8 7 12 - None 12 PEDESTRIAN OTHER PROPERTY (INCLUDE CARGO) Damage Est Name of Object OWNER'S NAME AND ADDRESS Pedestrian Traffic Control? □ No (16 17 18 19 20 21 22 23 24 25 26 27 28 29 3 DRIVER OF VEHICLE 3 (as listed above) 0 DRIVER OF VEHICLE 2 (as listed above) Certifica to be true com

Diagram			
•			
			Indicate NORTI
•	• • •		
		•	
		•	
	SEE PAGE #		
	JEE WHELL	•	
e de la calega de l			
	• • • • • • • • • • • • • • • • • • • •		
			• • • • • • • • • • • • • • • • • • •
			************************
• • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • •		
			· · · · · · · · · · · · · · · · · · ·
			· · · · · · · · · · · · · · · · · · ·
		•• •• • • • • • • • • • • • • • • • • •	
NA NA	RRATIVE (Refer to \	Shiele by Alumbert	
<del></del>			
20. A 1 . 1.2 11			
I SUITE LICHT LATE FOR LOC DIS LATE		الماد الماد والماد الماد	0 mar 11.1
soud light was red for NIS traffic		Ar. when vehicle	2 ranthe red light
		Av. when vehicle	2 ranthe red light
starting the chain reaction accident		Av. when vehicle	2 routhe red light
		Av. when Uthicle	2 ronthe red light
		A. when whicle	2 ronthe red light
		A. when whicle	2 ronthe red light
		Av. when we hicle "	2 ronthe red light
		Av. when vehicle	2 ranthe red light
		Av. when whicle	2 ranthe red light
		Av. when whicle	2 ranthe red light
		Av. when vehicle	2 ranthe red light
		Ar. when vehicle	2 ronthe red light
		Av. when vehicle	2 ranthe red light
		Av. when vehicle	2 ranthe red light
		Av. when vehicle "	2 ranthe red light
		Av. when vehicle "	2 ranthe red light
		Av. when vehicle "	2 ranthe red light
		Av. when vehicle "	2 ranthe red light
		Av. when vehicle "	2 ranthe red light
starting the chain reaction accident		Av. when vehicle "	2 ranthe red light
starting the chain reaction accident		A. when vehicle "	2 ranthe red light
starting the chain reaction accident		Av. when vehicle "	2 ranthe red light
starting the chain reaction accident			2 ranthe red light
starting the chain reaction accident		D2 Insured By	2 ranthe red light
starting the chain reaction accident			2 ranthe red light
Starting the chain reaction accident			2 ranthe red light
Starting the chain reaction accident			
Other Participant(s) Name, Address (etc.)  Name of Witness No. 1			2 ranthe red light  Location at Time of Accident
Starting the Chain reaction accident  Of Insured By Other Participant(s) Name, Address (etc.)			Location at Time of Accident
Of Insured By Other Participant(s) Name, Address (etc.) Name of Witness No. 2	Address Address	D2 Insured By	
Other Participant(s) Name, Address (etc.)  Name of Witness No. 1	Address		Location at Time of Accident
Starting the chain reaction accident  Distributed By Other Participantis) Name, Address (etc.)  Name of Witness No. 2  Name of Person Arressed	Address Address I.C. Code(s)	D2 Insured By	Location at Time of Accident Location at Time of Accident I.C. Code(a)
Starting the chain reaction accident  Distributed By Other Participantis) Name, Address (etc.)  Name of Witness No. 2  Name of Person Arressed	Address Address	D2 Insured By  Name of Person Arrested	Location at Time of Accident Location at Time of Accident I.C. Code(s)
Starting the chain reaction accident  Distributed By Other Participantis) Name, Address (etc.)  Name of Witness No. 2  Name of Person Arressed	Address Address I.C. Code(s) on of Investigation	D2 Insured By  Mame of Person Arrested	Location at Time of Accident  Location at Time of Accident  I.C. Code(a)  stigation Complete Photos Taken  Ves No
Starting the chain reaction accident  Distributed By Other Participantis) Name, Address (etc.)  Name of Witness No. 2  Name of Person Arressed	Address Address I.C. Code(s)	D2 Insured By  Name of Person Arrested	Location at Time of Accident  Location at Time of Accident  I.C. Code(s)  stigation Complete  Photos Token No Date of Report
Other Person Arrested  Name of Witness No. 2  Name of Person Arrested  Time Notified AM Time Arrived AM Other Location AM  Time Notified AM Time Arrived AM Other Location AM  The Manual AM Other Location AM AM  The Manual AM Other Location AM AM  The Manual AM Other Location AM  The Manual AM Oth	Address Address I.C. Code(s) on of Investigation I.D. No.	D2 Insured By  Name of Person Arrested  Inve	Location at Time of Accident  Location at Time of Accident  I.C. Code(a)  stigation Complete  Photos Taken  Ves No Yes No  Date of Report
Of Insured By  Other Participant(s) Name, Address (etc.)  Name of Witness No. 2  Name of Person Arressed  Time Notified AM Time Arrived AM Other Location Amisting Officer	Address  Address  I.C. Code(s)  on of Investigation  I.D. No.	D2 Insured By  Mame of Person Arrested	Location at Time of Accident  Location at Time of Accident  Location at Time of Accident  I.C. Code(s)  stigation Complete  Yes No Potos Taken  Yes No Date of Report  From 9 1
Of Insured By  Other Participant(s) Name, Address (etc.)  Name of Witness No. 2  Name of Person Arressed  Time Notified AM Time Arrived AM Other Location Amisting Officer	Address Address I.C. Code(s) on of Investigation I.D. No.	D2 Insured By  Name of Person Arrested  Inve	Location at Time of Accident  Location at Time of Accident  I.C. Code(a)  Itigation Complete  Photos Taken  No  Date of Report





# POLICE DEPARTMENT CITY OF I

1992

To Whom It May Concern,

1992, I received a call in my office of the for the Police Department from She stated she was involved in an accident on 1992 at Street and Avenue, and would like to change the narrative.

Ms. is deaf, and somewhere in the translation of her statement, she informed me that the statement of the accident report was not correct and she would like her version be placed on the report for the record.

Ms. stated to me that she was north bound on Avenue stopped at **Avenue** Street. The light changed to green for her, but because she wanted to turn left onto west bound . Street, she waited for the south bound traffic to clear the intersection. Before the south bound vehicle (1978 Ford Fairmont) was able to clear the intersection on the green light, a white Corvette, which was east bound on Street ran into the right side of the Fairmont knocking it into Ms vehicle. wanted to stress that the light was green for north/south bound Avenue and red for east/west bound Street at the time of the accident.

\*\*\*\* This addition will be attached to the original accident report at the

Respectfully submitted,

Accident Investigation force Dept Deaf Relations of Epile 22 true copy Torice Dept s Police Department


BEST AVAILABLE COPY




Memorandum

Subject:

DP92-011: Petition for Defect Investigation
Concerning Alleged Failure of Air Bag Deployment in
Certain GM Chevrolet Corvette Vehicles



From:





#### **BASIS**:

Ms. Petitioned the National Highway Traffic Safety Administration (NHTSA) by letter requesting that a defect investigation be conducted concerning alleged failure of the air bag system to deploy in an accident on 1990 Chevrolet Corvette vehicles.

# **ALLEGED PROBLEM AND SAFETY-RELATED CONSEQUENCES:**

The petitioner alleged that, while driving at 35 miles per hour (mph), she struck a 1972 Ford Fairmont broadside and the air bag in her Corvette did not deploy. The petitioner described the injuries she received in this crash. Further, she stated that following the accident, turning on the power to the ignition of the Corvette caused an indicator lamp to illuminate indicating that the air bag had failed.

# **DESCRIPTION OF COMPONENT OR VEHICLE SYSTEM:**

The 1990 Corvette is equipped with a Supplemental Inflatable Restraint (SIR) system. This system supplements the driver's safety belt to provide occupant crash protection by deploying an air bag from the center of the steering wheel during a moderate to severe vehicle impact. The SIR system consists of two front sensors attached to the vehicle which assess the severity of a crash, a diagnostic energy reserve module (DERM) with an arming sensor (a sensor that closes in a significant crash and "arms" the air bag system for deployment), an inflator module including air bag, gas generator and inflator squib, an "INFL REST" indicator lamp in the vehicle's visually-displayed Driver Information Center, a SIR coil assembly, front bumper impact bar/skid bar assembly, and wiring harness.



The SIR system is activated only when the crash is of sufficient severity such that at least one front discriminating sensor and the DERM's arming sensor have closed simultaneously. This is required to prevent unintentional or unnecessary deployment of the air bag, that is, deployment in crashes in which the supplemental restraint of the air bag is not necessary to ensure occupant crash protection. The air bag deploys when the vehicle is involved in a significant frontal collision, up to 30 degrees, both right and left, off the centerline of the vehicle.

The system status indicator lamp in the Driver Information Center is designed to illuminated for 5 seconds after the ignition is turned "ON," with the message "INFL REST." This indicates that the SIR system is operational and functioning properly. A lamp that does not illuminate or does not go out after 5 seconds is indicative that a problem may exist.

#### **VEHICLES INVOLVED:**

vehicles equipped with the SIR system. The production numbers for each model year are: 1990--21,985; 1991--18,367; and 1992--16,869. These vehicles are hereafter referred to as subject vehicles.

#### **COMPLAINT REPORTS:**

Analysis of the Office of Defects Investigation (ODI) computer records for all 1989 through 1992 model year vehicles equipped with a driver side air bag, revealed that there are two other complaint reports alleging air bag non-deployment and three reports concerning SIR warning lamp activation on the Corvette vehicles. Analysis of ODI's database of owner complaints shows that the complaint rate for air bag non-deployment in the subject vehicles (3.5 per 100,000 vehicles produced) is lower than the complaint rate for air bag non-deployment in all other vehicles equipped with air bags (5.3 per 100,000 vehicles produced). One of the two Corvette complaints alleged delay of air bag deployment rather than non-deployment. This additional information was obtained from the owner by phone.

According to its letter of has 1992, has received 34 owner complaints alleging failure of the air bag to deploy properly and 68 complaint reports concerning SIR warning lamp activation in the subject vehicles.

Analyses of the reports showed that many of the incidents alleging failure of the air bag to deploy apparently involved impacts that were either below the threshold of force necessary for air bag deployment or outside the area of the vehicle where frontal impact is designed to trigger deployment.

In addition, ODI's review of all complaint and accident reports on the subject vehicles concerning alleged air bag deployment failure revealed that no apparent mechanical and electrical component or device failure has been observed or identified which may cause air bag non-deployment. GM reported that it has inspected 24 complaint subject vehicles (70.1 percent of 34 complaint subject vehicles) and was unable to locate component failure which could cause air bag non-deployment.

## **MANUFACTURER'S EVALUATION:**

In its letter of 1992, GM reported its evaluation of alleged air bag non-deployment on the subject vehicles. It stated in part that:

"The air bag in the 1990-1992 Corvette is intended to inflate only on moderate to severe frontal and front angle impacts. Examples of impact conditions approximately equivalent to the inflation threshold are: (1) striking a fixed barrier at zero degrees at a speed of 12 miles per hour; (2) striking a fixed barrier at thirty degrees at a speed of 20 miles per hour; or (3) squarely striking, with complete overlap, a stopped vehicle of similar mass at a speed of 24 miles per hour.

"GM intends its air bags to inflate only in moderate to severe frontal crashes for at least the following reasons: (1) air bags are designed principally to reduce the likelihood of serious and life threatening injury, and they are not designed to prevent minor injuries; (2) air bags are expensive to repair and costs associated with repairing air bags are ultimately borne by the consumer; (3) air bags can cause serious or even fatal injury to occupants who are up against or very close to the air bag module at the moment when the air bag inflates; and (4) higher deployment thresholds reduce the risk of an air bag inflating in non-collision situations.

"The SIR system was first introduced in Corvettes in the 1990 model year. Accordingly, many customers were unfamiliar with these design considerations, which explains the volume of questions GM has received relating to the proper performance of air bags."

Additionally, GM conducted an Engineering Assessment on the petitioner's Corvette as shown in Attachment I. Based on a review of the photographs taken of the Corvette, GM concluded that the subject Corvette experienced an impact that was below the intended deployment threshold of the SIR system. Also, based on GM's experience with the 1990 SIR system, and the narrative report submitted by the GM representative who inspected the Corvette, GM concluded that the warning lamp illumination was the result of SIR system disassembly following the crash.

#### ANALYSIS:

Analysis of the available information revealed the following:

- 1. GM provided NHTSA with photographs of the subject crash-involved vehicle, as well as a police accident report concerning the crash (Attachment II). The agency's review of the photographs of the petitioner's crash-involved Corvette and the accident report revealed that the impact speed and the direction of the impact experienced by the petitioner's vehicle were not sufficient to cause air bag deployment. This conclusion is based on the following facts. First, a significant portion of the damage occurred to the left door, left quarter panel, and the hood, which shifted sideways due to a lateral impact force (from left to right). The principal direction of crash forces was outside the 30 degrees of frontal range. Second, the photographs indicate the severity of the crash impact was substantially below the deployment threshold of the SIR. In response to NHTSA's request for an engineering assessment of the crash, GM pointed out that the "deployment threshold speed for impacts into objects that absorb or convert energy (such as another vehicle) is higher than for rigid barrier impacts." Thus, the threshold speed for deployment in a vehicle-to-vehicle crash similar to the petitioner's would have been substantially above the 12 mph deployment threshold design speed in a frontal impact with a rigid barrier. Finally, the accident damage to the Corvette is much less than that which occurs in the angle impact SIR threshold validation test conducted by GM. Thus, all available information indicate that the petitioner's crash was of a severity less than that required to deploy the SIR.
- 2. The continuing illumination of the air bag warning lamp in the petitioner's vehicle after the accident appears to be the result of SIR system disassembly by the GM dealership technician, who inspected the petitioner's vehicle. The SIR system was disassembled to remove the DERM for further evaluation. The petitioner stated that the air bag warning lamp was not illuminating continuously or indicating any system malfunction before the accident.
- 3. NHTSA's review of GM's 34 owner complaints on Corvette vehicles reported to GM concluded that many of the incidents alleging failure of the air bag to deploy apparently involved impacts that were either below the threshold of force necessary for air bag deployment or the impact angle was more than 30 degrees off the centerline of the vehicle.
- 4. A review of the 68 owner complaint reports to GM pertaining to continuing illumination of the air bag warning lamp revealed the following: (1) no single failed component was identified causing the problem trend; (2) there is no indication that the air bag warning lamp fails to come on when the SIR system is malfunctioning; and (3) there is no complaint pertaining to intermittent air bag lamp "on" and "off"

problems during normal operation of the subject vehicles. Based on the above, it appears that the type of continuing illumination of the air bag warning lamp in the subject vehicles does not represent unreasonable risk to motor vehicle safety because illumination warns the driver of a potential malfunction of the SIR system as designed. The car can be safely driven (driver using the safety belts) to a GM dealer to identify whether a problem exists and get it corrected.

5. Based on owner information provided to NHTSA, the complaint rate (complaints per 100,000 vehicles produced) on the subject vehicles concerning non-deployment of the air bag is lower than the average for other vehicles equipped with an air bag.

#### **CONCLUSION:**

Based on the information available, no defect has been observed and identified in the subject vehicles for any component or device which could cause air bag non-deployment in crashes where the air bags should deploy to provide crash protection. Analysis of the available information indicates low complaint rates for the subject vehicles. The reports of illumination of the air bag warning lamp in the subject vehicles does not indicate the presence of an unreasonable risk to motor vehicle safety. Based on all available information, there are insufficient data to indicate a safety-related defect exists. Hence, further expenditure of resources to establish a safety-related defect is not warranted.

#### **RECOMMENDATION:**

It is recommended that the petition be denied.

Attachments



#### ENGINEERING ASSESSMENT

# 1990 CORVETTE

#### Alleged failure to deploy

Review of the photographs taken by the GM representative indicates that the frontal impact speed experienced by the vehicle was not sufficient to cause SIR deployment.

The 1990 Corvette design was validated for SIR threshold with a 12.5 mph 0 degree frontal barrier and a 20.4 mph 30 degree left angle barrier (reference attached photos). SIR deployment threshold speed for impacts into objects that absorb or convert energy (such as another vehicle) is higher than for rigid barrier impacts.

The 1990 Corvette SIR system is designed to deploy in response to impacts within 30 degrees of frontal and is not expected to deploy a result of lateral impacts. While it doesn't increase the chance for SIR deployment, an impact with a lateral as well as longitudinal input to the vehicle does create more damage to the front of the vehicle than a purely longitudinal impact because the hood is shifted sideways.

It appears that a significant portion of the damage on the subject Corvette was the result of lateral impact force (from left to right). This conclusion is reached based on the sideways shift of the hood and the damage to the left door and quarter panel, which likely occurred when the subject Corvette spun to the right and slapped the side of the struck vehicle which was moving from left to right across the front of the Corvette.

The type of impact experienced by the subject Corvette is more closely duplicated by an angle barrier impact rather than a frontal barrier impact. The damage to the subject Corvette is much less than that seen in the angle impact threshold validation test. Based on the photographic information available, it is concluded that the subject Corvette experienced an impact that was below the intended deployment threshold of the SIR system.

### Alleged problem indicated by the air bag warning light

Based on experience with the 1990 SIR system and the narrative report by the GM representative that viewed the subject Corvette, it is concluded that the warning lamp illumination was the result of SIR system disassembly following the crash.

The SIR diagnostic module (DERM) in the 1990 Corvette is not compatible with the "TECH 1" read out tool used in GM dealerships. Having been unsuccessful in employing the "Tech 1" to read the DERM, it appears that the dealership technician gained access to

ATTACHMENT I

the DERM for removal for further evaluation. The Corvette Service Manual instructs the technician to disconnect the base of the steering column to isolate the air bag module prior to working on or around the DERM. If the ignition is turned on with the DERM and/or base of the column disconnected, the air bag warning lamp will turn on to indicate that the SIR system needs service.

The illumination of the warning lamp does not prove that a problem existed at the time of the crash, only that a problem existed at the time the light was observed. The narrative seems to indicate that the disconnection of a SIR system component occurred at the dealership and not as a result of the crash.

1978 FORD ESCORT

OTHER VEHICLE SPEED ESTIMATE 35 MPH BY WHOM OWNER

MAME OF OWNER

OWNER ADDRESS

NAME OF DRIVER SAME

DRIVER ADDRESS PHONE

EXTENT OF DAMAGE CAMAGE, TO RT SIDE OF VEHICLE

NO ECCILY INJURY INFORMATION ENTERED FOR THIS CASE

HOW, WHEN, AND BY WHOM WAS BRANCH NOTIFIED OF INCIDENT? BY LETTER

LOCATION OF INCIDENT (DESIGNATE EXACT LOCATION)
INTERSECTION OF

KIND OF ROAD GRAVEL CONCRETE X ASPHALT CRUSHED ROCK DIRT CONDITION OF ROAD .ET X DRY ICY CTHER KIND OF SHOULDER CCNCRETE GRAVEL X ASPHALT CRUSHED ROCK DIRT CONDITION OF SHOULDER WET X DRY ICY OTHER NATURE OF WEATHER VISION CESTRUCTION (IF ANY DESCRIBE)

NONE

NAME AND ADDRESS OF CEALER WHO TOWED (INCLUDE TOW DRIVER'S NAME), STORED AND/OR PROVIDED TEMPCRARY SERVICE TO DAMAGED VEHICLE TOWING SERVICE

UNK

WHERE CAN VEHICLE BE SEEN? CHEVROLET, TO THE TRANSPORT OF THE PROPERTY OF THE

DID VEHICLE TURN CVER? YES X NO VEHICLE SPEED ESTIMATE MPH SOURCE OF SPEED ESTIMATE

POSTED SPEED LIMIT 35 BRAND AND SIZE TIRES P275/40 ZR17 GOCCYEAR CONDITION R.F. X SOOD POOR FLAT X GOOD POOR R.R. FLAT OF TIRES: L.F. COOD X POOR FLAT L.R. C009 X PCOR FLAT OTHER (TRUCK OR SPARE). T155

DID YOUR SEARCH OF THE VEHICLE SERVICE HISTORY PRODUCE SERVICE REPAIR ORDERS? YES X NO

POLICE REPORT ATTACHED? X YES NO IF "NO", WHAT STATION OR OFFICER MADE REPORT

NAMES AND ADDRESSES OF WITNESSES NO WITNESSES

WERE PHOTOS TAKEN? > YES NO IF "YES" HOW MANY 13 BY WHOM-NAME AND ADDRESS

NOTE: FURNISH PHOTOS TO SERVICE WITH THIS FORM. FORWARD NEGATIVES TO CENTRAL (HOME) OFFICE.

G 1241

## BUTOMOTIVE DIVISION COMPLETING REPORT CHEVROLET MOTOR DIVISION REPORT OF PRELIMINARY INVESTIGATION



DESIGNATION CODE

SERICUS INCIDENTS SHOULD BE IMMEDIATELY REPORTED BY TELEPHONE TO NEAREST OFFI

DATE OF INCIDENT 792 HOUR

\*\*\*\*\*\*\*\*\* I OWNER - CLAIMANT \*\*\*\*

NAME OF OWNER 100RESS.

ZIP

PHONE NO.

NAME OF DRIVER ADDRESS

STATE IN

STATE IN

ZIP AND BE

PHONE NO. 3

AGE

AGE

NAME OF CLAIMANT SAME

**ADDRESS** 

CITY STATE

LANE

ZIP

PHONE NO.

AGE

\*\*\*\*\*\*\*\*\*\*\* II VEHICLE \*\*\*\*\*\*\*\*

MAKE CHEVROLET TRANS AUTO DATE OF DEL.

VIN 16177338 AXLE NEW+USED OR DEMO U

YEAR 90 MODEL CORVETTE ENGINE 5.7

LICENSE NO.

MILEAGE 03800 STATE I

DEALER

ADDRESS

CITY

STATE

ZIP 000000000

INSPECTION STATION NBR.

INSPECTION STICKER NC.

EXPIRATION DATE / / PRINCIPLE USES OF VEHICLE

PLEASURE

SPECIAL VEHICLE FEATURES OR EQUIPMENT

NONE

IF VEHICLE IS A TRUCK, STATE GROSS PAY LOAD AND LOCATION AND DESCRIPTION OF LOAD AT TIME OF INCIDENT.

MATURE AND EXTENT OF CAMAGES TO VEHICLE. DAMAGED HOOD FRONT SUMPER, RT DOOR, LF DOOR & LF GUARTER LF ROCKER

ESTIMATE COST OF REPAIR (ATTACH COPY OF ESTIMATE) 3500 IS VEHICLE SUBJECT TO ANY PRODUCT CAMPAIGN(S) YES NO IF "YES" IDENTIFY CAPPAIGN(S) WAS CAMPAIGN PERFORMED? NO

\* III PROPERTY DAMAGE \*\*\*\*\*\*\*\*\*\*\*\*\*\*

WAS ANOTHER VEHICLE INVOLVED? Y STATE MAKE AND MODEL OF VEHICLE

ATTACHMENT I

NAME OF ROYAL REPRESENTATIVE, IF PRESENT, AT THE INVESTIGATION NONE PRESENT

CRIVER'S DESCRIPTION AS TO HOW INCIDENT HAPPENED AND HIS STATEMENT OF CAUSE. VEHICLE DRIVEN BY THE VEHICLE IN LEFT FRONT FENDER AREA. SHE STATED SHE WAS NOT ABLE TO AVOID COLLISION.

CID YOU PERSONALLY SPEAK WITH DRIVER? YES X NO IF "NO", GIVE SOURCE OF DRIVER"S DESCRIPTION. ATTORNEY INVOLVED WAS VEHICLE INSPECTED? X YES NO IF "YES" IDENTIFY ALL PARTIES WHAT VEHICLE COMPONENTS ARE ALLEGEDLY DEFECTIVE? S.I.R. SYSTEM

WHO MADE ALLEGATION OF DEFECT? OWNER

IF THE ALLEGED DEFECTIVE PART HAS BEEN REMOVED FROM THE VEHICLE, INDICATE EXAMPART(S), PRESENT LOCATION AND WHO IS CUSTODIAN.

INFORMATION FROM FURTHER INVESTIGATION OF INCIDENT, INCLUDING EXAMINATION OF VEHICLE AND SCENE OF INCIDENT. VEHICLE WAS HIT ON LEFT FRONT FENDER/HOOD AREA, PHYSICAL INSPECTION SHOWS ONLY FIBERGLASS DAMAGE, THERE DOESN'T SEEM TO BE ANY NOTICEABLE FRAME DAMAGE.

GENERAL COMMENTS THIS VEHICLE SUPPOSECLY RAN RED LIGHT CAUSING ACCIDENT WITH REPORT FROM BCDY SHOP WAS THIS DRIVER IS DEAF AND INFO TAKEN AT TIME OF ACCIDENT WAS INTERPRETED INCORRECTLY. THE LAWYER INVOLVED REQUESTED THAT CHEVRCLET REPLACE VEHICLE AS CUSTOMER DIDN'T FEEL SECURE IN DRIVING VEHICLE BECAUSE OF THE CONCERN SHE HAD BECAUSE THE AIR BAG DID NOT DEPLOY. ON I MET WITH ATTY, TO INSPECT VEHICLE SELONGING TO A 1990 CORVETTE. THE VEHICLE HAD BEEN INVOLVED IN AN ACCIDENT WITH ANOTHER VEHICLE. THE VEHICLE HAD PHYSICAL DAMAGE TO THE FIBERGLASS ON THE LEFT FRONT FENDER, HODD, LEFT FRONT DOOR (DAMAGED BY HOOD BEING PUSHED INTO DOOR). THE VEHICLE HAD BEEN HIT ON LEFT FRONT FENDER AREA. THERE WAS NO VISIBLE EVIDENCE OF FRAME DAMAGE TO VEHICLE. WE WERE UNABLE TO RAISE THE HOOD, HER EATTERY WAS DRAINED, THERE WAS SOME WIRING PROBLEMS AT ECH WHICH HAD BEEN KNOCKED FROM ITS MOUNT. WE WERE ABLE TO LIFE LEFT CORNER OF HOOD AND CONNECTED BATTERY CHARGER (CONT'D) HOW AND WHEN WAS MATTER LEFT WITH CLAIMANT? ATTY WAS INFORMED WE WOULD NOT PARTICIPATE IN REPLACEMENT OF THE VEH, WE WOULD INSPECT FOR THE CONCERN

DATE OF INVESTIGATION PRINTED NAME

CATE SIGNED \_\_\_\_\_\_ SIGNED

DIVISIONAL REPRESENTATIVE COMPLETING INVESTIGATION -







Comment continued from Screen 9

to recharge battery. We were not able to retrieve data from Derm, as it was a white unit and we are not able to retrieve with Tech 1, technicians were attempting to remove when this was discovered. The ignition was turned on with derm disconnected a code of 35 was picked up from the Dash System for the SIR, a continuing (code) fault, no other codes were evident.

The attorney would not allow the dealer to do an estimate of repair cost. The attorney was informed that we would not participate in replacement of the vehicle, a request he made because he stated his client had lost confidence in the SIR System. The attorney was informed that the vehicle was not involved in the type of accident that would have deployed the air bag.



Please note: As per comments from the Mgr. at the Chevrolet and from conversation with the police reports attached are incorrect, the information from driver, the incorrect. The deaf and information she gave was misinterpreted by the officer. In the states that they have signed affidavits from Mrs. The stating ran light causing accident.

		-	•	_		EEICEB'S	STAN	DARD ACC	'IDE	VT DEDG						ILABL		)PY	
<u> </u>	3	- 3	ì	S	ale form 23558R	2/Sicck 302	JIAN	DAND ACC	יוטבו	NI HEPC	ואי	Accido	ni ! D			JSE O		ida —	J
19.	1.4			<i>/</i> M	ail lo						Į		_4				Carrier S		厂
18 A		Onie Onie		CCIO	1"4"z	Day o	West	Actual Local 1	ime	₹ AN	No Ven	Wolor HCIES	140	Inju	<b>ec</b>	No De	-	No Trailers	)
77		Cov	Ny .	-			Tod	mship				City/To	m or I	<b>77.012</b>	si City	/Jown	T		
<b>₹</b>	CATION					Private [-]	OND	Distance and Di					# #						╢
2			140		d Occurred On	Private 17	Olher	Mile	S North	Mersecune Ro	Miles S		/Imerc		Hes Es	st _		_ Miles West	
V2,	E	II no	1 at 6	rteri	ection someon	Ovection	Neare	rsi intersecting Ro	120				<del></del>		$\dashv$				12
	•				(Last Seat MI)			periodicinations are		Orwer's Name	(Last.	First, Mi	)		!				
الم										197		8000							1 2
Z		**			CASING.					ASSIGN TOP	a de se se la							4002	14
77 V2	5	Stat (	enu	Phy r no	SUL S	3 S	1 64	Arrested?		Apparent Phy Stal (enter no	:  Se	u, (C	C-1111.	Berth DAY	Kadhada.			Arreside?	
	IDAI	Ome	7'8 L		No.		LIC TY		60	Orner's Licen	es No.	A STATE OF THE PARTY OF THE PAR				المرا	77	Lic. SI Restr.	
3		Coro			Ven Yr Ma	-	Model	Name		Color	Ve	n Yr. A				Mode	I Nan		(12)
'		AN	Typ			Chev.	loru	LE SUM	┨	White			For					Les State	بالا
		Veh I		<u>,,                                   </u>	91	Figur 185 M		. 12		(enter (io )	•	11	10	666				N.	[3]
9 V5 V9		ente	r no	,	35	7031 132 140	/			tenter no /	Sc	and Lin	m   F.	rel Ta	z No				
1 VZ		Drec Trave	•	<del>8</del> E	No.Occupant	Sur.	1	Transporting Mazardous Mai Ves (- No		Direction of Travel	N	000.0		70,		Auto	Tra	neporting ardous Mat Yes P No	
<b>ण्ड</b>	Ę,	ALC:	4.7				2		78	Towas Jo	Sec. 1	•		To		<u> </u>	<u>. بر</u>	Yes B No	儿
	VE	-			mer's Name (Lasi	Ferst, Mi)	/		VEHI	Registered O	omer's P	tame (L	est, Fe				2010111		┨ <u></u>
^3 ^, /	٠ -			1E	ri. Criy. State, Zip	,			4 🖪	Address (Stre		State :	Prot			,			
لثا	4									~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	<del>ы. Сіў</del>	. 3454. 4	. <del></del>						بار
		-494	iere	a 0-	mer's Name (Las	, Fust MI)	•	`		Registered O	wner's f	vame (L	ast, Fe	31, MI					154
<u></u>		Addn	P36 (	Sve	H. Cay, State. 340	13				Address (Stre	et. City.	. State. i	Zip)	/		•			卜
	TRA	Licen	***	40		Make	Year	LIC SI LIC. YO	TRAI	License No.			/"	ske		Year	L	c. St. Le. Yr.	j
		VI	7	<b>V</b> 7		To To Fig	_		74	V 50	Orre	chen S	reev	-gn-w	Y	Arrestes	7 4	poorene Prije.	<b>`</b>
	DAMAGENALINE	0A4 V}	446	E EST	1 200		- Traver		\$		Wh	l was po	desiru	n do	<u>ا</u>	Yes No lore soc	and a	Enter No.	$\mathbf{I}$
	GE,			<u> </u>	70-12	A PROPERTY		CMCO)		~ 3	PEDESTRIAN	2 Store		107 1005- 105-1	7/				1
		Nem	_	Obje		OWNERS NA		DORESS		Prope Est to Grant)	EST	5 Ome	~	72		oracto y trollec	_		
		مين	ь		Digi. o	France	وحامتاره	^	+	<del>-  </del>		8 Gen 9 Gen 10 Ciga				bes St onesis			
									1		£	0	***	-	~ .	******	•	·	]
	0	7 18	18	19				20 .				Pedesin 21	22 2	_			7 (c)	□ No	{
	泛	3	1	ı		DRIVER	OF VEH	ICLE 1 (as list	ed ab	ove)		"		7	1			<del></del>	1
	(3) (3)	3	1	1		DRIVER	OF VEH	ICLE 2 (as list	ed ab	ove)		11	7	+			H		1
				7										$\dagger$		1	П		1
		V					/	4	The Manager	n en	olica	Deal	$  \uparrow  $	†		+	П		1
	V					$\overline{}$		1.51	Čerti	fied to be				+	H	1			1

	Æ					· · ·		. ۔ ۔		~~~	~~~		ייו חבר	UH	1 L			OFFIC	E US	E 0N:	_ Y		)
				_	Form 4		Sicc's			_					• •	ccide	110	OFFIC Non-				and the same	
9				Mail	10				CIDER	gecord	Section						4						12
3				ccident			l Oe v	ol Wa	A STATE OF THE PARTY OF THE PAR	Actual	Local Ti						1850						ر ــــــــــــــــــــــــــــــــــــ
K	51	- CE:		A COLORA	N 1	42				-		<u></u>		اسو	No M	25 25	اس	O Injured	١.	Oeso	'	No Trailers	}
// /	7.5.1	Con	~			72		2.2	Town	1700	and the same	<u> </u>	1	PM	10	3		teares!		<u>z</u>		$\boldsymbol{z}$	
77	7	3500							200				1		_	1			700		1		11 1
احتما	20	100	شن ر⊶	former.	20015 7	Proc	×u,		المحالات	Distance	and Dw	tchan	From Corp	CVAIR I	- FINE			E 3.3.		_			ا
	CATIO			<b>.</b> [		-	•		μ <b>Α</b> 			Nort								1 T			
(I)	Ö				Sechanda		10014		<del>T</del>			_	Mersecting		es Sou		INDIE		s East	_=	==	Miles West	1_
2) V)		4	2.30.3	محتهز كالر					i			le:	. •	1000					- 1				
12 L		11 00	1 21 1	A COLOR	NON. MUS	Oer -	Directio	~/	Neares	I Interse	cing Ros	d/Mil	Contract Contract		راز محمد مرد اسا	E.T.	-1		+				12
	U	<b>a</b> #	et Irc	<b>&gt;</b>			//		1										- 1				1
G	4	Dr=	H S A	ume (l	asi, for	, MI)			175				Ormer's No	me (L	asi, fu	SL MI	)						<b>\</b>
<b>₽</b> , _		8	diament.					100															100
W-		400	914	Syget,	CHY. SI	14. Zo			de california de			1 📂	Address (S	weet.	Cay. S	love.	Žφ						12
	12	٠			-				<u> </u>														
7	E R			H (0)	₩/	Date			YEAR	Arresi D'ye			Apparent f Stat (enter	200	Sex		Date of	Birth	. 41	48		rresied?	
42	_ ≥			1	1 /	-	<u> </u>	6	446	No.		ORIVER	<u> </u>	- •								Yes/ No	]
	D.	0	7 8 4		No.		<b>1</b>		LE IYE		1 .	ő	Dimer's La	207124	No.				ľ	ue Ty	<b>Pe</b> L	C/SI Restr.	
7				·	Ven	i sec			Model N	110	IAD		Color		To	- I				10-0-0	$\mathcal{L}$		न
<b>V2</b>		Cox	RY	,	81		hev		I /	١٠ . /.	2 B	<b>)</b> (	<b>Land</b>		Agen	٧, ١	whet			Model /	75m	•	गिमा
1 1	5.1		Typ		Le V		nee No		LAW	10C/S	5°D		Ven Type		11.00	<del>,,  </del> ,		No		<del>/</del>	10	ic. State	النا
Ġ			H 70		9					1/1		2.	10Mer 10 )			''					٦	~ 544	ाउ
1 V V V V V V V V V V V V V V V V V V V		Ven	Use	<u> </u>	Speed	Lami	1700118	PNO 3	-	1		1 6	Ven Use		See	الله و	me  F	vel Tax	16.				1
2	6	1004	M 70	'' '		کد	1						(enter no )										النا
14	7	O-e		ol		0.0074	5:07	. No	Asies 1			1 🗆	Direction (	N	No	) (1)	- F		No /	Asies	Trans	poning	1_
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	-	Trav	H	N		1	17 No	1	-1 - 10	Tes	I No	E 2						Yes	}			rdous Met.	1
W-	HICE	Tow	<b>d,</b> [	10.00	Ler	اعكم		estal.	Sie Carlo								7		ed By				اللا
	H					TO	10.00			<u> </u>		VEHICL					/						.,
<u> </u>	>	Aeg:				e (Last	Fort Mi	)				>	Registered	0	er's No	7	ast, Fe	rat, MI)					न
				<u>⊕</u> ∿																			
V2/	- "	A00	ers.	(Street.	Cay. Su	He. Zo	)	/	القول ا	King.			Address (S	iveet.	94.1	late.	Z <sub>(P)</sub>						12
		Ŀ						_/	. 441.	-	<			_/	<u> </u>								•
•		200	2164.6	ig Own	# 5 PM	e (Lest	, Frist, Mi	'/			Ì	<b>)</b> [	Registered	9	er's No	ws (f	ast Pa	rst, skil)	•			1941 - 144 -	التقم
6		1==		(Steam)	Cuy. Su	10 7-0		<del>/     </del>				1 5	A 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	<u>/</u>	Ch. (	2000	7-01	•			<u> </u>		1542
	15	~~	433	19neer	Cay, Sc	M. 44	' /					E E	/ /		City. 3	Harry.	<b>4 (</b> )					·	
	A	رجه		<u> </u>			Make		Year	Lec Si	Le Yr	1	Ligarnee M				- 14	laka		rear	li io	. St. ILE. Yr	4
	E			-			7				,	) [	7	<b>U</b> .				-	- 1	-	-	. st.   CE. 17	• ]
		~	IAL I	MACT	Areas	Dàmec	ed (Mulle	D101)		ــــــــــــــــــــــــــــــــــــــ					Duce		iveet?	tighway	, IA	rested	71 AG	perent Phys.	
		7	2	7	7	3 4	الموا	FB .	Underca	mage :	.M3T	4	<b>~</b> √. ਜ਼ਰ							Yes	Sie	L Jeffler no.)	}
	-134 Pr	04	MAG	£ 151	7 四	7.	)•	⊡.	Trailer	į	2	•		١.٢	What	P	edesir	en down			Son P	Enter No.	1
	ů,	Y	ا د	13	1.12	79	لبجل.	<b>13</b> ·	None		ييدا.	9   1	<b>√</b> 🙃	2					, ,				1
							PROPE	RTY (E	NOLUDE	CARGO	)			PEDESTRIAN		701	ang in s		, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	EN:	•		<b>1</b> ·
	DAMAG	Nar	<b>~</b> 0	Object	<u> </u>		WHERS	NAME	AND AD	ORESS			luse cross	ESI	;	W	)			Mic			
	o				7									ED		Ger	~	- on -	<b>COLUMN</b>				
				_				_						4		Ç.	-	or off as orderer		-			1
	nie.		_													8	*	-	,	WASTI-O			_
	7	_			<u> </u>							$\angle$			<u> </u>	destr	en Tra	the Cor	Mrof*		Yes	□ No	)
	16	17 1	<u>•                                     </u>	19						20						21	22 2	23. 24.	25 20	27	28	29.	)
	2		Π,	J, $T$			DBIA	ER O	F VEHI	CLF4	(as liet	ed e	hovel				T.		٢		П		7
	Ę	The Control	4	<b>\</b>			J. 11 V				, (13)					1	И		恋爱				1
	E	9		H			DRIV	ER O	F VEHI	CLE 2	(as list	ed al	bove)		-	1	ΙJ	1	- <del> </del>		7		
	2	2	4	- -									,			1	$\Box$	$\perp$	1	4	$\perp$		4
•				11									•										1
	-	╀	+	++							-	apare di la	The state of the s			-	+-+		$\vdash \vdash$	+-+	4		4
		İİ									4			P	olice	ha	4.			1 1			
	$\vdash$	H	+	++								Ce	เปลี่ยย ((	110	ring	10.	70-1	-	<del>                                     </del>	╅┥	$\dashv$		┥
			1	1 1									11		1.110	40,	1		1 1	1	- 1		1

BEST AVAILABLE COPY Indicate NORTH SEE 846=41 NARRATIVE (Refer to Vehicle by Number) Hr. when vehicle "2 ran the red light starting the chain reaction accident. I.C. Code(s)

1.D. No.

a al

NEXT: HISTORY FILE INQUIRY PAGE 0: OF 02 (UPDATED THRU RUN # 2015 ) VEHICLE-ID-NUMBER C S-DLR DELDTE DEL EN AX TR REV CLM HIMILE FS 1G1YY3386L9 00040 00040 0 X8 R9 BK 4 5 26889 INUDER: 00040 SHIP-TO: 09134 INVDTE: INVNO: 1 FDIT: 2.3 OPTIONS: 41411001210010000160080600044050000070042000000000000000 FP: S EXT/MLS: REDUCTION-DTE: R-IND: GUNERSTATUS: EXT/DTE: T CLDLR RUN. RODATE RO-NO. O-DOC.-LN LAB-OP LN-TOT. MILES. D-A-C-R AUTH 1 B 09134 0025 062190 15488 176034 01 69.00 NEW VEHICLE INSPECTION 2 D 03398 1024 061091 39449 172004 01 J0200 188.98 22352 DEDUCT- 100.00 MANIFOLD/GASKET, INTAKE-REPLACE FC: 6C COMPONENT-INOPERATIVE PARTNO: 10148063 GSKT 3 D 09:41 1031 081291 75831 2280:4 01 J6396 34.86 26395 0 SOLENOID, VAC CONTROL EGR- REPLACE FC: 6C COMPONENT-INOPERATIVE PARTNO: G: 997195 SOLENOID FF::HELP PF4:MENU PF5:DESC PF6:PRINT PF8:FORWARD PF9:LAST PF10:LOGOFF RECORD FOUND HISTORY FILE INQUIRY VIN: 16177338 (CONTINUE) TOTAL CLAIMS: 5 PAGE 02 OF 02 T CLDLR RUN. RODATE RO-NO. O-DOC.-LN LAB-OP LN-TOT. MILES. D-A-C-R AUTH 4 D 09141 1031 081291 75831 228014 02 J6360 121.70 26395 CONTROLLER, ECM - REPLACE PARTNO ECM FC:EC COMPONENT-INOPERATIVE 5 D 03:4: 1034 082991 76309 247004 01 J5650 898.65

----- NO MORE CLAIMS FOR THIS VIN -----

PARTNO: MANAGE MPFI MULT

INJECTOR. FUEL - REPLACE

FC:3L OUT OF CALIBRATION

gen)	TOWING SERVICE ::
7	— 24 HOUR TOWING SERVICE —
	PHONE
1	DATE
ı	P.O. 1
ł	CUSTORER'S INTE
I	AGORESS
I	CASH CHE FROM CRAVE FROM
1	70 /·(·+· /s
1	MAKE OF CAR
Į	CRUPTE-JUNAL MOUNT 11.50
	LICENSE 5C (1)
I	13673 CRAME OUT 1000 55.00
	246 - S/V 6.50
1	AUTHORIZED BY DRIVER
	Mot Assponsible for Fire, Theft, or Oriver's Hegligence.
- {	

			Ģ O	0		<b>Z</b> '	O Acrossias •	A o growe	16   0		<b>်</b>	Ú		Bi	EST A	VAILA	ABLE COPY
					• • •					•	•	BODY		-			
		QUAN	PART NO & DESCRIPTI	ON	PRIC	Ε				E Maria de la companya  El Mar esse.	BOD 1	SHU	_	4			
. •														North	444	Concessor.	-
. :	.ن.		•									المحافظة المحافظة المحافظة المحافظة المحافظة المحافظة المحافظة المحافظة المحافظة المحافظة المحافظة المحافظة ال المحافظة المحافظة ال	The second	girery.	ed in		10 mm
•	<u> </u>	<u> </u>					Jan-	47 - Šlav		y and				arab	DIAN		
	<u> </u>				•			_		Ь,	· /	'Good pe	opie to			1035	with"
:.	•	·	, 10°- A	· · ·		:			<b>!</b>		IAG N	O.		DAIL			97
	; 👡	• •	***	• •	•		MAME A			)						-	
. 5	.÷.	=			••		ADDRESS								A CONTRACTOR OF THE PARTY OF TH	4	
•	٠٠٠		Jan 1994 Marie Marie	٠٠.				منسمان							(25°		
2.1	<b>!</b>		The first of the second		. •	٠.,	A	des Alle							A RE	5.	
•.** ÿ	<b>3</b> :	Pay?	rage the second contract		1.	•	0	w.	17	./					gi:		
		4	TO THE SECOND SECOND				YOUR !	<b>I</b>	L'H	<u> </u>	/ //	BRUE	COLON	<del>-</del>	<b></b>	: - ~ X	WWW.
•	٠`ي	14	THE STATE	•			CODE OR	16 -	_		<del></del>	1	WH	<u>':</u> -	=		<u> 30/4</u>
•	3.2	- **, **	÷ .	: • •				LØ. #	~			•					
( id.	•:	-		•			POURWA	<b>a c</b>	MPAIN	,							
20.00	:5%	~	- <b>- 2</b>				amm	WOLF !	-								
:	÷ .:										•						
	•		oth design a least to	•	• · .		ADDRESS	•									
	27						ADJUSTO	^				1	PHC	WE.			
/. "a\	÷.																
		.5					CUSTOMER PAYS										
	. 2						INSUR	ANC	E CC	). PA	YS	<del></del>					
-	-				•	_	SUPPL	.EMI	ENT	AMO	TNU						
	-			•	•		3				INSTA	UCTIONS				$\Rightarrow$	LABOR
3			The state of the second					AL	٢.						وردادد		<u> </u>
	57%			;	-									and the same	- 1		
.*.	16. 20	-		•		<u> </u>		CL	<u> </u>	A.	1 30	<i>G.</i>				4	
				• .	·												
	<u> </u>	<u> </u>						1 1			ALES		BODY				
	<u> </u>		<i>5</i> 4 • 5	<del> </del>	:	<u> </u>	<u> </u>	F	AMO	JWT	COST	DESC.	ACCT	NET.	AMOL	TM	COST
	• •			-		ļ. -	473	╀				TRUCK	470	╁┼			
		-		• .		<u> </u>	481	-				LASOR	471	<del>                                     </del>			
		<u>                                     </u>	to the saily sail of	•			<u> </u>				A1.55	CAR PARTS TRUCK	477	<u> -</u>			
	• • .	:	EVELET REPARE	TOTAL		<u> </u>		<del>, ,</del>	MAN	11 7 5	ALES	PARTS	478	1-			•
	ļ 	<u> </u>	<u> </u>				-472-	╀┤		-	•	SUS-REPAIR	476	-			
go.	3	- :1	Wheelow PO	. %	12	40	480	붜				GAS. OIL. GREASE PAINT &	491	-			
	_			-		Ĺ	<u> </u>					BOOY MAT	245	-			
							476	-				<u> </u> :	220	-			•
							491	-	٠,		<u> </u>	<del> </del>	220	┤╧┤	7.0		
				TOTAL			479	-				<del> </del>		-			
	1	<del></del>	TERMS: STRICTLY CASH URLE I hereby surfaces the agent report wer	SS ARRANGEMENT				-			BOI ICO UMA	742		-			
☐ CASH			I nereby summerce the appear upper upon to be done offing with integration motionals. You and your employees may operate above vehicle for purposes of integration or devicely at my rest. An express meditance is ten in				67E	<u> -</u>	•		BODY SHOP	CHG. BALE	220	-			
INTERNAL OK 'D BY		RNAL		-		15A	1 + 1			POLICY WORK	CASH SALE	225	1.				



Chevrolet Motor Division Branch Attn:

PO Box

Viewing of 1990 Chevrolet (Air bag failure) RE:



Please find enclosed the information requested regarding the above captioned matter:

Date of Collision: Time of Collision: Collision Scene:

Status of Automobile:

Police Report:

Personal Injuries to Client:

Parties Involved:

Vehicle Identification Number: Unknown at this

Name/Address of our Clients:

Indiana;

Street at intersection of

enclosed

Upper back and neck

With kind regards, I remain.

Cordially,

Enclosure:

Police Report





Certified Mail

Account Manager Service

ОН

Re: (Damaged in accident)

Wade:

This letter is sent to you to inform you to protect the integrity of any documents or pictures as a result of your viewing the automobile on 1992. Furthermore, you are specifically instructed NOT to view the automobile or remove any objects from it.

With kind regards, I remain.

