



U.S. Department of Transportation

National Highway Traffic Safety Administration

Dear Crash Data Researchers/Users:

Thank you for choosing crash data from the National Highway Traffic Safety Administration (NHTSA) for your research or other use. The information contained in this motor vehicle crash report is collected, maintained and distributed in accordance with Public Law 89-564. In accordance with this Public Law, NHTSA is required not to release any case information until completion of quality control procedures. These procedures include a review of the case material to extract all names, licenses and registration numbers, non-coded interview material, non-research related researcher comments in the margins, non-factual data, and the production number portion of the vehicle identification number (VIN).

If you requested NHTSA to query its database files in order to identify a specific crash, then that query was made using non-personal descriptors you provided for use in our search. This motor vehicle crash may have been identified from a data search and matches the general, non-personal descriptors you provided, but we cannot confirm that this is the specific crash report you requested.

If you have any questions with regard to the above procedures, please contact the Field Operations Branch, Crash Investigation Division, National Center for Statistics and Analysis at 202-366-4820. Again, please be advised that we cannot confirm that this is the case that you have specifically requested nor can we certify the information to be correct.

*** *** ***





TRANSPORTATION SCIENCES CENTER ACCIDENT RESEARCH GROUP

Division of Calspan Corporation

CALSPAN REMOTE AIR BAG DEPLOYMENT INVESTIGATION CALSPAN CASE NO. 94-34 VEHICLE: 1991 FORD CROWN VICTORIA LOCATION 1994

Contract No. DTNH22-94-D-07058

Prepared for:

U.S. Department of Transportation National Highway Traffic Safety Administration Washington, D.C. 20590

DISCLAIMER

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points are coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the pre-crash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

TECHNICAL REPORT STANDARD TITLE PAGE

1. Report No. 94-34	2. Government Accession No.	3	. Recipient's Catalog N	ю.		
4. Title and Subtitle Calspan Remote Air Bag Dep		5	5. Report Date: 1995			
Vehicle - 1991 Ford Crown V		6. Performing Organization Code				
7. Author(s) Accident Research Group		8	8. Performing Organization Report No.			
9. Performing Organization Nam. Transportation Sciences Cente Accident Research Group	er	1	10. Work Unit No. 1115 (5060-5069)			
Division of Calspan Corporat	10n	1	1. Contract or Grant No DTNH22-94-D-0705			
12. Sponsoring Agency Name and U.S. Department of Transpor National Highway Traffic Saf Washington, D.C. 20590	tation	1	13. Type of Report and Period Covered Technical Report Accident Date			
		1	14. Sponsoring Agency Code			
15. Supplementary Notes Remote investigation of an air Ford Crown Victoria.	r bag deployment crash that resulted in	forearm fract	ures to the belted 67 yea	r old female driver of a		
Nissan Sentra at a four-leg is into the path of the Nissan. At impact with the Nissan, the sair bag module cover with he cover flap contacted the antifracture of the tip of the ultimate in the sair bag module that the sair bag module cover with he cover flap contacted the antifracture of the tip of the ultimate in the sair bag module cover flap contacted the sair bag module that the sair bag m	nent investigation focused on the injuries Ford Crown Victoria. The Crown Victoria. The Crown Vintersection in S.C. The As a result of the crash, the Ford's driving the driver of the Ford was in a forwarder right hand positioned on the steering erior aspect of her right forearm result har styloid process, and a dislocation resulting in superficial contusions and all fracture.	Victoria was in a driver of the ver's side supped driving posing at the 11 o'c ting in a displator of the 1st me	avolved in a off-set head Ford initiated a left turn elemental air bag system tion with her right foreat lock position. The large aced, comminuted fractu- tacarpal. The deploying	d-on crash with a 1991 at the intersection and deployed. rm extended across the er upper air bag module re of the right radius, a grain bag contacted the		
17. Key Words Remote Investigation Supplemental Restraint System Off-set head-on configuration AIS-3 forearm fracture Large upper air bag module c		18. Distribution Statement General Public				
19. Security Classif. (of this report Unclassified	t) 20. Security Classif. (of this Unclassified	page)	21. No. of Pages 9	22. Price		

TABLE OF CONTENTS

	Page No.
Technical Summary	1
Crash Data	2
Ambience	2
Highway	2
Traffic Controls	3
Vehicles	3
Vehicle Damage	4
Supplemental Restraint System	5
Collision Sequence	5
Human Factors/Occupant Data	6
Driver Injuries	7
Driver Kinematics	7
Medical Treatment	8
Attachment A: Photographs	A1
Attachment B: NASS Occupant Forms	B1

CALSPAN REMOTE AIR BAG DEPLOYMENT INVESTIGATION CALSPAN CASE NO. 94-34 VEHICLE: 1991 FORD CROWN VICTORIA LOCATION

TECHNICAL SUMMARY

This remote air bag deployment investigation focused on the injury mechanism of the forearm fractures sustained by the 67 year old female driver of a 1991 Ford Crown Victoria. The vehicle was involved in a moderate off-set head-on crash with a 1991 Nissan Sentra at a four-leg intersection in S.C. The crash occurred during daylight hours of the Crown Victoria. 1994. The driver sustained multiple AIS-1 through 3 level injuries from her involvement with the deploying air bag and module cover flap of the Crown Victoria.

The driver of the Crown Victoria was traveling on a two-lane state route on an approach to a four-leg intersection with a green signal phase. She failed to detect the Nissan that was traveling in the opposite direction and initiated a left turn across the Nissan's path of travel. The center frontal area of the Nissan impacted the right front corner of the Crown Victoria. Impact forces were within the 12 o'clock sector for the Nissan and within the 01 o'clock sector for the Crown Victoria. Velocity changes were estimated at 14-18 km/h (9-11 mph) for the Ford and 16-19 km/h (10-12 mph) for the Nissan Sentra. As a result of the crash, the Ford Crown Victoria's driver's side air bag deployed.

The 67 year old female driver of the Ford Crown Victoria had a stated height of 162.6 cm (64.0") and weight of 68.9 kg (152.0 lbs.) She was restrained by the manual 3-point lap and shoulder belt system. At impact, the driver was in a normal posture with the seat adjusted to a forward track position. She had both hands positioned on the steering wheel at the 3 and 9 o'clock positions, however, due to the left turn maneuver, her right forearm crossed over the air bag module as her hand turned the wheel to the 11 o'clock position. The large upper air bag module cover contacted the anterior aspect of her right forearm resulting in a displaced, comminuted fracture of the right distal radius (AIS-3 Galeazzi fracture), a fracture of the tip of the ulnar styloid process (AIS-2), and a dislocation of the right 1st metacarpal from the trapezium (AIS-1). The deploying tethered air bag contacted the face and chest of the driver resulting in a contusion and abrasion of the left anterior breast (AIS-1) and multiple facial contusions (AIS-1).

The driver was transported to a local hospital by ambulance where she was admitted for open reduction fixation with a bone graft of the radial fracture. She was discharged three days following the crash.

CALSPAN REMOTE AIR BAG DEPLOYMENT INVESTIGATION CALSPAN CASE NO. 94-34

VEHICLE: 1991 FORD CROWN VICTORIA

DATE: 1994

CRASH DATA

Location:

Four-leg intersection

City/Township:

S.C.

Area/Type:

Urban/Commercial

Crash Date/Time:

1994, daylight hours

Investigating Police

Agency:

Police Department

Crash Type:

Offset, head-on configuration

Air Bag Vehicle

Driver Injury Severity:

Serious (AIS-3)

AMBIENCE

Viewing Conditions:

Daylight

Weather:

Clear

Precipitation:

None

Road Surface:

Dry

HIGHWAY

Type:

Intersection if two state routes

Number of Lanes:

2, divided

Surface:

Asphalt

HIGHWAY (CONT'D.)

Median:

Curbed

Edge:

Gravel/grass shoulders

Vertical Alignment:

Level

Horizontal Alignment:

Straight

Traffic Density:

Moderate

TRAFFIC CONTROLS

Signals:

Overhead signal system

Signs:

None pertinent

Markings:

Unknown

Speed Limit:

56 km/h (35 mph)

VEHICLES

Air Bag Vehicle

Vehicle #2

Description:

1991 Ford Crown Victoria,

1991 Nissan Sentra,

4 dr. sedan

4 dr. sedan

V.I.N.

2FACP74F5MX

1N4EB32A5MC

Odometer:

80,465 km (50,000 miles)

Unknown

Engine:

5.0 liter, V-8

1.6 liter, 4 cylinder

Transmission:

4-speed automatic

Unknown

Steering:

Power-assisted

Unknown

Brakes:

Power-assisted

Unknown

VEHICLES (CONT'D.)

Air Bag Vehicle

Vehicle #2

Padding:

Upper, mid, and lower instrument panel, soft-edged steering wheel rim and air bag module cover, adjustable head restraints, door panels

Upper, mid, and lower instrument panel

Manual Restraints:

3-point lap and shoulder belts in the four outboard seated positions, center rear lap belt

Rear seat lap belts

Automatic Restraints:

Driver's side air bag Supplemental Restraint System which deployed as a result of the crash

3-point door mounted lap and shoulder belt systems for the front outboard seated

positions

Tow Status:

Towed due to damage

Towed due to damage

VEHICLE DAMAGE

Exterior:

Air Bag Vehicle

Vehicle #2

The 1991 Ford Crown Victoria sustained moderate right frontal damage from its impact sequence with vehicle #2. Direct contact damage appeared to have involved the right corner area of the front bumper. Maximum crush was estimated at 10-15 cm (4-6") located at the right corner of the bumper.

Vehicle #2, the 1991 Nissan Sentra, sustained moderate center frontal damage from its offset, head-on impact with the air bag equipped Crown Victoria. Maximum crush was estimated at 20-25 cm (8-10") located at the mid point of the front bumper.

Damaged components included the front bumper, header panel, right headlamp assembly, and the right front fender.

Components damaged by the impact included the front bumper facia and reinforcement bar, grille, both headlamp assemblies,

VEHICLE DAMAGE (CONT'D.)

Air Bag Vehicle

Vehicle #2

CDC:

01-FREE-1

12-FZEN-1

Interior (Air

Bag Vehicle): Damage to the interior of the 1991 Ford Crown Victoria was limited to deployment of the supplemental driver's side air bag system. There was no intrusion of the interior components or damage related to occupant contact.

SUPPLEMENTAL RESTRAINT SYSTEM

The 1991 Ford Crown was equipped with a driver's side Supplemental Restraint System (SRS) which deployed as a result of the right frontal impact sequence with vehicle #2. Although the air bag vehicle was not inspected for this remote investigation, the typical Crown Victoria SRS consists of three front mounted crash sensors, an instrument panel mounted diagnostic module and safeing sensor, an instrument cluster SRS indicator lamp, the steering wheel mounted air bag module, and the clockspring assembly between steering wheel and the column.

The Crown Victoria driver's side air bag module consists of asymmetrical cover flaps which open in an H-configuration. The large upper module cover flaps are 12.4 cm (4.875") in height and 20.3 cm (8.0") in height while the lower cover flaps have respective measurements of 3.5 cm (1.375") and 20.3 cm (8.0").

The driver's side air bags are constructed of a woven nylon fabric with a neoprene liner and are approximately 61.0 cm (24") in diameter. The Crown Victoria air bags are tethered by four internal tether straps which extend from a 17.8 cm (7.0") diameter octagonal reinforcement that is sewn to the center of the bag. In addition, the bags are vented by two 2.5 cm (1.0") diameter ports located on the bag side of the bag at the 2 and 8 o'clock positions. It was unknown if there was damage or contact evidence on the deployed air bag and/or module cover flaps.

COLLISION SEQUENCE

Pre-Crash:

The driver of the air bag equipped Ford Crown Victoria was en route to a medical appointment and was traveling on a state route on an approach to a four-leg intersection. As she approached the intersection, the overhead traffic signal was in a green phase. The driver stated that she decelerated her vehicle and initiated a left turn across the intersection.

COLLISION SEQUENCE (CONT'D.)

Pre-Crash

(Cont'd.): Vehicle #2, the 1991 Nissan Sentra, was traveling in the opposite direction of

the Crown Victoria and approached the intersection on the green signal phase. The driver of vehicle #2 proceeded into the intersection as the driver of the Crown Victoria initiated her left turn across its path of travel. The driver of the Crown Victoria stated that she did not detect the Nissan prior to impact,

however, she estimated the speed of the vehicle at 72 km/h (45 mph).

Crash: The center frontal area of the Nissan Sentra impacted the right front corner

area of the Ford Crown Victoria. Resultant directions of force were 12 o'clock for the Nissan and 1 o'clock for the Crown Victoria. As a result of the head-on impact configuration, the Crown Victoria underwent a sufficient longitudinal deceleration which was sufficient to deploy the driver's side supplemental air bag system. Based on photographs of the involved vehicles (included as Attachment A), velocity changes were estimated at 14-18 km/h (9-11 mph) for the Crown Victoria and 16-19 km/h (10-12 mph) for the Nissan Sentra.

The driver of the Crown Victoria stated that the vehicles came to rest engaged at the point of impact, therefore impact speeds were comparable to the velocity

changes.

Post-Crash: The driver of the Crown Victoria noted that the impact stalled the engine of

her vehicle as it came to rest at or near the point of impact within the four-leg intersection. She remained in her vehicle following the crash and waited for emergency personnel to arrive on-scene. The driver was removed from the vehicle by rescue and was transported to a local hospital where she was

admitted for treatment of her injuries.

HUMAN FACTORS/OCCUPANT DATA

Air Bag Vehicle

Driver: 67 year old female

Height: 162.6 cm (64.0")

Weight: 68.9 kg (152 lbs.)

Manual Restraint

Usage: 3-point lap and shoulder belt

Usage Source: Driver interview

Eyeware: Prescription eyeglasses; remained on face, deformed beyond repair

Type of Medical

Treatment: Admitted to a local hospital for 3 days for surgical repair of right arm

DRIVER INJURIES

Injury	Severity OIC/AIS	-		
Displaced, comminuted fracture of the right distal radius (Galeazzi fracture)	Serious (752804.31)	Upper air bag module cover flap		
Fracture of the tip of the ulnar styloid process	Moderate (732202.21)	Upper air bag module cover flap		
Dislocation of the right 1st metacarpal from the trapezium	Minor (750404.11)	Upper air bag module cover flap		
Contusion with abrasion over the left anterior breast	Minor (490402.12, 490202.12)	Air bag		
Facial contusions over the lips and both cheeks	Minor (290402.18, 290402.11, 290402.12)	Air bag		

DRIVER KINEMATICS

The driver of the Ford Crown Victoria stated that she was in a normal driving posture with the seat track adjusted to a forward position. She was wearing the manual 3-point lap and shoulder belt system. The driver noted that as she approached the intersection, she had both hands on the steering wheel at the 3 and 9 o'clock positions. As she initiated the left turn, her right hand moved to the 11 o'clock position with her forearm extending across the air bag module cover flaps.

At impact, the supplemental driver's side air bag deployed. The large upper air bag module cover flap probably contacted the anterior aspect of the driver's right forearm which resulted in a displaced, comminuted (Galeazzi) fracture of the right distal radius, a fracture of the tip of the radial styloid process, and a dislocation of the right 1st metacarpal from the trapezium. The deploying air bag subsequently contacted and expanded across the driver's chest and face which resulted in a contusion and abrasion of the left anterior breast and facial contusions of the lips and both cheeks. The driver stated that the deployed air bag tore her silk blouse from the collar to the mid chest area. She was also wearing prescription eyeglasses which consisted of plastic frames. The driver reported that her involvement with the air bag deformed the frames, however, the glasses remained on her face.

The driver stated that she heard a loud "bang" at impact that was similar to a gun shot. In addition, she detected a blackish powder within the interior of the vehicle immediately following the crash, both of which she attributed to air bag deployment.

MEDICAL TREATMENT

The driver was removed from the vehicle by emergency medical technicians (EMTs). The EMTs placed a soft cervical collar and a splint on the driver's right forearm. She was subsequently transported by ambulance to a local hospital where she was admitted for treatment. The right forearm fractures were diagnosed by X-ray and the attending physician referred her to an orthopedic surgeon who scheduled reduction surgery.

The driver was admitted to surgery on the day following the crash. The radial fracture required open reduction and internal fixation which required the placement of a steel plate that was affixed with six screws. In addition to the plate, the driver required an autogenous bone graft with bone harvested from the right iliac crest. She was discharged following three days of hospitalization.

Following her discharge, the driver stated that she walked with the use of a cane for several weeks due to the soreness associated with the bone graft. She also noted that she developed trigger finger which resulted from the fractures and trauma to the nerves and ligaments.

ATTACHMENT A

PHOTOGRAPHS CALSPAN CASE NO. 94-34




Frontal damage to the Ford Crown Victoria.



2. Center frontal damage to vehicle #2.



3. Driver's injuries post-surgery.



4. Accident site.

ATTACHMENT B

NASS Occupant Forms



U.S. Department of Transportation

OCCUPANT ASSESSMENT FORM

Form Approved O.M.B. No. 2127-0021

NATIONAL ACCIDENT SAMPLING SYSTEM CRASHWORTHINESS DATA SYSTEM

National Highway Traffic Safety Administration

	OCCUPANT'S SEATING
1. Primary Sampling Unit Number	
2. Case Number - Stratum 94-34	10. Occupant's Seat Position
	(11) Left side
3. Vehicle NumberO_l	(12) Middle
4. Occupant Number	(13) Right side
	(14) Other (specify):
OCCUPANT'S CHARACTERISTICS	(15) On or in the lap of another occupant
5. Occupant's Age Code actual age at time of accident. (00) Less than one year old (specify by month): (97) 97 years and older (99) Unknown 6. Occupant's Sex (1) Male (2) Female (9) Unknown 7. Occupant's Height Code actual height to the nearest centimeter. (999) Unknown	Second Seat (21) Left side (22) Middle (23) Right side (24) Other (specify):
$\underline{6}\underline{4}$ inches X 2.54 = $\underline{1}\underline{6}\underline{3}$ centimeters	(97) In or on unenclosed area (98) Other seat (specify): (99) Unknown
8. Occupant's Weight Code actual weight to the nearest kilogram. (999)Unknown 1 5 2 pounds X .4536 = 0 6 9 kilograms	11. Occupant's Posture (0) Normal posture Abnormal posture (1) Kneeling or standing on seat (2) Lying on or across seat (3) Kneeling, standing or sitting in front of seat
9. Occupant's Role (1) Driver (2) Passenger (9) Unknown	 (4) Sitting sideways or turned to talk with another occupant or to look out a rear window (5) Sitting on a console (6) Lying back in a reclined seat position (7) Bracing with feet or hands on a surface in front of seat (8) Other abnormal posture (specify): (9) Unknown
grand the second terms of	

	EJE	CTION/E	NTRAPMENT
12. Ejection (0) No ejection (1) Complete ej (2) Partial eject (3) Ejection, un (9) Unknown	on	<u>o</u>	15. Medium Status (Immediately Prior To Impact) © (0) No ejection (1) Open (2) Closed (3) Integral structure (9) Unknown
13. Ejection Area (0) No ejection (1) Windshield (2) Left front (3) Right front (4) Left rear (5) Right rear (6) Rear (7) Roof (8) Other area (specify): (9) Unknown	e.g., back of pickup, etc.)		16. Entrapment (NOTE: Entrapped means that part of the person was in the vehicle and mechanically restrained; jammed doors and immobilizing injuries by themselves are not sufficient to constitute entrapment.) (0) Not entrapped (1) Entrapped (9) Unknown
14. Ejection Medium (0) No ejection (1) Door/hatch/ (2) Nonfixed ro (3) Fixed glazin (4) Nonfixed gl (5) Integral stru (8) Other medium	tailgate of structure g azing (specify):	<u>o</u>	

	RESTRAINT SYST	EM EVALUATION
	Manual (Active) Belt System Availability (0) None available (1) Belt removed/destroyed (2) Shoulder belt (3) Lap belt (4) Lap and shoulder belt (5) Belt available—type unknown	21. Air Bag System Availability/Function (O) Not equipped/not available (1) Air bag Non-functional (2) Air bag disconnected (specify):
	Integral Belt Partially Destroyed (6) Shoulder belt (lap belt destroyed/removed) (7) Lap belt (shoulder belt destroyed/removed)	(3) Air bag not reinstalled (9) Unknown
	(8) Other belt (specify): (9) Unknown	22. Air Bag System Deployment (0) Not equipped/not available (1) Air bag deployed during accident (as a result of impact)
18.	Manual (Active) Belt System Use (00) None used, not available, or belt removed/destroyed (01) Inoperative (specify): (02) Shoulder belt (03) Lap belt (04) Lap and shoulder belt (05) Belt used—type unknown (08) Other belt used (specify):	 (2) Air bag deployed inadvertently just prior to accident (3) Air bag deployed, accident sequence undetermined (4) Nondeployed (5) Unknown if deployed (6) Air bag deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical) (9) Unknown
	 (12) Shoulder belt used with child safety seat (13) Lap belt used with child safety seat (14) Lap and shoulder belt used with child safety seat (15) Belt used with child safety seat—type unknown (18) Other belt used with child safety seat (specify): (99) Unknown if belt used 	23. Are There Indications of Air Bag System Failure? (0) Not equipped/not available (1) No (2) Yes (specify): (9) Unknown
19.	Proper Use of Manual (Active) Belts (0) None used or not available (1) Belt used properly (2) Belt used properly with child safety seat	Note: See Variables 44 through 48 (Page 5) for Information on Automatic Belts
	Belt Used Improperly (3) Shoulder belt worn under arm (4) Shoulder belt worn behind back or seat (5) Belt worn around more than one person (6) Lap belt worn on abdomen (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): (8) Other improper use of manual belt system	24. Police Reported Restraint Use (0) None used (1) Police did not indicate restraint use (2) Shoulder belt (3) Lap belt (4) Lap and shoulder belt (5) Belt used, type not specified
	(specify): (9) Unknown	(6) Child safety seat (7) Other or automatic restraint (specify): (8) Restrained, type unknown
20.	Manual (Active) Belt Failure Modes During Accident (0) No manual belt used (1) No manual belt failure(s) (2) Torn webbing (stretched webbing not included) (3) Broken buckle or latchplate (4) Upper anchorage separated (5) Other anchorage separated (specify): (6) Broken retractor (7) Combination of above (specify):	(9) Police indicated "unknown"
	(9) Unknown	

	HEAD RESTRAINT AN	D SEAT EVALUATION
	Head Restraint Type/Damage by Occupant at This Occupant Position (0) No head restraints (1) Integral—no damage (2) Integral—damaged during accident (3) Adjustable—no damage (4) Adjustable—damaged during accident (5) Add-on—no damage (6) Add-on—damaged during accident (8) Other (specify): (9) Unknown Seat Type (this Occupant Position) (00) Occupant not seated or no seat (01) Bucket (02) Bucket with folding back (03) Bench (04) Bench with separate back cushions (05) Bench with folding back(s) (06) Split bench with separate back cushions	27. Seat Performance (this Occupant Position) (0) Occupant not seated or no seat (1) No seat performance failure(s) (2) Seat adjusters failed (3) Seat back folding locks or "seat back" failed (specify): (4) Seat track/anchors failed (5) Deformed by impact of occupant (6) Deformed by passenger compartment intrusion (specify): (7) Combination of above (specify): (8) Other (specify): (9) Unknown
	(07) Split bench with folding back(s)(08) Pedestal (i.e., column supported)(09) Other seat type (specify):	
	(10) Box mounted seat (i.e., van type) (99) Unknown	
L		v

	CHILD SA	ETY SEAT
28.	Child Safety Seat Make/Model (000) No child safety seat Applicable codes are found in your NASS CDS Data Collection, Coding and Editing (950) Built-in child safety seat (997) Other make/model (specify):	31. Child Safety Seat Harness Usage 32. Child Safety Seat Shield Usage 33. Child Safety Seat Tether Usage
	(998) Unknown make/model (999) Unknown if child safety seat used	Note: Options below applicable to Variables OA31-OA33. (00) No child safety seat
29.	Type of Child Safety Seat (0) No child safety seat (1) Infant seat (2) Toddler seat (3) Convertible seat (4) Booster seat (7) Other type child safety seat (specify): (8) Unknown child safety seat type (9) Unknown if child safety seat used	Not Designed With Harness/Shield/Tether (01) After market harness/shield/tether added, not used (02) After market harness/shield/tether used (03) Child safety seat used, but no after market harness/shield/tether added (09) Unknown if harness/shield/tether added or used Designed With Harness/Shield/Tether (11) Harness/shield/tether not used (12) Harness/shield/tether used
30.	Child Safety Seat Orientation (00) No child safety seat Designed for Rear Facing for This Age/Weight (01) Rear facing (02) Forward facing (08) Other orientation (specify): (09) Unknown orientation Designed For Forward Facing for This Age/Weight (11) Rear facing (12) Forward facing (18) Other orientation (specify): (19) Unknown orientation Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight (21) Rear facing (22) Forward facing (28) Other orientation (specify): (29) Unknown orientation (99) Unknown if child safety seat used	Unknown if Designed With Harness/Shield/Tether (21) Harness/shield/tether not used (22) Harness/shield/tether used (29) Unknown if harness/shield/tether used (99) Unknown if child safety seat used

	INJURY CONSEQUENCES	38. Working Days Lost <u>9 7</u>
34.	Injury Severity (Police Rating)	Code the number of days (up through 60) that the occupant
	(0) O - No injury	lost from work due to the accident (00) No working days lost
	(1) C - Possible injury	(61) 61 days or more
	(2) B - Nonincapacitating injury	(62) Fatally injured
	(3) A - Incapacitating injury	(97) Not working prior to accident
	(4) K - Killed (5) U - Injury, severity unknown	(99) Unknown
	(6) Died prior to accident	
	(9) Unknown	STOP - GO TO VARIABLE 44 ON PAGE 7
	,	
35	Treatment - Mortality <u>3</u>	VARIABLES 39 THROUGH 43 ARE
	(0) No treatment	COMPLETED BY THE ZONE CENTER
	(1) Fatal	
	(2) Fatal - ruled disease (specify):	39. Time to Death
		Code number of hours from time of
	Nonfatal	accident to time of death up through 24
	(3) Hospitalization	hours. If time of death is greater than 24
	(4) Transported and released	hours, code number of days. (Note: 1 day = 31 , 2 days = 32 , n days = $30 + n$ up
	(5) Treatment at scene - nontransported	through 30 days = 60)
	(6) Treatment later	(00) Not fatal
	(8) Treatment - other (specify):	(96) Fatal - ruled disease
	(9) Unknown	(99) Unknown
	(a) Change	
36.	Type Of Medical Facility (for Initial Treatment)	40. 1st Medically Reported Cause of DeathO_O
	(0) Not treated at a medical facility	41. 2nd Medically Reported Cause of DeathO O
	(1) Trauma center (2) Hospital	
	(3) Medical clinic	42. 3rd Medically Reported Cause of Death
	(4) Physician's office	Code the Occupant Injury from line number(s) for the medically reported
	(5) Treatment later at medical facility	injury(s) which reportedly contributed to
	(8) Other (specify):	this occupant's death
	(9) Unknown	(00) Not fatal or no additional causes
	(3) Olikilowii	(96) Mode of death given but specific
		injuries are not linked to cause of death. (specify):
37.	Hospital Stay 03	or death. (specify).
	(00) Not Hospitalized	(97) Other result (includes fatal ruled
	Code the number of days (up through 60)	disease) (specify):
	that the occupant stayed in hospital. (61) 61 days or more	
	(99) Unknown	(99) Unknown
		43. Number of Recorded Injuries for
		This Occupant OK
		injuries recorded for this occupant.
		(00) No recorded injuries
		(97) Injured, details unknown
		(99) Unknown if injured

	AUTOMATIC BELT SYSTEM	48	Automatic (Passive) Belt Failure Modes
44.	Automatic (Passive) Belt System Availability/ Function (0) Not equipped/not available (1) 2 point automatic belts (2) 3 point automatic belts (3) Automatic belts - type unknown Non-functional (4) Automatic belts destroyed or rendered inoperative (9) Unknown		During Accident (0) Not equipped/not available/not in use (1) No automatic belt failure(s) (2) Torn webbing (stretched webbing not included) (3) Broken buckle or latchplate (4) Upper anchorage separated (5) Other anchorage separated (specify): (6) Broken retractor (7) Combination of above (specify): (8) Other automatic belt failure (specify):
45.	Automatic (Passive) Belt System Use (0) Not equipped/not available/destroyed or rendered inoperative (1) Automatic belt in use (2) Automatic belt not in use (manually	49.	Seat Orientation (this Occupant Position) (0) Occupant not seated or no seat (1) Forward facing seat
46	disconnected, motorized track inoperative) (specify): (3) Automatic belt use unknown (9) Unknown		(2) Rear facing seat (3) Side facing seat (inward) (4) Side facing seat (outward) (8) Other (specify):
46.	Automatic (Passive) Belt System Type (0) Not equipped/not available (1) Non-motorized system (2) Motorized system (9) Unknown		Check the Primary Source Used In Determining Belt Use.
47.	Proper Use of Automatic (Passive) Belt System (0) Not equipped/not available/not used (1) Automatic belt used properly (2) Automatic belt used properly with child safety seat		 [] Not equipped/not available/destroyed or rendered inoperative [] Vehicle inspection [] Official injury data [] Driver/occupant interview [] Other (specify):
	 Automatic Belt Used Improperly (3) Automatic shoulder belt worn under arm (4) Automatic shoulder belt worn behind back (5) Automatic belt worn around more than one person (6) Lap portion of automatic belt worn on abdomen (7) Automatic lap and shoulder belt or automatic shoulder belt used improperly 		[] Unknown if belt used
	with child safety seat (specify): (8) Other improper use of automatic belt system (specify): (9) Unknown		
	ARE ALL APPLICABLE MEDICAL RECOR	RDS	INCLUDED NO[] YES[]
	UPDATE CANDIDATE?		NO[] YES[]

STOP - VARIABLES 50 THROUGH 53 ARE	BELT USE DETERMINATION
STOP - VARIABLES 50 THROUGH 53 ARE COMPLETED BY THE ZONE CENTER	53. Primary Source of Belt Use Determination (0) Not equipped/not available/destroyed or rendered inoperative
TRAUMA DATA	(1) Vehicle inspection
50. Glasgow Coma Scale (GCS) Score (at Medical Facility) (00) Not injured (01) Injured - not treated at medical facility (02) No GCS Score at medical facility (03-15) Code the actual value of the initial GCS Score recorded at medical facility. (97) Injured, details unknown (99) Unknown if injured	(2) Official injury data (3) Driver/occupant interview (8) Other (specify): (9) Unknown if belt used
51. Was the Occupant Given Blood? (1) No - blood not given (2) Yes - blood given (specify units): (9) Unknown if blood given	
52. Arterial Blood Gases (ABG) – HCO ₃ O (00) Not injured (01) Injured, ABGs not measured or reported (02-50) Code the actual value of theHCO ₃ (96) ABGs reported, HCO ₃ unknown (97) Injured, details unknown (99) Unknown if injured	

U.S. Department of Transportation National Highway Traffic Safety

1. Primary Sampling Unit Number

OCCUPANT INJURY FORM

Form Approved O.M.B. No. 2127-0021

NATIONAL ACCIDENT SAMPLING SYSTEM CRASHWORTHINESS DATA SYSTEM

Administration / JOSSI AIT INSORT I OTHER

3. Vehicle Number O 1

2. Case Number - Stratum 9 4 - 34

4. Occupant Number

01

INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.

				A.I.S	90				Injury	Occupant	
	Source of Injury Data	Body Region	Type of Anatomic Structure	Specific Anatomic Structure		A.I.S. Severity	Aspect	Injury Source	Source Confidence Level	Direct/ Indirect Injury	Area Intrusion Number
1st	5. <u>2</u>	6. <u>7</u>	7. <u>\$</u>	3.28	9. <u>04</u>	10. <u>3</u>	11. <u>l</u>	12. <u>l 6</u>	13. <u>l</u> 1	4. <u>l</u>	15. <u>00</u>
2nd	16. <u>2</u>	17. 7	18. <u>3</u> 1:	. <u>22</u>	20. <u>0 }</u>	21.2	22. <u>l</u>	23(_6	24. <u>l</u> 2	5. <u>]</u> . 2	26. <u>O</u> O
3rd	27. <u>2</u>	28. 7	29. <u>5</u> 30	o. <u>04</u>	31. <u>04</u>	32. <u>[</u>	33, <u>l</u>	34. <u>/ 6</u>	35. <u> </u>	6;	37. <u>0 0</u>
4th	38. <u>2</u>	39. <u>4</u>	40. <u>9</u> 4	ı. <u>04</u>	42. <u>02</u>	43. <u>l</u>	44. <u>2</u>	45. <u>4 5</u>	46. <u> </u>	7. <u> </u>	18. <u>0</u> 0
5th	49. <u>2</u>	50. <u>4</u>	51. <u>9</u> 5:	2. <u>0 3</u>	53. <u>0 2</u>	54. <u> </u>	55. <u>2</u>	56. <u>4 5</u>	57. <u>l</u> 5	8. <u>l</u> - 5	59. <u>O O</u>
6th	60. <u>7</u>	61. <u>2</u>	62. <u>9</u> 6:	3. <u>04</u>	64. <u>02</u>	65. <u>]</u>	66. <u>8</u>	67. <u>Y S</u>	68. <u>l</u> 6	9. <u>(</u> ;	70. <u>0 0</u>
7th	71. 7	72. <u>2</u>	73. <u>9</u> 74	1. <u>04</u>	75. <u>0 2</u>	76.]	77. <u> </u>	78. <u>4 S</u>	79. <u> </u>	o. <u>l</u> s	31. <u>O O</u>
8th	82. <u>7</u>	83. <u>2</u>	84. 9 8!	5. <u>04</u>	86. <u>0</u> <u>2</u>	87. <u>l</u>	88}	89. <u>4 5</u>	90. <u> </u> 9	1. <u>l</u> s	92. <u>00</u>
9th	93	94	959	3.	97	98	99	100	101 10	210	03,
10th	104 1	105 1	06 10		108	109	110	111	112 11	311	l 4

HS Form 433B (1/94)

This report is authorized by P.L. 89-563, Title 1, Section 106, 108, and 112. While you are not required to respond, your cooperation is needed to make the results of this data collection effort comprehensive, accurate, and timely.

SOURCE OF INJURY DATA

OFFICIAL

- (1) Autopsy records with or without hospital/ medical records
- Hospital/medical records other than emergency room (e.g., discharge summary)
- Emergency room records only (including associated X-rays or other lab reports)
- Private physician, walk-in or emergency clinic

UNOFFICIAL

- (5) Lay coroner report
- (6) E.M.S. personnel
- (7) Interviewee
- Other source (specify):
- (9) Police

INJURY SOURCE

FRONT

- (01) Windshield
- (02) Mirror
- (03) Sunvisor
- (04) Steering wheel rim
- (05) Steering wheel hub/spoke
- (06) Steering wheel (combination of codes 04 and 05)
- (07) Steering column, transmission selector lever, other attachment
- (08) Add on equipment (e.g., CB, tape deck, air conditioner)
- (09) Left instrument panel and below
- (10) Center instrument panel and below
- (11)Right instrument panel and below
- (12) Glove compartment door
- (13) Knee bolster
- (14) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
- (15) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
- (16) Driver side air bag compartment cover
- (17)Passenger side air bag compartment cover
- Windshield reinforced by exterior object (18)(specify):
- (19) Other front object (specify):

LEFT SIDE

- (20) Left side interior surface, excluding hardware or armrests
- (21) Left side hardware or armrest
- (22) Left A (A1/A2)-pillar
- (23) Left B-pillar
- (24) Other left pillar (specify):

- (25) Left side window glass or frame
- (26) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (27) Other left side object (specify):
- (28) Left side window sill

RIGHT SIDE

- (30) Right side interior surface, excluding hardware or armrests
- Right side hardware or armrest Right A (A1/A2)-pillar
- (33) Right B-pillar
- (34)Other right pillar (specify):
- (35) Right side window glass or frame
- (36) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (37) Other right side object (specify):
- (38) Right side window sill

INTERIOR

- (40) Seat, back support
- (41) Belt restraint webbing/buckle
- Belt restraint B-pillar or door frame (42)attachment point
- (43) Other restraint system component (specify):
- (44) Head restraint system
- (45) Air bag (use codes "16" and "17" for injuries sustained from air bag compartment covers)
- (46) Other occupants (specify):
- (47) Interior loose objects
- Child safety seat (specify):
- (49) Other interior object (specify):

ROOF

- (50) Front header
- (51) Rear header
- (52) Roof left side rail
- (53) Roof right side rail
- (54) Roof or convertible top

FLOOR

- (56) Floor (including toe pan)
- (57) Floor or console mounted transmission lever, including console
- (58) Parking brake handle
- (59) Foot controls including parking brake

RFAR

(60) Backlight (rear window)

- (61) Backlight storage rack, door, etc.
- (62) Other rear object (specify):

EXTERIOR of OCCUPANT'S VEHICLE

- (65) Hood
- (66) Outside hardware (e.g., outside mirror, antenna)
- Other exterior surface or tires (specify):
- (68) Unknown exterior objects

EXTERIOR OF OTHER MOTOR VEHICLE

- (70) Front bumper
- (71) Hood edge
- (72) Other front of vehicle (specify):
- (73) Hood
- (74) Hood ornament
- (75)Windshield, roof rail, A-pillar
- Side surface (76)
- Side mirrors
- Other side protrusions (specify)
- (79) Rear surface
- (80) Undercarriage
- Tires and wheels (81)
- Other exterior of other motor vehicle (82)(specify):
- (83) Unknown exterior of other motor vehicle

OTHER VEHICLE OR OBJECT IN THE ENVIRONMENT

- (84) Ground
- (85) Other vehicle or object (specify)
- (86) Unknown vehicle or object

NONCONTACT INJURY

- (90) Fire in vehicle
- (91) Flying glass
- (92)Other noncontact injury source (specify):
- Air bag exhaust gases
- (97) Injured, unknown source

INJURY SOURCE CONFIDENCE IFVFI

- (1)Certain
- (2)Probable
- Possible (3)
- Unknown

DIRECT/INDIRECT INJURY

- Direct contact injury
- (2)Indirect contact injury
- (3) Noncontact injury
- Injured, unknown source

OCCUPANT INJURY CLASSIFICATION

Body Region

- Head
- Face Neck
- (4) (5) Thorax
- Abdomen (6) Spine
- (7) **Upper Extremity**
- (8) Lower Extremity Unspecified

Type of Anatomic Structure

- Whole Area
- Vessels
- (3) Nerves
- (4) Organs (includes muscles/ ligaments)
- Skeletal (includes joints)
- (6) Head - LOC
- (9) Skin

- Specific Anatomic Structure
- Whole Area (02) Skin Abrasion (04) Skin Contusion
- (06) Skin Laceration (08) Skin - Avulsion
- (10) Amputation Burn
- (30) Crush
- (40)
- Degloving Injury NFS (50)

(02) Length of LOC

(10) Concussion

Trauma, other than mechanical

(04, 06, 08) Level of Consciousness

Head - LOC

- Vessels, Nerves, Organs. Bones, Joints are assigned consecutive two digit numbers beginning with 02

Level of Injury

(02) Cervical (04) Thoracic

Lumbar

Specific injuries are assigned consecutive two-digit numbers beginning with 02.

To the extent possible, within the organizational framework of the AIS, 00 is assigned to an injury NFS as to severity or where only one injury is given in the dictionary for that anatomic structure. 99 is assigned to any injury NFS as to lesion or severity.

Abbreviated Injury Scale

- Minor injury
- (2) Moderate injury
- Serious injury Severe injury
- (5) Critical injury Maximum (untreatable)
- Injured, unknown severity

Aspect

- Right
- Left Bilateral (3)
- Central
- (4) (5) (6) Anterior Posterior
- Superior (8) Inferior
- (9) Unknown Whole region