

Child Safety Seat Investigation / Vehicle to Vehicle
Dynamic Science, Inc. / Case Number: DS04001
2003 Toyota Corolla
California
January, 2004

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points be coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the pre-crash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crash-worthiness performance of the involved vehicle(s) or their safety systems.

1. Report No. DS04001		2. Government Accession No.		3. Recipient Catalog No.	
4. Title and Subtitle Child Safety Seat Investigation				5. Report Date October 28, 2004	
				6. Performing Organization Report No.	
7. Author(s) Dynamic Science, Inc.				8. Performing Organization Report No.	
9. Performing Organization name and Address Dynamic Science, Inc. 530 College Parkway, Ste. K Annapolis, MD 21401				10. Work Unit No. (TRAIS)	
				11. Contract or Grant no. DTNH22-01-C-27002	
12. Sponsoring Agency Name and Address U.S. Dept. of Transportation (NRD-32) National Highway Traffic Safety Administration 400 7th Street, SW Washington, DC 20590				13. Type of report and period Covered [Report Month, Year]	
				14. Sponsoring Agency Code	
15. Supplemental Notes					
16. Abstract <p>This three vehicle crash occurred in January, 2004 at 0750 hours. The crash occurred in the eastbound lanes of a divided four lane US highway. The speed limit is 105 km/h (65 mph). The case vehicle was a 2003 Toyota Corolla driven by a lap and shoulder belt restrained 28-year-old female. The rear right seat was occupied by a 6-month-old female infant who was seated in a Graco Quattro Tour child safety seat. The first other vehicle was a 1992 Ford Aerostar van driven by a 20-year-old male. The second other vehicle was a 1997 Buick LeSabre four door sedan driven by a 73-year-old male. There was one additional vehicle that played a role in the crash but did not sustain any damage. This was a 1999 Volkswagen Passat driven by a 50-year-old male.</p> <p>The case vehicle and the Volkswagen Passat were traveling westbound. The Ford Aerostar van and Buick LeSabre were traveling eastbound. The Passat was traveling to the right and in front of the case vehicle. The driver was talking on a cell phone and the vehicle drifted into the adjacent lane. The driver of the Toyota Corolla steered left to avoid the Passat, lost control of her vehicle, and crossed the depressed grass covered. The case vehicle continued on into the oncoming eastbound travel lanes. It was in a counterclockwise yaw at this time. The driver of the Aerostar van saw the Toyota Corolla and began braking and steering right. The driver of the Aerostar was unable to stop in time and the front of the Aerostar struck the Toyota Corolla in the right side. There was a second impact between the right side of the Corolla and the left rear of the Aerostar. This was a side slap type impact. As a result of Impact 1 and secondary sideslap, the Corolla rotated clockwise and swerved into the adjacent eastbound lane. The driver of the Buick LeSabre saw the Toyota and began braking. He was unable to stop in time. The front of the Buick struck the front of the Toyota. The Corolla was redirected to the south, left the eastbound roadway, and traveled down a grass embankment where it struck a fence before coming to rest. The Buick continued forward and appears to have slightly contacted the rear of the Aerostar. Damage was likely minimal. The driver of the case vehicle sustained multiple injuries, including: pelvic fractures, a foot fracture, and multiple abrasions and contusions. The 6-month-old child was badly injured and died shortly after transport to a local hospital.</p>					
17. Key Words Air bag, deployment, injury, crash, fatality, cell phone, distraction, child safety seat, passenger.			18. Distribution Statement		
19. Security Classif. (of this report)	20. Security Classif. (of this page)	21. No. of pages	22. Price		

Dynamic Science, Inc.
Crash Investigation
Case Number: DS04001

TABLE OF CONTENTS

Background	1
Description	1
Investigation Type	1
Crash Location	1
Crash Date	1
Notification Date	1
Field Work Completed	1
Summary	1
Crash Site	1
Pre-crash	2
Crash	3
Post-crash	3
Vehicle Data - 2003 Toyota Corolla	5
Vehicle Damage - 2003 Toyota Corolla	6
Exterior Damage	6
Interior Damage	7
Manual Restraint Systems	8
Frontal Air Bag System	9
Side Air Bags	10
Child Safety Seat	11
Vehicle Data - 1992 Ford Aerostar	13
Vehicle Data - 1997 Buick LeSabre	14
Occupant Demographics - 2003 Toyota Corolla	16
Occupant Injuries -2003 Toyota Corolla	19
Occupant Kinematics - 2003 Toyota Corolla	24
Attachment 1. Scene Diagram	26

BACKGROUND:

Description: This child safety seat case was identified through a news article by NHTSA staff members. DSI was assigned the case on January 29, 2004. All field work was completed on February 10, 2004. The child safety seat inspection took place in the offices of the investigating police agency. The vehicle inspection took place at a police holding facility. At the time of the inspection the vehicle was still on hold and the police had not completed their inspection.

Investigation Type: Child safety seat
Crash Location: California
Crash Date: January, 2004
Notification Date: January 29, 2004
Field Work Completed: February 10, 2004

SUMMARY

Crash Site

This three vehicle crash occurred in January, 2004 at 0750 hours. The crash occurred in the eastbound lanes of a divided four lane US highway. The eastbound and westbound travel lanes are divided by a dirt center median. The westbound roadway is bordered on the north by a solid white painted line and an asphalt shoulder and is bordered on the south by a solid white painted line and an asphalt/dirt center median. The eastbound roadway is bordered on the north by a solid white painted line and an asphalt shoulder. The roadway was dry and free of defects. According to the National Weather Service, the visibility was 16 km (10 miles), the wind was calm, and the temperature was 2 degrees C (36 degree F). The speed limit is 105 km/h (65 mph).



Figure 1. Path of travel (Corolla), westbound



Figure 2. Road departure path of travel (Corolla), westbound

Pre-Crash

The case vehicle was a 2003 Toyota Corolla (VIN: JTDBR38E530xxxxxx) driven by a lap and shoulder belt restrained 28-year-old female (68 kg/150 lbs, 173 cm/68 in). The rear right seat was occupied by a 6-month-old female (9 kg/19¹ lbs, 71 cm/28 in) infant who was seated in Graco Quattro Tour child safety seat (Model Number: 7411LV). The Corolla was equipped with dual stage front air bags, seat back mounted side air bags for the front seating positions, and retractor mounted seat belt pretensioners for the front seating positions.



Figure 3. Path of travel (Buick LeSabre/Ford Aerostar), eastbound

The first other vehicle was a 1992 Ford Aerostar van (1FMDA11U2NZxxxxxx) driven by a 20-year-old male. The second other vehicle was a 1997 Buick LeSabre four door sedan (VIN:1G4HR52K2VHxxxxxx) driven by a 73-year-old male. There was one additional vehicle that played a role in the crash but did not sustain any damage. This was a 1999 Volkswagen Passat driven by a 50-year-old male.



Figure 4. Aerial view of crash scene, North is to the left of photo

The case vehicle and the Volkswagen Passat were traveling westbound. The Ford Aerostar van and Buick LeSabre were traveling eastbound. The Passat was traveling to the right and in front of the case vehicle.

The driver indicated that he was traveling approximately 89 km/h (55 mph). At some point he recalled that he needed to call someone. He looked over to the right front passenger's seat and grabbed his cell phone. When he looked up he saw that he had drifted into the adjacent lane 0.6-0.9 m (2-3 ft). He swerved back to the right and heard tires squealing beside him.

¹EMS prehospital care report indicates a weight of 10 kg (22 lbs)

Crash

Impact 1:

The driver of the Toyota Corolla steered left to avoid the Passat, lost control of her vehicle, and crossed the depressed grass covered median—traveling diagonally approximately 62 m (204 ft). The case vehicle continued on into the oncoming eastbound travel lanes. It was in a counterclockwise yaw at this time. The driver of the Aerostar van saw the Toyota Corolla and began braking and steering right, depositing 17 m (55 ft) of locked wheel skids. The driver of the Aerostar was unable to stop in time and the front of the Aerostar (12FDEW3) struck the Toyota Corolla in the right side (03RZAW4). The Toyota had a maximum crush of 51.0 cm (20.0 in) at C3. The total velocity change as calculated by the WinSmash program was 72.2 km/h (44.9 mph). The longitudinal and lateral delta V components were -12.5 km/h (-7.8 mph) and -71.1 km/h (-44.2 mph), respectively. The front right passenger side air bag in the Toyota Corolla deployed at this time. The driver's air bag in the Aerostar also deployed at this time.

Impact 2:

There was a second impact between the right side of the Corolla and the left rear of the Aerostar. This was a side slap type impact. As a result of Impact 1 and this impact, the Corolla rotated clockwise entering the adjacent eastbound lane.

Impact 3:

The driver of the Buick LeSabre saw the Toyota and began braking, depositing 29 m (96 ft) of locked wheel skids. He was unable to stop in time. The front of the Buick (12FDEW2) struck the front of the Toyota (01FDEW2). The front bumper and backing bar were both missing from the vehicle at the time of inspection. The total velocity change as calculated by the WinSmash program was 50.3 km/h (31.3 mph). The longitudinal and lateral delta V components were -43.6 km/h (-27.1 mph) and -25.2 km/h (-15.6 mph), respectively. Both front air bags in the Toyota deployed at this time. The driver and front right passenger seat belt pretensioners also both actuated. The front air bags in the Buick LeSabre deployed at this time.

Impact 4:

The Corolla was redirected to the south, left the eastbound roadway, and traveled down a grass embankment where it struck a fence (unknown CDC) before coming to rest.

Impact 5:

The Buick continued forward and appears to have slightly contacted the rear of the Aerostar. Damage was likely minimal.

Post-Crash

The driver of the case vehicle sustained multiple injuries, including: pelvic fractures, a foot fracture, and multiple abrasions and contusions. She was removed from the vehicle by EMS personnel and transported by ground ambulance to a local hospital where she was admitted and hospitalized for four days.

The 6-month-old child was badly injured. She was removed from the child seat and placed on the ground. She was given CPR by a bystander nurse and a police officer shortly after the crash.

She was then transported by air to an area trauma center. The following is a compilation of transport and arrival times.

Ambulance call received	0755
Unit dispatched	0755
Ambulance en route	0801
Arrived at scene	0811
Initial patient contact	0812
Departed scene	0829
Time ER activated	0830
Arrival time	0852
Declared dead by trauma team	0855

The EMS pre-hospital care report indicated that she had a Glasgow Coma Scale score of 3 (indicating no eye, verbal, or motor responses), as well as a Pediatric Coma Scale of 3. The report indicated that she had sustained hematomas to the right maxillary area and the anterior of the frontal skull. She also had sustained bilateral thigh contusions and a left arm contusion. She was pronounced dead an hour after arriving at the hospital. According to the autopsy report, she sustained the following injuries: comminuted fractures of the skull, subarachnoid hemorrhage, cerebral contusion, multiple facial contusions/abrasions, left clavicle fracture, bilateral rib fractures, bilateral lung contusions, lacerations to the liver and spleen, contusions to the thymus glands, and multiple contusions to the torso and extremities. The cause of death was listed as “blunt force head and thoracoabdominal injuries.”

The driver of the Buick LeSabre was taken to the hospital with “moderate” injuries.

All the vehicles were towed from the scene.



Figure 5. Final rest, Toyota Corolla



Figure 6. Final rest positions for Buick LeSabre and Ford Aerostar

VEHICLE DATA -2003 Toyota Corolla

The case vehicle was a 2003 Toyota Corolla four-door sedan. The vehicle was equipped with a 4-cylinder, 1.8 L (109 CID) engine, 4-speed automatic transmission, front wheel drive, air conditioning, power steering, and a tilt steering wheel.

VIN: JTDBR38E530xxxxxx
 Odometer: 34,839 km
 (21,648 miles)
 Reported Defects: None based on police mechanical inspection.
 Cargo: Child seat in passenger compartment, stroller in trunk.

The 2003 Toyota Corolla was equipped with Gillette Golden Bear Touring SE P205/55R16 tires with Maxxim alloy rims. The specific tire data is as follows:

Tire	Tread	Measured pressure	Manufacturer recommended pressure
LF	6 mm (8/32 in)	179 kPa (26 psi)	241 kPa (35 psi)
LR	8 mm (10/32 in)	flat	241 kPa (35 psi)
RF	6 mm (8/32 in)	76 kPa (11 psi)	241 kPa (35 psi)
RR	8 mm (10/32 in)	flat	241 kPa (35 psi)

The front seating positions in the 2003 Toyota Corolla were configured with fabric covered bucket seats with adjustable head restraints. The rear seating positions were configured with a fabric covered bench seat with a 60/40 folding back and integral head restraints for the outboard positions.

VEHICLE DAMAGE

Exterior Damage - 2003 Toyota Corolla

Damage Description:	Major damage to front end, right side, and rear. The front bumper, hood, and fenders sustained damage. The right side intruded into the passenger compartment.	
CDC:	Impact 1: 03RZAW4 (Ford van) Impact 2: Unknown (Ford van) Impact 3: 01FDEW1 (Buick LeSabre) Impact 4: Unknown (fence)	
Delta V (Impact 1):	Total	72.2 km/h (44.9 mph)
	Longitudinal	-12.5 km/h (-7.8 mph)
	Latitudinal	-71.1 km/h (44.2 mph)
	Energy	136,553 joules (100,716 ft-lbs)
Delta V (Impact 3):	Total	50.3 km/h 31.3 mph)
	Longitudinal	-43.6 km/h (-27.1 mph)
	Latitudinal	-25.2 km/h (-15.6 mph)
	Energy	135,674 joules (100,068 ft-lbs)

Direct damage from Impact 1 (Ford van) began 153.0 cm (60.2 in) rearward from the front axle. It measured 180.0 cm (70.8 in) and extended to the rear of the vehicle. A crush profile was taken above the sill which measured: C1= 25.0 cm (9.8 in), C2= 46.0 cm (18.1 in), C3=51.0 cm (20.0 in), C4=27.0 cm (10.6 in), C5=0 cm (0 in), C6=1.5 cm (0.6 in).

Direct damage from Impact 3 (Buick LeSabre) began and the front left corner of the vehicle and extended across the entire front end. The bumper, bumper fascia, bumper backing bar, and radiator had been removed prior to the vehicle inspection.




Figure 7. Right rear, Toyota Corolla

Interior Damage - 2003 Toyota Corolla

Interior damage to the Toyota Corolla was significant and was attributed to occupant contact and passenger compartment intrusion. The windshield sustained fracture damage from impact forces and the front right passenger's air bag. The back light and all the glass on the right side was disintegrated by impact forces. There was extensive right side intrusion, including intrusion through both right side doors, the sill, and the B/C pillars. The maximum intrusion was the sill into the right rear seating position and measured 39.0 cm (15.3 in) laterally. The rear right door intruded 32.0 cm (12.6 in) laterally into this same area. There was loading damage to the right rear door arm rest from contact with the child seat in this location. There was loading damage to center console and center mounted shifter from contact with the driver.



Figure 8. Front, Toyota Corolla



Figure 9. Center console driver contacts




Figure 10. Right rear door intrusion

MANUAL RESTRAINT SYSTEMS - 2003 Toyota Corolla

The Toyota Corolla was configured with manual 3-point lap and shoulder belts with sliding latch plates for all five seating locations. The front seat restraints were configured with adjustable shoulder belt anchorages with the driver's side adjusted to the mid position and the front right passenger's adjusted to the full down position. The driver's manual restraint was configured with an emergency locking retractor (ELR). The remaining restraints were configured with switchable retractors that were in the ELR mode. Both front restraints were equipped with seat belt pretensioners that actuated as a result of the impact with the 1997 Buick LeSabre.




Figure 11. Driver's seat belt



Figure 12. Load marks to driver's seat belt

FRONTAL AIR BAG SYSTEM - 2003 Toyota Corolla

The Toyota Corolla was equipped with dual stage deployment frontal air bags that deployed as a result of the impact with the 1997 Buick LeSabre. The driver's air bag was housed in the steering wheel hub split H configuration cover flaps. The driver's air bag was circular in shape and measured 60.0 cm (23.6 in) in diameter in its deflated state. The air bag was vented by two circular ports located at the 11 and 1 o'clock positions on the rear aspect. The air bag was tethered by a single internal strap. There were no indications of damage or occupant contacts to either the air bag or the cover flaps.



Figure 13. Face of driver's air bag

The front right passenger's air bag deployed from a top mount module with a single cover flap. The flap measured 23.0 cm (9.0 in) wide by 6.0 cm (2.4 in) high. The air bag measured 42.0 cm (16.5 in) in width and 54.0 cm (21.2 in) in height. The air bag was not tethered and was vented by two circular ports that were located at the 9 and 3 o'clock positions. There were no occupant contacts to the air bag or the cover flap. The air bag sustained a 3.0 cm (1.2 in) cut that was 8.0 cm (3.1 in) from the left edge and 29.0 cm (11.4 in) from the top of the air bag face. The cut was as a result of contact to the windshield during deployment.




Figure 14. Cut on upper left portion of front right passenger's air bag

SIDE AIR BAGS - 2003 Toyota Corolla

The Toyota Corolla was equipped with seat back mounted side air bags for the front seating positions. The front right passenger's side air bag deployed as a result of the impact with the Ford Aerostar van. This air bag was shaped in a half-circle that measured 31.0 cm (12.2 in) in height and projected forward 21.0 cm (8.3 in) at the apex of the circle. The air bag was not tethered and did not have any vents. There were no indications of damage or occupant contacts to the air bag.



Figure 15. Front right side air bag

CHILD SAFETY SEAT - 2003 Toyota Corolla

The Graco Quattro Tour child safety seat (Model Number: 7411LV, manufacture date 12/09/02, serial number JJ12090210165) is part of a three-piece set that includes the Quattro Tour stroller, the child car seat, and a stay-in-car base. The stroller was in the trunk at the time of the crash. The manufacturer recommends that the seat be used with children weighing 9 kg (20 lbs) or less and whose height is 66 cm (26 in) or less. The child in this crash weighed 9 kg (19 lbs), putting her in the high range recommended by the manufacturer. The child seat was placed in the right rear seat position in a rear-facing fashion. The seat was attached to the stay-in-car base, the locking handle was in the up position, and the seat was equipped with a 5-point harness which had been threaded through the bottom set of slots. The seat base is designed to allow four different recline positions. The recline position is not known. The seat base was anchored to the vehicle using the available Lower Anchors and Tethers for Children (LATCH) system. According to the police, the seat was being tightly held in place at the time of the crash. It was necessary for the investigating police agency to cut the LATCH tethers to remove the child seat.

The right and left sides, as well as the front, of the base was cracked and deformed from the impact with the Ford and the resultant interior intrusion. The seat itself did not appear to have sustained any damage. There were no indications of any occupant contact to the inner seat shell.

The investigating officer had been trained as a Child Passenger Safety Technician. It was his opinion that the seat usage and installation met applicable state motor vehicle laws. He did note the following issues:



Figure 16. Graco Quattro Tour, Model Number: 7411LV. Image from www.gracobaby.com.




Figure 17. LATCH installation (Graco)



Figure 18. LATCH tethers

1. The passenger harness straps were folded at the point where they passed through the retaining clip reducing their width.
2. The carrier handle was in the full upright position.
3. There were toys hanging from the carrier handle above the head of the child. .



Figure 19. Front of Graco child seat



Figure 20. Fractures to front of child seat base.



Figure 21. Left side of seat (nearest impact).
Seat attached to base.

VEHICLE DATA - 1992 Ford Aerostar

Description:	1992 Ford Aerostar XL 4x2 van	
VIN:	1FMDA11U2NZxxxxxx	
Odometer:	Unknown	
Engine:	3.0 L V6	
Reported Defects:	None based on police mechanical inspection.	
Cargo:	Unknown	
Damage Description:	Major front end damage. Vehicle towed from the scene.	
CDC:	12FDEW3 (impact with Toyota Corolla) Unknown (impact with rear of Buick)	
Delta V:	Total	53.5 km/h (33.3 mph)
	Longitudinal	-52.7 km/h (-52.7 mph)
	Latitudinal	9.3 km/h (5.8 mph)
	Energy	266,950 joules (196,892 ft-lbs)



Figure 23. Front left, Ford Aerostar



Figure 22. Right rear, Ford Aerostar

VEHICLE DATA - 1997 Buick LeSabre

Description: 1997 Buick LeSabre Limited 4-door sedan
VIN: 1G4HR52K2VHXXXXXX
Odometer: 103,988 km
(64,615 miles)
Engine: 3.8 L V6
Reported Defects: None based on police mechanical inspection.
Cargo: Unknown
Damage Description: Major front end damage. Vehicle towed from the scene.
CDC: 12FDEW2 (impact with Toyota)
Unknown (impact with rear of Aerostar)
Delta V:
Total 36.6 km/h (22.7 mph)
Longitudinal -36.0 km/h (-22.4 mph)
Latitudinal 6.4 km/h (3.9 mph)
Energy 119,238 joules
(87,945 ft lbs)



Figure 24. Front left, Buick LeSabre



Figure 25. Front air bags, Buick LeSabre

OCCUPANT DEMOGRAPHICS - 2003 Toyota Corolla

	Driver	Occupant 2
Age/Sex:	28/Female	6 month/Female
Seated Position:	Front left	Rear right
Seat Type:	Fabric covered bucket seat. The seat track was found in the rear most position, but the seat was likely moved prior to inspection. Seat back slightly reclined.	Fabric covered bench seat with 60/40 folding back. Seat back slightly reclined by design.
Height:	173 cm (68 in)	71 cm (28 in) ²
Weight:	68 kg (150 lbs)	9 kg (19 lbs)
Occupation:	Unknown	NA
Pre-existing Medical Condition:	None	None
Alcohol/Drug Involvement:	None	NA
Driving Experience:	Approximately 10 years	NA
Body Posture:	Normal, upright	Upright in infant safety seat
Hand Position:	Both hands presumed to be on steering wheel, involved in steering maneuver	NA
Foot Position:	Right foot on brake, left on floorboard	NA
Restraint Usage:	Lap and shoulder belt available, used.	Lap and shoulder belt available. Not used.
Air bag:	Steering wheel mounted front air bag, deployed.	None

²Additional measurements: crown-rump length 50.0 cm (19.6 in), head circumference 45.0 cm (17.7 in), chest circumference 44.5 cm (17.5 in), abdominal circumference 44.0 cm (17.3 in).

OCCUPANT DEMOGRAPHICS - 1992 Ford Aerostar

	Driver
Age/Sex:	20/Male
Seated Position:	Front left
Seat Type:	Unknown
Height:	185 cm (73 in)
Weight:	84 kg (185 lbs)
Occupation:	Unknown
Pre-existing Medical Condition:	None noted
Alcohol/Drug Involvement:	None
Driving Experience:	Unknown
Body Posture:	Unknown
Hand Position:	Unknown
Foot Position:	Left foot on floor, right presumed to be on brake
Restraint Usage:	Lap and shoulder belt used, per police

OCCUPANT DEMOGRAPHICS - 1997 Buick LeSabre

	Driver
Age/Sex:	73/Male
Seated Position:	Front left
Seat Type:	Bucket
Height:	180 cm (71 in)
Weight:	77 kg (170 lbs)
Occupation:	Unknown
Pre-existing Medical Condition:	None noted
Alcohol/Drug Involvement:	None
Driving Experience:	Presumed to be greater than 20 year
Body Posture:	Unknown
Hand Position:	Unknown
Foot Position:	Left on floor, right presumed to be on floor board
Restraint Usage:	Lap and shoulder belt used, per police report

OCCUPANT INJURIES -2003 Toyota Corolla

Driver: Skeletal injuries obtained from consultation report, emergency room report, physician's record, progress notes, and radiology reports. A CT scan was completed for the head with no pathological findings. There were notes regarding a possible pulmonary contusion, possible rib fractures, and some type of back injury. None of these were confirmed.

<u>Injury</u>	<u>OIC Code</u>	<u>Injury Mechanism</u>	<u>Confidence Level</u>
Comminuted left superior and inferior ramus fracture	852604.3,2	Center console	Probable
Minimally displaced right superior ramus fracture	852602.2,1	Center console	Probable
Left medial malleolus fracture (coded under fibula)	853412.2,2	Foot controls	Possible
Head contusions/abrasions, left frontal region	190402.1,5 190202.1,5	Driver's air bag	Possible
Chin contusions/abrasions	290402.1,8 290202.1,8	Driver's air bag	Probable
Teeth mark laceration, lower inner lip	290600.1,8	Driver's air bag	Probable
Abrasion, left shoulder extending down onto the left breast	790202.1,2 490202.1,2	Torso belt	Probable
Ecchymosis, left upper arm	790402.1,2	Left side door panel	Probable
Abrasions, abdomen	590202.1,9	Lap belt	Certain

Right rear Occupant: Injuries obtained from autopsy report and the EMS pre-hospital care report from the air ambulance. Virtually all injuries were as a result of contact to the interior of the child seat that exacerbated by the right side vehicle intrusion.

<u>Injury</u>	<u>OIC Code</u>	<u>Injury Mechanism</u>	<u>Confidence Level</u>
Bilateral parietal bone fractures	150402.1,1 150402.1,2	Interior, child safety seat	Certain
Subarachnoid hemorrhage	140684.3,9	Interior, child safety seat	Certain
Contusion hemorrhage, left thalamus	140602.3,2	Interior, child safety seat	Probable
Fracture, right temporal bone	150402.2,1	Interior, child safety seat	Probable
Comminuted fracture, left middle cranial fossa	150404.3,2	Interior, child safety seat	Certain
Laceration, liver, 1cm on inferior surface at porta hepatis, 0.5 cm deep	541820.2,1	Interior, child safety seat	Probable
Laceration, spleen, 1 cm, upper pole	544222.2,2	Interior, child safety seat	Probable
Rib fractures, right 1 st - 2 nd , left 1 st -3 rd	450220.2,3	Interior, child safety seat	Certain
Left clavicle fracture, midline	752200.2,2	Interior, child safety seat	Certain
Lacerations/abrasions right parietal scalp, 4x2 cm, faint dicing pattern	190202.1,1	Interior, child safety seat	Certain
Contusion, right occipital scalp, ovoid, 2 cm. Contusion, lower right mid occipital scalp, 4x3 cm.	190402.1,6	Interior, child safety seat	Probable
Contusion, right ear	290402.1,1	Interior, child safety seat	Probable
Contusion/abrasion, near right ear	290402.1,1	Interior, child safety seat	Probable

Abrasion, from right eyebrow to right cheek, 5.5 x 1 cm, curved	290202.1,1	Interior, child safety seat	Probable
Contusion, right cheek, 4 x 1.2 cm. Contusion, right temple.	290402.1,1	Interior, child safety seat	Probable
Abrasion, right forehead	290202.1,7	Interior, child safety seat	Probable
Abrasions, left upper parietal scalp, 2 x 1.5 cm	190202.1,2	Interior, child safety seat	Certain
Contusion, left forehead, 2 x 0.5 cm. Contusion, left lateral forehead extending over the lateral orbital rim, 5 x 2.5 cm	290402.1,7	Interior, child safety seat	Certain
Abrasions, left side of face	290202.1,2	Interior, child safety seat	Certain
Abrasion, left chin, 2.5 x 0.8 cm, ovoid	290202.1,8	Interior, child safety seat	Certain
Contusion, left jaw line, 1.5 cm	290402.1,8	Interior, child safety seat	Certain
Abrasion, above left ear, 2cm, ovoid	290202.1,2	Interior, child safety seat	Certain
Abrasion, left parietal scalp, 1.2 cm	190202.1,2	Interior, child safety seat	Certain
Contusion, left cheek, 2 cm	290402.1,2	Interior, child safety seat	Certain
Linear marks, red, top of left shoulder	Unknown	Harness	Probable
Contusion, left upper pectoral area, 2.5 x 1 cm	490402.1,2	Interior, child safety seat	Child seat harness
Contusion, left lateral abdomen, 4 cm	590402.1,2	Unknown	Unknown
Contusion, right index finger	790402.1,1	Unknown	Unknown
Contusion, lateral upper right arm, 1.5 cm	790402.1,1	Interior, child safety seat	Probable

Contusion, right anterior upper arm extending onto ventral forearm, 9.5 x 6 cm	790402.1,1	Interior, child safety seat	Probable
Contusion, left dorsal wrist, 1.5 cm	790402.1,2	Interior, child safety seat	Certain
Contusion, left dorsal forearm, 4.5 x 2 cm	790402.1,2	Interior, child safety seat	Certain
Contusion, anterior upper left arm, 6 x 5.5 cm, ovoid	790402.1,2	Interior, child safety seat	Certain
Contusion, anterior upper left arm, 3 cm, ovoid	790402.1,2	Interior, child safety seat	Certain
Contusion, lateral left upper arm, oblique oriented from upper anterior to lower posterior, 7 x 1 cm, with 3 x 2 cm angle at end	790402.1,2	Interior, child safety seat	Certain
Contusion, right hip to medial thigh, 16 cm long by up to 2 cm wide	890402.1,1	Child seat harness	Probable
Abrasion, right hip, 1.2 cm	890202.1,1	Interior, child safety seat, rebound	Probable
Contusion, right lateral knee, 3.5 x 2 cm	890402.1,1	Interior, child safety seat, rebound	Probable
Contusion, 2 cm, lower leg, unknown aspect	890402.1,9	Unknown	Unknown
Contusion, right calf, 1.5 cm	890402.1,1	Interior, child safety seat	Probable
Contusion, left upper thigh onto the medial thigh, 7 x 2.5 cm (almost merges with contusion of abdomen)	890402.1,2	Interior, child safety seat	Certain
Contusion, left medial thigh, 6 x 2.5 cm with 1.5 cm abrasion	890402.1,2	Interior, child safety seat	Certain
Contusion, left medial knee, 3 x 1 cm	890402.1,2	Interior, child safety seat	Certain

Contusion, left lower leg, 0.7 cm, ovoid	890402.1,2	Interior, child safety seat	Certain
Contusion, left lateral lower leg, 3 cm	890402.1,2	Interior, child safety seat	Certain
Contusion, left calf, 1 cm, ovoid	890402.1,2	Interior, child safety seat	Certain
Contusions, both lobes of thymus ³	490402.1,3	Child safety seat harness	Probable
Fracture, right petrous bone	150402.2,1	Interior, child safety seat	Certain
Contusion, behind left ear	290402.1,2	Interior, child safety seat	Certain

OCCUPANT INJURIES -1992 Ford Aerostar

Driver: No reported injuries.

OCCUPANT INJURIES - 1997 Buick LeSabre

Driver: Injuries obtained from police report.

<u>Injury</u>	<u>OIC Code</u>	<u>Injury Mechanism</u>	<u>Confidence Level</u>
Multiple abrasions, entire body	990200.1,0	Unknown	Unknown
Multiple contusions, entire body	990400.1,0	Unknown	Unknown

³A lymphoid organ situated in the center of the upper chest just behind the sternum.

OCCUPANT KINEMATICS - 2003 Toyota Corolla

The 28-year-old female driver of the case vehicle was seated in a normal, upright fashion in a fabric covered bucket seat. The seat was found adjusted to the rear most track position but given the driver's height (173 cm/68 in) it is more likely that the seat had been moved prior to the vehicle inspection. The seat back was slightly reclined. The driver was using the available lap and shoulder belt. The shoulder belt anchorage was adjusted to the mid position. Prior to impact, the case vehicle had been involved in an evasive maneuver. Both hands were on the steering wheel actively involved in efforts to steer out of the counterclockwise vehicle rotation. The right foot was on the brake, the left on the floorboard. At impact with the Aerostar, the driver responded to the 3 o'clock direction of force by pitching sharply to the right. While the restraint system kept her generally in place, her hips went to the right and engaged the shifter and center console—causing the bilateral pelvic fractures—and her lower legs pitched to the right and engaged the foot controls—causing the medial malleolus fracture. The case vehicle was redirected in a clockwise direction before being struck in the front by the Buick LeSabre. The driver responded to the 1 o'clock direction of force by moving forward and to the right. At impact, the driver's air bag deployed and the driver's seat belt pretensioner actuated. The driver pitched forward and engaged the locked seat belt system—causing abrasions to her shoulder and hip. Her face engaged the deployed air bag—causing abrasions and contusions to her face/head and also caused her to bite her lip.



Figure 26. Contact to shifter and center console



Figure 27. Damage to right rear door side panel due to impact, intrusion, and contact with infant safety seat

The 6-month-old female rear right occupant was seated in a Graco Quattro Tour infant safety seat placed on the fabric covered 60/40 bench seat. The infant seat was placed in the right rear seat position in a rear-facing fashion. The seat was attached to the stay-in-car base, the locking handle was in the up position, and the seat was equipped with a 5-point harness which had been threaded through the bottom set of slots. The seat base was anchored to the vehicle using the available Lower Anchors and Tethers for Children (LATCH) system. According to the police, the seat was being tightly held in place at the time of the crash. At impact with the Aerostar, this occupant initially moved sharply to the right within the confines of the seat and engaged the

child seat interior with essentially the whole left side of her body. As the impact progressed, the right rear door intruded into and fractured the child seat exacerbating the left side injuries, including the clavicle and skull fractures. This occupant also sustained right side skull and rib fractures and lacerations to the spleen and liver. Given the amount of intrusion and the fact that the restraint remained in place, the injuries were a combination of impact and compression as the child safety seat was intruded on by the right door panel. At impact with the Buick, this occupant would have responded to the 1 o'clock direction of force by moving forward (with her back) and to the right.



Figure 28. Front of Graco child seat

Attachment 1. Scene Diagram

