

Side Curtain Air Bag Investigation  
Dynamic Science, Inc. (DSI), Case Number DS08022  
2006 Subaru B9 Tribeca  
Nebraska  
May 2008

---

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points be coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the pre-crash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

---

1. Report No. DS08022		2. Government Accession No.		3. Recipient Catalog No.	
4. Title and Subtitle Side Curtain Air Bag Investigation				5. Report Date December 22, 2008	
				6. Performing Organization Report No.	
7. Author(s) Dynamic Science, Inc.				8. Performing Organization Report No.	
9. Performing Organization name and Address Dynamic Science, Inc. 299 West Cerritos Avenue Anaheim, CA 92805				10. Work Unit No. (TRAIS)	
				11. Contract or Grant no. DTNH22-07-00045	
12. Sponsoring Agency Name and Address U.S. Dept. of Transportation (NVS-411) National Highway Traffic Safety Administration 1200 New Jersey Ave, SE Washington, DC 20590				13. Type of report and period Covered [Report Month, Year]	
				14. Sponsoring Agency Code	
15. Supplemental Notes					
16. Abstract This on-site investigation focused on the deployment of the side curtain and seat mounted side air bags in a 2006 Subaru Tribeca that was involved in a three vehicle crash. The Tribeca was being driven by a restrained 27-year-old female. The Tribeca was struck on the left side by a 2003 Chevrolet Tahoe sport utility vehicle. The impact resulted in sufficient lateral deceleration of the Subaru to command the deployment of the left side curtain air bag and left seat mounted air bag. After the initial impact, the Subaru was deflected laterally to the right across the intersection and contacted a 1999 Mercedes-Benz E430 four-door sedan. There were no reported injuries. The Subaru was towed from the scene due to damage and was later to be declared a total loss by the insurance company. The Chevrolet was towed from the scene and was not available for an inspection. The Mercedes was driven from the scene.					
17. Key Words Side air bag, side air curtain, deployment, side impact			18. Distribution Statement		
19. Security Classif. (of this report)	20. Security Classif. (of this page)	21. No of pages	22. Price		

**Dynamic Science, Inc.**  
**Crash Investigation**  
**Case Number: DS08022**

**TABLE OF CONTENTS**

Background .....	1
Summary .....	1
Crash Site .....	1
Pre Crash .....	2
Crash .....	2
Post Crash .....	2
Vehicle Data - 2006 Subaru B9 Tribeca .....	2
Vehicle Damage .....	3
Exterior Damage .....	3
Interior Damage .....	4
Manual Restraints .....	5
Occupant Demographics .....	7
Occupant Kinematics .....	7
Occupant Injuries .....	7
Attachment 1. Scene Diagram .....	8

## BACKGROUND

This on-site investigation focused on the deployment of the side curtain and seat mounted side air bags in a 2006 Subaru Tribeca that was involved in a three vehicle crash (**Figure 1**). The Tribeca was being driven by a restrained 27-year-old female. The front right seat was occupied by a 28-year-old female. The Tribeca was struck on the left side by a 2003 Chevrolet Tahoe sport utility vehicle. The impact resulted in sufficient lateral deceleration of the Subaru to command the deployment of the left side curtain air bag and left seat mounted side air bag. After the initial impact, the Subaru was deflected laterally to the right across the intersection and contacted a 1999 Mercedes-Benz E430 four-door sedan. There were no reported injuries. The Subaru was towed from the scene due to damage and was later declared to be a total loss by the insurance company. The Chevrolet was towed from the scene and was not available for an inspection. The Mercedes was driven from the scene.



**Figure 1.** Damaged 2006 Subaru Tribeca

This crash was identified by the National Highway Traffic Safety Administration (NHTSA) during a review of General Estimates System (GES) police reports. On July 3, 2008, DSI was sent a copy of the police report and instructed to obtain permission to inspect the subject vehicle, a 2006 Subaru Tribeca sport utility vehicle. On July 9, 2008, DSI located the vehicle at an auto salvage facility and obtained permission to conduct the inspection. The case number was assigned on July 10, 2008 and the field work was completed on July 17, 2008.

## SUMMARY

### Crash Site

This crash occurred at a four-leg intersection in May 2008 at 2115 hours. At the time of the crash, there were no adverse weather conditions and the concrete roadways were dry. The roadways were dark and the streetlights were on. The intersection was controlled by traffic signals at each leg. The westbound leg of the intersection was comprised of two westbound travel lanes, a left hand turn lane, and two eastbound travel lanes. There was a right curve approaching the intersection (**Figure 2**). The eastbound leg of the intersection was comprised of a right turn lane, two eastbound travel lanes, a left turn lane, and three westbound travel lanes (**Figure 3**). The left turn lane was separated from the westbound travel lanes by a raised median. The southbound leg of the intersection was comprised of a right turn lane, a southbound lane, a left turn lane, and a single northbound lane (**Figure 4**). The speed limit was 64 kmph (40 mph) for all the involved roadways.



**Figure 2.** Westbound approach for the Subaru Tribeca

## Pre Crash

The Subaru Tribeca was traveling west in the second lane from the right and was approaching the intersection. A 2003 Chevrolet Tahoe truck was being driven east by a restrained 29-year-old male and had come to a stop in the left turn lane. A 1999 Mercedes E430 four-door sedan was being driven south by a 48-year-old female and had come to a stop at the intersection. As the Tribeca entered the intersection, the Tahoe began a left turn to the north.

## Crash

The driver of the Tribeca steered her vehicle to the right, but the front of the Tahoe struck the left side of the Tribeca. The seat mounted side air bag and the side curtain air bag deployed at impact. The Missing Vehicle algorithm of the WinSmash program computed a total delta V of 21.0 km/h (13.0 mph), based on the Tribeca's left side crush profile. The longitudinal and lateral components were -13.5 km/h (-8.4 mph) and 16.1 km/h (10.0 mph), respectively. After the initial impact, the Tribeca began a counterclockwise rotation, traveled in a northwest direction across the intersection, and struck the left side of the Mercedes.

## Post Crash

There were no injuries reported. The Tribeca was towed from the scene and was later declared to be a total loss by the insurance company. The Tahoe was towed from the scene to an undisclosed location. The Mercedes was driven from the scene.

## Vehicle Data - 2006 Subaru B9 Tribeca

The 2006 Subaru Tribeca was identified by the Vehicle Identification Number (VIN): 4S4WX82C064xxxxxx. The date of manufacture was October 2005. The vehicle's odometer could not be read because there was no power to the vehicle. The Tribeca was a 4-door, 5-passenger sport utility vehicle that was equipped with a 3.0 liter, 6-cylinder engine, a 5-speed automatic transmission, front/rear anti-lock disc brakes, vehicle dynamics control (VDC), power steering, and a tilt steering wheel. The Tribeca was configured with Goodyear Eagle P255/55R18 tires. The vehicle manufacturer's recommended cold tire pressure was 221 kPa (32 psi); the tire manufacturer's stated maximum pressure was 303 kPa (44 psi).

The specific tire information was as follows:



**Figure 3.** Eastbound approach for the Chevrolet Tahoe



**Figure 4.** Southbound approach for the Mercedes E430

Position	Measured Pressure	Measured Tread Depth	Restricted	Damage
LF	276 kPa (40 psi)	10 mm (12/32 in)	No	None
LR	Tire Flat	7 mm (9/32 in)	No	Sidewall and tread holed
RR	248 kPa (36 psi)	9 mm (11/32 in)	No	None
RF	290 kPa (42 psi)	6 mm (7/32 in)	No	None

The left rear tire was torn during the crash (**Figure 5**). There was a T-shaped tear that began in the sidewall and extended to the outboard portion of the tread. The base of the “T” measured 11 cm (4.3 in) in a diagonal direction. The left portion of the “T” measured 19 cm (7.5 in) and the right portion measured 5 cm (2.0 in). There was also a 12 cm (4.7 in) long tear in the tread. The tear was diagonal and began 4 cm (1.6 in) from the side wall and terminated 2 cm (0.8 in) from the sidewall.



**Figure 5.** Damaged left rear tire

The seating in the Subaru Tribeca was configured with front bucket seats with active head restraints and a rear 40/20/40 split back bench seat. The front seat head restraints are designed to automatically tilt forward in the event of a rear impact thereby decreasing the amount of rearward head movement. The driver’s seat was located in the mid track position. The seat back was at a 19 degree angle from vertical and the seat cushion was at an 18 degree angle from horizontal.

## Vehicle Damage

### Exterior Damage - 2006 Subaru B9 Tribeca

The 2006 Subaru Tribeca sustained moderate left side plane damage from the impact with the Chevrolet pickup (**Figure 6**). The direct damage began 68 cm (26.8 in) aft of the front axle and extended 254 cm (100 in) rearward along the left side plane. The height of the maximum door crush was 63 cm (24.8 in) from the ground and was located near the trailing edge of the left rear door. The left rear door was jammed shut.



**Figure 6.** Left side damage, Subaru Tribeca

The suspension trailing arm for the left rear wheel was fractured and separated at the wheel from impact with the pickup. At the time of the inspection, the wheel/tire had a positive camber of approximately 45 degrees. The left rear bumper fascia was dislodged and tilted downward. The combined direct and induced damage began 65 cm (25.6 in) aft of the front axle and extended 265 cm (104.3 in) rearward along the left side plane. Six crush measurements were documented at the mid-door level as follows: C1 = 0 cm, C2 = 9 cm (3.5 in), C3 = 18 cm (7.0 in), C4 = 15 cm (5.9 in), C5 = 6 cm (2.4 in), C6 = 0 cm. The maximum lateral crush was located at C3 and was 61 cm (24.0 in) above the ground. The Collision Deformation Classification (CDC) for the impact with the pickup was 10LZEW2.



**Figure 7.** Light scratches to left bumper corner and area below tail light

The police report stated that the right rear of the Subaru contacted the left side of the Mercedes after the initial impact with the Chevrolet pickup. There were no indications of damage on the right rear corner. There were, however, several light scratches located at the left rear bumper corner and below the left tail light that seem consistent with the impact. The CDC for this second event was 06BLEE1.



**Figure 8.** Left lower door intrusion

### Interior Damage - 2006 Subaru B9 Tribeca

The 2006 Subaru Tribeca sustained minor interior damage as a result of passenger compartment intrusion (**Figure 8**). The lower leading edge and the rear upper quadrant of the left rear door and left A-pillar sustained lateral intrusion. As a result of the lateral intrusion, the inboard area of the left rear door was pressed against the second row seat cushion

The specific passenger compartment intrusions were documented as follows:

Position	Intruded Component	Magnitude of Intrusion	Direction
Second row left	Door/Rear upper quadrant	9 cm (3.5 in)	Lateral
Front row left	A-pillar	4 cm (1.6 in)	Lateral



### Manual Restraints - 2006 Subaru B9 Tribeca

The 2006 Subaru Tribeca was configured with 3-point manual lap and shoulder belts for all five seating positions. Both front seat safety belts were equipped with retractor pretensioners and adjustable D-rings that were in the full down position. The driver's safety belt was configured with a sliding latch plate and an Emergency Locking Retractor (ELR). At the time of the vehicle inspection, the driver's retractor was restricted in the used position as a result of pretensioner actuation (**Figure 9**). A 6.5 cm (2.6 in) linear plastic transfer from the plastic-covered latch plate was located 61 cm (24.0 in) above the anchor and extended across the entire width of the webbing. There was an area of abrasion located in the belt path of the latch plate (**Figure 10**). The abrasion extended across the entire width of the belt path.

The remaining safety belts were configured with sliding latch plates and switchable ELR/Automatic Locking Retractors (ALR). The retractor for the second row middle seat was located in the roof. The front right safety belt was restricted in the stowed position at the time of inspection as a result of pretensioner actuation.

### Supplemental Restraint Systems - 2006 Subaru B9 Tribeca

The Subaru Tribeca was equipped with advanced occupant protection systems including multi-stage Certified Advanced 208-Compliant driver and front right passenger air bags. The multi-stage air bags were certified by the manufacturer to meet the advanced air bag requirements of Federal Motor Vehicle Safety Standard (FMVSS) No. 208. The frontal air bags did not deploy.

The Tribeca was also equipped with side curtain air bags and seat mounted side air bags. The left side curtain and left seat mounted air bags deployed as a result of the impact with the pickup truck (**Figures 11-12**). The right side air bags did not deploy. The curtain air bags included curtain air bag modules in the roof rail behind the C-pillars and sensors located forward of the rear wheels.



**Figure 9.** Driver's belt restricted in used position



**Figure 10.** Loading to driver's seat belt latch

The seat mounted side air bags included the module in the seat back and a side air bag sensor located in the B-pillar. The curtain air bags and side air bags were not controlled by the Subaru's advanced frontal air bag system

The left side curtain air bag deployed vertically from roof cladding. The curtain measured 166 cm (65.3 in) in length and 47 cm (18.5 in) in height. It provided coverage for both the first and second rows of the vehicle. The curtain was attached to the left A-pillar by a 3 cm (1.2 in) tether. The forward portion of the curtain was comprised of a single piece of nylon cloth that measured 28 cm (11.0 in) in width and 31 cm (12.2 in) in height. The rear of the curtain was secured to the vehicle by a fabric tether that was located in the roof just aft of the C-pillar. There were no indications of damage or contact to the curtain.

The left side air bag deployed longitudinally from the driver's seat back. The deployed air bag measured 32 cm (12.6 in) wide by 59 cm (23.2 in) high in its deflated state. The air bag was generally oval in shape. There were a set of three 0.5 cm (0.2 in) vent ports on both the outboard and inboard aspect of the air bag. There was one 2 cm (0.8 in) circular vent port located on the leading edge of the outboard aspect of the air bag. There were no indications of damage or contact to the side air bag.



**Figure 11.** Exterior view, side air bags



**Figure 12.** Interior view, side air bags

**OCCUPANT DEMOGRAPHICS - 2006 Subaru B9 Tribeca**

	<b>Driver</b>	<b>Front Right Passenger</b>
Age/Sex:	27/Female	28/Female
Seated Position:	Front left	Front right
Seat Type:	Bucket	Bucket
Height:	168 cm (66 in)	Unknown
Weight:	64 kg (140 lbs)	Unknown
Alcohol/Drug Involvement:	None	None
Body Posture:	Normal, upright	Normal, upright
Hand Position:	Both hands on steering wheel, actively steering to right	Unknown
Foot Position:	Right foot on brake, left on floorboard	Both on floorboard
Restraint Usage:	Lap and shoulder belt used	Lap and shoulder belt available, not used
Air bag:	Driver's frontal air bag available, did not deploy. Side curtain and side air bag available, deployed.	Front right passenger air bag, side curtain air bag, seat mounted side air bag available, did not deploy.

**OCCUPANT KINEMATICS - 2006 Subaru B9 Tribeca****Driver Kinematics**

The 27-year-old female driver was seated in an upright posture and was restrained by the 3-point manual lap and shoulder belt. The seat was positioned at the mid track position. The seat back was positioned 19 degrees from vertical and the seat cushion was positioned 18 degrees from horizontal. Prior to impact, the driver was actively steering to the right and was braking. At impact, the left side curtain air bag and the seat mounted side air bag deployed and the safety belt pretensioner actuated. The female driver initiated a lateral and slightly forward trajectory to the left in response to the 10 o'clock direction of force. She loaded the safety belt and likely contacted the deployed curtain air bag and side air bag, although no physical evidence of contact was identified. The vehicle rotated in a counterclockwise direction and the driver was likely displaced to the right. The rear of the subject vehicle struck the stopped Mercedes, but this was a minor impact that would have had a negligible effect on the driver. The driver came to rest in her original seating position. She did not sustain any injuries and was able to exit the vehicle under her own power.

**Front Right Occupant Kinematics**

The 28-year-old female front right occupant was seated in an upright posture and was not restrained by the 3-point manual lap and shoulder belt. Prior to impact, the driver was actively steering to the right and was braking. This occupant was displaced in a forward direction due to braking. At impact, this occupant initiated a lateral and slightly forward trajectory to the left. The vehicle rotated in a counterclockwise direction and the this occupant was likely displaced somewhat to the right. The rear of the subject vehicle struck the stopped Mercedes, but this was a minor impact that would have had a negligible effect on the this occupant. The front right occupant came to rest in her original seating position. She did not sustain any injuries and was able to exit the vehicle under her own power.

**OCCUPANT INJURIES - 2006 Subaru B9 Tribeca**

Driver: No injuries

Front Right Passenger: No injuries.

Attachment 1. Scene Diagram

