CRASH DATA RESEARCH CENTER

Calspan Corporation Buffalo, NY 14225

NOT-IN-TRAFFIC SURVEILLANCE CALSPAN REMOTE FALLING VEHICLE INCIDENT INVESTIGATION SCI CASE NO.: CA09010

VEHICLE: 2002 PONTIAC GRAND PRIX

LOCATION: TEXAS

INCIDENT DATE: FEBRUARY 2009

Contract No. DTNH22-07-C-00043

Prepared for:

U.S. Department of Transportation National Highway Traffic Safety Administration Washington, D.C. 20590

DISCLAIMER

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points are coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the pre-crash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

TECHNICAL REPORT STANDARD TITLE PAGE

1. Report No. CA09010	2. Government Accession No.	3. Recipient's Catalog No.		
4. Title and Subtitle Calspan Remote Falling Vehicle In Vehicle: 2002 Pontiac Grand Prix Location: Texas	cident Investigation	5. Report Date: February 2011		
		6. Performing Organization Code		
7. Author(s) Crash Data Research Center		8. Performing Organization Report No.		
9. Performing Organization Name and Calspan Corporation Crash Data Research Center P.O. Box 400 Buffalo, New York 14225	d Address	10. Work Unit No.		
		11. Contract or Grant No. DTNH22-07-C-00043		
12. Sponsoring Agency Name and Address U.S. Department of Transportation National Highway Traffic Safety Administration Washington, D.C. 20590		13. Type of Report and Period Covered Technical Report Incident Date: February 2009		
		14. Sponsoring Agency Code		

15. Supplementary Note

An investigation of the falling of a 2002 Pontiac Grand Prix from a jack which caused the death of a 47-year-old male victim.

16. Abstract

This remote investigation focused on the type of jack and the surface conditions that contributed to the death of a 47-year-old male victim of this falling vehicle incident. The victim was working under a 2002 Pontiac Grand Prix GT and was in the process of performing an oil change on the Pontiac when the vehicle fell off the jack, pinning the victim between the vehicle and the ground. He was discovered by his female companion approximately 45-60 minutes after she last conversed with him. The companion immediately called the emergency response system to report the incident and request emergency assistance. The local fire department arrived within 2-3 minutes of the call. The firefighters lifted the vehicle and pulled the victim from under the Pontiac. He was evaluated and pronounced deceased at the scene.

17. Key Words		18. Distribution Statement			
Jack	Falling	Incident	Victim	General Public	
19. Security	Classif. (of t	this report)	20. Security Classif. (of this page)	21. No. of Pages	22. Price
Unclassified		Unclassified Unclassified		17	

TABLE OF CONTENTS

BACKGROUND	1
SUMMARY	1
Incident Site	
Vehicle	
Exemplar Vehicle Jack/Owner's Manual	2
Victim	
Victim's Injuries	4
Incident Sequence	
Pre-Incident	5
Post-Incident	6
Incident Schematic	7
Not-In-Traffic Surveillance Forms	8

NOT-IN-TRAFFIC SURVEILLANCE CALSPAN REMOTE FALLING VEHICLE INCIDENT INVESTIGATION

SCI CASE NO.: CA09010

VEHICLE: 2002 PONTIAC GRAND PRIX

LOCATION: TEXAS
INCIDENT DATE: FEBRUARY 2009

BACKGROUND

This remote investigation focused on the type of jack and the surface conditions that contributed to the death of a 47-year-old male victim of this falling vehicle incident. The victim was working under a 2002 Pontiac Grand Prix GT and was in the process of performing an oil change on the Pontiac when the vehicle fell off the jack, pinning the victim between the vehicle and the ground (**Figure 1**). He was discovered by his female companion approximately 45-60 minutes after she last conversed with him. The



Figure 1. On-scene view of the position of the Pontiac within the yard. (Image provided by the investigating police department.)

companion immediately called the emergency response system to report the incident and request emergency assistance. The local fire department arrived within 2-3 minutes of the call. The firefighters lifted the vehicle and pulled the victim from under the Pontiac. He was evaluated and pronounced deceased at the scene.

This incident was identified by the Calspan Special Crash Investigations (SCI) team through an Internet news search on February 23, 2009. The news article was forwarded to NHTSA's Crash Investigation Division and assigned for remote follow-up on the day of the notification. Cooperation was established with the investigating police agency and an interview was conducted with the investigating police officer. The case was classified by the police as a death investigation and was reported as an Informational Report. This case was not reported to the State crash database. The Informational Report and on-scene images of the incident site, the

Pontiac, and the jack, in addition to the Medical Examiner's report were obtained by the SCI team and provided the basis for this report.

SUMMARY

Incident Site

This falling vehicle incident occurred in the backyard area of the victim's residence (Figure 2). The yard consisted of cut grass with a subtle cross slope of the yard, sloping downward from left to right across the heading of the Pontiac. The investigating officer



Figure 2. Overall view of the Pontiac on the lawn area. (Image provided by the investigating police department.)

reported that the ground was soft. According to local weather forecasts, the conditions at the time of the incident were dry with a temperature of 10 degrees C (50 degrees F). The sky was clear and the wind speed was reported at 16 km/h (10 mph). A schematic of the incident is included as **Figure 15**.

Vehicle

The involved vehicle in this incident was a 2002 Pontiac Grand Prix GT, four-door sedan. The police Informational Report did not capture the Vehicle Identification Number (VIN). The Pontiac Grand Prix GT model was equipped with a transverse-mounted 3.8 liter, V-6 gasoline engine linked to a 4-speed automatic transmission with a console mounted transmission selector lever. This vehicle was front-



Figure 3. View of the 2002 Pontiac Grand Prix. (Image provided by the investigating police department.)

wheel drive platform. The service brakes were power-assisted 4-wheel disc. The parking brake was pedal activated with the foot pedal located adjacent to the left lower kick panel. The cable actuated parking brake mechanically engaged the rear disc brake pads against the rotor. It is unknown if the parking brake was set on this vehicle at the on-set of the victim's attempted mechanical repairs.

The victim raised the Pontiac with the OEM jack that was stowed in the trunk of the vehicle. The on-scene police images of the incident suggested the victim removed several items from the trunk of the vehicle to retrieve the jack. These items included a Child Restraint System (CRS), spare tire, and a 12-volt car vacuum. The spare tire and the CRS were located directly behind the rear bumper of the Pontiac.

Exemplar Vehicle Jack/Owner's Manual

A 2001 Pontiac Grand Prix was used as an exemplar vehicle to document the OEM jack for this falling vehicle investigation. The exemplar OEM scissors jack was examined and the Vehicle Owner's Manual was reviewed for safety warnings. The exemplar jack was a scissors-style jack with a maximum extension height (Figure 4) of 34 cm (13.5 in). The H-configuration base



Figure 4. Maximum extension of the exemplar jack.



Figure 5. Base dimensions of the exemplar jack.

(Figure 5) of the jack was 15x13 cm (6x5 in). The saddle of the jack was channel-shaped (Figures 6 and 7) to fit the lip of the vehicle's sill. The saddle measured 7 cm (2.75 in) in length, 1 cm (0.375 in) in width and 1 cm (0.5 in) in depth.



Figure 6. Length of the saddle of the exemplar jack.



Figure 7. Width of the saddle of the exemplar jack.

The jack was stamped with a warning that read "Use Only On Vehicle Specified" (Figure 8). A yellow and black warning label affixed to the jack (Figure 9) advised the following:

Caution/Attention:

To help avoid personal injury, follow jacking instructions and use this jack only for changing tires on this vehicle.




Figure 8. Stamped warning on the exemplar jack.



Figure 9. Warning label on exemplar jack.

The Vehicle Owner's Manual identified the proper jacking point for this exemplar vehicle as approximately 15 cm (6 in) aft of the forward edge of the sill. The Cautions noted in **Figure 10** warned of the risks associated with getting under the vehicle with the jack in place. Cautions were also noted regarding the improper placement of the jack with respect to vehicle damage and personal injury.



Victim

The victim in this falling vehicle incident was a 47-year-old male with an autopsy reported height of 170 cm (67 in) and a weight of 72 kg (158 lb). He was dressed in gray sweat pants over blue denim jeans, a black and white pullover long-sleeve shirt, white socks and white and gray athletic shoes. The victim was in the process of changing the oil in his car when the incident occurred. He was alone in the yard to his residence; however, his companion was in the residence attending to two young children. The Medical Examiner reported cause of death was traumatic asphyxiation due to overlay by vehicle. The victim's injuries and the probable sources of those injuries are identified below.

Victim's Injuries

Injury	Injury Severity	Probable Injury Sources
	(AIS 90/Update 98)	
Left rib fractures (2 nd thru 7 th)	Serious (450230.3,2)	Vehicle undercarriage
anterior-lateral aspect		
Right chest contusions 4 x 4.5	Minor (490402.1,1)	Compression against the
cm area right pectoral chest,		ground
extending onto deltoid;		
parallel contusions 0.7cm		
center to center, Individual		
contusions are linear and up to		
4.5 x 0.2cm. A 2.5 x 0.8 cm		
contusion lies slightly below		
the larger injury		

Injury	Injury Severity (AIS 90/Update 98)	Probable Injury Sources
D: 14	1 /	
Right upper arm contusion	Minor (790402.1,1)	Compression against the
		ground
Left posterior upper arm	Minor (790402.1,2)	Vehicle undercarriage
contusion (5 x 0.1 cm)		
Left back contusion	Minor (690402.1,2)	Vehicle undercarriage
Upper back abrasion (7 x 5	Minor (690202.1,7)	Vehicle undercarriage
mm abrasion over the medial		
scapular border)		

Source: Autopsy report

Incident Sequence Pre-Incident

The 47-year old male victim parked the 2002 Pontiac on the grass surfaced lawn area. In the area where he parked the vehicle, the lawn sloped slightly downward from left to right across the heading of the Pontiac. The investigating officer noted that the ground was soft. The victim opened the trunk of the Pontiac and removed the OEM spare tire from the tire well. The OEM scissors jack was stowed in the bottom of the spare tire well. The victim used the OEM jack to raise the vehicle to a sufficient height to remove the right front tire and wheel. The specific jacking point was not police reported; however, the recommended jacking point was on the sill immediately aft of the wheel opening. A small block of wood was noted under the right front axle position. This block was partially compressed into the soft ground. It was unknown if the victim placed a block under the base of the OEM scissors jack. The rear tires of the front wheel drive vehicle were not chocked and the parking brake was not set. The automatic transmission was in the "Park" position. Figures 11 and 12 are images of the exemplar vehicle jacked with the OEM jack at the vehicle manufacturer recommended position.



Figure 11. Exemplar vehicle manufacturer's recommended position of the jack at the right front position.



Figure 12. Aft view of the recommended jack position of the exemplar vehicle.

The victim removed the right front tire and wheel from the Pontiac and placed the tire approximately 1 m (3 ft) to the right of the axle position. The removal of the tire was to provide the victim with greater access to the undercarriage of the vehicle. With the Pontiac supported on the OEM jack, the victim crawled under the right front aspect of the vehicle. He was positioned on his right side, facing the back of the Pontiac with his lower extremities extending outboard of the right side surface of the vehicle. The first responders reported that his body was parallel to the front bumper of the vehicle and was completely concealed by the undercarriage.

As the victim initiated his process to change the oil in the Pontiac, the vehicle either rolled rearward and fell off the scissors jack, or the base of the jack compressed into the soft soil, causing the Pontiac to roll rearward. It could not be determined if the wood block found under the right front brake rotor (Figure 13) was initially under the jack, and as the vehicle rolled rearward, the rotor came to rest on top of the block.

The Pontiac fell onto the victim and compressed him against the ground. He sustained left side rib fractures, soft tissue injuries of the upper extremities and the torso.



Figure 13. Wood block under the right front brake rotor. (Image provided by the investigating police department.)



Figure 14. Post-incident status of the OEM scissors jack and the removed right front tire. (Image provided by the investigating police department.)

Post-Incident

The victim's companion became concerned for his well being and walked to the yard where the Pontiac was parked. She observed the fallen position of the vehicle and the position of the victim under the vehicle. She immediately called the emergency response system and requested assistance. The local fire department was dispatched to the residence and arrived within 2-3 minutes of the call. The firefighters lifted the vehicle and pulled the victim from under the Pontiac. They conducted an initial assessment of his condition and determined that no further efforts to revive him were needed, as he was deceased. The cause of death was traumatic asphyxiation. The firefighter also pulled the jack out from under the Pontiac and placed it to the right side of the vehicle (Figure 14). The firefighters could not recall the position of the jack at the time of their arrival. The victim's companion estimated the time duration between her last contact with him to the time of discovery at approximately 45-60 minutes.




Figure 15. Incident Schematic

Not-In-Traffic Surveillance Forms

SCENE FORM

	SCENE INFORMATION
Case Number	7. Type of area in which crash occurred (Select all that apply)
	O Single family residential
IDENTIFICATION	O Row houses/townhouses
	O Multi family housing O Commercial
2. Date of Crash/	O Industrial
	O Rural O Unknown
3. Time of Crash	Olikilowii
	8. Driver exterior sightline obstructions
Code reported military time of crash.	(Select all that apply)
NOTE: Midnight = 2400	O None O Utility poles
Unknown = 9999	O Other vehicles O Signs O Building O Glare
	O Trees O Unknown
AMBIENT CONDITIONS	O Shrubbery O No driver present
4. Light Conditions	O Other (specify)
	9. Crash location
O Daylight O Dark	O Driveway O Road / street
O Dark but lighted	O Parking Lot O Roadside / shoulder
O Dawn O Dusk	O Sidewalk O Other (specify)
O Unknown	O Alley O Unknown O Intersection of driveway and sidewalk
- 4	·
5. Atmospheric Conditions (Select all that apply)	Non motorist sightline obstructions (Select all that apply)
O Clear-No adverse conditions O Cloudy	O None O Other vehicles
O Rain	O Building
O Snow O Fog, Smog, Smoke	O Trees O Shrubbery
O Sleet, Hail (freezing rain or drizzle)	O Utility poles
O Blowing Snow	O Signs
O Severe Crosswinds O Blowing Sand, Soil, Dirt	O Glare O Other (specify)
O Other (specify):	O Unknown
O Unknown	+ / - 11. Grade at parked position %
6. Temperature	· · · · — — —
O Below 0 degrees Celsius (Below 32 F)	12. Estimated distance from parked position to impact
O 1-10 degrees Celsius (33-50 F)	m
O >10-24 degrees Celsius (51-75 F) O Over 24 degrees Celsius (Over 75 F)	13. Estimated speed at impactm kmph
O Unknown	+/ -
	14. Grade at impact %
	15. Estimated distance from impact to vehicle final
	rest
	m
	Unknown = 999 Reference Items 11,12, 13, 14, 15

VEHICLE FORM

1. Case Number						
		VEHICLE IDEN	TIFICATION			
2. VIN	·					
3. Model Ye	ear					
4. Vehicle N	Make (specify	/):			_	
5. Vehicle N	Model (specif	y):			_	
		GLAZI	NG			
Location	Presence (check)	Status (select)	Clarity (select)	Tint (check)	Glazing Obstructions (specify if present)	
Windshield		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown			
LF		Fixed / Closed / Open / Partially Open	Clear / Hazy / Very Dirty			
RF		Fixed / Closed / Open / Partially Open	Clear / Hazy / Very Dirty			
2 nd Left		Fixed / Closed / Open / Partially Open	Clear / Hazy / Very Dirty			
2 nd Right		Fixed / Closed / Open / Partially Open	Clear / Hazy / Very Dirty			
3 rd Left		Fixed / Closed / Open / Partially Open	Clear / Hazy / Very Dirty			
3 rd Right		Fixed / Closed / Open / Partially Open	Clear / Hazy / Very Dirty			
Backlight		Fixed / Closed / Open / Partially Open	Clear / Hazy / Very Dirty			
Left Backlight		Fixed / Closed / Open / Partially Open	Clear / Hazy / Very Dirty			
Right Backlight		Fixed / Closed / Open / Partially Open	Clear / Hazy / Very Dirty			
Roof		Fixed / Closed / Open / Partially Open	Clear / Hazy / Very Dirty			
Other (specify)		Fixed / Closed / Open / Partially Open	Clear / Hazy / Very Dirty			
		TIRE D	ATA			
6. Vehicle Manufacturer Recommended Tire Size						
7. LF Tire	Size	9.	RF Tire Size			
8. LR Tire Size 10. RR Tire Size						

Seats / Head Restraint Data					
Seat Position	Seat Type (Select from below)	Head Restraint (Check if available)	Head Restraint Adjustment (select)	NOTES:	
Front Left			Full Down / Mid / Full Up		
Front Middle			Full Down / Mid / Full Up		
Front Right			Full Down / Mid / Full Up		
2 nd Left			Full Down / Mid / Full Up		
2 nd Middle			Full Down / Mid / Full Up		
2 nd Right			Full Down / Mid / Full Up		
3 rd Left			Full Down / Mid / Full Up		
3 rd Middle			Full Down / Mid / Full Up		
3 rd Right			Full Down / Mid / Full Up		

Seat Type codes:

0 = No seat or seat folded down

1 = Bucket

2 = Bucket w/ folding back

3 = Bench

4 = Bench with folding back cushions

5 = Bench w/ folding back

6 = Split bench w/ separate back cushions

7 = Split bench w/ separate folding back

8 = Pedestal (i.e. column supported)

9 = Box mounted (i.e. van type)

10= Other seat type (specify)

99= Unknown seat type

VEHICLE MEASUREMENTS					
Clearance Heights	Measurements (all from ground, and in centimeters	NOTES			
Beltline					
Top of trunk/tailgate					
Bottom of bumper					
Trailer hitch (if applicable)					
Undercarriage					
Sway bar					
Axle					
Differential					
Other (specify):					
Sensor Height (if equipped)					
Camera Height (if equipped)					

Back Up / Parking Aid Form

1. Case Number	Video image quality under scene lighting conditions
PARKING AID PRESENCE 2. Type of backing/parking aid present	O None present O Good O Average O Poor (specify): O Unknown
O OEM camera O OEM ultrasonic/radar sensor O OEM combination camera-ultrasonic/radar sensor O OEM Fresnel lens O OEM interior mirrors O Aftermarket camera O Aftermarket ultrasonic/radar sensor O Aftermarket combination camera-ultrasonic radar sensor O Aftermarket Fresnel lens O Aftermarket interior mirrors O Other (specify):	8. Was the camera functioning properly O None present O Yes O No, poor image quality due to glare O No, poor image quality due to atmospheric conditions O No, camera turned off O No, camera inoperable O Unknown ULTRASONIC/RADAR SENSOR Specify object detection range on diagram
CAMERA INFORMATION	System make/model
Specify field of view measurements on diagram	
3. System make/model 4. Video monitor type O None present O LCD (color) O CRT (black & white) O Unknown 5. Video display size cm (Diagonal) 6. Camera location O None present O Bumper O License plate O Trilleto (Latab Trunk	10. Auditory warning illumination O No sensor present O Yes O No O Unknown 11. Number of sensors 12. Sensor locations (Select all that apply) O No sensor present O Left bumper O Center bumper O Right bumper O License plate area O Tailgate/Hatch/Trunk
O Tailgate/Hatch/Trunk O Other (specify):	13. Was warning system functioning properly O No sensor present O Yes, system alerted driver O No, system did not alert driver O No, system turned off O No, system inoperable O Unknown

Spe	ecial Crash Investigations – Not In Traffic Surveill	ance:	: Ba	ck Up	Parkin	g Aid I	Form	Page 2
14.	Did driver react to warning							
	O No sensor present O Yes O No O Unknown							
15.	Did driver report common false warnings							
	O No sensor present O Yes O No O Unknown							

DRIVER FORM

Case Number	10. Driver entry interruption (Select all that apply)
DRIVER PROFILE 2. Driver's Age 99 = Unknown 3. Driver's Sex O Male O Female O Unknown 4. Driver's Height 999 = Unknown	O Direct trip from building to vehicle O Loaded items into vehicle O Spoke with family O Spoke with neighbors O Spoke with contacted nonmotorist O Return trip (backing into driveway/lot) O Other (specify): O N/A Unknown 11. Purpose of backing
5. Driver's Weight 999 = Unknown 6. Driver eyewear worn (Select all that apply) O None O Eyeglasses O Sunglasses O Contacts O Unknown	O Leaving parking space in parking lot O Backing onto roadway from driveway O Entering parking space in parking lot O Backing into driveway from roadway O Other (specify): O N/A Unknown 12. Where was driver going Description:
7. Driver vision deficiency condition (Select all that apply) O None O Near sighted O Far sighted O Astigmatism O Other (specify) O Unknown	13. Driver in a hurry O Yes N/A O No Unknown O Unknown 14. How did driver check behind (rear area of vehicle)
8. Non motorist's relationship to driver O No relationship O Child O Grandchild O Sibling O Neighbor O Friend O Other (specify): O Unknown DRIVER ACTIONS	after vehicle entry (Select all that apply) O Did not look O Checked mirrors O Turned right and looked back O Turned left and looked back Viewed Camera Listened for auditory/visual warning from system
9. Driver approach to vehicle for entry From left front O From left O From left rear O From right rear O From right front O Circled vehicle O Return trip (backing into driveway/lot) O Other (specify): O N/A O Unknown	O Other (specify): N/A Unknown 15. Estimated time between vehicle entry and start of backing O 0-10 Seconds O 11-30 Seconds O 31-60 Seconds Unknown

	gament control		
16.	What direction was the driver looking during backing maneuver	19.	Did driver see struck non motorist prior to impact (Select all that apply)
	(Select all that apply) O Straight ahead O Right O Left O Rearward		O No, never saw non motorist O Saw non motorist prior to entering vehicle O Saw non motorist after entering vehicle O Other (specify): Unknown
	O At object inside the car	20	Fat time between start of backing and impost
	O At mirrors O Other (specify):	20.	Est time between start of backing and impact
	O N/A		O <2 or = 1 second O 2-5 seconds
17	Unknown		O 6-10 seconds
17.	Was the driver distracted during back up maneuver		O > 10 seconds
	(Select all that apply)		O N/A Unknown
	O No non-driving activities External	21.	Driver interior sightline obstructions (Select all that apply)
	O Looking at other vehicles O Looking at other non motorist O Looking at intended turn destination O External focus, not specified		O Pillar O Other occupant O Headrest O Other (specify) O Cargo O Unknown
	O Other external focus (specify):	22	None Recent experience driving this vehicle
	Internal	22.	Recent experience driving this vehicle
	 O Looking at other occupant O Talking to passenger O Dialing phone O Talking on phone O Listening to radio/cd/portable playback device O Adjusting radio/cd player O Adjusting climate controls 		O More than 10 times the last three months O 6-10 times the last three months O 2-5 times the last three months O Less than 2 times the last three months O First time driving this vehicle O N/A Unknown
	O Using a device/controls integral to vehicle	23.	Frequency of driving in this parking lot/driveway
	(specify): O Reading/adjusting navigation system O Eating or drinking O Smoking related O Retrieving fallen object (specify): O Internal focus, not specified O Focused on other internal object		O Daily O Weekly O Several times a month O Monthly O Rarely O First time in lot/driveway O N/A Unknown
	(specify):	24.	. Driver Impairment
	O N/A Unknown		(Select all that apply)
18.	Driver avoidance actions prior to impact (Select all that apply)		O No drugs or alcohol present O Alcohol present (specify BAC):
	O None O Braking		O Drugs present (specify):O Unknown
	O Steering left O Steering right	25.	. Source of alcohol/drug results
	O Accelerating		O Police reported
	O Other (specify):O N/A		O Medical record
	Unknown		O Other (specify) O Not Tested
			Unknown if tested

Non Motorist Form

1. Case Number	11. Non-motorist motion
NON-MOTORIST PROFILE	O Not moving O Walking slowly O Walking rapidly
2. Non-motorist's Age Years 99 = Unknown	S O Running or joggingO Skipping/Hopping/JumpingO Falling/Stumbling/Rising
3. Non-motorist's Sex O Male O Female O Unknown	O On skates/skateboard O On bike/scooter O Other (specify): O Unknown
4. Non-motorist's Height cm 999 = Unknown	12. Non-motorist approach relative to rear of vehicle
5. Non-motorist's Weight kg999 = Unknown6. Medical outcome	O Stationary O From left O From right O From behind O Other (specify):
O Not injured O ER only O Hospitalized 1-4 days	O Unknown 13. Non-motorist first avoidance action
O Hospitalized 5 days or moreO Treatment laterO FatalO Unknown	O No avoidance actions O Stopped O Accelerated pace O Ran away (along vehicle path)
7. Source of most severe injury Bumper O Tire O Undercarriage O Other Specify: O Ground	O Jumped O Turned away from vehicle O Turned toward vehicle and braced O Dove or fell away from vehicle O Other (specify): O Unknown
O N/A Unknown	14. Non-motorist primary focus of attention
8. Non-motorist impairment (Select all that apply) O No drugs or alcohol present O Positive for alcohol (specify BAC): O Positive for drugs (specify): O Unknown	O Striking vehicle O Play object O Person O Surrounding traffic O Animal O Handheld electronic (phone, MP3 player, etc.)
Source of alcohol/drug results Police reported Medical Report	O Other Object (specify) O Unknown 15. Were any other Non-motorists present?
O Other (specify) O Not Tested O Unknown if tested	(Select all that apply) O Alone
NON-MOTORIST ACTIONS	O One adult present O One other child present
10. Non-motorist attitude	O Multiple adults present O Multiple children present O Unknown
O Standing O On skates/skateboard O Bending at waist O On bike/scooter O Sitting O Other (specify) O Crouching O Unknown O Kneeling	O Ulikilowii

NON MOTORIST CLOTHING

NOTES:

- Specify Color, Fabric and Texture/Weight for outermost layer only
- Indicate "NONE" if applicable
- Available codes:

<u>Colors</u>		<u>Fabrics</u>	<u>Textures</u>	<u>Weights</u>
Black	Charcoal gray	Natural	Soft	Heavy
Lt gray/silver	Brown	Synthetic	Slick	Medium
Gold/tan	Purple	Blend	Coarse	Light
Dark blue	Light blue			
Dark green	Light green			
Maroon	Red			
Orange	Yellow			
White	Other (specify)			

	Clothing	Color	Fabric	Texture	Weight
H E A D W E A	Hat				
	Helmet				
	Hood				
	Other (specify):				
R					
U P P E R	Short Sleeve				
	Long Sleeve				
	Light Jacket				
	Heavy Jacket				
O D	Other (Specify):				
Y					
L O	Shorts				
W E R	Pants				
R B O D Y	Shoes				
	Other (specify):				