Remote Investigation/Non-contact deployment Dynamic Science, Inc. / Case Number:DS97029 1996 Ford Aspire Colorado December, 1997 This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points be coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the precrash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

**Technical Report Documentation Page** 1. Report No. 2. Government Accession No. 3. Recipient Catalog No. DS9729 4. Title and Subtitle 5. Report Date In-Depth Accident Investigation 6. Performing Organization Report No. 7. Author(s) 8. Performing Organization Report No. Dynamic Science, Inc. 9. Performing Organization name and Address 10. Work Unit No. (TRAIS) Dynamic Science, Inc. 530 College Parkway, Ste. K 11. Contract or Grant no. Annapolis, MD 21401 DTNH22-94-D-27058 12. Sponsoring Agency Name and Address 13. Type of report and period Covered [Report Month, Year] U.S. Dept. of Transportation (NRD-32) National Highway Traffic Safety Administration 14. Sponsoring Agency Code 400 7th Street, SW Washington, DC 20590 15. Supplemental Notes 16. Abstract This incident occurred in December 1997 at approximately 0600 hours. The case vehicle, an unoccupied 1996 Ford Aspire 2-door hatchback, was parked in an industrial area parking lot. This vehicle was equipped with both driver's side and passenger's side frontal air bags. The vehicle was equipped with air bag sensors at the right front and left front of the vehicle, and a safing sensor in the center of the instrument panel. There was crashrelated damage found on the right front fender and on the front bumper. The damage is not related to the fire nor the subsequent air bag deployment. The vehicle had been stolen. The person reporting the fire saw several males in a vehicle near the involved vehicle. The lights of the vehicle were off. As the reporting party approached, the vehicle sped off with the lights still off. As the vehicle sped away, the case vehicle burst into flames. A fire was deliberately set in the passenger compartment. It appears that gasoline was used to set the fire. The fire caused the driver's side air bag to deploy. During the deployment, portions of the driver's side air bag module were propelled through the roof, causing a 10-15 cm (4-6 in.) hole in the roof. Portions of the module were found on the ground approximately 30-38 m (100-125 ft) directly behind the vehicle. The interior of the vehicle was badly burned and it is unclear if the passenger's side air bag deployed.

Form DOT F 1700.7 (8\_72) Reproduction of this form and completed page is authorized

17. Key Words

19. Security Classif. (of this report)

Air bag, deployment, fire, no injury, no occupant

20. Security Classif. (of this page)

18. Distribution Statement

22. Price

21. No of pages

## Dynamic Science, Inc. Accident Investigation Case Number: DS97029

## TABLE OF CONTENTS

BACKGROUND	l
Description	1
Investigation Type	1
Crash Location	
Notification Date	
Field Work Completed	
SUMMARY	1
DETAILED INFORMATION	1
Vehicles	1

### **BACKGROUND:**

Description: This case was initiated in response to a report of a fire-initiated air bag

deployment. This case is being conducted as a remote investigation. The NHTSA was notified by a city arson squad. DSI was notified on December

30, 1997.

Investigation Type: Remote

Crash Location: Colorado

Incident Date: December, 1997 Notification Date: December, 1997

Field Work Completed: NA

#### **SUMMARY:**

This incident occurred in December 1997 at approximately 0600 hours. The case vehicle, an unoccupied 1996 Ford Aspire 2-door hatchback, was parked in an industrial area parking lot. This vehicle was equipped with both driver's side and passenger's side frontal air bags. The vehicle was equipped with air bag sensors at the right front and left front of the vehicle, and a safing sensor in the center of the instrument panel. There was crash-related damage found on the right front fender and on the front bumper. The damage is not related to the fire nor the subsequent air bag deployment.

The vehicle had been stolen. The person reporting the fire saw several males in a vehicle near the involved vehicle. The lights of the vehicle were off. As the reporting party approached, the vehicle sped off with the lights still off. As the vehicle sped away, the case vehicle burst into flames.



Figure 1. Exterior, case vehicle




Figure 2. Roof exit point.

A fire was deliberately set in the passenger compartment. It appears that gasoline was used to set the fire. The fire caused the driver's side air bag to deploy. During the deployment, portions of the driver's frontal air bag module were propelled through the roof, causing a 10-15 cm (4-6 in.) hole in the roof. Portions of the module were found on the ground approximately 30-38 m (100-125 ft) directly behind the vehicle. The interior of the vehicle was badly burned and it is unclear at this time if the passenger's side air bag deployed.



Figure 3. Exterior, close up of hole in roof.



Figure 4. Close up of exit point.



Figure 5. Steering wheel



Figure 6. Exit point, interior view

# **DETAILED INFORMATION**

## Vehicles

<u>Case vehicle</u>		
Description:	1996 Ford Aspire	
VIN:	KNJLT0SA6Txxxxxx	
Odometer:	Unknown	
Engine:	1.3 L I4	
Reported Defects:	None	
Cargo:	Unknown	
Damage Description:	Extensive burn damage, hole in roof, un-related crash damage to right front fender and on the front bumper.	
CDC:	NA	
Delta V:	Total	NA
	Longitudinal	NA
	Latitudinal	NA
	Energy	NA