

**TRANSPORTATION SCIENCES  
CRASH RESEARCH SECTION**

Veridian  
Calspan Operations  
Buffalo, New York 14225

**REDESIGNED AIR BAG SPECIAL STUDY (RABSS)  
SCI TECHNICAL SUMMARY REPORT**

**NASS RABSS CASE NO. 1998-43-801G**

**RABSS VEHICLE - 1998 CHEVROLET S-10 PICKUP TRUCK**

**LOCATION - STATE OF NORTH CAROLINA**

**CRASH DATE - JULY, 1998**

Contract No. DTNH22-94-D-07058

Prepared for:

U.S. Department of Transportation  
National Highway Traffic Safety Administration  
Washington, D.C. 20590

## **DISCLAIMER**

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points are coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the pre-crash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

## TECHNICAL REPORT STANDARD TITLE PAGE

<i>1. Report No.</i> 98-43-801G	<i>2. Government Accession No.</i>	<i>3. Recipient's Catalog No.</i>	
<i>4. Title and Subtitle</i> Redesigned Air Bag Special Study (RABSS) RABSS Vehicle - 1998 Chevrolet S-10 pickup truck Location - State of North Carolina		<i>5. Report Date:</i> July, 1999	
		<i>6. Performing Organization Code</i>	
<i>7. Author(s)</i> Crash Research Section		<i>8. Performing Organization Report No.</i>	
<i>9. Performing Organization Name and Address</i> Transportation Sciences Crash Research Section Veridian Engineering (Calspan Operations) P.O. Box 400 Buffalo, New York 14225		<i>10. Work Unit No.</i> C01115.0225.(0000-0009)	
		<i>11. Contract or Grant No.</i> DTNH22-94-D-07058	
<i>12. Sponsoring Agency Name and Address</i> U.S. Department of Transportation National Highway Traffic Safety Administration Washington, D.C. 20590		<i>13. Type of Report and Period Covered</i> Technical Summary Report Crash Date: July, 1998	
		<i>14. Sponsoring Agency Code</i>	
<i>15. Supplementary Notes</i> NASS investigation of a head-on collision that involved a 1998 Chevrolet S-10 pickup truck with redesigned frontal air bags.			
<i>16. Abstract</i> This investigation focused on a two-vehicle crash involving a 1998 Chevrolet S-10 pickup truck (subject vehicle) and a 1996 Honda Accord EX 4-door sedan. The Chevrolet S-10 was equipped with redesigned frontal air bags that deployed as a result of a head-on collision with the Honda Accord. The Honda was westbound and attempted to turn left (south) at a 4-leg intersection when it crossed into the path of the eastbound Chevrolet. As the Honda turned left and crossed the eastbound lane the front left area of the Chevrolet struck the front right area of the Honda. Impact resulted in moderate damage to both vehicles. At this point, the Honda rotated counterclockwise as both vehicles came to rest in the south sector of the intersection facing southeast. The 16 year old male driver of the Chevrolet S-10 was properly restrained by the 3-point manual lap and shoulder belt system and initiated a forward trajectory in response to the 11 o'clock impact force, loading the manual restraint and deployed redesigned driver air bag. He sustained a laceration to the posterior aspect of the right hand from contact to the ashtray. Neither driver was transported to a local hospital for treatment.			
<i>17. Key Words</i> Redesigned frontal air bag system Collision Deformation Classification (CDC): 71-FDEW-3 Proper use of the manual belt system		<i>18. Distribution Statement</i> General Public	
<i>19. Security Classif. (of this report)</i> Unclassified	<i>20. Security Classif. (of this page)</i> Unclassified	<i>21. No. of Pages</i> 5	<i>22. Price</i>

## **TABLE OF CONTENTS**

BACKGROUND .....	1
SUMMARY	
Crash Site .....	1
Pre-Crash .....	1
Crash .....	2
Post-Crash .....	2
RABSS VEHICLE .....	2
VEHICLE DAMAGE	
Exterior Damage .....	3
Interior Damage .....	3
REDESIGNED AIR BAG SYSTEM .....	4
DRIVER DEMOGRAPHICS .....	4
Driver Injuries .....	5
Driver Kinematics .....	5
NASS SCENE DIAGRAM .....	5

**REDESIGNED AIR BAG SPECIAL STUDY (RABSS)  
SCI TECHNICAL SUMMARY REPORT  
NASS RABSS CASE NO. 1998-43-801G  
RABSS VEHICLE - 1998 CHEVROLET S-10 PICKUP TRUCK  
CRASH DATE - JULY, 1998**

***BACKGROUND***

This investigation focused on a two-vehicle crash involving a 1998 Chevrolet S-10 pickup truck (subject vehicle) and a 1996 Honda Accord EX 4-door sedan. The Chevrolet S-10 was equipped with redesigned frontal air bags that deployed as a result of a head-on collision with the Honda Accord. The Honda was westbound and attempted to turn left (south) at a 4-leg intersection when it crossed into the path of the eastbound Chevrolet. As the Honda turned left and crossed the eastbound lane the front left area of the Chevrolet struck the front right area of the Honda. Impact resulted in moderate damage to both vehicles. At this point, the Honda rotated counterclockwise as both vehicles came to rest in the south sector of the intersection facing southeast. The 16 year old male driver of the Chevrolet S-10 was properly restrained by the 3-point manual lap and shoulder belt system and initiated a forward trajectory in response to the 11 o'clock impact force, loading the manual restraint and deployed redesigned driver air bag. He sustained a laceration to the posterior aspect of the right hand from contact to the ashtray. Neither driver was transported to a local hospital for treatment.

This crash was initially selected for investigation by the National Automotive Sampling System (NASS) as case number 98-43-801G for the Redesigned Air Bag Special Study. The Field Operations Branch of the National Highway Traffic Safety Administration (NHTSA) assigned the Special Crash Investigation (SCI) team at Veridian/Calspan the task of case review and final report preparation.

***SUMMARY***

**Crash Site**

This two-vehicle crash occurred during the evening hours of July, 1998. At the time of the crash, it was dark (street lighted) with no adverse conditions as the roads were dry. The crash occurred in the eastbound lane of a 4-leg rural (level/asphalt) intersection which is controlled by overhead tri-lights (see **Figure 9 - page 5**). The speed limit at the crash scene was 72 km/h (45 mph).

**Pre-Crash**

The 16 year old male driver of the 1998 Chevrolet S-10 was operating the vehicle eastbound (**Figure 1**) at a police reported speed of 72 km/h (45 mph) and proceeding straight when he observed the Honda Accord turn left (south) across his lane of travel. Upon recognition of the impending harmful event, the driver braked in avoidance remaining in the eastbound travel lane prior to the collision. The 1996 Honda Accord was driven by a 25 year old male who was operating the vehicle westbound (**Figure 2**) when he failed to detect the Chevrolet as he turned left (south) at a police reported speed of 24 km/h (15 mph).



**Figure 1. Eastbound approach for the 1998 Chevrolet S-10 pickup truck.**



**Figure 2. Westbound approach for the 1996 Honda Accord EX.**

### **Crash**

As the Honda crossed the eastbound lanes of the 3-lane undivided roadway, the front left area of the Chevrolet struck the front right area of the Honda. The impact induced deceleration was sufficient to deploy the Chevrolet's redesigned frontal air bag system. The damage algorithm of the WinSMASH program computed velocity changes of 30.6 km/h (19.0 mph) for the subject vehicle and 31.7 km/h (19.7 mph) for the struck Honda. Respective longitudinal components were -23.5 km/h (-14.6 mph) and -29.8 km/h (-18.5 mph). The Collision Deformation Classification (CDC) for this impact to the Chevrolet S-10 was 71-FDEW-3 (PDOF incremented for lateral end shifting to the right) and 01-FZEW-2 for the Honda Accord. At this point, the Honda rotated counterclockwise as both vehicles came to rest in the south sector of the intersection facing southeast.

### **Post-Crash**

Each driver exited the vehicle under their own power. No ambulance was summoned to the crash site. Both vehicles were towed from the scene.

### ***RABSS VEHICLE***

The 1998 Chevrolet S-10 was identified by the Vehicle Identification Number (VIN): 1GCCS19X0W8 (production sequence deleted). The vehicle was an extended cab pickup truck (3-door model) equipped with rear wheel drive and a 4.3 liter, V-6 engine. Air bag warning labels were affixed to each sun visor. The vehicle's odometer reading was unknown at the time of the crash. The police report listed the driver's father as the owner of the vehicle. The seating was configured with a front split bench (with folding backs) and a folding side facing seat for the rear right position. The driver reported no previous crashes or maintenance on the air bag system (original equipment). A bag phone was present but not in use at the time of the collision.

## VEHICLE DAMAGE

### Exterior Damage

The Chevrolet S-10 sustained moderate frontal damage as a result of the impact with the Honda Accord (**Figure 3**). The direct contact damage encompassed the full frontal width resulting in a combined direct and induced damage length (Field L) of 141.0 cm (55.5 in). Six crush measurements were documented at the level of the bumper: C1= 0 cm, C2= 18.0 cm (7.1 in), C3= 33.0 cm (13.0 in), C4= 48.0 cm (18.9 in), C5= 53.0 cm (20.9 in), C6= 58.0 cm (22.8 in). Damage was noted to the hood which was displaced up and rearward from the impact force. The end structure was displaced approximately 12.0 cm (4.7 in) to the right. Induced buckling was noted to the roof area between the A-pillar and B-pillar. The right fender was displaced rearward which restricted/deflated the wheel/tire and jammed the right door. Bed to cab contact was documented to the right side. No windshield damage was found from exterior forces or the (interior) front right air bag deployment.



**Figure 3. Frontal damage to the 1998 Chevrolet S-10 pickup truck.**



**Figure 4. Frontal damage to the 1996 Honda Accord EX.**

out of place.

### Interior Damage

Interior damage to the Chevrolet S-10 identified through the NASS vehicle inspection was minimal and was attributed to occupant contact. The front left energy management loop deployed, located at the lower (sill) anchorage point (**Figure 5**). A scratch mark was documented to the ashtray. No contacts were found on the left knee bolster (rigid plastic type). No steering wheel rim deformation was noted (fixed column). Longitudinal intrusions into the front right passenger space included 15.0 cm (5.9 in) of toepan intrusion and 10.0 cm (3.9 in) of instrument panel intrusion.

The Honda Accord sustained moderate frontal damage as a result of the impact with the Chevrolet S-10 (**Figure 4**). The direct contact damage began at the front right bumper corner and extended 62.0 cm (24.4 in) inboard. The impact deformed the full frontal width resulting in a combined direct and induced damage length (Field L) of 94.0 cm (37.0 in). The bumper fascia separated from the reinforcement bar. The direct contact damage continued rearward to the A-pillar from sustained contact between the vehicles during spinout. This damage pattern restricted/bowed the right front door and shattered the side glazing. The right fender was displaced laterally which restricted the right front wheel/tire (not deflated). The windshield was fractured and



**Figure 5. Loading to the front left manual restraint.**

### ***REDESIGNED AIR BAG SYSTEM***

The 1998 Chevrolet S-10 was equipped with redesigned frontal air bags for the driver and front right passenger positions. The air bags had deployed as a result of the crash. The driver air bag was housed in the center of the steering wheel with a vertically oriented flap tear seam (I-configuration). The flaps were symmetrical in shape and measured 12.0 cm (4.7 in) in width and 10.0 cm (3.9 in) in height. No contact evidence was identified on the air bag or exterior surface of the module cover flaps. The NASS researcher measured the diameter of the driver air bag at 60.0 cm (23.6 in) in its deflated state (**Figure 6**). The bag was tethered by two internal straps and vented by two ports located at the 11 o'clock and 1 o'clock sectors on the rear aspect of the air bag.



**Figure 6. 1998 Chevrolet S-10 redesigned driver air bag.**



**Figure 7. 1998 Chevrolet S-10 redesigned passenger air bag.**

The front right passenger air bag deployed from a mid-mount module in the right instrument panel with a single cover flap design hinged at the bottom aspect. No contact evidence was identified on the air bag or exterior surface of the module cover flap. The cover flap was rectangular in shape which opened in a downward direction away from the windshield and measured 32.0 cm (12.6 in) in width and 13.0 cm (5.1 in) in height. The NASS researcher measured the passenger air bag at 56.0 cm (22.0 in) in width and 44.0 cm (17.3 in) in height in its deflated state (**Figure**



**Figure 8. Cutoff switch for the passenger air bag.**

**7**). No tether straps were present. The bag was vented by two ports located at the 9 o'clock and 3 o'clock sectors on the side aspect of the air bag. A cutoff switch was located on the instrument panel (**Figure 8**) to the right of the steering column.

### ***DRIVER DEMOGRAPHICS***

Age/Sex:	16 year old male
Height:	160 cm (63 in)
Weight:	54 kg (120 lb)
Seat Track Position:	Forward most position
Manual Restraint Use:	3-point lap and shoulder belt system
Usage Source:	NASS vehicle inspection, driver interview
Eyewear:	Prescription contact lenses
Type of Medical Treatment:	None



## Driver Injuries

<i>Injury</i>	<i>Severity (AIS 90)</i>	<i>Injury Mechanism</i>
Laceration posterior right hand (1.3 cm)	Minor (790602.1,1)	Ashtray

## Driver Kinematics

The 16 year old male driver of the 1998 Chevrolet S-10 was seated in an upright posture with his left hand at the 10 o'clock position on the steering wheel rim and the right hand on the seat cushion. He was properly restrained by the 3-point manual lap and shoulder belt system with the seat track adjusted to a forward position. At impact, he initiated a forward trajectory in response to the 11 o'clock impact force and loaded the manual belt system and deployed redesigned driver air bag. Belt usage was confirmed by the deployment of the energy management loop at the lower (sill) anchorage point. The air bag provided additional restraint against further contact to the steering wheel hub/rim preventing serious injury. His right hand struck the ashtray resulting in a minor laceration to the posterior aspect of the right hand, evidenced by the scratch mark documented to this component. The driver was not transported to a local hospital for treatment.




Figure 9. NASS Scene Diagram