

U.S. Department of Transportation

National Highway Traffic Safety Administration

March 19, 2014

Mr. Timothy Lafon Director, Regulatory Affairs Mack Trucks, Inc. 7900 National Service Rd. Greensboro, NC 27409 NVS-215KS 14V-088

1200 New Jersey Avenue SE Washington, DC 20590

Subject: Exhaust Pipe may Disconnect from Muffler/Catalyst

Dear Mr. Lafon:

This letter serves to acknowledge Mack Trucks, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MACK/LEU/2010-2015

Mfr's Report Date: February 20, 2014

NHTSA Campaign Number: 14V-088

Components:

ENGINE AND ENGINE COOLING: EXHAUST SYSTEM

Potential Number of Units Affected: 958

Problem Description:

Mack Trucks, Inc. (Mack) is recalling certain model year 2010-2015 LEU vehicles manufactured May 14, 2009, through February 14, 2014, and equipped with a Cummins ISL engine. In the affected vehicles, the exhaust pipe may disconnect from the muffler/catalyst.

Consequence:

If the exhaust pipe separates from the muffler on a twin-steer configured vehicle where the vehicle is operated from the right side, the operator may be exposed to carbon monoxide levels which may cause personal injury. Additionally, the separated exhaust pipe creates a road hazard.

Remedy:

Mack will notify owners. The manufacturer has not yet determined a remedy plan. The recall is expected to begin in late April 2014. Owners may contact Mack Trucks at 1-336-393-2000. Mack's number for this recall is SC0376.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



Please provide Mack's remedy plan for this recall as soon as it has been determined.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kelly Schuler who may be reached by phone at (202) 366-5227, or by email at kelly.schuler@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian

Chief, Recall Management Division Office of Defects Investigations

Enforcement

