

GM CUSTOMER CARE AND AFTERSALES  
DCS3561  
URGENT - DISTRIBUTE IMMEDIATELY

Date: February 24, 2015

Subject: 12106D – Safety Recall  
Shift Lever Indicator May Not Display Correct Gear  
Revised Part Information Section

Models: 2007-10 Saturn AURA, 2008-10 Chevrolet Malibu, Pontiac G6  
Equipped with 4-Speed Automatic Transmission (ME7/MN5)  
and  
2005-07 Saturn AURA, 2005-08 Pontiac G6 Equipped with 4-Speed  
Automatic Transmission (ME7/MN5) and Serviced with a Suspect  
Replacement Shift Cable

To: All GM Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, Used Vehicle Sales Manager,  
and Warranty Administrator

The Part Information section has been revised. The part numbers for the transmission shift cables have been revised. The new transmission shift cables will include the clam shell (cable kit). Please discard all copies of bulletin 12106C.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES