

National Highway Traffic Safety Administration (NHTSA)
Vehicle Safety Recall Quarterly Progress Report for Fleetwood RV, Inc., a brand of Allied Recreation Group
Quarterly Report from October 1, 2013 through December 31, 2013
Report Date - January 30, 2014 / Report Author - Julie Jones (260) 724-5716

| # of Quarters Reported | NHTSA Recall # | FRV Recall # | Date of 1st Mailing | Date of 2nd Mailing | Date of 3rd Mailing | Total # Vehicles Involved | Total # Inspected & Remedied | Total # Inspected & Not Requiring Remedy | Total # Exported | Total # Inspected / Defective / Owner Declined | Total # Unable to Notify | Description of Recall |
|------------------------|----------------|--------------|---------------------|---------------------|---------------------|---------------------------|------------------------------|--|------------------|--|--------------------------|---|
| 6 | 12V-412 | 120813FRV | 09/11/12 | 12/07/12 | 03/08/13 | 74 | 31 | 31 | 4 | 0 | 0 | MY13 Excursion 33A Diesel Fuel Fill Hose - Inspect the diesel fuel fill hose for possible contact with a threaded fastener on the slide-out turn shaft. |
| 5 | 12V-535 | 121025FRV | 12/19/12 | 03/22/13 | 06/25/13 | 842 | 513 | 0 | 17* | 0 | 11 | MY10-13 Encr-Storm-Terra (E mdi only) Entry Step Support - The entry step cage may become damaged by repeated use as a result of insufficient structural support and may separate from the sub-floor. (*Includes 1 exported to UK, 1 exported to Germany, 1 exported to Italy, 1 exported to Mongolia) |
| 4 | 13V-007 | 130102FRV | 01/31/13 | 04/26/13 | 07/26/13 | 14 | 6 | 0 | 0 | 0 | 0 | MY12-13 Bdr CI 30T Federal Certification Tag Incorrect Rim and Tire Sizes and Pressures |
| 3 | 13V-189 | N/A | 07/17/13 | N/A | N/A | 196 | 41 | 0 | 0 | 0 | 0 | DOMETIC 13E-019 Power Awning Recall. Dometic implemented a design change on its power awnings. The design change altered the torque load on the awning motor such that the motor assembly screws absorb the rotational torque. Abnormal torque creates the potential to shear the motor assembly screws inside the awning roller tube, allowing the awning to unfurl unexpectedly. Dometic is handling all notifications. |
| 3 | 13V-217 | 130517FRV | 06/12/13 | 09/13/13 | 12/13/13 | 184 | 97 | 1 | 0 | 0 | 0 | MY14 Am Rev, Bdr, Disc, Expd, Sthwnd. Solar panel attachment hdwe. on units built 3/20/13- 5/15/13. |
| 3 | 13V-218 | 130417FRV | 06/20/13 | 09/20/13 | 12/20/13 | 113 | 51 | 0 | 0 | 0 | 0 | MY 13 Bdr CI and Terra Certification Label. Incorrect load index letter printed on labels. Correct load index letter is "G". |
| 1 | 13V-580 | 131112FRV | 01/17/14 | | | 774 | 2 | 0 | 0 | 0 | 0 | MY14 All Products Indiana Mills Seat Belt Buckles, which are potentially noncompliant with the requirements of FMVSS No. 209. |