

SAFETY RECALL ALERT



To: U.S. and Canada Distributors
Dealer Principals
Service Managers
Warranty Managers
Parts Managers

Bulletin: SRA-M-0376
Date: February 27, 2014
Action Required? **YES**

From: Regulatory Affairs Department

Subject: Safety Recall, SC0376, Exhaust Pipe

Summary:

Description of Defect:

The exhaust pipe may disconnect from the muffler/ catalyst. If this occurs on a twin-steer configured vehicle where the vehicle is operated from the right side, the operator may be exposed to carbon monoxide levels which may cause personal injury.

Models/ Model Years Affected:

Mack: Certain Mack LEU model vehicles manufactured from May 14, 2009 through February 14, 2014 with a Cummins ISL engine.

Vehicle Quantities:

Mack: 1,081 in Total (958 U.S., 123 Canada)

Dealer's Responsibility:

The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act requires dealers to ensure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer.

Dealers should make their personnel aware of the safety recall. In the event that a dealer has a vehicle included in the safety recall in their inventory to be sold, the condition must be corrected before releasing it to a customer.

Release Schedule:

- Vehicle will be posted on the Trucks Dealer Portal by end of day February 27, 2014.
- Repair Instructions are tentatively scheduled for release no later than April 11, 2014.
- Owner Notices are scheduled to be mailed on or before April 18, 2014.

Questions:

Contact the Regulatory Affairs Department at vtna.regulatoryaffairs@volvo.com if you have questions.