400 Seventh Street, S.W. Washington, D.C. 20590



U.S. Department of Transportation

National Highway Traffic Safety Administration

Dear Crash Data Researchers/Users:

Thank you for choosing crash data from the National Highway Traffic Safety Administration (NHTSA) for your research or other use. The information contained in this motor vehicle crash report is collected, maintained and distributed in accordance with Public Law 89-564. In accordance with this Public Law, NHTSA is required not to release any case information until completion of quality control procedures. These procedures include a review of the case material to extract all names, licenses and registration numbers, non-coded interview material, non-research related researcher comments in the margins, non-factual data, and the production number portion of the vehicle identification number (VIN).

If you requested NHTSA to query its database files in order to identify a specific crash, then that query was made using non-personal descriptors you provided for use in our search. This motor vehicle crash may have been identified from a data search and matches the general, non-personal descriptors you provided, but we cannot confirm that this is the specific crash report you requested.

If you have any questions with regard to the above procedures, please contact the Field Operations Branch, Crash Investigation Division, National Center for Statistics and Analysis at 202-366-4820. Again, please be advised that we cannot confirm that this is the case that you have specifically requested nor can we certify the information to be correct.

*** *** ***



DISCLAIMERS

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points are coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the pre-crash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

REMOTE AIR BAG REPORT

FLEET - PRIVATE VEHICLE LOCATION - HONOR OHIO CASE NO. - 91-01

Submitted By:

Research Scientist

Transportation Research Center Indiana University Bloomington, Indiana

1991

Summary

This report concerns a motor vehicle accident involving an air bag equipped 1990 Chrysler Lebaron and a 1982 Ford F600 straight truck occurring on **Magnetic Straight truck**, 1990 at **Straight mar** in Dayton, Ohio on an urban Interstate Highway.

The Lebaron was traveling north in the east (right) northbound lane of a six-lane divided trafficway (3 lanes northbound, 3 lanes southbound) when it impacted the straight truck which was stopped, providing security for street maintenance personnel ahead, in the same lane on the same northbound roadway. The Lebaron rotated slightly clockwise after impact and came to rest obstructing the right (east) half of the center northbound travel lane. The straight truck remained essentially in its original position after impact (i.e., the east northbound lane).

The front of the Lebaron impacted the rear of the truck-mounted attenuator, which was attached to the rear of the straight truck. The CDC is estimated as: 12-FDEW-3 for the Lebaron. CDC is not applicable for the straight truck. No reconstruction program was used on this collision.

The 1990 Chrysler Lebaron was equipped with a driver supplemental restraint system (air bag) which deployed as a result of the frontal impact. The driver of the vehicle (40 year-old female) was also restrained by the active three-point lap and shoulder belt. She sustained minor (AIS-1) facial lacerations and other minor injuries. The driver of the Chrysler was listed on the Police Accident Report as sustaining a "B" (nonincapacitating-evident, possible) injury as a result of this accident. The driver (47 year-old male) of the Ford was listed on the Police Accident Report as sustaining a "C" (possible) injury.

TRC/IU REMOTE AIR BAG REPORT

•

FLEET - PRIVATE VEHICLE LOCATION - OHIO CASE NO. - 91-01

ACCIDENT DATA

.

Location/Street:	Urban Interstate
City/Township:	Ohio
Area/Type:	Urban, commercial
Accident Date/Time:	199 4 a. m.
Investigating Police Agency:	Police Department
Accident Type:	Car / Medium Truck - rear-end
Occupant Injury Severity (air bag vehicle):	Minor injury (AIS-1)
AMBIENT CONDITIONS	
light conditions.	Davlight

	Dayright
Weather Condition:	Clear
Precipitation:	None
Road Surface:	Dry

<u>ROADWAY</u>

	<u>Case Vehicle</u>	<u>Vehicle #2</u>
Location:	Urban interstate	Urban interstate
Number of Travel Lanes:	3-lanes, divided	3-lanes, divided
Surface Type:	Asphalt	Asphalt
Vertical alignment:	Level	Level
Horizontal alignment:	Straight	Straight
Traffic Density:	Moderate	Moderate
Speed Limit:	55 m.p.h.	55 m.p.h.

TRC/IU REMOTE AIR BAG REPORT

ROADWAY (CONT'D.)

Damage location:

Estimated Maximum Crush:

CDC:

	<u>Case Vehicle</u>	<u>Vehicle #2</u>	
Traffic Controls:	Truck-mounted flashing lane control arrow	Unknown	

VEHICLES

	<u>Case Vehicle</u>	<u>Vehicle #2</u>
Year:	1990	1982
Make:	Chrysler	Ford
Model:	Lebaron	F600
Body Type:	2-door convertible	Straight truck
V.I.N.:	1C3XJ4536LG	Unknown
Mileage:	Approximately 2,500	
Securiflex windshield:	None	
Windshield damage/source:	Yes/hood	
Fleet:	Private vehicle	
Tow status:	Towed due to damage	Driven
Reported Defects:	None	None
VEHICLE DAMAGE		
	<u>Case Vehicle</u>	Vehicle #2
<u>Deployment Impact</u>		
Object Struck:	Vehicle #2	Case vehicle
Event number:	1	1

Front

12-FDEW-3

20-24 inches

Rear

Not applicable

<u>VEHICLE DAMAGE</u> (CONT'D.)

<u>Case Vehicle</u>

Vehicle #2

Deployment Impact

Damage components:	Front bumper, LF turn signal assembly, front grille, hood, RF fender, windshield, right A-pil- lar, right outside rear- view mirror, right door panel	Truck-mounted attenuator
Repair Estimate:	Totalled	
Interior damage:	Right instrument panel, right A-pillar, radio	

COLLISION SEQUENCE

The case vehicle (Lebaron) was traveling north in the first lane (east northbound lane) of a 6-lane divided urban interstate (3 lanes northbound, 3 lanes southbound) and was attempting to continue in its direction of travel. Vehicle #2 was traveling north in the same lane and was stopped providing security for street maintenance personnel ahead. The accident occurred on a straight and level segment of the east northbound lane.

The front of the case vehicle impacted the rear of the truck-mounted attenuator, which was attached to the rear of vehicle #2, causing the driver side supplemental restraint system (air bag) to deploy. The case vehicle rotated slightly clockwise after impact and came to rest obstructing the right (east) half of the center northbound travel lane. Vehicle #2 remained essentially in its original position after impact (i.e., the east northbound lane).

The driver of the case vehicle indicated that she was wearing the available lap/shoulder restraint at the time of the accident. The driver sustained: a small laceration over the right eyebrow, small cut over bridge of nose between eyebrows, slight chin abrasion, left wrist laceration, contusion right forearm, and multiple (unspecified) contusions. All injuries are AIS-1. She was transported by ambulance to a medical facility where the driver was treated and released. In addition, the driver missed one day of work as a result of this accident.

DRIVER DATA

	<u>Case Vehicle</u>	<u>Vehicle #2</u>		
Age:	40	47		
Sex:	Female	Male		
Height:	63 inches			

DRIVER DATA (CONT'D.)

	<u>Case Vehicle</u>	<u>Vehicle #2</u>
Weight:	125 pounds	
Occupation:	Professor	
Active Restraint System/Usage:	3-point lap and shoulder belt/used	
Usage Source:	Driver	
Eye glasses/contacts:	None; was wearing nonprescription sun- glasses at time of accident	
Vehicle Familiarity:	Two months	
Route Familiarity:	Daily	
Trip Plan:	To work	
Manner of Leaving Scene:	Ambulance	
Type of Medical Treatment:	Treated and released	

DRIVER INJURIES


Injury	<u>Severity (AIS)</u>	Source
Laceration over right	FSLI-1	air bag
eyebrow and over bridge		
of nose between eyebrows		
Laceration left wrist	WLLI-1	unknown
Multiple contusions	OWCI-1	unknown
Abrasion chin	FIAI-1	air bag
Contusion right forearm	RRCI-1	radio

ATTACHMENTS

Police Report Vehicle Photographs Case Vehicle Vehicle Photographs Vehicle #2 Truck-Mounted Attenuator (TMA) Promotional Literature NASS CDS Interview Form--injury data page NASS CDS Occupant Injury Form

	OHIO TR	AFFIC CRASH	REPORT				0)H-1 (Rev.	1-82)				
	LOC/ REPO		OH-2 REP	ORTING A	GENCY			NCIC		11.			5
									L	4#		4 (100 NO	DT MARK ABOVE
		C STATION DEN	ESTRIANS 2		× /					VEH/PR	op 2_ ''		HIT SKIP
	IN COUNTY							PERTY DAMA					TIME MILITARY
1	CRASH OCC			VILLAGE			1.00	WITHIN T		RECTION	Y 90		0930
		<u> </u>											
			- w	E,		n	F POS	T	IG STREE	T, MILEPO	ST, HOUSE N	O .	CITY CODE
	LOG-1	LOG-2	<u> </u>					DESC		r			
		1	I					1 1 1	1 1				
	A NO.		PANTS /		G PARI	ED	DRIVER	LESS HIT		NON-CON			
	DRIVER-PED	ESTRIAN NAME (LA	ST, FIRST, MI)		<u>L</u>	-1	DORESS (NO., STREET,	CITY, ST.	ATE, ZIP (
	PHONE NO.		BIRTH DA			soc	AL SECUP	NO.				T'S LICENSE	
_	OWNER (IF S	AME AS DRIVER, W	RITE SAME)			4	DORESS				7	<u> </u>	
NOL		SAN	nE										
SECTION	VEH YR	MAKE	MODEL				STYLE	1 1	LICENSE	PLATE N	0. T	OWING SER	VICE VEH/PED DIR
		CHRYSLE	K LIBA	RON		/			CALE			0.000	FROM S TON
lΩ	DAMAGE	Rui								DERATE			NO FIRE
Ň.			11 LO	10					г 🗶 не/	AVY		NED AT SCI	ENE
Ż	UNIT	NO. OF	· · · · · · · · · · · · · · · · · · ·		DIS DIS DARI	ABLI	DRIVE	ALESS HIT	& RUN	NON-CON			
TRI				X	[1						ENT	
ũ							ODHE33	(NO., STREET,	. CITT, 31	ATE, LIP	CODE)		
E-PE	PHONE NO.		BIRTHDA			SOCI	AL SECUR	ITY NO.				'S LICENSE	NO. OCCUPATION
VEF	OWNER US R			1 4	17 10					0,	H		UP.
DR	ownen (ir s		A CONTRACTOR	and the second		Î	DDRESS					0410	
	VEH YR	MAKE	MODEL		COLO	R I		STATE	LICENSE	PLATE NO	<u>0.</u>	OWING SER	IVICE VEH/PED DIR
		FORD	F-60	0	· · ·			OH				NOVE	FROM S TO N
	DAMAGE									DEDATE			FIRE
	1					-							
	- ERON		· <u> </u>	ILER	Dos	ABLI	_				TOWE	D	
	C UNIT NO.	NAME (LAST, FIRS	I. MIT)						AGE	AB	POSITION		INJURIES
		ADDRESS					PHONE		SEX	17			345
	D UNIT	NAME (LAST, FIRST	r, Mł)				BH	RTHDATE	AGE				1 FATAL 2 SERIOUS VISIBLE
NO) NO.	ADDRESS			******				SEX		100		4 NO VISIBLE INJURY
SECTION	FROM	NAME (LAST, FIRS)	r, MI)		·		81	RTHDATE	AGE		· 7 \ 2 9	7	CONDITION
		1000544	·····				M	D Y				1)	
OCCUPANT							PHONE		SEX		mlater		1 APPARENTLY NORMAL
5	F UNIT	NAME (LAST, FIRS	r, MI)						AGE			-	3 FATIGUED
8		ADDRESS	<u>.</u>						SEX				5 PHYSICAL DEFECT 6 OTHER CONDITION
	A) B 0	INJURED TAKE	N TO			87			_1	A., 8.	C D	S E F	
						/	MEDIC						A TESTED B TESTED
		<u>·</u>	N TO			87				2 NON	EAVAILABLE		1 VES / VES
		OFFENSE	CHARGED AND	DESCRIPTI	ON					4 LAP/S	SHOULDER BE JLDER BELT U	SED	1 NO ALCOHOL DETECTED
Z													
ACTION		I.C.:											
		DISPATCHED	APPIVED	I CI EA		1				^	CD	EF	
POLICE													
۲,													
١		V70 NO										LINGLE	J USING ILLICIT DRUG

•



HSY 0001



# 01 1		1990	
	Ohio		
TRC/IU:	91-01,	Task:	0071
Lebaron	frontal	right	view




02 -- 1990 Ohio TRC/IU: 91-01, Task: 0071 Full view of frontal plane



03 -- Ohio TRC/IU: 91-01, Task: 0071 Air bag & instrument panel










05 - Ohio TRC/IU: 91-01, Task: 0071 Final rest from left side














March Street

The HEX-FOAM TMA

The durable, high-performance, efficient truck-mounted attenuator

Now meets expanded vehicle weight range
Utilizes the revolutionary Hex-Foam cartridge to increase its lifesaving capability
Protects maintenance and construction crew members and errant motorists
Attaches and detaches easily
Optional 90° hydraulic tilting for storage convenience


Energy Absorption Systems' Hex-Foam Truck-Mounted Attenuator provides superior portable lifesaving protection for maintenance crews, highway construction workers, and errant motorists.

In numerous tests, the Hex-Foam TMA has proven to be capable of protecting a stationary maintenance vehicle from an impacting vehicle at speeds up to 45 mph. The Hex-Foam TMA has also been proven to maintain a consistently safe deceleration G-level for the expanded 1,600-to-5,400pound impacting vehicle weight range. (Test reports available upon request.)

The basic lifesaving component of the unit is Hex-Foam, a matrix of hexagonshaped honeycomb cells filled with polyurethane foam. The two-inch-thick honeycomb cell layers are stacked in a crosshatched fashion.


When Hex-Foam is impacted, it crushes and the walls of one honeycomb layer shear into the walls of the adjoining layer as well as into the foam. The foam helps stabilize the honeycomb walls to control the resistance that dissipates collision energy, bringing the impacting vehicle to a controlled, safe stop.

As used in the TMA, Hex-Foam is encased in a fiberglass shell with an integral support frame for better weatherability and easier attachment to the truck. The fiberglass shell is bolted onto a lightweight backup that can be disconnected from the truck simply by jacking up the unit (adjustable jacks and jack stands optional) and removing three pins. An optional hydraulic tilting mechanism raises the rear of the unit from the horizontal position for increased mobility over uneven terrain, and it can also be raised to a mechanically locked 90° position for convenient storage of the unit. In all, the TMA system -which includes the Hex-Foam TMA cartridge, integral frame, backup, mounting brackets, optional hydraulic actuator, optional adjustable jacks, and lighting system -weighs only 1,400 pounds.




SEE OTHER SIDE FOR MORE DESCRIPTIVE INFORMATION AND SPECIFICATIONS

The HEX-FOAM TMA



DESIGN ADVANTAGES:


- The Hex-Foam TMA meets 80-hour vibration test specifications.
- The Hex-Foam TMA maintains a consistently safe G-level for 1,600 to 5,400 pound vehicles, making larger, more cumbersome systems unnecessary.
- Durable fiberglass cartridge provides long life under normal use and severe weather conditions.
- Designed for easy replacement of the Hex-Foam TMA cartridge.
- Quick attachment and detachment. Trucks can be used for other purposes by having the total system pin-mounted.
- The TMA is designed to permit tilting of the unit with an optional actuator. Tilt options include:
 - 0° fixed-ability to convert to 90° tilt.
 - 90° tilt with mechanical-locking hydraulics operated at rear of truck (cab-activated switch also available).
- · Protects equipment from damage.





APPLICATIONS:

- Ideal protection for maintenance and work crews wherever portability is important.
- Where work crews are moving slowly, followed by a shadow truck, as in striping, sweeping, marking, mowing, and spraying.
- Where stationary work crews are protected by a shadow truck, as in the repair of guardrails, bridges, and road surfaces.
- Wherever there is a need to protect highway work crews.
- Wherever there is a need to protect the errant motorist from impact with the shadow truck.



HEX-FOAM TMA DIMENSIONS:

Length: 84" Height: 26" Width: 95" Maximum Weight: 1,400 lb Road Clearance: 10 to 12

Maximum Weight: 1,400 lbs (less without options) Road Clearance: 10 to 12 inches

HEX-FOAM

TRUCK MOUNTED ATTENUATOR

GENERAL SPECIFICATIONS

I. GENERAL

- A. All Hex-Foam Truck Mounted Attenuators, hereinafter referred to as Hex-Foam TMA, shall be designed and manufactured by Energy Absorption Systems, Incorporated, of the state of the stat
- B. The Hex-Foam TMA is a lightweight attenuator system designed for installation at the back of trucks with a 10,000 to 35,000 lb. gross vehicle weight rating.
- C. The truck and TMA combined shall have a roll distance, during an impact by either a 1600 lb or a 5400 lb vehicle at a design speed of 45 mph, of less than 32 ft. for trucks weighing greater than 10,000 lbs. (Less than 20 ft. during impacts with an 1800 lb 4500 lb vehicle). This distance is dependent on the truck wheels being locked, the transmission in gear, the parking brake set, and the truck situated on clean, dry pavement.

II. PERFORMANCE CRITERIA

- A. The Hex-Foam TMA, when mounted to a truck weighing up to 25,000 lbs. (actual weight), with the transmission in second gear, and the brakes locked, and impacted at 45 mph shall perform as follows:
 - For vehicles weighing up to 5400 lbs, impacting straight into the rear of the TMA the average overall longitudinal deceleration shall be less than 9 g's; the calculated 2 ft. flail space velocity shall be less than 40 ft./sec.; and the 10 millisecond average ride down deceleration shall be less than 20 g's. This is modified Test #50 of NCHRP #230 with a 5400 lb. inertial mass vehicle at 45 mph.
 - 2. For vehicles weighing 1600 lbs., impacting straight into the rear of the TMA the average overall longitudinal deceleration shall be less than 12 g's; the calculated 2 ft. flail

90

space velocity shall be less than 40 ft./sec.; and the 10 millisecond average ride down deceleration shall be less than 20 g's. This is modified Test #52 of NCHRP #230 with a 1600 1b. inertial mass vehicle at 45 mph.

For vehicles weighing 5400 lbs. impacting the 3. rear of the TMA at a 10-15 degree impact angle 0-3 ft. offset from center, the average overall longitudinal deceleration shall be less than 12 g's; the calculated 2 ft. flail space velocity shall be less than 40 ft./sec.; and the 10 millisecond average ride down deceleration shall be less than 20 g's. This test is modified Test #54 of NCHRP #230, with a 5400 lb. inertial mass vehicle at 45 mph.

All certified test results, associated test reports and films showing ground targets, car targets, and a method of timing for obtaining vehicle speed must be submitted showing that the TMA cartridge assembly the vendor is providing has met all test and performance criteria as called out in these specifications. This report should be in the format of and evaluated by NCHRP #230 guidelines.

All test shall be certified by a registered professional engineer. This engineer's certification document shall be sealed with his Professional Engineer (P.E.) seal and shall be submitted with the bid to supply TMA's.

- B. The Hex-Foam TMA shall be capable of passing the accelerated endurance and weathering test. One (1) Truck Mounted Attenuator assembly (TMA) shall be subjected to the three tests listed in the following sequence:
 - 1. Vibration Test 2. Moisture Test 3. Corrosion Test

 - 1. Vibration Test:

Two vibration tests will be conducted with a standard TMA cartridge. No extra tie-downs, dampeners, or supports not included in the

production model will be allowed. Vibration data forms and vibration test time log forms (attached) are to be used for recording the data required and must be submitted with the bid.

The complete TMA cartridge assembly, shall be weighed prior to and after each vibration test utilizing a certified scale. These certified TMA weights shall be recorded and submitted.

- a. <u>Test No. 1:</u> The TMA cartridge assembly shall be mounted to the vibration apparatus in its normal horizontal operating position (as shown in Figure 1). The indicated measurements shall be recorded prior to, during, and on completion of this vibration test and recorded on the attached vibration data forms.
- b. Test No. 2: The TMA cartridge assembly shall be mounted to the vibration apparatus in a position elevated to 90° (as shown in Figure 2). The indicated measurements shall be recorded prior to, during, and on completion of this vibration test and recorded on the attached vibration data forms.

The test fixture will be free of springs or dampeners, and shall have a pivot point that is located 139 inches + 9 inches from the TMA support structure, and capable of inducing the required frequency and excursion into the attenuator through a mechanically positive system. Photos of the TMA cartridge assembly mounted to the test fixture in the horizontal operating position (Figure 1) and the 90° position (Figure 2) must be submitted, on and/or before the bid opening schedule.

The frequency of the vibration will be 5 Hz to 8 Hz for a period of 40 hours in each test, 80 hours total. Excursion is to be .60 + .05 inch, measured peak to peak vertically at the location where the attenuator attaches to the back support. Measurements before and after the vibration tests will be recorded with the TMA cartridge assembly as shown in Figure 1 mounted in its normal operating position, and as shown in Figure 2 mounted in its 90° elevated position. A 0.50 inch variance of any component dimension, damage to the energy absorbing cells that would affect their performance, or damage to the back support, exterior skin, light bracket attachment, under support, or rear jack attachment will constitute failure of the device.

2. Moisture Test:

The moisture test will be conducted with the complete TMA cartridge equipped as per paragraph 1 of the Vibration Test of these specifications. The complete TMA cartridge shall be weighed prior to and after the moisture test, utilizing a certified scale. These certified TMA cartridge weights will be a part of the test data submitted with the bid.

The above attenuator will be placed in its normal horizontal operating position and subjected to precipitation equivalent to 6 inches of water per hour delivered from nozzles with spray cones, mounted so that the required precipitation is evenly distributed over the entire area of the cartridge top, sides, and ends. After a period of 24 hours, the attenuator will be turned over on its top side and the same precipitation rate continued on its bottom side for 24 hours. The water shall be turned off, the attenuator returned to its normal operating position, and the attenuator will be allowed to drain for 1 hour. The attenuator will then be examined. The complete outer covering of the TMA cartridge assembly shall be removed and the energy absorbing cells shall be examined and photographs of the energy absorbing cells shall be submitted with the moisture test data.

The cells shall be free of moisture absorption and retain 100% of their energy absorbing qualities. The results of the examination of the energy absorbing cells for moisture retention shall be submitted on and or before the bid scheduled opening.

Attenuator cells showing retention of moisture by absorption or any damage whatsoever will constitute failure of the device.

3. Corrosion Test:

A sample of attenuator energy absorbing cell material shall be subjected to a salt spray (fog) test in accordance with ASTM B117-73, Method of Salt Spray (Fog) Testing, for a period of 50 hours and consisting of two (2) periods. Each period shall consist of 24 hours exposure and one (1) hour drying time. The sample taken of the cell structure shall consist of a section with a minimum dimension of 4 cubic inches, and must include any adjacent bonding material. Photographs of the sample cell structure will be made prior to and after removal from the TMA cartridge assembly. Also, photographs will be made of this same cell sample prior to and after the corrosion test. All photographs listed above will be submitted with the corrosion test results.

Immediately after the device has been subjected to the corrosion test, there shall be no evidence of corrosion which would affect the energy absorbing qualities of the sample.

All of the above tests shall be conducted prior to bidding. All test data recorded and test procedures certified by a professional engineer shall be submitted and must show engineering proof that the TMA cartridge assembly has met all the test requirements under "Tests" in these specifications. Only units tests and certified as having been properly tested and passing these tests by a professional engineer will be accepted as meeting this specification. A written copy of test results shall accompany the bid. Failure to provide thorough test procedures, test data and prints traceable to the tested TMA assembly and components, shall be cause for rejection and/or cancellation of the order.

III. DESCRIPTION OF BASIC SYSTEM

A. Hex-Foam TMA shall consist of three basic components: a crushable Hex-Foam cartridge with fiberglass shell, a backup, and a backup support structure properly designed for attaching the system to the truck. Total weight of the basic system shall be approximately 1400 lbs. The complete Hex-Foam TMA shall be designed to make

90

attachment, or detachment, from the truck simple and fast, with the major sub-assemblies listed above remaining together when detached from truck.

- B. The Hex-Foam TMA cartridge shall have a standard trailer lighting system, including brake lights, tail lights, turn signals, and ICC bar lights. The wiring from the rear lights shall be routed and secured inside the cartridge. A strain relief connector shall secure the wiring at its exit point. The wiring exit point shall be located along the cartridge centerline within 12" of the cartridge backup.
- C. The standard cartridge will also be equipped with two steel wheeled, rear-mounted jacks, which in their retracted position shall act as skid protectors.
- D. The exposed steel shall be primed and painted yellow. All welding shall be done by or under the direct supervision of a certified welder.
- E. The rear facing surface of the cartridge shall have a 4" wide black on yellow inverted "V" chevron pattern.

IV. OPTIONAL ACCESSORIES

A. Two front hand crank jacks with swivel casters attached to the backup for removing unit from truck for storage.

B. <u>Tilt System</u>, Hydraulic, 90°

The optional hydraulic package shall consist of a pump with a 12 volt DC motor, cylinder, hoses, switches, wiring and necessary subcomponents to facilitate the tilting of the TMA cartridge to a 90° position from horizontal. The unit shall have a hydraulically activated latching system which automatically hydraulically extends and engages two 3/4" diameter locking pins to secure the TMA System in the 90° position.


The complete hydraulic system (including pump, hoses and latching system) shall be factory assembled and mounted to the backup and backup support structure. Once assembled, each unit shall be operated through two complete cycles (horizontal, tilted to a latched position and

2/90

.


lowered back to horizontal is one cycle) to insure proper operation of the pump, tilting mechanism, and the automatic hydraulically activated latching system. The hydraulic system shall be shipped assembled, but unfilled of hydraulic fluid.

The "Up" operation of the hydraulic tilt may be actuated from either the cab of the truck or the hand held control switch at the end of a 6 ft. cord, near the right rear corner of the truck. The "Down" operation from the 90° locked position can only be activated with the control at the right rear corner of truck positioned to allow the operator to first visually check the safety clearance behind and under the unit, prior to lowering the Hex-Foam cartridge to the travel position.



ATTENUATOR CARTRIDGE IN NORMAL HORIZONTAL OPERATING POSITION

FIGURE NO.1



ATTENUATOR CARTRIDGE IN 90 DEGREE POSITION


FIGURE NO. 2

Рап No.: _____ Serial No.: _____

TMA CARTRIDGE ASSEMBLY **VIBRATION DATA FORM**

ĵ

		Test No. 1		Test No.2			
Dimension in Inches	Before Test	20 Hours	40 Hours	Before Test	20 Hours	40 Hours	
Α							
A							
В							
B ₁			_				
С				· -			
C							
D					·		
D							
E							
E ₁							
F					;		
F ₁							
G							
G							
Н							
H,							
I							
I,							
J				_			
J	-		-				
WEIGHT		·	······································				



The space provided on the back of this page may be used to document injuries noted by the interviewee(s).

U.S. Department of Transportation

National Highway Traffic Safety Administration

OCCUPANT INJURY FORM

Form Approved O.M.B. No. 2127-0021 NATIONAL ACCIDENT SAMPLING SYSTEM CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number 10 3. Vehicle Number 01 2. Case Number – Stratum 9101 4. Occupant Number 01


INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.


			0.1.C. — A.I.S.					Injury		
	Source [—] of Injury Data	Body Region	Aspect	Lesion	System Organ	A.I.S. Severity	Injury Source	Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion No.
1st	5. 3	6. <i>E</i>	7. S	8. <i>L</i>	9. <u>F</u>	10. <u>/</u>	11. <u>45</u>	12	13/	14. 00
2nd	15. <u>3</u>	16. <u>w</u>	17. <u>L</u>	18. <u>L</u>	19. <u>I</u>	20. <u> </u>	21. <u>97</u>	<u>22. 9</u>	<u>23. 7</u>	99
3rd	25. 3	26. <u>0</u>	27. <u>w</u>	28. <u>C</u>	29. L	30. <u>/</u>	31. <u>97</u>	32. _9	33. <u>7</u>	34. <u>99</u>
4th	35. <u>7</u>	36. <u>F</u>	37. I	28. <u>A</u>	38.Ľ	40. <u>/</u>	41. <u>45</u>	- <u>42 </u>	43. <u> </u>	44. 00
5th	45. <u>7</u>	46. R	47. <u>K</u>	48. <u>C</u>	49. <u>I</u>	50. <u>/</u>	51. <u>/0</u>	<u>52.</u> 2	<u>53. /</u>	54. 99
6th	55	56	57	58	59	60	61	62	63.	64
7th	65	66	67	68	69	70	71	72	73	74
8th	75	76	77	78	79	80	81	82	83	84
9th	85	86	87	88	89	90	91	92	93	94
10th	9 5	96	97	98	39.	100	101	102	103	104

HS Form 433B (1/91)

This report is authorized by P.L. 89-563, Title 1, Section 106, 108, and 112. While you are not required to respond, your cooperation is needed to make the results of this data collection effort comprehensive, accurate, and timely.




OFFICIAL INJURY DATA-SKELETAL INJURIES



Page 3

OFFICIAL INJURY DATA-INTERNAL INJURIES

Indicate the Location, Lesion, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



DATE:					
LAST NAME:			FIRST	NAME :	INT:
DOB:	AGE:	40			

ACCT. NO.:


HISTORY: This is a 40-year-old white female who was involved in a motor vehicle accident. The patient is complaining of no specific injuries. She just feels "sore all over." She denies loss of consciousness. No medications, allergies, or past medical history of note. The patient remembers the entire accident stating a large utility vehicle of some kind pulled out in front of her on the highway, and she was unable to stop, ramming up under the vehicle. Her air bag in her car inflated, saving her from major injury. However, the car was totally destroyed. Her tetanus is up-to-date.

PHYSICAL EXAM

GENERAL: The patient is a 40-year-old white female in no apparent distress. VITAL SIGNS: Stable, afebrile. **HEENT:** Except for a small, superficial laceration above the right eye the head was normocephalic, atraumatic. The pupils equal, round, regular, react to light, extraocular movements intact. Sclerae are nonicteric, conjunctivae pink and moist. The tympanic membranes are without hemotympanum. Negative Battle's and negative Raccoon. NECK: Supple and nontender. Cervical collar was removed. CHEST: Clear to auscultation and percussion and nontender. CARDIO: Normal. **ABDOMEN:** Bowel sounds positive. Soft and nontender. **EXTREMITIES:** Within normal limits. **NEUROLOGICAL:** The patient is alert and oriented to person, place, and time. The eyes are PERRLA with EOMI. Funduscopic exam reveals no papilledema, hemorrhage, or abnormal venous pulsations. Cranial nerves II-XII are intact. Deep tendon reflexes are symmetrically equal and within the normal range. Motor strength is 5/5 and symmetric. No sensory deficits are present. Cerebellar function is intact (no ataxia was observed). 🦏 reflexes are downward bilaterally. The patient's cranial checks were negative. The wounds were cleaned and prepped and sterilely dressed. The patient was re-examined by myself and had no new complaints or injuries that she noted. She was discharged to home on Ansaid 100 mg b.i.d. Rest. Follow-up p.r.n. Instructions given. IMPRESSION: (see_page_3)

D:

EMERGENCY RECORD	
PRESCRIPTIONS	
	LABS
	WBC
	Hbg/Hct:
	Lytes, Na CL
	 ксо,
	BUN: CR: GLU
	ABG's #1 #2 PEFR
	рН 1
	pCO, 2
	HCO, 3
	PO,
HISTORY	0, SAT
	0,341
	· · · · · · · · · · · · · · · · · · ·
SEE DICTATED H&P ON PAGE 2	
PHYSICAL EXAM	
FOLLOW-UP EXAM [TIME]:	
CONSULTANT [TIME]:	,
X-RAY IMPRESSION	
PROVISIONAL D'AGNOSIS: Superficient CAR To forchead 1	Har A
= antipl commens 2" rowt uA	
Physician Attending Physician Physician	
Signature for History and Physical and Documentation for Pages 1.2.3.	on for Pages 1.2.3.
NAME AST	
FIRST INIT. DATE OF BUTT	AGE JEX MAR ACCT NO.
	PAGE 3



CVL D ECG HC N	- Climica - Cardiov	ras cullar cs card±ogri lare 1	OT - Occupational Therapy aphy PMR - Phys. Med. & Rehap, PS - Pastoral Services RS - Respiratory Service
Date	Time	Code	Emergency Visit Supplement
			BP 124 1,00 Plet R 16 T 97 all-sulla Midso
			hest IT - unsuse, himed by squad
			\$ A.A Arenes - air has reland. Sm
			around doud blood to forchead & a hand
		1	Du in roted a 90 per nurvey. Back board
·			
			C- Calean resserved from the transfer
		 	frant -
		i	· · · · · · · · · · · · · · · · · · ·
	-		
	•	1	