

GM CUSTOMER CARE AND AFTERSALES
DCS2568
URGENT - DISTRIBUTE IMMEDIATELY

Date: March 22, 2011

Subject: 10282B - Safety Recall
Harsh Transmission Shift, Engine Stall, Engine May Not Start,
MIL or SES Lamp
Revised Service Procedure

Models: 2005-2008 Pontiac Vibe
Two Wheel Drive Equipped with 1.8L MFI Engine (LV6)

To: All GM Dealers

Attention: General Manager, Service Manager, Parts Manager,
Used Vehicle Sales Manager, and Warranty Administrator

The Service Procedure in bulletin 10282B has been revised to advise technicians that the replacement control modules are preprogrammed at the factory, and only require the VIN to be programmed. Please discard all copies of bulletin 10282A, issued February 2011.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES

Nothing in this message is intended to constitute an electronic signature unless a specific statement to the contrary is included in this message.

Confidentiality Note: This message is intended only for the person or entity to which it is addressed. It may contain confidential and/or privileged material. Any review, transmission, dissemination or other use, or taking of any action in reliance upon this message by persons or entities other than the intended recipient is prohibited and may be unlawful. If you received this message in error, please contact the sender and delete it from your computer.