



Truxxx Manufacturing LLC
810 E 19th Street, Tucson, AZ 85719
Toll free phone or fax at 888-660-5892
Email: lesley@truxxx.com :: See our products online at <http://www.truxxx.com>

August 4, 2009

Ms. Kelly Schuler
Recall Management Division
National Highway Traffic Safety Administration
400 Seventh St. S.W.
Washington, DC 20590

VIA MAIL/E-Mail (Kelly.schuler@dot.gov)

RE: Fifth Quarter Defect Report (49 CFR Part 573)
Voluntary Campaign:
Manufacturer: Truxxx Manufacturing, LLC
Subject: Aftermarket replacement welded 3" lift blocks for rear suspension: Part # 206073 for Ford 2005-2008 F-250 SuperDuty 4x4 light trucks, included with TruxxxTM suspension kits # 108035, 108036

Dear Ms. Schuler:

Please find Truxxx Manufacturing, LLC's Fifth quarter recall report information regarding the above identified voluntary campaign.

Should you have any comments or questions regarding this campaign please contact Dave Ishim (dave@truxxx.com) or myself (lesley@truxxx.com) at Truxxx Manufacturing, LLC 810 E. 19th St., Tucson, Arizona 85719, phone (480) 882-0717 ext. 415; Fax (520) 623-1663.

Sincerely,

Lesley Stevenson
Truxxx Manufacturing, LLC

[Recipient Name]

July 24, 2008

Page 2

Equipment Safety Recall Quarterly Report Information

Required per 49 CFR 573.6

Report Date: 8/4/2009

Calendar Quarter: Fifth

Voluntary Safety Recall Quarter: 4/16/09 through 7/15/09

Manufacturer: Truxxx Manufacturing, LLC

Recall Subject: Aftermarket replacement welded 3" lift blocks for rear suspension: Part # 206073 for Ford 2005-2008 F-250 SuperDuty 4x4 light trucks, included with Truxxx™ suspension kits # 108035, 108036

1. NHTSA Recall Number: 08E026000

2. (a.) Date notification to purchasers began: 5/2/2008

(b.) Date notification to purchasers completed: 5/3/2008

3. Total number of Items of Equipment Involved: Approx. 322 (for both kits)

(The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items returned from Inventory or Remedied Prior to Sale: 30 (individual blocks)

(Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or retailer inventory or (b) otherwise remedied prior to sale to customers).

4. (a.) Total Number Inspected & Remedied: 115 (individual blocks)

(Total number of items which were inspected and/or otherwise repaired or remedied)

(b.) Total Number Inspected & NOT REQUIRING REMEDY: 0

(Total number of items involved in the recall and inspected, but determined to not require remedial or recall repair work.)

5. Items Determined to be Unreachable.

Total Number Exported: 0

Total Number Stolen: 0

Total Number Scrapped: 1

Total Number unable to Notify: 0

Total Number Otherwise Unreachable: Unknown

Describe Other: N/A