GENERAL MOTORS LLC



Vehicle Safety and Crashworthiness

March 17, 2014

Ms. Nancy Lewis Associate Administrator for Enforcement National Highway Traffic Safety Administration Recall Management Division (NVS-215) 1200 New Jersey Avenue, SE – Room W45-306 Washington, DC 20590

Dear Ms. Lewis:

The following information is submitted pursuant to the requirements of 49 CFR 573.6 as it applies to a determination by General Motors to conduct a safety-related recall for 2013 and some 2014 model year Cadillac XTS vehicles.

573.6(c)(1): Cadillac Brand of General Motors Company

573.6(c)(2)(3)(4): This information is shown on the attached sheet.

573.6(c)(5): General Motors has decided that a defect which relates to motor vehicle safety exists in 2013 and some 2014 model year Cadillac XTS vehicles. Pressure within the brake booster pump harness may cause a brake booster pump cavity plug to dislodge from the connector. This could allow contamination which may cause corrosion of the brake booster pump relay connector. If there is sufficient corrosion of the relay connector, it may cause a resistive short and melt the connector, which could cause a fire.

<u>573.6(c)(6)</u>: The issue was presented to the Field Performance Evaluation Review Committee and on March 11, 2014, the Executive Field Action Decision Committee decided to conduct a safety recall. General Motors will be submitting a supplemental chronology within two weeks.

573.6(c)(8): Dealers are to ensure that the vacuum pump vent hose is re-routed so it cannot be restricted. Silicone sealer will be applied to increase the retention of the connector cavity plugs, and where necessary, dealers are to replace the front body wiring harness.

GM will provide the dealer bulletin and owner letter mail dates when available.

Pursuant to 577.11(e), GM does not plan to provide notice about reimbursement to owners because all involved vehicles are covered under the new vehicle warranty.



Letter to Ms. Nancy Lewis N140062 573 Letter March 17, 2014 Page 2

573.6(c)(10): GM will provide copies of the dealer bulletin and owner letter under separate cover.

573.6(c)(11): GM's assigned recall number is 14062.

Sincerely,

M. Com 1

M. Carmen Benavides, Director Product Investigations and Safety Regulations

14062 Attachment

VEHICLES POTENTIALLY AFFECTED BY MAKE, MODEL, AND MODEL YEAR <u>PLUS INCLUSIVE DATES OF MANUFACTURE</u>

MAKE	MODEL <u>SERIES</u>	MODEL <u>YEAR</u>	NUMBER INVOLVED	INCLU MANUFACTU <u>(FROM)</u>		DESCRIPTIVE INFO. TO <u>PROPERLY IDENT, VEH.</u>	EST. NO. W/CONDITION
Cadillac	1	2013	41,966	02/14/2012	06/21/2013	XTS	*
Cadillac	1	2014	21,937	02/12/2013	03/07/2014	XTS	a
GM Total Vehicles: 63,903							

* All involved vehicles will be corrected as necessary.

<u>573.6(c)(2)(iv)</u>: Not applicable – this is a vehicle integration issue.

14062