## Rapaport, Martin ZU-A-21

From:

Quality & Service Engineer [QSENG@dealers.bmwna.com]

Sent:

Monday, November 04, 2002 5:53 PM

To:

DCS 2000 Server

Subject:

DCS 2000 Server 223 E46 Recall Campaign 02V-233 (Recode Airbag Control Unit)

To: BMW Service Managers To: BMW Parts Managers

RE: E46 Recall Campaign 02V-233 (Recode Airbag Control Unit)

Service Information Bulletin (#B72 03 02) and the customer notification letter state that vehicles affected by this recall are certain 1999 Model Year BMW 323i & 328i 4-door automobiles.

It has been brought to our attention that some of the affected vehicles are actually 2000 Model Year vehicles. This had led to some confusion for customers of affected vehicles which are indeed 2000 MY. Production of these models for the 2000 MY began in 06/1999. Vehicles affected by this recall were produced 04/1999 through 08/1999.

The actual vehicles and the chassis number ranges provided in SI B72 03 02 have not changed.

As always, to determine if a specific vehicle is affected by a recall campaign, utilize the "Service Menu" of the DCS (Dealer Communication System). Based upon the response of the system, either proceed with the corrective action or take no further action.

SI B72 03 02 and the customer notification letter will be revised to state "certain 1999 and 2000 Model Year BMW 323i & 328i 4-door automobiles".

We apologize for any confusion caused by this error.

BMW of North America

## Distribution:

Department

W Service Dept

Title Μ ProductType

Manager Α Auto

Dealer Number

UX

Division Region

Market Area XX All Regions XX All Areas

Area PDC Country State

Department

Parts Dept

Title

Μ

Manager

ProductType A
Dealer Number
Division UX

Division UX Market Area
Region XX All Regions
Area XX All Areas
PDC

Auto

PDC Country State