



Mercedes-Benz

Mercedes-Benz USA, LLC
A Daimler Company

SENT VIA CERTIFIED U.S. MAIL

October 3, 2012

National Highway Traffic Safety Administration
Attention: Jennifer Timian, Chief, Recall Analysis Division
1200 New Jersey Avenue Seventh, S.E.
Washington, D.C. 20590

Dear Ms. Timian:

Please find the Quarterly Report of Defect Notification Campaigns for the quarter ending September 30, 2012.

Should you have any questions, please do not hesitate to contact me at brunnert@mbusa.com.

Sincerely,

R-Thomas Brunner
Department Manager,
Vehicle Compliance and Analysis

Stephen Kraitz
Compliance Engineer
Vehicle Compliance and Analysis

Enclosure

Mercedes-Benz USA, LLC
One Mercedes Drive
P.O. Box 350
Montvale, NJ 07645-0350
Phone (201) 573-0600
Fax (201) 573-0117
www.MBUSA.com

MANUFACTURER MERCEDES-BENZ USA, LLC.		QUARTER ENDING September 30, 2012			
MOTOR VEHICLE SAFETY DEFECT REPORT QUARTERLY REPORT DEFECT NOTIFICATION CAMPAIGNS					
MBUSA REFERENCE NUMBER ABBREVIATED DESCRIPTION	2011030004 E VIBRATION DAMPER	2011090001 ML BRAKE SWITCH	2011110002 ML, GL, R, E DIESEL FUEL FILTER	2012070006 E WAGON LEVEL SENSOR	
REPORT NO. (573.6)	6	4	4	1	
CAMPAIGN NO. b(1)	11V-213	11V-208	11V-496*	12V-264	
DATE STARTED b(2)	4/8/2011	9/23/2011	11/23/2011	9/7/2012	
NOTIFICATION ENDED b(2)					
NUMBER OF VEHICLES					
INVOLVED IN CAMPAIGN: b(3)	41	135060	6785	3617	
REPAIRED: b(4i)	40	37258	4687	884	
INSPECTED					
REPAIR NOT NEEDED: b(4ii)	0	0	0	0	
CORRECTIVE MEASURES					
COMPLETED: b(5)	40	37258	4687	884	
UNREACHABLE b(6)	0	0	0	0	
STOLEN	0	0	0	0	
SCRAPPED	0	0	0	0	
SOLD-OWNER UNKNOWN	0	0	0	0	
OUT OF U.S.	0	0	0	0	
MOVED-NO ADDRESS	0	0	0	0	
UNCLAIMED LETTER	0	0	0	0	
UNCOOPERATIVE	0	0	0	0	
COMPLETION PERCENT	97.56%	27.59%	69.08%	24.44%	

* Per MBUSA's November 15, 2011 Part 573 Defect Information Report Update, Recall 10V-540 (2010110001) was closed on November 23, 2011 with the launch of Recall 11V-496. MBUSA will discontinue reporting on 10V-540 after fourth quarter 2011. Going forward, all of the vehicles will be covered and reported under MBUSA Recall Campaign Number 2011110002 (NHTSA recall number 11V-496).