

**National Highway Traffic Safety Administration (NHTSA)**  
**Vehicle Safety Recall Quarterly Progress Report for Fleetwood RV, Inc.**  
**Quarterly Report from July 1, 2012 through September 30, 2012**  
**Report Date - October 18, 2012 / Report Author - Julie Jones (260) 724-5716**

# of Quarters Reported	NHTSA Recall #	FRV Recall #	Date of 1st Mailing	Date of 2nd Mailing	Date of 3rd Mailing	Total # Vehicles Involved	Total # Inspected & Remedied	Total # Inspected & Not Requiring Remedy	Total # Exported	Total # Inspected / Defective / Owner Declined	Total # Unable to Notify	Description of Recall
6	11V-298	110520FRV	07/08/11	10/14/11	01/18/12	703	371	235	5*	0	1-Germany	Wire Harness Routing on Class A Units Built on Ford F53 Chassis MY 2011 Bounder, Bounder Classic, Storm, Terra, Southwind and MY 2012 Southwind and Bounder (*Includes 1 exported - Germany)
5	11V-383	110715FRV	08/25/11	11/23/11	02/24/12	220	109	6	11*	1	3-UK	Federal Certification Tag - Incorrect Intermediate and Rear Tire KPA Values (*Includes 3 exported - UK)
5	11V-399	110728FRV	08/25/11	11/29/11	03/01/12	408	96	196	8*	0	1-Poland	MY 10-11 Class A Motor Homes - Siemens 15-20-30 Amp 120-volt Circuit Breakers. Note: The Total # Vehicles Involved was updated per the Amendment filed December 16, 2011 - 49 additional units 1st mailing 12-21-11 / 2nd mailing 3-23-12 / 3rd mailing 6-21-12. (*Includes 1 exported - Poland)
1	12V-412	120813FRV	09/11/12			74	0	0	1	0	0	MY13 Excursion 33A Diesel Fuel Fill Hose - Inspect the diesel fuel fill hose for possible contact with a threaded fastener on the slide-out turn shaft.