Instructions for Reimbursement: Safety Recall: 2007–08 TL Power Steering Feed Hose Leak

Reimbursement eligibility

You may be eligible for reimbursement if you previously paid to have the power steering feed hose replaced.

- You must have had your vehicle repaired before receiving this notice.
- You must have owned the vehicle at the time of repair. You are still eligible if you no longer own the vehicle.

NOTE: Any incidental expense or inconvenience you may have suffered due to the loss of use of your vehicle may not be reimbursable.

To apply for reimbursement

- ✓ Complete the attached Request for Reimbursement form.
- ✓ Attach a copy of the repair receipt or invoice for the repair. A copy of the repair invoice from an authorized Acura dealer or independent repair facility, indicating replacement of the power steering feed hose, will meet this need. This invoice should show your vehicle's model, vehicle identification number (VIN), the name and address of the facility that did the repair, the itemized cost of the repair (parts and labor), and the date the work was completed.
- ✓ Attach proof of payment, such as a copy of the cancelled check, bank statement, cash receipt, or credit card receipt showing that you paid for the repair.
- ✓ Mail this completed form and copies of the receipts and invoices to:

American Honda Motor Co., Inc. Automobile Customer Service P.O. Box 2964 Torrance, CA 90509-2964

Please allow 6 to 8 weeks for reimbursement.

Failure to include proper documentation can delay your reimbursement. If you have questions, please call your local authorized Acura dealer. If they cannot help you, call 1-800-382-2238, and select option 4.

Make sure to include all required supporting information with your request.