



U.S. Department of Transportation  
**National Highway Traffic Safety  
Administration**

1200 New Jersey Avenue SE  
Washington, DC 20590

August 19, 2015

Ms. Joy Hotchkiss  
General Motors LLC  
30001 Van Dyke  
Warren, MI 48090

NVS-215SM  
15V-463

**Subject:** Power Operated Roof Panel/FMVSS 118

Dear Ms. Hotchkiss:

This letter serves to acknowledge General Motors LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

CADILLAC/ATS/2013-2016

**Mfr's Report Date:** July 20, 2015

**NHTSA Campaign Number:** 15V-463

**Components:**

VISIBILITY:SUN ROOF ASSEMBLY

**Potential Number of Units Affected:** TBD

**Problem Description:**

General Motors LLC (GM) is recalling certain model year 2013-2016 Cadillac ATS vehicles manufactured April 25, 2012, to June 25, 2015. The affected vehicles may experience the roof panel closing automatically when the non-recessed switches are pressed and the roof panel is open. These vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) No. 118, "Power-Operated Window, Partition, and Roof Panel Systems."

**Consequence:**

If the switch fails and causes the roof panel to close automatically, it can increase the risk of injury.

**Remedy:**

GM will notify owners and dealers will replace the roof console accessory switch trim plate, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Cadillac customer service at 1-800-458-8006. GM's number for this recall is 15568.

**Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.safercar.gov](http://www.safercar.gov).

GM did not indicate the number of vehicles affected. Please provide this information via an amended 573 as soon as it is known.

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

We have received GM's proposed owner notification letter and have approved it for distribution. Letters must be mailed to owners within 60 days of the recall filing.


Please be reminded of the following requirements:

You are required to submit copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Mcshane who may be reached by phone at 202-366-7401, or by email at [sarah.mcshane@dot.gov](mailto:sarah.mcshane@dot.gov) or through the office email at [rmd.odi@dot.gov](mailto:rmd.odi@dot.gov). We look forward to working with you.

Sincerely,

A handwritten signature in black ink, appearing to read "Jennifer Timian".

Jennifer Timian  
Chief, Recall Management Division  
Office of Defects Investigations  
Enforcement