

Vehicle Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.6

Report Date: 10/27/11

Calendar Quarter: 2

Safety Recall Quarterly Report from July 1, 2011 through September 30, 2011

Manufacturer: Fleetwood RV, Inc.

Report Author: Julie Jones

Phone: (260)724-5716

**Recall Subject: Wire Harness Routing on Class A Units Built on Ford F53 Chassis.
MY 2011 Bounder, Bounder Classic, Storm, Terra, Southwind,
and MY 2012 Southwind and Bounder**

1. NHTSA Safety Recall Campaign Number: 11V-298

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: 110520FRV

2. (a) The date notification to purchasers began:

1st mailing: 7/8/11

2nd mailing: 10/14/11

(b) The date the 3rd notification to purchasers was completed:

3. The Total Number of Vehicles Involved: 703

The total number of vehicles involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

4. (a) Total Number Inspected & Remedied: 231

Total number of vehicles which were inspected and/or otherwise repaired or remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: 118

Total number of vehicles involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Vehicles Determined to be Unreachable

Total Number Exported: 1

Total Number Stolen: 0

Total Number Scrapped: 0

Total Number Unable to Notify: 0

Total Number Otherwise Unreachable: 0

Describe Other: