



Truxxx Manufacturing LLC

810 E 19th Street, Tucson, AZ 85719

Toll free at 888-660-5892 - Fax: 520-623-1663

email lesley@truxxx.com :: See our products online at <http://www.truxxx.com>

July 2, 2008

Ms. Kelly Schuler
Recall Management Division
National Highway Traffic Safety Administration
400 Seventh St. S.W.
Washington, DC 20590

VIA MAIL/E-Mail (Kelly.schuler@dot.gov)

RE: First Quarter Defect Report (49 CFR Part 573)

Voluntary Campaign:

Manufacturer: Truxxx Manufacturing, LLC

Subject: Aftermarket replacement welded 3" lift blocks for rear suspension: Part # 206073 for Ford 2005-2008 F-250 SuperDuty 4x4 light trucks, included with Truxxx™ suspension kits # 108035, 108036

Dear Ms. Schuler:

Please find Truxxx Manufacturing, LLC's first quarter recall report information regarding the above identified voluntary campaign. Note that with respect to report item 4 (a.) we have furnished 72 additional replacement blocks for which we have not received returned "suspect" blocks for inspection.

Should you have any comments or questions regarding this campaign please contact Eric Hasenberg (eric@truxxx.com) or myself (lesley@truxxx.com) at Truxxx Manufacturing, LLC 810 E. 19th St., Tucson, Arizona 85719, phone (480) 882-0717 ext. 415; Fax (520) 623-1663.

Sincerely,

Lesley Stevenson

Equipment Safety Recall Quarterly Report Information
Required per 49 CFR 573.6

Report Date: 7/1/2008 **Calendar Quarter:** First
Voluntary Safety Recall Quarter: 4/15/08 through 6/15/08

Manufacturer: Truxxx Manufacturing, LLC

Recall Subject: Aftermarket replacement welded 3” lift blocks for rear suspension: Part # 206073 for Ford 2005-2008 F-250 SuperDuty 4x4 light trucks, included with Truxxx™ suspension kits # 108035, 108036

1. NHTSA Recall Number: 08E026000

2. (a.) Date notification to purchasers began: 5/2/2008

(b.) Date notification to purchasers completed: 5/3/2008

3. Total number of Items of Equipment Involved: Approx. 322 (for both kits)

(The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items returned from Inventory or Remedied Prior to Sale: 16

(Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or retailer inventory or (b) otherwise remedied prior to sale to customers).

4. (a.) Total Number Inspected & Remedied: 20

(Total number of items which were inspected and/or otherwise repaired or remedied)

(b.) Total Number Inspected & NOT REQUIRING REMEDY: 0

(Total number of items involved in the recall and inspected, but determined to not require remedial or recall repair work.)

5. Items Determined to be Unreachable.

Total Number Exported: 0

Total Number Stolen: 0

Total Number Scrapped: 0

Total Number unable to Notify: 0

Total Number Otherwise Unreachable: Unknown

Describe Other: N/A