

GM CUSTOMER CARE AND AFTERSALES  
DCS3752  
URGENT - DISTRIBUTE IMMEDIATELY

Date: August 19, 2015

Subject: 15568A – Noncompliance Recall  
Sunroof Switch MVSS 118 Compliance  
Customer Letter Added

Models: 2013-2016 Cadillac ATS Equipped with Power Sunroof RPO CF5

To: All Cadillac Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, New and Used Vehicle Sales  
Manager, and Warranty Administrator

Bulletin 15568 has been revised to include a copy of the customer letter. Please discard all copies of bulletin 15568.

**Customer Letter Mailing**

The customer letter mailing begins today, August 19, 2015.

END OF MESSAGE

GM CUSTOMER CARE AND AFTERSALES