

U.S. Department of Transportation

National Highway Traffic Safety Administration

September 10, 2012

Mr. WES CHESTNUT SENIOR COMPLIANCE ANALYST SPARTAN CHASSIS, INC. 1000 REYNOLDS ROAD CHARLOTTE, MI 48813 NVS-215ET 12V-429

1200 New Jersey Avenue SE Washington, DC 20590

Subject: Brake Chamber Interfering with Upper Control Arms

Dear Mr. CHESTNUT:

This letter serves to acknowledge SPARTAN CHASSIS, INC.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

SPARTAN/K2/2008-2009 SPARTAN/MM/2008-2010, 2012-2013

Mfr's Report Date: August 31, 2012

NHTSA Campaign Number: 12V-429

Components:

SERVICE BRAKES, AIR:DRUM:CHAMBER SUSPENSION:FRONT:CONTROL ARM

Potential Number of Units Affected: 491

Problem Description:

Spartan is recalling certain model year 2008-2013 K2 and MM motor home chassis, equipped with a Hendrickson independent front suspension. The front brake chambers may contact the upper control arm of the independent front suspension. Continued contact may result in damage sufficient enough to inhibit the full release of the brakes. If the brakes do not fully release, as they drag, heat could be generated causing the brakes to engage even further.

Consequence:

As the brakes self-engage, the driver could lose control of the vehicle, increasing the risk of a crash.

Remedy:

Spartan chassis will notify owners, and repair the vehicles. Spartan Chassis has not provided a notification schedule. Owners may contact Spartan at 1-800-543-5008.

Notes:

Spartan's safety recall number is 12010. Owners may also contact the National Highway Traffic Safety Administration's Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to http://www.safercar.gov.



Please be reminded of the following requirements:

You are required to provide an estimated date including month, day, and year, when you will send notifications to owners, dealers, and distributors as soon as it becomes available. Please be reminded that it is expected owners will be notified of a safety defect in their vehicles within 60 days of a manufacturer's notification to NHTSA of a safety defect in those vehicles. You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers.

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Edison Thompson who may be reached by phone at 202-366-9525, or by email at edison.thompson@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian

Chief, Recall Management Division Office of Defects Investigations

Enforcement

