

## R-5 EXCESS FIRE EQUIPMENT CONDITION REPORT

1. REPORTING FOREST: <u>CNF</u>	2. VEHICLE LOCATION: <u>G.V.</u>	3. VEHICLE CLASS: _____	4. MAKE AND TYPE: _____	INT. Type 3 Engine
5. EQUIPMENT FS NO: <u>6018</u>	6. ODO / METER READING: _____	7. DATE INSPECTED: <u>4/14/2021</u>	8. INSPECTOR: _____	M.Rhodes
9. YEAR: <u>2003</u>	10. MODEL / TYPE: _____	12. DRIVE: _____	13. VIN for Serial #: _____	1HTWCADN94J020151

### TOTAL ESTIMATE REPAIR COST

IN-HOUSE: \$ \_\_\_\_\_ COMMERCIAL: \$ \_\_\_\_\_ DATE PARKED: \_\_\_\_\_

### VEHICLE CONDITION

	GOOD	FAIR	BAD	Est. Cost	REMARKS
1. STEERING SYSTEM		X			
CLUTCH (# APPLICABLE)					
3. BRAKES, FOOT AND HAND		X			
4. VEHICLE QUAGE OPERATION		?			Unable to check, Batteries Dead.
5. SEATS AND CUSHIONS, SEATBELTS	X				
6. COOLING SYSTEM		?			Unable to check, Batteries Dead.
7. ENGINE		?			Looks in good working order Batteries Dead so can not start
8. CYLINDER COMPRESSION					
1. 2. 3. 4. 5. 6. 7. 8.					
9. ELECTRICAL SYSTEM		X			
10. BATTERY			X		Batteries Dead
11. TRANSMISSION OPERATION		X			
12. DRIVE LINE U JOINTS		X			
13. DIFFERENTIAL OPERATION		X			
14. 4 WHEEL DRIVE OPERATION					N/A
15. SPRINGS AND SHOCKS		X			
16. FRAME CRACKS AND BENT		X			
17. TIRES AND WHEELS		X			Front & Rear Tires 70% tread
18. LIGHTS		X			
19. GLASS		X			
20. BODY CONDITION		X			
21. EXHAUST SYSTEM		X			
22. FUEL SYSTEM		X			
23. JACK, WHEEL WRENCH, SPARE TIRE/WHEEL					N/A

### PUMP UNIT

	GOOD	FAIR	BAD	Est. Cost	REMARKS
1. ENGINE OR PTO OPERATION					
2. PUMP PRESSURE AND VOLUME					
3. PLUMBING LEAKS					
4. VALVE OPERATION					
5. COMPARTMENT CONDITION (FUEL SYSTEM)					
6. HOSE REEL OPERATION					
7. PRIMER PUMP OPERATION					
8. PUMP INSTRUMENTS AND GAUGES					
9. OTHER					

ACCURATE EQUIPMENT SERVICE,  
 INC  
 PO Box 412  
 Ramona, CA 92065

# Estimate

Date	Estimate #
8/24/2020	165

Name / Address
USFS 6018

Description	Qty	Rate	Project
			Total
ACCURATE EQUIPMENT SERVICE INC DUNS #:969054373 EMAIL: RHI@AESERVICEINC.COM PHONE: 760-789-9911			
ANNUAL SERVICE	1	450.00	450.00
ANNUAL INSPECTION			
REMOVE WHEELS AND INSPECT BRAKES-FRONT BRAKES NEED TO BE REPLACED			
CHANGE ENGINE OIL AND FILTER			
LUBE CHASSIS			
FILL OUT CUSTOMER SUPPLIED FORM			
LUBE FILTER	1	49.11	49.11T
KENDALL SUPER CK4-15W40	8	21.5825	172.66T
OIL DISPOSAL FEE	8	0.65	5.20
REMOVE WHEELS			
REMOVE AND REPLACE REAR BRAKE DRUMS AND SHOES			
REPLACE WHEELS			
Q-PLUS BRAKE SHOE KIT	2	98.985	197.97T
BRAKE DRUM	2	161.56	323.12T
BRAKE CLEAN	2	5.50	11.00T
SHOP MECHANIC LABOR	3	105.00	315.00
OPACITY TEST , INCLUDES WINDSHIELD STICKER AND TEST REPORT	1	125.00	125.00T
DRAIN AND REFILL TRANSMISSION			
REMOVE AND REPLACE CARTRIDGE FILTERS			
Thank you for your business.			
			<b>Subtotal</b>
			<b>Sales Tax (0.0%)</b>
			<b>Total</b>

ACCURATE EQUIPMENT SERVICE,  
 INC  
 PO Box 412  
 Ramona, CA 92065

# Estimate

Date	Estimate #
8/24/2020	165

Name / Address
USFS 6018

Description	Qty	Rate	Project	
			Total	
TRANSMISSION FILTER KIT	1	84.00	84.00T	
ALLISON TES389 TRANSMISSION OIL	6	28.97	173.82T	
SHOP MECHANIC LABOR	1.5	105.00	157.50	
OIL DISPOSAL FEE	6	0.65	3.90	
SEPARATE AND LOAD TEST BATTERIES SERVICE TERMINALS SHOP MECHANIC LABOR	0.75	105.00	78.75	
REMOVE AND REPLACE FUEL FILTERS FUEL FILTER	1	18.44	18.44T	
ELEMENT FILTER	1	75.05	75.05T	
SHOP MECHANIC LABOR	0.25	105.00	26.25	
REMOVE AND REPLACE CABIN AND ENGINE AIR FILTERS AIR CLEANER	1	113.64	113.64T	
FILTER	1	28.25	28.25T	
SHOP MECHANIC LABOR	0.5	105.00	52.50	
REMOVE AND REPLACE AIR DRYER CARTRIDGE AIR DRYER FILTER	1	125.47	125.47T	
SHOP MECHANIC LABOR	0.75	105.00	78.75	
REMOVE AND REPLACE BROKEN AIR CLEANER COVER AIR CLEANER COVER	1	114.67	114.67T	
SHOP MECHANIC LABOR	0.25	105.00	26.25	
FIX COOLANT LINE DRAIN AND VACUUM REFILL WITH COOLANT PRESTONE LOW TOX ANTIFREEZE	6	32.18667	193.12T	
Thank you for your business.			<b>Subtotal</b>	
			<b>Sales Tax (0.0%)</b>	
			<b>Total</b>	

ACCURATE EQUIPMENT SERVICE,  
 INC  
 PO Box 412  
 Ramona, CA 92065

# Estimate

Date	Estimate #
8/24/2020	165

Name / Address
USFS 6018

Description	Qty	Rate	Project	
			Total	
SHOP MECHANIC LABOR	2	105.00	210.00	
COOLANT DISPOSAL FEE	6	0.65	3.90	
REPAIR FUEL PRIMER PUMP				
FUEL PRIMER PUMP	1	194.70	194.70T	
SHOP MECHANIC LABOR	2	105.00	210.00	
SEVERAL COMPARTMENT LIGHTS OUT REMOVE AND REPLACE COMPARTMENT LIGHTS WITH LED LIGHTS				
LED 2" ROUND LIGHT	32	14.54688	465.50T	
SHOP MECHANIC LABOR	2	105.00	210.00	
REMOVE AND REPLACE BROKEN PRIMER VALVE				
PVG VALVE WITH SWITCH	1	530.33	530.33T	
SHIPPING AND HANDLING	1	35.00	35.00T	
SHOP MECHANIC LABOR	3	105.00	315.00	
REPAIR AC SYSTEM AC SYSTEM IS NOT ORIGINAL TO THE TRUCK. A NEWER MODEL WAS PUT ON. RECHARGE AC SYSTEM				
FILTER/DRIER	1	351.23	351.23T	
SUCTION LINE TUBE ASSEMBLY	1	283.54	283.54T	
INLET MOUNTING PLATE	1	54.60	54.60T	
SPECIAL FASTENER SCREW	1	38.93	38.93T	
AC EXPANSION VALVE	1	119.97	119.97T	
OUTLET MOUNTING PLATE	1	84.90	84.90T	
R134 REFRIGERANT, PER LB	2	18.99	37.98T	
SHOP MECHANIC LABOR	6	105.00	630.00	
Thank you for your business.			<b>Subtotal</b>	
			<b>Sales Tax (0.0%)</b>	
			<b>Total</b>	

ACCURATE EQUIPMENT SERVICE,  
 INC  
 PO Box 412  
 Ramona, CA 92065

# Estimate

Date	Estimate #
8/24/2020	165

Name / Address
USFS 6018

			Project
Description	Qty	Rate	Total
TRUCK CURRENTLY DOES NOT HAVE ANY FOREST SERVICE DECALS			
MUST PUT ON ALL DECALS			
FULL TRUCK STICKER SET	1	495.00	495.00
SHOP MECHANIC LABOR	4	105.00	420.00
ADMINISTRATIVE FEES	1	404.50	404.50
Thank you for your business.			
<b>Subtotal</b>			\$8,094.50
<b>Sales Tax (0.0%)</b>			\$0.00
<b>Total</b>			\$8,094.50

91QSCI-22-328 #401