

Driveable: Yes
 Visual Frame Damage: N
 GeneralCondition: 4.0



Stock: 264912
 Date: 11/09/2021 11:14 AM
 Sale Date: 11/19/2021
 Lot: G0010

Year 2016	Make CHEVRO	Model IMPALA LIMITED		Body Type SEDAN	VIN 2G1WD5E32G1102406
Drive FWD	Ext Color White	Int Color Black	Int Material Cloth	Sound w/CD	Roof Hard Top
Fuel Gas	Mileage 40014	Odo. Type Digital	Engine 6-Cyl. 3.6Liters	Transmission Automatic	Airbags Dual
Doors 4				Plate Expires	End of Term

- **Accessories:** Keyless entry remote(s), (1) Ignition keys (1)
- **Interior:** Seat count, (5) Power mirrors, Child seat anchors, Steering wheel controls, Dual air bags, Cd player, Security alarm, Tachometer, Rear view mirror, Rear defroster, 5 passenger seating, Tilt steering wheel, Bucket seats: front, (2) Power locks, Power windows, Cruise control, Tilt wheel, Safety restraint system, Owners manual, Odometer scale, (Miles) Speedometer, Power driver and passenger seat, Traction control, Side air bags
- **Exterior:** Fog lights, Antenna, Brake light, W/s wiper, Outside mirrors, Alloy wheels, 4 door cab, Child safety locks, Spare tire, Tinted windows
- **Equipment:** Automatic headlights, Trip counter, Air conditioner, No rear air conditioning, Fuel injected engine, Front wheel drive, Liquid cooled, Antilock brake system, Power steering, Power brakes, Heater
- **Electronics:** Auxiliary pwr outlet, Trip computer, Tire pressure monitor system
- **Other:** 50 state emissions

Tires	Left	Right
Front	08/32in Federal 235/55ZR17	08/32in Federal 235/55ZR17
Rear	06/32in Goodyear 235/55R17	05/32in Goodyear 235/55R17
Spare		



Announcements:

- *
- Former law enforcement vehicle

Notes:

Inspection Date

Description

10/20/2021	Deck lid mult scratches light - Chips. 2. Repair.
10/20/2021	Front bumper mult scratches heavy - Light scratches and chips. 3. Repair.
10/20/2021	Front bumper photo only
11/08/2021	Oil needs oil
10/20/2021	Hood mult scratches light - Chips. 2. Repair.

10/20/2021	L qtr panel mult scratches light - Chips. 2. Repair.
10/20/2021	Lf door mult scratches light - Chips. 2. Repair.
10/20/2021	Lf fender mult scratches light - Chips. 2. Repair.
10/20/2021	Lf mirror housing multiple chips - 2. Repair.
10/20/2021	Lr door mult scratches heavy - Light scratches and chips. 2. Repair.
10/20/2021	R qtr panel mult scratches light - Chips. 2. Repair.
10/20/2021	Rear bumper mult scratches light - Chips. 2. Repair.
10/20/2021	Rear bumper photo only
10/20/2021	Rf door mult scratches light - Chips. 2. Repair.
10/20/2021	Rf fender mult scratches light - Chips. 2. Repair.
10/20/2021	Rf mirror housing multiple chips - 2. Repair.
10/20/2021	Rr door mult scratches light - Chips. 2. Repair.



Other



Left front



Left rear



Right rear



Dash



Radio



Front of vehicle



Odometer



Instrument cluster



Back seat



Manufacturer plate

Engine



Trim badge



Trunk/rear cargo



Option 1



Option 2



Front bumper mult scratches heavy



Front bumper photo only



Hood mult scratches light



Lf fender mult scratches light



Lf mirror housing multiple chips



Lf door mult scratches light



Lr door mult scratches heavy



L qtr panel mult scratches light



Rear bumper mult scratches light



Rear bumper photo only



Deck lid mult scratches light



Rr door mult scratches light



R qtr panel mult scratches light



Rf door mult scratches light



Rf mirror housing multiple chips



Rf fender mult scratches light



Lf tire 08/32in tread



Rf tire 08/32in tread



Lr tire 06/32in tread



Rr tire 05/32in tread